



August 5, 2019

Mr. Daniel Boggs
Air Safety Investigator
National Transportation Safety Board
45065 Riverside Parkway
Ashburn, VA 20147

Re: N832R

Mr. Boggs,

Textron Citation 560-0585 entered West Star Aviation located in East Alton, IL for a technical survey as part of a sales agreement.

There were 2 findings related to the aircraft's environmental system that exceeded the OEM's maintenance publications criteria:

1. Air cycle machine coalescer filter, part number 21BC115G.
2. Main entrance door secondary door seal, part number R860086.

Also, a foul weather window and seal assy., part number 5511275-24 were found to exceed the OEM's maintenance publications criteria.

All 3 articles were replaced and a satisfactory operational check of the aircraft's environmental system was completed. All tasks were performed in accordance with the OEM's maintenance publications.

If you have any further question or comments, please contact me at your earliest convenience.

Regards,



Darren M. Nash
Accountable Manager
West Star Aviation