



# Equipment Work Order History Report

Unit/Serial # :133

Rpt Start Date :12/1/2021

Rpt End Date :6/27/2022

WO Type Code :\*

WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/25/2022	CLO	8813652	Repair	LAX	Cab Hot: Air Conditioning Problems		Incident	6/23/22
06/25/2022	CLO	8812181	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/22/22
06/22/2022	CLO	8808679	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/19/22
06/22/2022	CLO	8811408	Repair	CSX	SCF/SCM CSU or wiring failure		Corrective	6/22/22
06/22/2022	CLO	8811247	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/22/22
06/19/2022	CLO	8798239	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/10/22
06/18/2022	CLO	8803294	Repair	LAX	#1 Traction Motor Blower Boot Has 2 Silver Dollar Size Holes In Boot		Corrective	6/15/22
06/17/2022	CLO	8803295	Repair	LAX	BOTH Air Tank Wiring / Conduit To Air Drain Valves Damaged BAD!		Corrective	6/15/22
06/16/2022	CLO	8803279	Repair	LAX	Left Side #1 Sand Bracket Missing Top Bolt		Corrective	6/15/22
06/16/2022	CLO	8700677	Quarterly Inspection-Loco	LAX	P42 Q3 PM (SQPM)		Preventive Maint.	3/18/22
06/16/2022	CLO	8791342	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION		Preventive Maint.	6/4/22
06/15/2022	CLO	8803284	Repair	LAX	#3 Traction Motor Has Good Oil Leak Where Case Halves Meet		Corrective	6/15/22
06/10/2022	CLO	8793115	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/6/22
06/08/2022	CLO	8794990	24 Hour Inspection	WAS	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/7/22
06/06/2022	CLO	8789461	24 Hour Inspection	HIA	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/2/22
06/06/2022	CLO	8792861	Repair	HIA	FIREMAN SIDE REAR SAND KNOZZLE BROKEN		Corrective	6/6/22
06/06/2022	CLO	8792863	Repair	HIA	ENG SIDE FRONT SAND BRACKET LOOSE		Corrective	6/6/22
06/06/2022	CLO	8792860	Repair	HIA	RADIATOR WATER LOW		Corrective	6/6/22
06/06/2022	CLO	8792864	Repair	HIA	ENG SIDE FRONT DAMPER MISSING BOLTS		Corrective	6/6/22
06/04/2022	CLO	8774856	0015 Day Inspection-Loco	WAS	P42 15-DAY PM INSPECTION		Preventive Maint.	5/22/22
06/02/2022	CLO	8788070	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/1/22
06/01/2022	CLO	8779699	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/26/22
05/31/2022	CLO	8781666	Repair	CSX	A.E.S.S. Shut Down Engine/Unable To Restart		Incident	5/27/22
05/26/2022	CLO	8775712	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/23/22
05/23/2022	CLO	8774857	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/22/22
05/22/2022	CLO	8769885	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/17/22
05/22/2022	CLO	8756682	0015 Day Inspection-Loco	CSX	P42 15-DAY PM INSPECTION		Preventive Maint.	5/5/22
05/17/2022	CLO	8769804	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/17/22
05/17/2022	CLO	8765340	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/13/22
05/13/2022	CLO	8764860	Repair	CPC	Cab radio missing handset		Corrective	5/12/22
05/13/2022	CLO	8761568	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/10/22
05/10/2022	CLO	8756683	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/5/22
05/08/2022	CLO	798895	Modification-Loco (Expense)	OAK	P42 Inspect Main Reservoir Pipe		Campaign	2/1/06
05/05/2022	CLO	8743524	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	4/25/22



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
05/05/2022	CLO	8730406	0015 Day Inspection-Loco	CPC	P42 15-DAY PM INSPECTION		Preventive Maint.	4/13/22
05/04/2022	CLO	8754515	Repair	CPC	#3 wheel Thin flange (TRUED)		Corrective	5/4/22
05/03/2022	CLO	7528001	Continuous Maintenance (CM)	CSX	P42 Walkway Fuel Hose		Preventive Maint.	9/20/19
05/03/2022	CLO	8751046	Repair	CSX	Transition section cracked		Corrective	5/1/22
05/02/2022	CLO	8751053	Repair	CSX	Brake cylinder pressure too low to run eab		Corrective	5/1/22
04/25/2022	CLO	8739883	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	4/21/22
04/21/2022	CLO	8735002	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	4/17/22
04/20/2022	CLO	8736220	Repair	LAX	Traction Motor #3 Leaking		Corrective	4/19/22
04/17/2022	CLO	8732824	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	4/15/22
04/15/2022	CLO	8730407	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	4/13/22
04/13/2022	CLO	8718014	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	4/2/22
04/13/2022	CLO	8718000	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION		Preventive Maint.	4/2/22
04/12/2022	CLO	8725463	Repair	LAX	Engine Dead - Would Not Start at ABQ		Incident	4/8/22
04/07/2022	CLO	8718727	Repair	LAX	Bail off issues - pressure switch/valve b/o		Incident	4/3/22
04/02/2022	CLO	8716298	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	4/1/22
04/02/2022	CLO	8700678	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION		Preventive Maint.	3/18/22
04/01/2022	CLO	8708748	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	3/25/22
03/30/2022	CLO	8708893	Repair	CSX	ATS Penalty - Cut Out		Incident	3/26/22
03/25/2022	CLO	8700679	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	3/18/22
03/22/2022	CLO	8696670	Repair	LAX	Rear Coupler is Condemnable		Corrective	3/16/22
03/22/2022	CLO	8696620	Repair	LAX	Coolant needs additive (pink borate)		Corrective	3/16/22
03/21/2022	CLO	8696615	Repair	LAX	Coolant leak under turbo		Corrective	3/16/22
03/19/2022	CLO	8699742	Repair	LAX	reprofile wheels traction motor number one		Corrective	3/18/22
03/18/2022	CLO	8693266	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	3/12/22
03/18/2022	CLO	8689297	Repair	LAX	Speedometer Jumping		Incident	3/9/22
03/18/2022	CLO	8697844	Repair	LAX	TM#2 Brushes are short and damage		Corrective	3/16/22
03/18/2022	CLO	8696616	Repair	LAX	Front Fireman side 480V Receptacle Damage and Misaligned		Corrective	3/16/22
03/18/2022	CLO	8683944	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION		Preventive Maint.	3/4/22
03/18/2022	CLO	8602642	Quarterly Inspection-Loco	LAX	P42 Q2 PM (SQPM)		Preventive Maint.	12/25/21
03/12/2022	CLO	8688468	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	3/8/22
03/08/2022	CLO	8686040	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	3/7/22
03/07/2022	CLO	8683945	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	3/4/22
03/04/2022	CLO	8671660	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	2/22/22
03/04/2022	CLO	8668171	0015 Day Inspection-Loco	CPC	P42 15-DAY PM INSPECTION		Preventive Maint.	2/19/22
02/26/2022	CLO	8676127	Repair	OAK	Missing Radio		Corrective	2/26/22



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
02/22/2022	CLO	8663841	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	2/16/22
02/19/2022	CLO	8643841	0015 Day Inspection-Loco	CPC	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	1/29/22
02/16/2022	CLO	8648617	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	2/2/22
02/16/2022	CLO	8662056	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	2/14/22
02/14/2022	CLO	8660780	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	2/13/22
02/13/2022	CLO	8652609	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	2/6/22
02/08/2022	CLO	8654701	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	2/8/22
02/06/2022	CLO	8650377	24 Hour Inspection	OAK	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	2/3/22
02/03/2022	CLO	8645925	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	1/31/22
01/31/2022	CLO	8640312	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	1/26/22
01/29/2022	CLO	8629672	0015 Day Inspection-Loco	CPC	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	1/17/22
01/26/2022	CLO	8637622	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	1/24/22
01/24/2022	CLO	8635034	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	1/21/22
01/21/2022	CLO	8632729	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	1/19/22
01/19/2022	CLO	8622948	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	1/11/22
01/17/2022	CLO	8602504	0015 Day Inspection-Loco	SEA	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	12/25/21
01/11/2022	CLO	8608764	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/30/21
01/11/2022	CLO	8621985	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	1/10/22
12/30/2021	CLO	8604725	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/27/21
12/27/2021	CLO	8602643	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/25/21
12/25/2021	CLO	8590032	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/15/21
12/25/2021	CLO	8490805	Quarterly Inspection-Loco	CSX	P42 Q1 PM (SQPM)	[REDACTED]	Preventive Maint.	9/30/21
12/25/2021	CLO	8586039	0015 Day Inspection-Loco	CSX	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	12/11/21
12/25/2021	CLO	8597066	Repair	CSX	E/side windshield leaking.	[REDACTED]	Corrective	12/20/21
12/25/2021	CLO	8597080	Repair	CSX	turbo coolant drain plug leaking.	[REDACTED]	Corrective	12/20/21
12/25/2021	CLO	8597061	Repair	CSX	F/side eng room to a/c room door latch coming off.	[REDACTED]	Corrective	12/20/21
12/25/2021	CLO	8597069	Repair	CSX	F/seat L armrest torn	[REDACTED]	Corrective	12/20/21
12/25/2021	CLO	8597070	Repair	CSX	M/seat R armrest torn.	[REDACTED]	Corrective	12/20/21
12/25/2021	CLO	8597073	Repair	CSX	Transition section cracked.	[REDACTED]	Corrective	12/20/21
12/25/2021	CLO	8597075	Repair	CSX	F/side engine roof bolt loose.	[REDACTED]	Corrective	12/20/21
12/25/2021	CLO	8597052	Repair	CSX	E/seat cushion torn.	[REDACTED]	Corrective	12/20/21
12/23/2021	CLO	8597064	Repair	CSX	BP leak test failed, BC increased 18 lbs in 2 minutes.	[REDACTED]	Corrective	12/20/21
12/23/2021	CLO	8599405	Repair	CSX	F/S rear sand bracket bent out./ sand nozzle torn.	[REDACTED]	Corrective	12/22/21
12/23/2021	CLO	8598318	Repair	CSX	f/s sand bracket cracked	[REDACTED]	Corrective	12/21/21
12/22/2021	CLO	8598312	Repair	CSX	cab signal bracket cracked	[REDACTED]	Corrective	12/21/21
12/22/2021	CLO	8599316	Repair	CSX	BKT -A & B mag valve leaking	[REDACTED]	Corrective	12/22/21



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
12/21/2021	CLO	8598320	Repair	CSX	missing horn cones	[REDACTED]	Corrective	12/21/21
12/21/2021	CLO	8598004	Repair	CSX	fire exting. out of date	[REDACTED]	Corrective	12/21/21
12/17/2021	CLO	8593498	Repair	CSX	TRUED ALL WHEELS	[REDACTED]	Corrective	12/17/21
12/15/2021	CLO	8588776	24 Hour Inspection	NOL	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/14/21
12/14/2021	CLO	8586619	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/12/21
12/12/2021	CLO	8581946	24 Hour Inspection	BEE	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/8/21
12/11/2021	CLO	8564705	0015 Day Inspection-Loco	CPC	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	11/25/21
12/08/2021	CLO	8578669	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/6/21
12/06/2021	CLO	8571752	24 Hour Inspection	CPC	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/1/21
12/01/2021	CLO	8566999	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	11/27/21
12/01/2021	CLO	8544221	Repair	CSX	QAI for Unit: 133,RS Head 7 High Pressure Cable Missing Torque Seals	[REDACTED]	Corrective	11/10/21



# Equipment Work Order History Report

Unit/Serial # :166  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/25/2022	CLO	8798241	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION		Preventive Maint.	6/10/22
06/19/2022	CLO	8800667	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/12/22
06/19/2022	CLO	8801906	Repair	LAX	Brake Issues		Incident	6/13/22
06/19/2022	CLO	8799915	Repair	LAX	speedo jumps		Corrective	6/11/22
06/19/2022	CLO	8805550	Repair	LAX	Loading Problems		Incident	6/16/22
06/12/2022	CLO	8797881	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/9/22
06/10/2022	CLO	8796154	Repair	CSX	top door engineer side needs new frame seal		Corrective	6/8/22
06/10/2022	CLO	8628894	0015 Day Inspection-Loco	CSX	P42 15-DAY PM INSPECTION		Preventive Maint.	1/16/22
06/10/2022	CLO	8636675	Repair	CSX	speedometer jumps at 60MPH		Corrective	1/23/22
06/09/2022	CLO	8795090	24 Hour Inspection	CSX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/7/22
06/07/2022	CLO	8791131	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/4/22
06/04/2022	CLO	8786450	24 Hour Inspection	NOL	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	6/1/22
06/01/2022	CLO	8783188	24 Hour Inspection	NOL	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/29/22
05/29/2022	CLO	8782980	24 Hour Inspection	BEE	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	5/29/22
05/29/2022	CLO	8636120	24 Hour Inspection	BEE	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	1/22/22
05/27/2022	CLO	8653738	Component Planned Replacement Quarterly	BEE	BEE - P42 - LCPM Paint (10 Year)		Life Cycle Maint.	2/7/22
05/24/2022	CLO	8777300	Inspection-Loco Quarterly	BEE	P42 Q2 PM (SQPM)		Preventive Maint.	5/24/22
05/24/2022	CLO	8557503	Inspection-Loco Quarterly	BEE	P42 Q1 PM (SQPM)		Preventive Maint.	11/19/21
05/24/2022	CLO	8275110	Modification-Loco (Expense)	BEE	CAM098 - Plug Kit Instal MB-20-068 [P40/P42]		Campaign	4/21/21
05/24/2022	CLO	8632399	Repair	BEE	(H) Fuel Level Not Reporting sensor #09064081 (TCD Level I - Urgent)		Corrective	1/19/22
05/24/2022	CLO	8671073	Repair	BEE	Inspection Ports		Corrective	2/22/22
01/26/2022	CLO	8639518	Repair	CSX	REPROFILE ALL WHEELS SEE D/R REMARKS FOR FINISHED RIM SIZES		Corrective	1/26/22
01/22/2022	CLO	8615267	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	1/5/22
01/20/2022	CLO	8633107	Repair	LAX	Lateral Bolts on Fireman Side of the rear truck loose		Corrective	1/20/22
01/18/2022	CLO	8630402	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	1/18/22
01/16/2022	CLO	8612817	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION		Preventive Maint.	1/3/22
01/09/2022	CLO	8619903	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	1/8/22
01/07/2022	CLO	8617813	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	1/7/22
01/05/2022	CLO	8610735	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	1/1/22
01/03/2022	CLO	8594501	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION		Preventive Maint.	12/18/21
01/01/2022	CLO	8608333	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	12/30/21
12/30/2021	CLO	8605965	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION		Daily Inspection	12/28/21



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
12/28/2021	CLO	8564900	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	11/25/21
12/26/2021	CLO	8603007	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/26/21
12/24/2021	CLO	8601065	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/23/21
12/24/2021	CLO	7897823	Modification (Capital)	SEA	MOD00556 - 90 Degree Cable adaptor[DL]	[REDACTED]	Campaign	6/9/20
12/22/2021	CLO	8598610	Repair	LAX	E/S ON AXLE #4 SAND BRACKET UPPER BOLT MISSING	[REDACTED]	Corrective	12/22/21
12/22/2021	CLO	8594096	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/18/21
12/20/2021	CLO	8595798	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/19/21
12/18/2021	CLO	8584635	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	12/10/21
12/18/2021	CLO	8583279	Repair	LAX	Event Recorder - No Downloads (TCD Level I - Urgent)	[REDACTED]	Corrective	12/9/21
12/16/2021	CLO	8591161	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/15/21
12/14/2021	CLO	8588361	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/14/21
12/12/2021	CLO	8586209	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/11/21
12/10/2021	CLO	8573709	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	12/2/21
12/10/2021	CLO	8292142	Repair	LAX	HVAC vent over electrical cabinets missing cover	[REDACTED]	Corrective	5/4/21
12/10/2021	CLO	8570998	Repair	LAX	QAI for Unit: 166,Engineer side #8 low fuel pressure hose not torque stripped	[REDACTED]	Corrective	11/30/21
12/08/2021	CLO	8580712	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/7/21
12/08/2021	CLO	8579569	Repair	SEA	Wi-PU crosslink with Loco 196.call Support for assistance (TCD Level I - Urgent)	[REDACTED]	Corrective	12/7/21
12/08/2021	CLO	8574867	Repair	SEA	Wi-PU crosslink with another Locomotive 196. call Support for assistance (TCD	[REDACTED]	Corrective	12/3/21
12/08/2021	CLO	7767385	Wreck/Accident (Expense)	CSX	TRESPASSER INCIDENT -Download/Inspect	[REDACTED]	Incident	2/17/20
12/06/2021	CLO	8577804	24 Hour Inspection	LAX	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/5/21
12/04/2021	CLO	8575840	24 Hour Inspection	SEA	P42/P40 LOCOM DAILY INSPECTION	[REDACTED]	Daily Inspection	12/3/21
12/02/2021	CLO	8559679	0015 Day Inspection-Loco	LAX	P42 15-DAY PM INSPECTION	[REDACTED]	Preventive Maint.	11/21/21



# Equipment Work Order History Report

Unit/Serial # :61053

Rpt Start Date :12/1/2021

Rpt End Date :6/27/2022

WO Type Code :\*

WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
05/07/2022	CLO	8524172	Semi-Annual-Car	LAX	184d - Viewliner II Bag Inspection		Preventive Maint.	10/26/21
05/06/2022	CLO	8756644	Repair	LAX	B/L and A/L 480V cable damage		Corrective	5/5/22
05/05/2022	CLO	8679303	Repair	LAX	FLAT SPOT BX # 8 FINISHED RIM SIZE		Corrective	3/1/22
05/05/2022	CLO	8753091	Repair	LAX	WHEEL 1 & 2 FLAT SPOT W/T		Corrective	5/3/22
05/05/2022	CLO	8753092	Repair	LAX	WHEEL 3 & 4 FLAT SPOT W/T		Corrective	5/3/22
03/04/2022	CLO	8683457	Repair	LAX	WHEEL # 4 REPROFILE		Corrective	3/4/22
03/04/2022	CLO	8683454	Repair	LAX	WHEEL #6 REPROFILE		Corrective	3/4/22
12/13/2021	CLO	8539675	Repair	LAX	FLAT SPOT BX Axel #2 multiple small flats, W/T, roll all wheels		Corrective	11/7/21
12/13/2021	CLO	8539670	Repair	LAX	FLAT SPOT BX Wheel # 1, NT, Roll all wheels.		Corrective	11/7/21
12/13/2021	CLO	8539673	Repair	LAX	FLAT SPOT BX Wheel #8, WT, Roll all wheel		Corrective	11/7/21
12/09/2021	CLO	8581976	Repair	LAX	eMAP21A-(Vanity) Toilet paper dispenser rolls are BO./H-/A-End/ADA/Lower		Incident	12/8/21



# Equipment Work Order History Report

Unit/Serial # :39045  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/19/2022	CLO	8806382	Repair	LAX	eMAP21A-(110v AC Electric Otfl Dmg) Room # 5 the electrical out is loosely hangi		Corrective	6/17/22
06/08/2022	CLO	8795007	Repair	CPC	eMAP21A-(Car Too Hot) Too warm on B end.//B-End//		Incident	6/7/22
06/03/2022	CLO	8783499	Repair	CPC	eMAP21A-(Toilet Not Operatable) Restroom ?1? not working////		Incident	5/29/22
05/29/2022	CLO	8782746	Repair	LAX	eMAP21A-(Car Too Hot) Controls do not work in the room and attendant instructs t		Incident	5/28/22
05/10/2022	CLO	8646741	Overhaul (Capital)	BEE	BEE - Superliner II Transition Sleepers/Dorms - Level 2 Overhaul		Campaign	2/1/22
05/10/2022	CLO	5682782	Air Brake Inspection-Car	BEE	AMT SYS - COT&S		Preventive Maint.	7/6/16
05/09/2022	CLO	7595823	0030 Day Inspection-Car Special Project	BEE	30 Day Carpet Extraction --closed BEE OH		Preventive Maint.	11/6/19
05/06/2022	CLO	7315764	Quarterly Inspection-Car	BEE	MOD00501 - Waste Line Flush - SL2		Campaign	4/29/19
05/06/2022	CLO	7905506	Annual Inspection-Car	BEE	SL II TRANS.SLEEPER ANNUAL PM INSP--closed BEE OH		Preventive Maint.	6/16/20
05/06/2022	CLO	7905507	Modification (Capital)	BEE	SL II Annual Handbrake Insp - closed BEE OH		Preventive Maint.	6/16/20
05/04/2022	CLO	8713905	Modification (Capital)	BEE	MOD00466 - Room H Handrails (SL2)		Campaign	3/30/22
05/04/2022	CLO	7495158	Modification (Capital)	BEE	MOD00421 Emergency Lighting Upgrade (SL2 Trans SLEEPER)		Campaign	8/28/19
02/01/2022	CLO	7928757	Repair	BEE	BEE - Prep car for Service Reduction - 238 compliant to store		Corrective	7/6/20





# Equipment Work Order History Report

Unit/Serial # :32104  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
05/28/2022	CLO	8780536	Repair	CPC	eMAP21A-(Car Too Hot) B end too hot//B-End//		Incident	5/27/22
05/28/2022	CLO	8781294	Repair	CPC	ac not staying on		Corrective	5/27/22
05/26/2022	CLO	8773795	Repair	LAX	UPHY/INTERIOR PM REPAIRS		Corrective	5/21/22
05/26/2022	CLO	8773592	Repair	LAX	THIN FLANGE WH #3,4,7,8 W/T		Corrective	5/20/22
05/24/2022	CLO	8692367	Quarterly Inspection-Car	LAX	92d - Superliner II Sleeper		Preventive Maint.	3/11/22
05/24/2022	CLO	8773883	Repair	LAX	Electrical Repairs		Corrective	5/21/22
05/24/2022	CLO	8773740	Repair	LAX	SMW REPAIR		Corrective	5/21/22
05/24/2022	CLO	8777487	Repair	LAX	PMF Electrical Defects		Corrective	5/24/22
05/24/2022	CLO	8773824	Repair	LAX	Carpenter Repair PMF		Corrective	5/21/22
05/24/2022	CLO	8768044	Repair	LAX	QAI - Carpets, wall in front of delux rooms filthy from HVAC vents		Corrective	5/16/22
05/23/2022	CLO	8773593	Repair	LAX	WHEEL PIT REPAIRS		Corrective	5/20/22
05/12/2022	CLO	8692331	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	3/11/22
04/26/2022	CLO	8734054	Repair	LAX	RM10 THE TRACK FOR THEDOOR IS DAMAGE (ABOVE THE DOOR)		Corrective	4/16/22
04/09/2022	CLO	8726127	Repair	LAX	SMW Repairs - Room D Toilet Leaking Water		Corrective	4/9/22
03/18/2022	CLO	8689381	Repair	LAX	23 eco seat, 10 delx 12 pads and 8 mattresses baby pad jumping seat		Corrective	3/9/22
03/18/2022	CLO	8692380	Repair	LAX	ROOM #9 BUNK LATCH B/O		Corrective	3/11/22
03/16/2022	CLO	8688079	Repair	LAX	eMAP21A-(Attendant Call Sys/Button) Call bell system bo.////		Incident	3/8/22
03/11/2022	CLO	8580633	Quarterly Inspection-Car	LAX	368d - Superliner II Sleeper		Preventive Maint.	12/7/21
03/11/2022	CLO	8690974	Repair	LAX	A/R brake indicator (amber) out		Corrective	3/10/22
03/11/2022	CLO	8690036	Repair	LAX	Carpenter Repair PMF		Corrective	3/10/22
03/11/2022	CLO	8455927	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	9/3/21
03/11/2022	CLO	8688089	Repair	LAX	eMAP21A-(Shower) Room C shower leaking onto the lower level vestibule.////		Incident	3/8/22
03/11/2022	CLO	8683679	Repair	LAX	eMAP21A-(Shower) Shower leaked water onto floor soaking the carpet. Passengers w		Incident	3/4/22
03/11/2022	CLO	8690022	Repair	LAX	No floor heat on @ RM # 8.		Corrective	3/10/22
03/11/2022	CLO	8690818	Repair	LAX	smw inspections		Corrective	3/10/22
03/11/2022	CLO	8689997	Repair	LAX	Electrical Inspections		Corrective	3/10/22
03/11/2022	CLO	8684445	Repair	LAX	eMAP21A-(Leaks) Water leaking above to restroom area in lower level.////Lower		Corrective	3/4/22
03/10/2022	CLO	8083534	Modification (Capital)	LAX	MOD00466 - Room H Handrails (SL2)		Campaign	11/13/20
03/10/2022	CLO	8690029	Repair	LAX	SMW Repairs		Corrective	3/10/22
03/10/2022	CLO	8690018	Repair	LAX	Electrical Inspections		Corrective	3/10/22
03/10/2022	CLO	7236901	Inspection/Survey-Car	LAX	CHI - EPA Three Year Water Sampling		Campaign	3/5/19
02/15/2022	CLO	8378029	Annual Inspection-Car	LAX	Superliner II Annual Handbrake Inspection		Preventive Maint.	7/8/21



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
02/12/2022	CLO	8659956	Repair	CPC	Smoke deflector missing		Corrective	2/12/22
02/11/2022	CLO	8652949	Repair	CPC	Freeze damage in bathroom #2 and the H/C Rm		Corrective	2/6/22
02/01/2022	CLO	8647340	Repair	CPC	High flange wheel box 7		Corrective	2/1/22
02/01/2022	CLO	8626079	Repair	CPC	hi flange b/o too thin to cut		Corrective	1/13/22
01/11/2022	CLO	8623217	Repair	LAX	DECAL IS MISSING UPPER LEVEL (RM A-E RM 1-10)		Corrective	1/11/22
12/07/2021	CLO	8579987	Repair	BPK	QAI for Unit: 32104,UL Center Smoke detector is missing		Corrective	12/7/21
12/07/2021	CLO	8579986	Repair	BPK	QAI for Unit: 32104,Emergency window decal is peeling off Room 6		Corrective	12/7/21
12/07/2021	CLO	8579990	Repair	BPK	QAI for Unit: 32104,All Aisle, Stair, Vestibule and "Exit" lights are inoperativ		Corrective	12/7/21
12/07/2021	CLO	8579992	Repair	BPK	QAI for Unit: 32104,A&B end doors are inoperative		Corrective	12/7/21
12/07/2021	CLO	8579991	Repair	BPK	QAI for Unit: 32104,x-Inoperative for Doors, Manual / Door, Body End		Corrective	12/7/21
12/07/2021	CLO	8579993	Repair	BPK	QAI for Unit: 32104,Attendant call system is inoperative		Corrective	12/7/21
12/07/2021	CLO	8579989	Repair	BPK	QAI for Unit: 32104,Rooms B&D RR door inner door latch is loose		Corrective	12/7/21
12/07/2021	CLO	8472028	Quarterly Inspection-Car	BPK	92d - Superliner II Sleeper		Preventive Maint.	9/16/21
12/07/2021	CLO	8579677	Repair	BPK	92d - PM E-Clean per MCC004 - Sleeper		Corrective	12/7/21
12/06/2021	CLO	8574272	Repair	BPK	emergency window inspection		Corrective	12/2/21
12/04/2021	CLO	8574540	Repair	BPK	A End coupler height B/O		Corrective	12/3/21
12/02/2021	CLO	8573631	Repair	BPK	Inspection and trash removal		Corrective	12/2/21



# Equipment Work Order History Report

Unit/Serial # :38060  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/25/2022	CLO	8814989	Repair	LAX	eMAP21A-(End Doors) Transition between dining car and lounge car has Hilow varia		Corrective	6/24/22
06/22/2022	CLO	8810054	Repair	CPC	eMAP21A-(Elevator/Dumbwaiter) Right side dumb waiter will not open. Shows fault.		Incident	6/21/22
06/19/2022	CLO	8806331	Repair	LAX	eMAP21A-(Elevator/Dumbwaiter) The right side elevator not working////		Incident	6/17/22
06/19/2022	CLO	8805604	Repair	LAX	b end blower not staying on		Corrective	6/16/22
06/19/2022	CLO	8806328	Repair	LAX	eMAP21A-(HVAC Failure) Hot downstairs... Cold upstairs////		Incident	6/17/22
06/12/2022	CLO	8796345	Repair	LAX	eMAP21A-(High/Low (Vestibule)) Ruff ride on A end. Bounce and sway //A-End//		Incident	6/8/22
06/12/2022	CLO	8797929	Repair	LAX	eMAP21A-(Vibration/Rocking) The car is extremely rough!! Also it is a high low v		Incident	6/10/22
06/12/2022	CLO	8757658	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	5/6/22
06/12/2022	CLO	8797761	Repair	LAX	eMAP21A-(Car Too Hot) Ac unit is out. Abq mechanical checked it and was unable t		Incident	6/9/22
06/12/2022	CLO	8797748	Repair	LAX	b end h vac will not stay on		Corrective	6/9/22
06/08/2022	CLO	8793432	Repair	CPC	right side dumb waiter B/O		Corrective	6/6/22
06/08/2022	CLO	8794815	Repair	CPC	eMAP21A-(High/Low (Vestibule)) Ruff ride//A-End//		Incident	6/7/22
05/26/2022	CLO	8771730	Repair	LAX	WHEEL PIT REPAIRS		Corrective	5/19/22
05/26/2022	CLO	8770337	Repair	LAX	A/L Inner Bolster Spring Broken		Corrective	5/18/22
05/26/2022	CLO	8771946	Repair	LAX	HVAC temp. cntrl. panel yellow 1/3 cool light is on continually.		Corrective	5/19/22
05/25/2022	CLO	8773869	Repair	LAX	Gaylord Motor duct NIS		Corrective	5/21/22
05/24/2022	CLO	8771711	Repair	LAX	THIN FLANGE ON WHEEL #7 W/T		Corrective	5/19/22
05/24/2022	CLO	8771703	Repair	LAX	HIGH FLANGE ON WHEEL # 6 W/T		Corrective	5/19/22
05/24/2022	CLO	8771709	Repair	LAX	THIN FLANGE ON WHEEL #3 W/T		Corrective	5/19/22
05/21/2022	CLO	8771700	Repair	LAX	HIGH FLANGE ON WHEEL # 1 W/T		Corrective	5/19/22
05/21/2022	CLO	8771943	Repair	LAX	HVAC a-end has a damper fault.		Corrective	5/19/22
05/21/2022	CLO	8756568	Special Project	LAX	CAM108 - COVID Signage Removal [SL2		Campaign	5/5/22
05/21/2022	CLO	8769875	Repair	LAX	eMAP21A-(HVAC Failure) Thermostat is not working correctly. Car temperature does		Incident	5/17/22
05/21/2022	CLO	8772194	Repair	LAX	PMF Carpenter Defects		Corrective	5/19/22
05/21/2022	CLO	8772255	Repair	LAX	SMW repairs		Corrective	5/19/22
05/21/2022	CLO	8684543	Quarterly Inspection-Car	LAX	92d- Superliner II Diner		Preventive Maint.	3/5/22
05/21/2022	CLO	8773699	Repair	LAX	ALL DINNER PARTS MISSING		Corrective	5/20/22
05/14/2022	CLO	8763049	Repair	LAX	eMAP21A-(Microwave) Microwave shorts out////Lower		Incident	5/11/22
05/06/2022	CLO	8684532	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	3/5/22
05/06/2022	CLO	8754924	Repair	LAX	QAI for Unit: 38060,LLEPM emergency light strap A-End.		Corrective	5/4/22
04/30/2022	CLO	8748536	Repair	SEA	Loss of Shunt - Please Inspect		Incident	4/28/22



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
04/28/2022	CLO	8746801	Repair	LAX	eMAP21A-(PA System) POS system base and drawer broken.////	██████	Corrective	4/27/22
04/24/2022	CLO	8741785	Repair	LAX	eMAP21A-(Elevator/Dumbwaiter) Right elevator broke inner door won't close to let	██████	Incident	4/23/22
04/22/2022	CLO	8739998	Repair	SEA	eMAP21A-(Elevator/Dumbwaiter) The right elevator does not work.////	██████	Incident	4/21/22
04/16/2022	CLO	8732750	Repair	LAX	eMAP21A-(Elevator/Dumbwaiter) Right outermost elevator door stiffness up.////Uppe	██████	Incident	4/15/22
04/08/2022	CLO	8723643	Repair	LAX	eMAP21A-(Warming Table) Food warmer tray circuit breaker constantly tripping. Ne	██████	Incident	4/7/22
03/29/2022	CLO	8705573	Repair	SEA	QAI for Unit: 38060,LLEPM Emergency lighting out on A-End of car.	██████	Corrective	3/23/22
03/27/2022	CLO	8709122	Repair	LAX	eMAP21A-(Elevator/Dumbwaiter) Inner door opens outer door is closed electrical f	██████	Incident	3/26/22
03/27/2022	CLO	8709123	Repair	LAX	Dumbwaiter Inoperative	██████	Incident	3/26/22
03/27/2022	CLO	8709408	Repair	LAX	03/26/22 , #11 , dumbwaiter	██████	Corrective	3/26/22
03/21/2022	CLO	8702159	Repair	LAX	eMAP21A-(Elevator/Dumbwaiter) Right elevator is bad order//B-End//	██████	Incident	3/20/22
03/15/2022	CLO	8694798	Repair	LAX	eMAP21A-(Coffee Maker) Hot water valve bo.////	██████	Incident	3/14/22
03/15/2022	CLO	8693251	Repair	LAX	eMAP21A-(Coffee Maker) hot water lever bo.////	██████	Incident	3/12/22
03/15/2022	CLO	8694790	Repair	LAX	eMAP21A-(110v AC Electric Outl Dmg) Stewards desk outlet bo. Upstairs dining car	██████	Corrective	3/14/22
03/11/2022	CLO	8691758	Repair	LAX	SMW repair sink sprayer b/o	██████	Corrective	3/11/22
03/11/2022	CLO	8691637	Repair	LAX	freezer #1 shelves (2) missing	██████	Corrective	3/11/22
03/06/2022	CLO	8682798	Repair	LAX	HVAC a-end failed shunt trip test.	██████	Corrective	3/3/22
03/05/2022	CLO	8684529	Repair	LAX	B/L vestibule door latch damaged	██████	Corrective	3/5/22
03/05/2022	CLO	8575117	Quarterly Inspection-Car	LAX	92d- Superliner II Diner	██████	Preventive Maint.	12/3/21
03/05/2022	CLO	8569822	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (Superliner II)	██████	Preventive Maint.	11/30/21
03/04/2022	CLO	8682888	Repair	LAX	Refrigeration Repair	██████	Corrective	3/3/22
03/04/2022	CLO	8682649	Repair	LAX	SMW	██████	Corrective	3/3/22
03/04/2022	CLO	8682730	Repair	LAX	PM Carp. Defects	██████	Corrective	3/3/22
03/04/2022	CLO	8683219	Repair	LAX	NEED TO CHECK HANDBRAKE	██████	Corrective	3/4/22
03/02/2022	CLO	8678747	Repair	LAX	eMAP21A-(Vibration/Rocking) Very rough ride especially at switches and max speed	██████	Incident	2/28/22
03/02/2022	CLO	8680648	Repair	LAX	WHEEL PIT DEFECTS	██████	Corrective	3/2/22
03/02/2022	CLO	8680651	Repair	LAX	WHEEL # 2 REPROFILE	██████	Corrective	3/2/22
03/02/2022	CLO	8680653	Repair	LAX	WHEEL # 7 REPROFILE	██████	Corrective	3/2/22
02/24/2022	CLO	8670369	Repair	LAX	eMAP21A-(Coffee Maker) Faulty hot water switch (no hot water)////Upper	██████	Incident	2/22/22
02/24/2022	CLO	8667968	Repair	LAX	eMAP21A-(Table-Seating) Filters are extremely dirty and tables are Getting a dir	██████	Incident	2/19/22
02/23/2022	CLO	8655352	Repair	CPC	grill thermostat B/O	██████	Corrective	2/8/22
02/08/2022	CLO	8654418	Repair	LAX	grill not working correctly	██████	Corrective	2/7/22



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
01/07/2022	CLO	8616864	Repair	CPC	eMAP21A-(Coffee Maker) No water flowing.////Upper	[REDACTED]	Incident	1/6/22
01/07/2022	CLO	8617046	Repair	CPC	eMAP21A-(Sink/Faucet) No water upstairs to faucet and. Coffee machine due I beli	[REDACTED]	Incident	1/6/22
01/07/2022	CLO	8616863	Repair	CPC	eMAP21A-(Leaks) Water leaking under upstairs sink.////Upper	[REDACTED]	Corrective	1/6/22
01/04/2022	CLO	8611087	Repair	LAX	eMAP21A-(Vibration/Rocking) Check suspension in this car. It?s a very rough ride	[REDACTED]	Incident	1/1/22
12/29/2021	CLO	8607381	Repair	LAX	SMW Repairs - Hose Reel no water	[REDACTED]	Corrective	12/29/21
12/24/2021	CLO	8601248	Repair	LAX	eMAP21A-(Elevator/Dumbwaiter) Right side elevator stopped working.////Lower	[REDACTED]	Incident	12/24/21
12/12/2021	CLO	8569706	Repair	LAX	SMW - floor drain covers missing 3sink, and middle	[REDACTED]	Corrective	11/30/21
12/04/2021	CLO	8565479	Repair	LAX	Oven parts missions shrouds 2, shelves 6, shelf holders 4	[REDACTED]	Corrective	11/26/21
12/04/2021	CLO	8571081	Repair	LAX	TRAY TABLE THT GOES IN FRONT OF WARMER IS MISSING	[REDACTED]	Corrective	11/30/21
12/03/2021	CLO	8470715	Quarterly Inspection-Car	LAX	368d - Superliner II Diner	[REDACTED]	Preventive Maint.	9/15/21
12/03/2021	CLO	8569708	Repair	LAX	SMW - above Ptrap leaking stairs sink L/L	[REDACTED]	Corrective	11/30/21
12/03/2021	CLO	8564126	Repair	LAX	SMW Repair	[REDACTED]	Corrective	11/25/21
12/02/2021	CLO	8560307	Repair	LAX	eMAP21A-(Dishwasher) ////	[REDACTED]	Incident	11/22/21
12/02/2021	CLO	8561658	Repair	LAX	WHEEL PIT REPAIRS	[REDACTED]	Corrective	11/23/21
12/01/2021	CLO	8564227	Repair	LAX	Electrician HVAC repairs	[REDACTED]	Corrective	11/25/21
12/01/2021	CLO	8564229	Repair	LAX	Electrical Repairs	[REDACTED]	Corrective	11/25/21



# Equipment Work Order History Report

Unit/Serial # :33046  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/25/2022	CLO	8811802	Repair	LAX	Microwave B/O		Corrective	6/22/22
06/25/2022	CLO	8814980	Repair	LAX	eMAP21A-(Track-Pocket) Lock bracket on outside of the Cafe door broken////Lower		Incident	6/24/22
06/25/2022	CLO	8814990	Repair	LAX	eMAP21A-(First Aid Kit) Lower level emergency equipment needs new first aid kit/		Corrective	6/24/22
06/19/2022	CLO	8798869	Repair	LAX	Electrical repairs.		Corrective	6/10/22
06/17/2022	CLO	8799311	Repair	LAX	Tread Brake Unit #4 B/O see notes		Corrective	6/11/22
06/14/2022	CLO	8798134	Repair	LAX	THIN FLANGE Wheel #4, N/T, Rim thickness 23, roll all wheels		Corrective	6/10/22
06/14/2022	CLO	8799546	Repair	LAX	wheel pit repair coupler height to low 33 1/2		Corrective	6/11/22
06/14/2022	CLO	8798138	Repair	LAX	THIN FLANGE Wheel #8, w/T, Rim thickness 31, roll all wheels		Corrective	6/10/22
06/14/2022	CLO	8798745	Repair	LAX	A End Oil Low		Corrective	6/10/22
06/14/2022	CLO	8756546	Special Project	LAX	CAM108 - COVID Signage Removal [SL2		Campaign	5/5/22
06/14/2022	CLO	8797945	Repair	LAX	eMAP21A-(Seat Cushion) Seat cushion at top of stairs needs to be replaced.////Up		Corrective	6/10/22
06/14/2022	CLO	8713198	Quarterly Inspection-Car	LAX	92d- Superliner II Lounge		Preventive Maint.	3/30/22
06/11/2022	CLO	8798902	Repair	LAX	PM Carp Repair		Corrective	6/10/22
06/06/2022	CLO	8706162	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	3/23/22
06/06/2022	CLO	8792656	Repair	LAX	eMAP21A-(Refrigerator Cooling) Refrigerator 1-7 fluctuate between 40 degrees and		Incident	6/6/22
05/29/2022	CLO	8782797	Repair	LAX	eMAP21A-(PA System) Keeps cutting in and out when train in motion////		Corrective	5/29/22
05/29/2022	CLO	8782803	Repair	LAX	eMAP21A-(Carpet) Carpets soiled, need cleaning////		Corrective	5/29/22
05/25/2022	CLO	8777729	Repair	LAX	eMAP21A-(Door Operator) Powered door on B end getting stuck takes long time to s		Incident	5/24/22
05/25/2022	CLO	8775009	Repair	LAX	eMAP21A-(Door Operator) Once door opens, it stays open. Seems like the motor is		Incident	5/22/22
05/25/2022	CLO	8772297	Repair	LAX	eMAP21A-(Diaphragm - Curtain) Diaphragms on both sides between cafe car 33046 an		Corrective	5/19/22
05/25/2022	CLO	8772291	Repair	LAX	eMAP21A-(Diaphragm - Curtain) Diaphragms on both sides between cafe car 33046 an		Corrective	5/19/22
05/13/2022	CLO	8765417	Repair	LAX	vest. side door hold open BO		Corrective	5/13/22
04/21/2022	CLO	8738921	Repair	SEA	Coffee Maker Inop		Corrective	4/21/22
04/13/2022	CLO	8727098	Repair	LAX	eMAP21A-(Coffee Maker) Coffee maker functional, wires hanging out////Lower		Incident	4/10/22
04/13/2022	CLO	8729525	Repair	LAX	eMAP21A-(Coffee Maker) Coffee pot wires sticking out by the funnel. Inoperative		Incident	4/12/22
03/30/2022	CLO	8711294	Repair	LAX	HVAC a-end is low of R22.		Corrective	3/28/22
03/30/2022	CLO	8713220	Repair	LAX	REPLACE 20 MISSING SEAT CUSHIONS & SECURE AS NEEDED		Corrective	3/30/22
03/30/2022	CLO	8711272	Repair	LAX	ELECT REPAIR'S		Corrective	3/28/22
03/30/2022	CLO	8711290	Repair	LAX	PM Carp. Defects		Corrective	3/28/22



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
03/30/2022	CLO	8713170	Repair	LAX	smw assemble car interior		Corrective	3/30/22
03/30/2022	CLO	8607466	Quarterly Inspection-Car	LAX	92d- Superliner II Lounge		Preventive Maint.	12/29/21
03/30/2022	CLO	8713147	Repair	LAX	ASSEMBLE CAR INTERIOR		Corrective	3/30/22
03/29/2022	CLO	8708989	Repair	LAX	Sup II <SHELLS WHEEL DEFECTS> WHEELS #1, #5		Corrective	3/26/22
03/29/2022	CLO	8711660	Repair	LAX	PIN ON HANDBRAKE UNIT LOOSE		Corrective	3/29/22
03/26/2022	CLO	8708993	Repair	LAX	WP REPAIRS		Corrective	3/26/22
03/26/2022	CLO	8708991	Repair	LAX	HIGH FLANGE BX WHEEL#4 W/T		Corrective	3/26/22
03/23/2022	CLO	8607465	0030 Day Inspection-Car	CPC	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	12/29/21
03/20/2022	CLO	8701901	Repair	LAX	THIN FLANGE BX Wheel #8, W/T, Roll all wheels		Corrective	3/20/22
03/20/2022	CLO	8701904	Repair	LAX	B-End Knuckle out of gauge		Corrective	3/20/22
03/16/2022	CLO	8690642	Repair	SEA	QAI for Unit: 33046, Emergency light out stairwell 5th light up. Repair		Corrective	3/10/22
03/14/2022	CLO	8690643	Repair	LAX	QAI for Unit: 33046, AED is missing Emergency Instructions card for use. Required		Corrective	3/10/22
02/07/2022	CLO	8654254	Repair	LAX	A end and B end leaking.		Corrective	2/7/22
02/07/2022	CLO	8654255	Repair	LAX	Display refri. warm.		Corrective	2/7/22
01/08/2022	CLO	8613404	Repair	LAX	eMAP21A-(PA System) PA system not transmitting clear throughout entire consist./		Corrective	1/3/22
12/29/2021	CLO	8604651	Repair	LAX	REPLACE 20 DIRTY SEAT CUSHIONS		Corrective	12/27/21
12/29/2021	CLO	8599890	Repair	LAX	eMAP21A-(Coffee Maker) Water supply to coffee maker slow////Lower		Incident	12/23/21
12/29/2021	CLO	8604928	Repair	LAX	SMW REPAIR		Corrective	12/28/21
12/29/2021	CLO	8480154	Quarterly Inspection-Car	LAX	368d - Superliner II Lounge		Preventive Maint.	9/23/21
12/29/2021	CLO	8604913	Repair	LAX	Electrical work.		Corrective	12/28/21
12/29/2021	CLO	8345249	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	6/15/21
12/29/2021	CLO	8599882	Repair	LAX	eMAP21A-(Track-Pocket) Track pocket security door to secure cafe is difficult to		Incident	12/23/21
12/29/2021	CLO	8605013	Repair	LAX	Carpenter Repair PMF		Corrective	12/28/21
12/29/2021	CLO	8604647	Repair	LAX	Refrigeration repair		Corrective	12/27/21
12/28/2021	CLO	8605836	Repair	LAX	smw inspections		Corrective	12/28/21
12/28/2021	CLO	8599894	Repair	LAX	eMAP21A-(Refrigerator Cooling) Refrigeration in cafe freezes causing temperature		Incident	12/23/21
12/28/2021	CLO	8601348	Repair	LAX	WHEEL PIT REPAIRS		Corrective	12/24/21
12/28/2021	CLO	8392548	Annual Inspection-Car	LAX	Superliner II Annual Handbrake Inspection		Preventive Maint.	7/19/21
12/15/2021	CLO	8586862	Repair	LAX	eMAP21A-(Refrigerator Cooling) Upper refers are too col//B-End//Lower		Incident	12/12/21
12/15/2021	CLO	8586864	Repair	LAX	eMAP21A-(Refrigerator Door) Light is flickering door 6//B-End//Lower		Incident	12/12/21
12/11/2021	CLO	8570963	Repair	LAX	FLAT SPOTS BX FINISHED RIM SIZE wheel true 7&8 flat spot		Corrective	11/30/21



# Equipment Work Order History Report

Unit/Serial # :34026  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/22/2022	CLO	8811648	Repair	CPC	Toilet B/O		Corrective	6/22/22
06/03/2022	CLO	8786151	Repair	CPC	eMAP21A-(Toilet Not Operatable) Car number 34026 toilets stopped flushing at RIV		Incident	5/31/22
05/30/2022	CLO	8777959	Repair	LAX	Carpenter Repair PMF		Corrective	5/25/22
05/29/2022	CLO	8777154	Repair	LAX	B/End Guidelink Bushing BO		Corrective	5/24/22
05/28/2022	CLO	8777931	Repair	LAX	SMW REAPIR		Corrective	5/25/22
05/26/2022	CLO	8697820	Quarterly Inspection-Car	LAX	92d - Superliner I Coach		Preventive Maint.	3/16/22
05/26/2022	CLO	8777974	Repair	LAX	STRIP & QUALIFY PER 92 DAY		Corrective	5/25/22
05/26/2022	CLO	8777932	Repair	LAX	Electrical Inspection		Corrective	5/25/22
05/26/2022	CLO	8774185	Repair	LAX	Toilets Inoperative-Low Air		Incident	5/21/22
05/26/2022	CLO	8780014	Repair	LAX	PMF Electrical Defects		Corrective	5/26/22
05/26/2022	CLO	8588198	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (superliner I)		Preventive Maint.	12/13/21
05/25/2022	CLO	8778004	Repair	LAX	HVAC		Corrective	5/25/22
05/21/2022	CLO	8773855	Repair	NOL	seat cushion dirty		Corrective	5/21/22
05/13/2022	CLO	8765878	Repair	LAX	SMW		Corrective	5/13/22
05/04/2022	CLO	8748357	Repair	LAX	eMAP21A-(First Aid Kit) Replace first aid kit. Seal broken ////Upper		Corrective	4/28/22
04/30/2022	CLO	8750160	Repair	LAX	THIN FLANGE BX Wheel #7, W/T, Roll all wheels		Corrective	4/30/22
04/30/2022	CLO	8747183	Repair	LAX	check for thin flange , ped.#7 ,reported		Corrective	4/28/22
04/30/2022	CLO	8750264	Repair	LAX	WHEEL 5/6 HIGH FLANGE W/T.		Corrective	4/30/22
04/14/2022	CLO	8729518	Repair	LAX	eMAP21A-(PA System) PA super scratchy and unintelligible. Combined with unlockab		Corrective	4/12/22
04/10/2022	CLO	8726724	Repair	LAX	Power Supply Missing		Corrective	4/10/22
04/08/2022	CLO	8724606	Repair	SEA	Ground Strap on rear truck broken.		Corrective	4/8/22
04/02/2022	CLO	8717598	Repair	LAX	cushions # 20,44,45 dirty		Corrective	4/2/22
03/16/2022	CLO	8601077	Quarterly Inspection-Car	BPK	92d - Superliner I Coach		Preventive Maint.	12/23/21
03/16/2022	CLO	8696825	Repair	BPK	BX 1/2 B/O (HIGH FLANGE)		Corrective	3/16/22
03/16/2022	CLO	8647235	Inspection/Survey-Car	BPK	CAM114 - MD-76 Truck Inspection [SL1]		Campaign	2/1/22
03/15/2022	CLO	8696425	Repair	BPK	B/O Seat #60		Corrective	3/15/22
03/15/2022	CLO	8696052	Repair	BPK	Emergency Release Latch Missing for ADA Restroom		Corrective	3/15/22
03/11/2022	CLO	8691766	Repair	BPK	INBOUND INSPECTION & STRIP		Corrective	3/11/22
03/11/2022	CLO	7342336	Inspection/Survey-Car	BPK	CHI_ EPA Three Year Water Sampling		Campaign	5/17/19
02/24/2022	CLO	8669376	Repair	CPC	eMAP21A-(Diaphragm - Curtain) Diaphragm curtain won't stay attached to neighborin		Corrective	2/21/22
02/24/2022	CLO	8669373	Repair	CPC	eMAP21A-(Toilet Not Operatable) Toilet 4 won't stop flushing, pops breaker. Loc		Incident	2/21/22
02/11/2022	CLO	8658104	Repair	LAX	a& b end doors b/o breaker keeps tripping		Corrective	2/10/22
02/11/2022	CLO	8656802	Repair	LAX	eMAP21A-(Door Operator) All doors in car are not working.////		Incident	2/9/22
02/08/2022	CLO	8655595	Repair	CPC	B-end knuckle b/o		Corrective	2/8/22





# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
02/06/2022	CLO	8650271	Inspection/Survey-Car	LAX	CAM115 - MD-76 Guidlink Hardware Inspection - LAYOVER OVER-PIT		Campaign	2/3/22
01/10/2022	CLO	8619684	Repair	CPC	eMAP21A-(Toilet Not Operatable) Bathroom #4 toilet unit BO////Lower		Incident	1/8/22
01/10/2022	CLO	8619512	Repair	CPC	restroom 4 toilet		Corrective	1/8/22
01/02/2022	CLO	8611777	Repair	SEA	SEAT BOTTOM B/O seat #32 & # 28		Corrective	1/2/22
12/30/2021	CLO	8602467	Repair	CPC	First Stage Floor Heat Trips Breaker		Corrective	12/25/21
12/23/2021	CLO	8439465	Quarterly Inspection-Car	BPK	368d - Superliner I Coach		Preventive Maint.	8/23/21
12/22/2021	CLO	8367134	Annual Inspection-Car	BPK	Superliner I Annual Handbrake Inspection		Preventive Maint.	6/30/21
12/20/2021	CLO	8566703	Repair	BPK	eMAP21A-(Dog Ears/Side Collision) Engineer side westbound. Door latch that secur		Incident	11/27/21
12/17/2021	CLO	8593031	Repair	BPK	INBOUND INSPECTION & STRIP		Corrective	12/17/21
12/13/2021	CLO	8439466	0030 Day Inspection-Car	NOL	30 Day Carpet Extraction (superliner I)		Preventive Maint.	8/23/21
12/13/2021	CLO	8586613	Repair	NOL	eMAP21A-(Seat Cushion) Passenger got sick and vomited. Passenger got off in MKS/		Corrective	12/12/21
12/13/2021	CLO	8586479	Repair	NOL	eMAP21A-(Carpet) Seats 61-62 and middle aisle carpet need deep cleaning in New O		Corrective	12/12/21
12/06/2021	CLO	8576893	Repair	CPC	eMAP21A-(Car Too Hot) All passengers complaining about car being to hot. Car is		Incident	12/5/21



# Equipment Work Order History Report

Unit/Serial # :31029  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/20/2022	CLO	8805772	Repair	LAX	eMAP21A-(Toilet Not Operatable) Toilets #1 and #5 (ladies lounge)////Lower		Incident	6/16/22
06/19/2022	CLO	8804365	Repair	LAX	eMAP21A-(PA System) PA not working to any other car////		Corrective	6/15/22
06/12/2022	CLO	8773394	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (superliner I)		Preventive Maint.	5/20/22
05/24/2022	CLO	8776369	Repair	LAX	B end A/C B/O		Corrective	5/23/22
05/23/2022	CLO	8766785	Repair	LAX	eMAP21A-(Car Too Hot) AC is not cooling, air blowing BUT not coolcold////		Incident	5/14/22
05/23/2022	CLO	8771358	Repair	LAX	HVAC Repairs		Corrective	5/19/22
05/23/2022	CLO	8773540	Repair	LAX	Inside Temp Guage stuck at 70 degrees		Corrective	5/20/22
05/20/2022	CLO	8697930	Quarterly Inspection-Car	LAX	92d - Superliner I Coach Bag		Preventive Maint.	3/17/22
05/20/2022	CLO	8771382	Repair	LAX	Electrical Repairs		Corrective	5/19/22
05/20/2022	CLO	8771336	Repair	LAX	Carpenter Repair PMF		Corrective	5/19/22
05/20/2022	CLO	8771276	Repair	LAX	SMW REPAIR		Corrective	5/19/22
05/20/2022	CLO	8771304	Repair	LAX	SMW REPAIR		Corrective	5/19/22
05/20/2022	CLO	8698074	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (superliner I)		Preventive Maint.	3/17/22
05/20/2022	CLO	8773200	Repair	LAX	L/L ada door sensitive edge closing gap needs adjustment		Corrective	5/20/22
05/20/2022	CLO	8769025	Repair	LAX	WHEELS 5 & 6 SHELLING & THERMAL CRACKS W/T		Corrective	5/17/22
05/18/2022	CLO	8769024	Repair	LAX	WHEEL PIT DEFECTS		Corrective	5/17/22
05/18/2022	CLO	8766916	Repair	LAX	MR Hose Parting		Incident	5/14/22
05/02/2022	CLO	8751543	Repair	LAX	eMAP21A-(Car Too Hot) In the heat of the day with sun beating down, car does not		Incident	5/1/22
05/02/2022	CLO	8750966	Repair	LAX	eMAP21A-(Toilet Not Operatable) Toilets don?t flush////ADA/Lower		Incident	5/1/22
04/29/2022	CLO	8748476	Repair	CPC	eMAP21A-(Tray Table) Tray broken/10-///Upper		Corrective	4/28/22
04/27/2022	CLO	8745170	Repair	LAX	QAI for Unit: 31029,Emergency light at upstairs has two 2 lights B/O.		Corrective	4/26/22
04/14/2022	CLO	8726512	Repair	CPC	eMAP21A-(Dog Ears/Side Collision) Left side baggage door doesn?t latch//B-End//L		Incident	4/10/22
04/09/2022	CLO	8717691	Repair	LAX	eMAP21A-(Release Handle) Coach baggage door engineer side will not lock. Notifie		Incident	4/2/22
04/04/2022	CLO	8719099	Repair	NOL	step light out		Corrective	4/4/22
03/28/2022	CLO	8710482	Repair	NOL	first aid kit missing		Corrective	3/28/22
03/17/2022	CLO	8696364	Repair	LAX	Electrical Repairs		Corrective	3/15/22
03/17/2022	CLO	8696413	Repair	LAX	SMW REPAIRS		Corrective	3/15/22
03/17/2022	CLO	8600880	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (superliner I)		Preventive Maint.	12/23/21
03/17/2022	CLO	8696298	Repair	LAX	PMF Carpenter Defects		Corrective	3/15/22
03/17/2022	CLO	8695192	Repair	LAX	SMW repairs		Corrective	3/14/22
03/17/2022	CLO	8696709	Repair	LAX	REPLACE 44 MISSING SEAT CUSHIONS		Corrective	3/16/22
03/17/2022	CLO	8697886	Repair	LAX	ASSEMBLE CAR INTERIOR		Corrective	3/16/22



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
03/17/2022	CLO	8607115	Quarterly Inspection-Car	LAX	92d - Superliner I Coach Bag	██████	Preventive Maint.	12/29/21
03/16/2022	CLO	8647132	Inspection/Survey-Car	LAX	CAM114 - MD-76 Truck Inspection [SL1]	██████	Campaign	2/1/22
02/25/2022	CLO	8674764	Repair	SAS	restroom #2 toilet clogged wont flush	██████	Corrective	2/25/22
02/16/2022	CLO	8659611	Repair	LAX	Broken faucet cartridge	██████	Corrective	2/12/22
02/16/2022	CLO	8612794	Repair	LAX	smw inspections	██████	Corrective	1/3/22
02/07/2022	CLO	8647467	Repair	LAX	QAI for Unit: 31029,Wrong washer used on Lateral guide link (B-end) use (2034500	██████	Corrective	2/1/22
02/07/2022	CLO	8647466	Repair	LAX	QAI for Unit: 31029,Worn bushings Lateral Guide link (A-end) and (B-end)	██████	Corrective	2/1/22
02/05/2022	CLO	8650168	Inspection/Survey-Car	NOL	CAM115 - MD-76 Guidlink Hardware Inspection - LAYOVER OVER-PIT	██████	Campaign	2/3/22
02/05/2022	CLO	8651834	Repair	NOL	b end door stuck open	██████	Corrective	2/5/22
01/19/2022	CLO	8629917	Repair	LAX	eMAP21A-(Bulk Head) Trash can by stairway does not stay closed////Upper	██████	Corrective	1/17/22
12/23/2021	CLO	8598190	Repair	LAX	Pipe Support Laying on top of Compressor	██████	Corrective	12/21/21
12/23/2021	CLO	8598189	Repair	LAX	Inside Temp Guage stuck at 55 degrees	██████	Corrective	12/21/21
12/23/2021	CLO	8598188	Repair	LAX	Oil And R22 Low both units	██████	Corrective	12/21/21
12/23/2021	CLO	8598143	Repair	LAX	SMW repair	██████	Corrective	12/21/21
12/23/2021	CLO	8598119	Repair	LAX	REPLACE 57 SEAT CUSHIONS & 1 BACK REST	██████	Corrective	12/21/21
12/23/2021	CLO	8598108	Repair	LAX	PMF Carpenter Defects	██████	Corrective	12/21/21
12/23/2021	CLO	8597942	Repair	LAX	ELECT REPAIR' S	██████	Corrective	12/21/21
12/23/2021	CLO	8490853	Repair	LAX	eMAP21A-(Carpet) Carpet dirty center aisle near seats 1&2/1-Aisle/A-End//Upper	██████	Corrective	9/30/21
12/23/2021	CLO	8464936	Quarterly Inspection-Car	LAX	LAX SUPERLINER I COACH BAG 92 -DAY PM INSPECTION	██████	Preventive Maint.	9/10/21
12/23/2021	CLO	8464935	0030 Day Inspection-Car	LAX	30 Day Carpet Extraction (superliner I)	██████	Preventive Maint.	9/10/21
12/22/2021	CLO	8596258	Repair	LAX	#5 And #8 SHELLED TREAD W/T FINISHED RIM SIZE	██████	Corrective	12/20/21
12/22/2021	CLO	8596257	Repair	LAX	#1 and #3 FLAT SPOTS W/T FINISHED RIM SIZE	██████	Corrective	12/20/21
12/21/2021	CLO	8596259	Repair	LAX	Wheel Pit Repairs	██████	Corrective	12/20/21
12/16/2021	CLO	8009540	Repair	BEE	Overhaul Acceptance Inspection	██████	Corrective	9/17/20
12/01/2021	CLO	8562530	Repair	CPC	eMAP21A-(Side Doors) Baggage door fireman side will not open////	██████	Corrective	11/23/21



# Equipment Work Order History Report

Unit/Serial # :34102  
 Rpt Start Date :12/1/2021  
 Rpt End Date :6/27/2022  
 WO Type Code :\*  
 WO Maint Type Code :\*



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
06/25/2022	CLO	8815728	Repair	LAX	RR#1 & RR#3 Sink Faucets Leaking		Corrective	6/25/22
06/25/2022	CLO	8815715	Repair	LAX	Break Indicator Light is out Amber		Corrective	6/25/22
06/18/2022	CLO	8806812	Repair	LAX	QAI for Unit: 34102,Missing label #5000013487, on wall facing ADA seat.		Corrective	6/17/22
06/18/2022	CLO	8804613	Repair	LAX	Carpenter Repair PMF		Corrective	6/16/22
06/18/2022	CLO	8805276	Repair	LAX	QAI for Unit: 34102,Emergency Window instructions decal. Window #73 is wrong one		Corrective	6/16/22
06/18/2022	CLO	8805277	Repair	LAX	QAI for Unit: 34102,Missing Emergency Window instructions decal. Window #75.		Corrective	6/16/22
06/18/2022	CLO	8804514	Repair	LAX	SMW REPAIR		Corrective	6/16/22
06/18/2022	CLO	8804593	Repair	LAX	Electrical Inspection		Corrective	6/16/22
06/18/2022	CLO	8804498	Repair	LAX	SMW REPAIR		Corrective	6/16/22
06/18/2022	CLO	8720267	Quarterly Inspection-Car	LAX	92d - Superliner II Coach		Preventive Maint.	4/5/22
06/16/2022	CLO	8804223	Repair	LAX	BUILD-UP TREAD OR THERMAL CRACKS WH #2,4 W/T		Corrective	6/15/22
06/11/2022	CLO	8799564	Repair	LAX	tray table # 63,41, 53 BO		Corrective	6/11/22
06/03/2022	CLO	8788784	Repair	LAX	eMAP21A-(Seat Back) Passenger bled on seat./75-/B-End/ADA/Lower		Corrective	6/2/22
05/30/2022	CLO	8369003	0030 Day Inspection-Car	SEA	30 Day Carpet Extraction (Superliner II)		Preventive Maint.	7/1/21
05/30/2022	CLO	8406660	Modification (Capital)	SEA	MOD00594 - Superliner Refresh [SL2 COACH]		Campaign	7/29/21
05/30/2022	CLO	8784147	Repair	SEA	Toilet b/o room H		Corrective	5/30/22
05/28/2022	CLO	8777330	Repair	SEA	LED emergency floor lighting b/o - damaged		Corrective	5/24/22
04/05/2022	CLO	8631484	Quarterly Inspection-Car	BPK	368d - Superliner II Coach		Preventive Maint.	1/18/22
04/04/2022	CLO	8719513	Repair	BPK	Air vane switch not working properly on a end of car.		Corrective	4/4/22
04/02/2022	CLO	8714163	Repair	BPK	Missing Custions		Corrective	3/30/22
04/02/2022	CLO	8378033	Annual Inspection-Car	BPK	Superliner II Annual Handbrake Inspection		Preventive Maint.	7/8/21
03/31/2022	CLO	8715637	Repair	BPK	Rightside waste dump piping union leaking ( loose)		Corrective	3/31/22
03/31/2022	CLO	8715627	Repair	BPK	Restroom# 4 toilet seat B/o		Corrective	3/31/22
03/30/2022	CLO	8714160	Repair	BPK	Rest bRoom Lock B/O		Corrective	3/30/22
03/30/2022	CLO	8713584	Repair	BPK	INBOUND INSPECTION & STRIP		Corrective	3/30/22
03/26/2022	CLO	8708960	24 Hour Inspection	WAS	Superliner II Daily 238 Car Inspection (MAP 10C)		Daily Inspection	3/26/22
03/26/2022	CLO	8708770	Repair	WAS	R4 journal Box weld is broken		Corrective	3/25/22
03/17/2022	CLO	8695748	Repair	WAS	car smells like urine		Corrective	3/15/22
03/07/2022	CLO	8686585	Repair	WAS	Kick Plate b/o		Corrective	3/7/22
03/07/2022	CLO	8678971	Repair	WAS	eMAP21A-(Seat Cushion) Lower Level #74 seat urinated on./74-/ADA/Lower		Corrective	3/1/22
03/02/2022	CLO	8680551	24 Hour Inspection	WAS	Superliner II Daily 238 Car Inspection (MAP 10C)		Daily Inspection	3/2/22
03/02/2022	CLO	8679999	Repair	WAS	R 4 Journal box weld is broken		Corrective	3/1/22
03/02/2022	CLO	8680787	Repair	WAS	B-End R/S body panel damaged by step still		Corrective	3/2/22
02/22/2022	CLO	8671243	Repair	WAS	Freeze Protection valve B/o		Corrective	2/22/22



# Equipment Work Order History Report



Print Date: 6/27/2022

Status Date	Status	W/O #	Maint Type	Completed at Facility	WO Title	Status By	WO Type	WO Created
02/21/2022	CLO	8670135	Repair	WAS	Electrical conduit bracket	██████████	Corrective	2/21/22
01/18/2022	CLO	8472248	Quarterly Inspection-Car	BPK	92d - Superliner II Coach	██████████	Preventive Maint.	9/16/21
01/18/2022	CLO	8626631	Repair	BPK	Mirror cracked over the vanity in the back dressing room	██████████	Corrective	1/14/22
01/18/2022	CLO	8529081	Repair	BPK	eMAP21A-(Walls) Outside of bathroom walls need to be cleaned////Lower	██████████	Corrective	10/30/21
01/14/2022	CLO	8627385	Repair	BPK	Dirty waste water in waste tank	██████████	Corrective	1/14/22
01/13/2022	CLO	8625233	Repair	BPK	Strip and Trash Removal	██████████	Corrective	1/13/22
12/05/2021	CLO	8574090	Repair	NOL	Emergency window decals missing at seats 25 & 29	██████████	Corrective	12/2/21
12/05/2021	CLO	8574094	Repair	NOL	UL FE service tag is missing when put into Service info	██████████	Corrective	12/2/21
12/05/2021	CLO	8574079	Repair	NOL	LL Light sticks missing, only 6 in the box	██████████	Corrective	12/2/21
12/05/2021	CLO	8574087	Repair	NOL	ADA RR door missing upper release lever on vestibule door	██████████	Corrective	12/2/21