



Memorandum for Record

Eric M. Gutierrez
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR22FA164
Aircraft Registration & Make/Model: N321PF, Diamond Aircraft, DA 40
Accident Location: Cedar City, Utah
Accident Date: April 23, 2022

An autopsy of the pilot was performed by the Utah Department of Health, Office of the Medical Examiner, Taylorsville, Utah. The cause of death was blunt force injuries.