



Heidi Kemner
Senior Air Safety Investigator
Eastern Region Aviation

January 19, 2022

Subject: ERA22LA106
Who: Carl Brogunier - Mechanic

In an email, Mr. Brogunier stated the following:

January 14th, 2022 I performed a bench test in accordance with the startup initialization and revolutions per minute setting procedures on the Safari throttle governor regulator serial number 032118502702 model number L4-A and found it to operate within the programmed specifications.