



**Heidi Kemner**  
**Senior Air Safety Investigator**  
**Eastern Region Aviation**

**January 14, 2022**

---

**Subject:** ERA22LA106  
**Who:** David Robinson – FAA Inspector

In a conversation, Inspector Robinson stated the following:

- He examined the helicopter and noted no anomalies with the helicopter that would have precluded normal operation prior to the accident.
- He asked a mechanic to bench test the throttle governor and there were no anomalies noted with the test.