

Motor Carrier Attachment 19:

Post-Accident Driver Vehicle Roadside Inspection

Cranbury, NJ; 06/07/2014 HWY14MH012

(2 pages)



NEW JERSEY STATE POLICE

TRANSPORTATION SAFETY BUREAU

PRINCETON, NJ 08540

Phone: (

Report Number: NJSPDP002367 Inspection Date: 06/11/2014

Inspection Level: | - Full HM Inspection Type: None

| WAL-MART 1 | FRANSPOR | TATION I | LLC |
|------------|----------|----------|-----|
|------------|----------|----------|-----|

BENTONVILLE, AR 72716-0650

USDOT#: 00063585

MC/MX#: 311233

Fax#:

Phone#:

Driver: ROPER, KEVIN J

License#:

State: GA

Date of Birth:

CoDriver: License#:

State:

Date of Birth:

MilePost: 0 Origin: BRISTOL, PA

Shipper:

Bill of Lading: Cargo: EMPTY

Location: GEORGES TOWING

Highway: NJTPK

State#:

County: MIDDLESEX, NJ

Destination: PERTH AMBOY, NJ

VIN

VEHICLE IDENTIFICATION

<u>Unit Type Make Year State</u> 1 TT PTRB 2011 OK ST GDAN 2003 OK

| Plate # | _ |
|---------|---|
| | Ì |
| | |

Equipment ID 0-2568 77397

1XPHD49X6BI 1GRAA06253

50,000 68,000

GVWR CVSA # CVSA Issued # OOS Sticker

BRAKE ADJUSTMENTS

| <u>Axle#</u> | <u>1</u> | · <u>2</u> | <u>3</u> | <u>4</u> | <u>5</u> |
|--------------|----------|------------|----------|----------|----------|
| Right | 1 | 1 3/8 | 1 1/2 | 1 1/2 | 1 3/4 |
| Left | 1 1/4 | 1 1/8 | 1 5/8 | 1 1/2 | 2 |
| Chamber | C-20 | C-30 | MM | L-30 | L-30 |

| ı | ΙV | ı | V | L | 4 | ı | H | J | N | Þ |
|---|----|---|---|---|---|---|---|---|---|---|
| ı | | | | | | | | | | |

| <u>Vio Code</u> | <u>Section</u> | <u>Unit</u> | <u>008</u> | Citation # | <u>Verify</u> | <u>Crash</u> | <u>Violations Discovered</u> |
|-----------------|----------------|-------------|------------|------------|---------------|--------------|--|
| 392.3-FPROP | 392.3 | D | Y | SP5424287 | N | N | Fatigue - Operate a property-carrying CMV while impaired by fatigue. As per driver's statement after the crash, "I fell asleep" |
| 395.15C | 395.15(c) | D | N | | N | N | Onboard recording device improper form and manner. Driver records deliveries /"drop & hooks" as off duty, not on duty not driving. |
| 396.5A-HNLOW | 396.5(a) | 2 | N | | N | Ν | Hubs - Oil and/or Grease Leaking from hub - inner wheel seals leaking on both left and right side of axle 4. |

HazMat: No HM Transported.

Placard: No

Cargo Tank:

Special Checks: Post Crash

Pursuant to NJAC 13:60 (Federal Motor Carrier Safety Regulations Parts 390, 391, 392, 393, 394, 395, 396, 397) and NJAC 16:49 (Title 49 Code of Federal Regulations Parts 171, 172, 173, 177, 178, and 180). I hereby notify and declare KEVIN ROPER named on this report OUT OF SERVICE. No motor carrier shall permit or require this driver to drive or operate any

The undersigned certifies that all OOS violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state.

Signature Of Repairer X:

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears on this report.

NOTE TO MOTOR CARRIER: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state. Please sign the certification below and return this report within fifteen days to: New Jersey State Police, 3925 US Hwy. 1 Princeton, N.J. 08540. ATTN: Hazardous Materials

Signature Of Motor Carrier X:

Date:

Report Prepared By:

Badge #: 6509

Copy Received By: **KEVIN ROPER**

