



**Motor Carrier Attachment 31:**


**Walmart Work Order 9218003**

**Cranbury, NJ; 06/07/2014**

**HWY14MH012**

(3 pages)

# Work Order

<b>Facility</b> 007734 - Smyrna, DE [REDACTED] Smyrna DE 19977 [REDACTED]	<b>Bldg Ty</b> Region F <b>Bldg</b> 007834 - Smyrna, DE <b>EqType</b> Tractor <b>Unit</b> WMT02568	 9218003 <b>Status</b> Closed
<b>Primary RFR</b> 04 <b>WO Contains DVCR?</b> No <b>WO Red Tag Status</b> Not Red Tagged <b>Repair Class</b> Scheduled		
<b>Display Currency:</b> \$ US		

<b>Year / Make / Model</b> 2010 PTRBL 386 <b>Primary Meter Reading</b> 346,774 Odometer Miles	<b>S/N</b> 1XPHD49X6BD1 [REDACTED] <b>Secondary Meter Reading</b>	<b>License Plate</b> [REDACTED] <b>License State/Province</b> Oklahoma	<b>WO Date</b> 31-May-14
--	---	---	-----------------------------

<b>Line</b> 1 <b>Status</b> C	<b>Reason For Repair</b> 04 --- Driver's Report	<b>SJ Code</b>	<b>Reference</b>
	<b>Repair Line DVCR?</b> No <b>Repair Line Red Tag</b> Not Red Tagged		
	<b>Problem Description</b> C) Complaint truck wanders and rips steering wheel from hands when hitting pot holes.		

Labor		Sys/Assy	Regular	OT	Labor Cost
Technician	In/Outside Date	Work Accomplished			
[REDACTED] mart.com	Inside 31-May-14	016/000 Suspension/Suspension	2.33	0.00	73.40
		06 Inspect Taking truck for test drive. After test drive brought truck back into shop to start inspecting suspension and steering components. Jacked front wheels off the ground one at a time to check kingpin wear. Kingpin is tight. Checked steering and drive line components. Greased the front end. Took steering shaft apart found it was stiff and needed to be cleaned and greased could have been to possible cause for issues.			
[REDACTED] mart.com	Inside 31-May-14	016/000 Suspension/Suspension	0.33	0.00	10.40
		24 Repair Taking truck for test drive. After test drive brought truck back into shop to start inspecting suspension and steering components. Jacked front wheels off the ground one at a time to check kingpin wear. Kingpin is tight. Checked steering and drive line components. Greased the front end. Took steering shaft apart found it was stiff and needed to be cleaned and greased could have been to possible cause for issues.			

Parts	In/Outside	PO #	Part #	Sys/Assy/Comp	Description	Qty	Total
Inv Site				Failure Code			


Fluid	In/Outside	PO #	Part #	Description	Qty	Total
Inv Site						

**Outside Repair**  
 Date    PO #    Supplier #    Supplier Name

Note: - If a part or labor cost has a '?' prepended, it means that the cost is estimated.

<b>WO Notes</b> gaw	<b>Signature</b>	<b>Date</b>
------------------------	------------------	-------------

# Work Order

<b>Facility</b> 007734 - Smyrna, DE [REDACTED] Smyrna DE 19977 [REDACTED]	<b>Bldg Ty</b> Region F <b>Bldg</b> 007834 - Smyrna, DE <b>EqType</b> Tractor <b>Unit</b> WMT02568	 9218003 <b>Status</b> Closed
Primary RFR <b>04</b> WO Contains DVCR? <b>No</b> WO Red Tag Status <b>Not Red Tagged</b> Repair Class <b>Scheduled</b>		

Display Currency: \$ US

### Outside Repair Summary

Date	PO #	Vendor #	Vendor Name	Labor	Part Cost	Misc Cost	Shipping	Sales Tax	Total Cost
------	------	----------	-------------	-------	-----------	-----------	----------	-----------	------------

### Summary

	<b>Cost-Discout</b>
<b>Labor</b>	83.80
<b>Parts</b>	0.00
<b>Fluids</b>	0.00
<b>Outside</b>	0.00
<hr/>	
<b>WO</b>	83.80

<b>Total</b>	83.80
--------------	-------

WO 9218003

**Grand Total** 83.80

Note: - If a part or labor cost has a '?' prepended, it means that the cost is estimated.

<b>WO Notes</b> gaw	<b>Signature</b>	<b>Date</b>
------------------------	------------------	-------------