

From: [REDACTED]
Subject: N56907 ignition harness test
Date: Tuesday, June 18, 2024 11:06:14 AM

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Hello Fabian,

This is Tom Boyce from Laurel, MT emailing you regarding the ignition harness test for Bo Ewald's Stearman. I tested the leads and found the R/H harness to be good. The L/H harness, #9, #6, and #2 did not pass a continuity test from the distributor lugs to the end of the plug wires... although when I removed the plug wires from the distributor, the plug wires themselves did pass a continuity test.

If you have any questions, please let me know.

Thanks you,
Tom Boyce