



NATIONAL TRANSPORTATION SAFETY BOARD

Eastern Region – Ashburn, Virginia

Summary of Findings

From: Adria Drew, Principal Operations Inspector FRG FSDO

To: Leah D. Read, NTSB

Date: December 21, 2020

An inspector with the Farmingdale, New York, Federal Aviation Administration (FAA) Flight Standards District Office (FSDO) responded to an accident that involved a Beechcraft Hawker 800, N412JA, operated by Talon Aviation, at Farmingdale Airport, New York, on December 20, 2020.

According to the inspector, the airplane impacted the right side of the runway, about 2,000 ft down, then veered right of the runway, about 1,500 ft before coming to rest. The nose wheel and both main gears departed the airplane and were found on the runway. There was no postimpact fire.

The inspector also spoke with two people who responded to the accident shortly after it happened. These responders stated that fog had “quickly” and “unexpectedly” developed on the airport around the time of the accident.

End