



**NATIONAL TRANSPORTATION SAFETY BOARD
OFFICE OF HIGHWAY SAFETY
WASHINGTON, D.C.**

**North Las Vegas, Nevada
HWY22FH004**

CRASH INFORMATION

Location: Intersection of West Cheyenne Avenue and North Commerce Street,
North Las Vegas, Clark County, Nevada

Vehicle 1: 2018 Dodge Challenger passenger vehicle

Operator 1: 59-year-old male (fatal)

Passenger: 46-year-old male (fatal)

Vehicle 2: 2013 Toyota Sienna minivan

Operator 2: 35-year-old male (fatal)

Passenger: 13-year-old female (fatal)

Passenger: 23-year-old male (fatal)

Passenger: 25-year-old male (fatal)

Passenger: 5-year-old male (fatal)

Passenger: 10-year-old male (fatal)

Passenger: 15-year-old male (fatal)

Vehicle 3: 2016 Ford Fusion passenger vehicle

Operator 3: 31-year-old female (serious injury)

Vehicle 4: 2005 Chevrolet Malibu passenger vehicle

Operator 4: 23-year-old male (no injuries)

Passenger: 32-year-old female (no injuries)

Vehicle 5: 2016 Hyundai Tucson sport utility vehicle (SUV)
Operator 5: 38-year-old male (minor injury)

Vehicle 6: 2021 Mercedes GLE-350 SUV
Operator 6: 53-year-old male (no injuries)
Passenger: 59-year-old male (no injuries)

Date: January 29, 2022
Time: 3:12 p.m. (local time)

CRASH SUMMARY

On Saturday, January 29, 2022, at about 3:12 p.m. Pacific standard time, a 2018 Dodge Challenger passenger car, occupied by a 59-year-old driver and a 46-year-old passenger, was traveling north on North Commerce Street in North Las Vegas, Clark County, Nevada. The Dodge was approaching the intersection with West Cheyenne Avenue at a recorded speed of 103 mph. The intersection is controlled by a traffic signal light, and the approach for both roadways include multiple lanes for through-traffic and for vehicles making turning maneuvers. The Dodge entered the intersection against a red traffic signal, causing a multivehicle collision.

The collision also involved a 2013 Toyota Sienna minivan, a 2016 Hyundai Tucson sport utility vehicle (SUV), a 2005 Chevrolet Malibu sedan, a 2016 Ford Fusion sedan, and a 2021 Mercedes GLE-350 SUV. A total of 15 vehicle occupants were involved in the collision. Following the impact, the Dodge, Toyota, and Ford all came to rest off the roadway, in the northeastern corner of the intersection. The Chevrolet came to rest in the westbound lane of West Cheyenne Avenue. The Hyundai and the Mercedes SUVs drove to a stop nearby. As a result of the crash, the driver and passenger of the Dodge and all 7 occupants of the minivan died. The driver of the Ford Fusion was transported to the hospital.

North Commerce Street is a two-lane asphalt road with one southbound lane, one northbound lane, and a center turn lane, traveling through an industrial area. At the crash location, the roadway is straight with a slight upgrade as it approaches the intersection. Two 35-mph speed limit signs are posted on North Commerce Street in the crash area. West Cheyenne Avenue is a six-lane asphalt road with three westbound lanes, three eastbound lanes, and center turn lanes that allow for turns onto North Commerce Street in the north or southbound directions. At the crash location, the roadway is straight and level. The speed limit on West Cheyenne Avenue in this area is 50 mph.