

Track Inspection & FRA Reports

Return To: UP Employees Home Logged In As: Log Out

Fri, October 05, 2018 11:31:40 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 10/03/2018 Inspected By: Ian Watkins
Inspection Type: FRA Required How Conducted: Hi-Rail

Date Inspection Uploaded into the Central System: 10/03/2018 04:20:04 PM

Date Inspection Closed by Inspector: 10/03/2018 04:20:04 PM

Tracks Inspected

Service Unit	Subdivsion	Original Subdivsion	Seg/ Trk Type		Begin MP		Rail Xing Insp	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.31		ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29		ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	545.58		ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 1		512.00	519.09		ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29		ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09		ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.31		ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58		ALLEN	HINKER	BORIE TO DALE JCT
Track Traversed Information										
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09		ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58		ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29		ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.31		ALLEN	HINKER	HERMOSA TO LARAMIE
Comments										

Track Defects

No track defect records found

Curves Walked

No Curves Found

Switch Defects

Subdivision	Original Subdivision	_	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
LARAMIE SUB	LARAMIE SUB	4146 NO 2	<u>519.09</u> 519.10		133AC-133.A12 - Loose, worn, or	Repaired Before Traff c	10/03/2018	Corr from Trk Mtce Plan	10/03/2018		replaced broken bolt
		4146				Repaired					replaced

http://home.www.uprr.com [10/5/2018 11:32:35 AM]

LARAMIE SUB	LARAMIE SUB	<u>NO 2</u>	<u>519.09</u> 519.10	133AE-133.A14 - Loose, worn or	Before Traff c	10/03/2018	Corr from Trk Mtce Plan	10/03/2018	missing shims	
LARAMIE SUB	LARAMIE SUB	4146 NO 2	<u>545.47</u> 545.49		Repaired Before Traff c	10/03/2018	Corr from Trk Mtce Plan	10/03/2018	replaced frog bolt	

Joint Bar Inspections No Joint Bar Inspections Found

TMP Joint Bar Re-Inspect No TMP Joint Bar Re-Inspect Records Found





Top of Page

Home | Search | Crew Boards | New Stuff | UP Phonebook | UP Online | Help/Info | Feedback

[10/5/2018 11:32:35 AM] http://home.www.uprr.com