


gas indications found on
flare stack w/ RMLD
no sustained readings ~~was~~ found



(2) unions on flare
stack shot from (4)
different directions w/ RMLD
- NO leaks found



Each segment of vent pipe
has an internal O-ring. CGI
was used on every union and
no leaks were found

Tom Cox (Atmos Energy)
performed leak checks.

Sensit Gold Z SN G2 30000
Calibrated 6/21/21

Greg Smith - Atmos Energy witness

Brad Cox - TRRC witness

Kevin Colter yahn - TRRC witness