

Norfolk Southern Corporation  
Pittsburgh Division

Superintendent's Notice # 56

September 10, 2020

SUBJECT: PBSN -56 RADIO FREQUENCY CHANGES - CONWAY TERMINAL

ALL CONCERNED:

Effective 09:00AM EST SEPTEMBER 15, 2020, the following radio changes are made:  
Pittsburgh Division – Conway Terminal Dispatcher

Currently Reads As:

Base Station	Channel 1 TX and RX	Channel 2 TX and RX
Highland Cut VHF	064-064	
Wood VHF	064-064	
Koppel VHF	046-046	
Rochester VHF	064-064	
E Conway VHF	046-046	
Ambridge VHF	046-046	
Sewickley VHF	046-046	
Esplin VHF	064-064	
Midsteel VHF	064-064	
Yellow Creek VHF	064-064	
New Castle VHF	046-046	

Detectors	Channel 1 TX and RX
Castle SAD [YG 074.50]	064-064
Vale SAD [YG 091.90]	046-046
Beaver Falls SAD [PC 030.60]	064-064
Sewickley TRK1-2-3 SAD [PC 012.00]	046-046
Industry SAD [RD 008.70]	064-064

Changed to Read As:

Base Station	Channel 1 TX and RX	Channel 2 TX and RX
Highland Cut VHF	089-089	041-041
Wood VHF	089-089	041-041
Rochester VHF	089-089	041-041
E Conway VHF	089-089	041-041
Sewickley VHF	089-089	041-041
Esplin VHF	089-089	041-041
Midsteel VHF	089-089	
Yellow Creek VHF	089-089	
New Castle VHF	089-089	041-041

Detectors	Channel 1 TX and RX
Castle SAD [YG 074.50]	089-089
Vale SAD [YG 091.90]	089-089
Beaver Falls SAD [PC 030.60]	089-089
Sewickley TRK1-2-3 SAD [PC 012.00]	089-089
Industry SAD [RD 008.70]	089-089

All DTMF codes remain the same.

Be governed accordingly.

Neil Palmer  
Division Superintendent  
Pittsburgh Division  
Transportation Department