

## **Motor Carrier Photos 8-9:**

## Accident Walmart Truck-Tractor Blind Spotter

Cranbury, NJ; 06/07/2014 HWY14MH012

(2 pages)



Photo 8: This photo depicts the Blind Spotter that was located on the right side (passenger side) of the Walmart accident truck-tractor.



Photo 9: This photo depicts a close up view of the Blind Spotter Sensor located on the Walmart accident truck tractor