



**Photo 1 – Aft the view of airplane showing right horizontal stabilizer bent**





**Photo 2 – View of bottom of fuselage (empennage) showing buckling**



**Photo 3 – View of punctured tire inner tube**





**Photo 4 – View of nail found in punctured tire inner tube.**