



**Photo 1 – View of damage to the horizontal stabilizer, wind screen, and main rotor system (Courtesy of FAA)**