

WPR25LA009

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N4199M at the accident site (Courtesy of the operator)



Photograph 2 - Photo showing substantial damage to the floor (Courtesy of the operator)



Photograph 3 - Photo showing exterior view of substantial damage. (Courtesy of the operator)