

Photo 1-N74706, showing substantial damage to the fuselage. Photo courtesy of the FAA.



Photo 2-N74706, showing substantial damage to the lower vertical stabilizer. Photo courtesy of the FAA.



Photo 3 – N74706, showing substantial damage to the left side of the fuselage. Photo courtesy of the FAA.