



Photo 1 –N54173, at the accident site. Photo courtesy of the pilot.




Photo 2 – Substantial damage to the vertical stabilizer and the rudder. Photo pilot.



Photo 3 – Rear view of the substantially damaged empennage. Photo pilot.