From:
 End

 To:
 Image: Comparison of the system of the syst

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Mr. Swick,

I witnessed the Marvel-Schebler personnel remove the carburetor from the packaging and perform a functional test on the unit. The following report was provided by Mr. Mark Keeney.

I have recorded the action in the FAA SAS data base activity EA39202402079

Please let me know if you need any additional assistance.

V/r, Jake Thomas Jacob King Federal Aviation Administration Greensboro Flight Standards District Office

From: Andrew Swick
Sent: Friday, March 1, 2024 1:46 PM
To: King, Thomas J (FAA)
Subject: RE: WPR23LA162 Marvel-Schebler Carburetor Examination

CAUTION: This email originated from outside of the Federal Aviation Administration (FAA). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

Yes, sorry.

I sent that info to MSA originally but forgot to send you the information.

Engine Manufacturer Part No.: LW-15960-70 Marvel Schebler HA-6 Part No.: 10-5235 Serial No.: MSC51201

Andrew L. Swick

Aviation Accident Investigator National Transportation Safety Board Western Pacific Region

Phoenix, Arizona

Phone:

From: King, Thomas J (FAA)

Sent: Wednesday, February 28, 2024 1:14 PM

To: Andrew Swick

Subject: RE: WPR23LA162 Marvel-Schebler Carburetor Examination

[CAUTION] This email originated from outside of the organization. Do not click any links or open attachments unless you recognize the sender and know the content is safe.

Mr. Swick,

Did you have any identifiable information for the carburetor, s/n or pictures? I just want to verify same part when observing testing with MSA.

V/r, Jake Thomas Jacob King Federal Aviation Administration Greensboro Flight Standards District Office

From: Andrew Swick
Sent: Monday, February 26, 2024 3:28 PM
To: King, Thomas J (FAA)
Subject: WPR23LA162 Marvel-Schebler Carburetor Examination

CAUTION: This email originated from outside of the Federal Aviation Administration (FAA). Do not click on links or open attachments unless you recognize the sender and know the content is safe.

Good afternoon,

I was given your contact information from Mark Keeney at MSA, after expressing interest in getting a carburetor tested at their facility. Would you be able to provide federal oversight or find someone to provide federal oversight on this examination? I still have the carburetor in my possession and will plan to send this to Burlington, NC. Attached is information pertaining to the accident. Thanks for your time.

Andrew L. Swick

Aviation Accident Investigator National Transportation Safety Board Western Pacific Region Phoenix, Arizona CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.

CONFIDENTIALITY NOTICE - THIS E-MAIL TRANSMISSION MAY CONTAIN INFORMATION THAT IS PRIVILEGED, CONFIDENTIAL, PROPRIETARY, SUBJECT TO COPYRIGHT, AND/OR EXEMPT FROM DISCLOSURE UNDER APPLICABLE LAW. IT IS FOR THE USE OF INTENDED RECIPIENTS ONLY. If you are not an intended recipient of this message, please notify the original sender immediately by forwarding what you received and then delete all copies of the correspondence and attachments from your computer system. Any use, distribution, or disclosure of this message by unintended recipients is not authorized and may be unlawful.