



Image from the NS 4055, lead unit on the RHKPHQ15, as it traversed the C yard switch on arrival at Chico. This confirms that the crew that moved the RDACO14 in the C yard lined the C yard switch back for main track movement when they were complete.