

RECORD OF CONVERSATION

Aaron M. Sauer Aviation Accident Investigator Central Region

Date: 07/21/2021 Person Contacted: FAA Inspector Donald Hoerstkamp RE: CEN21LA307

Narrative:

During a telephone conversation, FAA inspector Hoerstkamp reported he's made multiple phone calls to the pilot and the pilot's girlfriend in an attempt to gather information regarding the accident circumstances. During one of the phone calls, the pilot stated he only needed a driver's license to operate the airplane; no pilot's license is required. The pilot then told the inspector he needed to provide no additional information and hung up. Several follow-up phone calls have not be returned.

The NTSB investigator-in-charge has made multiple attempts to contact the pilot regarding the accident circumstances and also to complete a NTSB Pilot/Operator Accident Report. Contact with the pilot has not been successful.