



RECORD OF CONVERSATION

Samantha Link
Aviation Accident Investigator
Central Region

Date: January 7, 2022
Person Contacted: Mr. Kyle Kinder (Pilot)
NTSB Accident Number: CEN22LA095

Narrative:

During a telephone conversation, the pilot reported that after coming into land, a strong gust of wind pushed the airplane off the runway. It struck the nearby PAPI (precision approach path indicator light), which damaged the airplane's left wing and the PAPI. There were no mechanical issues with the airplane at the time of the accident.

END.

Submitted by: Samantha Link