

Fabian Salazar
Air Safety Investigator
Western Pacific Region

Date: November 27, 2024

Subject: WPR25LA009/ Record of Conversation

Contact: David Wagner, Director of Maintenance, CAE, Phoenix

In a telephone conversation with the Director of Maintenance, he provided additional information for the accident airplane that was not identified on the NTSB Form 6120.1 submitted by the accident pilot. This information included the following:

- Engine manufacturer: Continental
- Engine Model: IO-240B
- Engine serial number: 650331
- Engine total time: 1788
- Propeller make: Sensenich
- Propeller type: Fixed Pitch
- Airworthiness certificate: Normal
- ELT Manufacturer: Emergency Beacon Corp.
- ELT Model: EBC-502
- TSO number: C91A(121.5MHz)