



RECORD OF EMAIL

Samantha Link
Aviation Accident Investigator
Central Region

Date: March 9, 2022
Person Contacted: Mr. Robert Arispe (Federal Aviation Administration)
NTSB Accident Number: CEN22LA134

Narrative:

During an on scene examination, the airplane was moved to level ground. Its electrical system was turned on and the "LT fuel low," "RT fuel low," and "reservoir fuel low" lights were all illuminated. In addition, the left and right fuel gauges showed 'Empty.'

Both the left and right fuel tanks were sumped and no fuel was noted. About 2 cups of fuel was removed from the reservoir fuel tank, and a couple ounces was removed from the fuel strainer.

Mr. Arispe attached the following photos:

Intentionally left blank. Please proceed to the next page.



Figure 1: Airplane on Level Ground



Figure 2: Activated Annunciator Lights



Figure 3: Fuel Gauges.

END.

Submitted by: Samantha Link