



RECORD OF EMAIL

Samantha Link
Aviation Accident Investigator
Central Region

Date: April 14, 2021
Person Contacted: Mr. Keenon Wood (Federal Aviation Administration)
NTSB Accident Number: CEN21LA178

Narrative:

During an email conversation Mr. Wood reported the following:

- The airplane's firewall exhibited horizontal ripples near the nose gear attachment point, as well as an overall large vertical bend.
- Mr. Wood examined the brake system, and he did not note anything abnormal that would have precluded normal operations
- He shared the following photos of the airplane's damage.



Figure 1: Horizontal Ripples in Firewall




Figure 2: Overall Vertical Bend

END.

Submitted by: Samantha Link