



MEMORANDUM OF CONVERSATION

Aaron McCarter
Air Safety Investigator
Eastern Region Aviation

Date and Time: April 11, 2022 @ 0945
Person Contacted: FAA ASI; Michael Bevan [REDACTED]
NTSB Accident Number: ERA22LA176

RE: Discussed the circumstances surrounding the accident

Narrative:

The airplane struck a perimeter fence about 150-200 feet from the runway. The airplane is substantially damaged. The engine and firewall are compressed. The left wing tip is bent, and the landing gear is damaged. He has a video that he will send; it showed the entire accident sequence. The pilot allowed his airspeed and altitude to decrease, and he sunk and struck the fence.

Witnesses near the site stated that the aircraft had gone once around the traffic pattern and when approaching to land was very low and appeared to be at an abnormally slow airspeed. It nosed up just before hitting the fence. He will send an email with the contacts and witness accounts in addition to more photographs.

[END]