



RECORD OF CORRESPONDENCE

Michael J. Folkerts
Aviation Accident Investigator
Central Region

Date: July 12, 2021
NTSB Accident Number: CEN21LA269

Mr. Brian Fricker, an FAA inspector, provided the following information:

- Mr. Fricker performed a detailed examination of the airplane's systems.
- No anomalies were found with the rudder, rudder cables, or nosewheel steering connections.
- The underside of the right wing was substantially damaged.