



Vessel Name: SABINE
 Work Order: 5056278
 First Visit Date: 06-Dec-2021
 Last Visit Date: 09-Dec-2021

SURVEY AFTER CONSTRUCTION VESSEL REPORT

Vessel Name SABINE
 Class Number 07175711
 IMO Number 9397391
 of

Port Arthur, TX, United States of America

This is to certify that the undersigned surveyor(s) to this Bureau, did at the request of the Owner's representative, attend the subject Vessel from 06-Dec-2021 to 09-Dec-2021 as the vessel lay afloat at Port Neches in order to carry out the survey(s) noted below.

Survey Task	Task Status	Finding Issued
-------------	-------------	----------------

Surveys for Classification

Repair Survey (Class)	Completed	Yes
-----------------------	-----------	-----

Report Findings

Conditions of Class

Rectified Findings

Finding No	Status	Asset	Survey Task	Due Survey Task	Finding Type/Criticality	Date Created	Due Date
202.0	Closed	Bulwerk	Repair Survey (Class)		Outstanding/ Recommendation	09-Dec-2021	

Found

Owners reported that the subject vessel suffered contact damage from another vessel on 25 November 2021 at approximately 2300 while moored at Motiva Port Neches.

The stbd aft main deck bulwarks and stbd stack plating were found to have been set-in.

Recommended

It is recommended that permanent repairs be carried out to the satisfaction of the attending surveyor.

Rectified

The following permanent repairs were carried out:

- stbd main deck bulwarks were cropped and renewed as original, starting at frame 35 extending aft approximately 11'
- stbd upper stack plating was inserted on the forward side above the focsle deck, approximately 66" x 40" x 3/8" plating
- stbd upper stack plating was inserted on the outboard upper edge, approximately 43" x 24" x 3/8" plating
- stbd upper stack plating was inserted on the top side forward outboard corner, approximately 12" x 24" x 3/8" plating

Repairs were carried out by qualified welders using approved procedures and materials. Upon completion the welding was visually examined, tested for tightness, and found to be satisfactory as permanent repairs.

Closing Paragraph:

It is recommended that the Vessel, SABINE, be retained as classed with this Bureau.

Attending Surveyor(s):

Hartman, John Matthew

1 of 2

NOTE: This Report evidences that the survey reported herein was carried out in compliance with one or more of the Rules, guides, standards or other criteria of the American Bureau of Shipping and is issued solely for the use of the Bureau, its committees, its clients or other authorized entities. This Report is a representation only that the vessel, structure, item of material equipment, machinery or any other item covered by this Report has been examined for compliance with, or has met one or more of the Rules, guides, standards or other criteria of American Bureau of Shipping. The validity, applicability and interpretation of this Report is governed by the Rules and standards of American Bureau of Shipping who shall remain the sole judge thereof. Nothing contained in this Report or in any notation made in contemplation of this Report shall be deemed to relieve any designer, builder, owner, manufacturer, seller, supplier, repairer, operator or other entity of any warranty express or implied.



Vessel Name: SABINE
Work Order: 5056278
First Visit Date: 06-Dec-2021
Last Visit Date: 09-Dec-2021

Signed-off Date: 09-Dec-2021

Reviewing Surveyor(s)

Work Order Reviewer: Bucchi, Joey
Work Order Credit Date: 10-Dec-2021