



## Track Inspection & FRA Reports

Return To: [UP Employees Home](#)Logged In As: XXXXXXXXXX [Log Out](#)

Fri, October 05, 2018 12:07:17 PM

### Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/25/2018 Inspected By: William Johnson  
Inspection Type: FRA Required How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/25/2018 04:51:00 PM

Date Inspection Closed by Inspector: 09/25/2018 04:51:00 PM

#### Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4146 SIDE	03 103	528.55	529.52	No	ALLEN	HINKER	GRANITE SIDING
DENVER	LARAMIE SUB	LARAMIE SUB	4140 SIMN		99.92	103.16	No	ALLEN	HINKER	SPEER TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29	No	ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4138 NO 4		518.27	519.76	No	ALLEN	HINKER	SPEER
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4138 SIDE	03 142	518.29	519.71	No	ALLEN	HINKER	SPEER CENTER SIDING

#### Track Traversed Information

DENVER	LARAMIE SUB	LARAMIE SUB	4138 NO 4		518.27	519.76	No	ALLEN	HINKER	SPEER
DENVER	LARAMIE SUB	LARAMIE SUB	4140 SIMN		99.92	103.16	No	ALLEN	HINKER	SPEER TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	529.53		ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		529.59	545.58		ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29	No	ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE

#### Comments

--

#### Track Defects

**No track defect records found**

#### Curves Walked

**No Curves Found**

#### Switch Defects

Subdivision	Original Subdivision	Seg /	MP/	Defect	Nature of Defect	Remedial	Remedial	Permanent	Permanent	By Whom	Comments
-------------	----------------------	-------	-----	--------	------------------	----------	----------	-----------	-----------	---------	----------

		Trk Type / Zone / Track	User MP	Measurement		Action	Action Date	Repairs	Repair Date		
LARAMIE SUB	LARAMIE SUB	<u>4147</u> NO 1	<u>547.29</u> 547.29		133AC-133.A12 - Loose, worn, or	Scheduled for Repair	09/25/2018				
LARAMIE SUB	LARAMIE SUB	<u>4147</u> NO 2	<u>545.59</u> 545.62		137E-137.E - Severe frog condi	Scheduled for Repair	09/25/2018	Corr from Trk Mtce Plan	10/02/2018		

### Joint Bar Inspections

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4140</u> SIMN		99.92	103.16	ALLEN	HINKER	SPEER TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4146</u> NO 2		519.09	545.58	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4146</u> NO 1		519.09	545.58	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4147</u> NO 1		545.58	547.29	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4147</u> NO 2		545.58	547.29	ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4148</u> NO 1		547.29	565.22	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	<u>4148</u> NO 2		547.29	565.22	ALLEN	HINKER	HERMOSA TO LARAMIE

**TMP Joint Bar Re-Inspect**  
**No TMP Joint Bar Re-Inspect Records Found**



Top of Page

[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)