



Track Inspection & FRA Reports

Return To: [UP Employees Home](#)Logged In As: XXXXXXXXXX [Log Out](#)

Fri, October 05, 2018 11:50:46 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/29/2018 Inspected By: William Johnson
Inspection Type: FRA Required How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/29/2018 12:17:17 PM

Date Inspection Closed by Inspector: 09/29/2018 12:17:19 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 SIDE	03 103	528.55	529.52	No	ALLEN	HINKER	GRANITE SIDING
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 1		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 1		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29	No	ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
Track Traversed Information										
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.22	No	ALLEN	HINKER	HERMOSA TO LARAMIE
Comments										

Track Defects

No track defect records found

Curves Walked

No Curves Found

Switch Defects

Subdivision	Original Subdivision	Seg /	MP/	Defect	Nature of Defect	Remedial	Remedial	Permanent	Permanent	By Whom	Comments
-------------	----------------------	-------	-----	--------	------------------	----------	----------	-----------	-----------	---------	----------

		Trk Type / Zone / Track	User MP	Measurement		Action	Action Date	Repairs	Repair Date		
LARAMIE SUB	LARAMIE SUB	<u>4148</u> <u>NO 1</u>	<u>553.89</u> 553.89		133AH-133.A17 - Obstruction in	Repaired Before Traff c	09/29/2018	Corr from Trk Mtce Plan	09/29/2018		
LARAMIE SUB	LARAMIE SUB	<u>4148</u> <u>NO 2</u>	<u>547.35</u> 547.35		133A9-133.A9 - Loose or missing	Repaired Before Traff c	09/29/2018	Corr from Trk Mtce Plan	09/29/2018		

Joint Bar Inspections
No Joint Bar Inspections Found

TMP Joint Bar Re-Inspect
No TMP Joint Bar Re-Inspect Records Found

