

Fri, October 05, 2018 11:21:28 AM

Union Pacific Railroad FRA Track Inspection & Defect Report

Inspection Date: 09/09/2018 Inspected By: Ian Watkins
Inspection Type: FRA Required How Conducted: Hi-Rail Walk

Date Inspection Uploaded into the Central System: 09/09/2018 08:45:03 PM
Date Inspection Closed by Inspector: 09/09/2018 08:45:03 PM

Tracks Inspected

Service Unit	Subdivision	Original Subdivision	Seg/ Trk Type	Zone/ Track	Begin MP	End MP	Rail Xing Insp	Director	Manager	Track Description
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 1		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 1		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 1		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 1		547.29	565.31	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.31	No	ALLEN	HINKER	HERMOSA TO LARAMIE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 1		545.58	547.29	No	ALLEN	HINKER	DALE JCT TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29	No	ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE

Track Traversed Information

DENVER	LARAMIE SUB	LARAMIE SUB	4135 NO 2		509.50	512.00	No	ALLEN	HINKER	EAST CHEYENNE TO CHEYENNE
DENVER	LARAMIE SUB	LARAMIE SUB	4145 NO 2		512.00	519.09	No	ALLEN	HINKER	CHEYENNE TO BORIE
DENVER	LARAMIE SUB	LARAMIE SUB	4146 NO 2		519.09	545.58	No	ALLEN	HINKER	BORIE TO DALE JCT
DENVER	LARAMIE SUB	LARAMIE SUB	4147 NO 2		545.58	547.29	No	ALLEN	HINKER	DALE JCT. TO HERMOSA
DENVER	LARAMIE SUB	LARAMIE SUB	4148 NO 2		547.29	565.31	No	ALLEN	HINKER	HERMOSA TO LARAMIE

Comments

Track Defects

No track defect records found

Switches Inspected

Switch Inspected by	Subdivision	Original Subdivision	From Track		Mile Value	To Track		User Switch Description	Frog Type Description
			Segment/ Track	ZTS		Segment/ Track	ZTS		
Walked	LARAMIE SUB	LARAMIE SUB	4145 NO 2	-	514.46	4145 INDU	01 -800		Spring-Peg Leg (joint at toe)
Walked	LARAMIE SUB	LARAMIE SUB	4146 NO 2	-	519.09	4140 SIMN	-	#3 2-BORIE CUT-OFF	RBM Standard Point
Walked	LARAMIE SUB	LARAMIE SUB	4146 NO 2	-	519.1	4146 MLXO	77 -038	#1B XO 2-1	RBM Standard Point
Walked	LARAMIE SUB	LARAMIE SUB	4146 NO 1	-	519.15	4146 MLXO	77 -038	#1A XO 2-1	RBM Standard Point
Walked	LARAMIE SUB	LARAMIE SUB	4146 NO 2	-	519.21	4146 YARD	03 -115		Spring-Peg Leg (joint at toe)
Walked	LARAMIE SUB	LARAMIE SUB	4146 NO 1	-	536.22	4146 YARD	03 -512	536 20 per EEI 01/02/09	Spring-All Rail Extd length
Walked	LARAMIE SUB	LARAMIE SUB	4146 NO 1	-	539.03	4146 YARD	03 -526		
Walked	LARAMIE SUB	LARAMIE SUB	4146 NO 2	-	543.05	4146 YARD	03 -132		Spring-Peg Leg (joint at toe)
Walked	LARAMIE SUB	LARAMIE SUB	4148 NO 1	-	553.89	4148 YARD	03 -136		Spring-Peg Leg (joint at toe)
Walked	LARAMIE SUB	LARAMIE SUB	4148 NO 2	-	561.69	4148 YARD	03 -140	Forelle House Track	Jump

Curves Walked

No Curves Found

Switch Defects

Subdivision	Original Subdivision	Seg / Trk Type / Zone / Track	MP/ User MP	Defect Measurement	Nature of Defect	Remedial Action	Remedial Action Date	Permanent Repairs	Permanent Repair Date	By Whom	Comments
LARAMIE SUB	LARAMIE SUB	<u>4146</u> NO 2	<u>519.09</u> 519.10		133AC-133.A12 - Loose, worn, or	Repaired Before Traffic	09/09/2018	Corr from Trk Mtce Plan	09/09/2018		loose bolt
LARAMIE SUB	LARAMIE SUB	<u>4146</u> NO 2	<u>519.10</u> 519.11		127A2-127.A2 - Insufficient fas	Scheduled for Repair	09/09/2018				loose lags

Joint Bar Inspections
No Joint Bar Inspections Found

TMP Joint Bar Re-Inspect
No TMP Joint Bar Re-Inspect Records Found



[Home](#) | [Search](#) | [Crew Boards](#) | [New Stuff](#) | [UP Phonebook](#) | [UP Online](#) | [Help/Info](#) | [Feedback](#)

[Top of Page](#)