



SUMMARY OF FINDINGS

Tealeye Cornejo
Air Safety Investigator (Field)
Western Pacific Region

Person Contacted: Tim Burtch, NTSB
NTSB Accident Number: WPR17LA088

Narrative:

The limited video footage recorded from the accident, showed the engine rpm in an “appropriate” range.