

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI	
Division	KEYSTONE	Date Inspected	02/03/2023	
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Joshua Lonca	
Inspection ID	10289175			
Comments	FRA Inspection & Cold Inspection - No exceptions			

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Defects					
Location	Defect	Immediate Remedial Action			
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair			
Defect Comments					
five rod is broke under the c	uff at bolt hole. scheduled to be replaced on monda	y or tuesday			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/02/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10288811		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	



Date Range Location

KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Divi	sion KEYSTONE	Date Inspected	02/01/2023
Inspecte	d By Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspectio	n ID 10288545		
Comm	ents Switch inspection only		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 1	RD	67.0000	86.0000		Inspected Only	
Main 2	RD	67.1800	86.0000		Inspected Only	

Switches Walked			
Location Switch Name			
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		

Defects						
Location	Defect	Immediate Remedial Action				
RD 67.18 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed				
Defect Comments						
1 missing clip in Ohio Edison	switch- fixed					



KEYSTO	NE KS-ALI	2/3/2022 to 2/4/2023		
Div	rision Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/01/2023
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Jamie Swanson
	Inspection ID	10288518		
	Comments	Cold Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

ŒΥ	STONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	01/31/2023
	Inspected By	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	N/A
	Inspection ID	10288184		
	Comments	cold patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How					How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/31/2023
Inspected By	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	N/A
Inspection ID	10288114		
Comments cold patrol			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspec					How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisi	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	01/31/2023
lı	nspected By	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	Scott Steinbach
In	spection ID	10288102		
	Comments	cold patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/31/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10288048		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked			
MP Range	Туре		
RD 67.0000 - 86.0000 Main 1	Straight Joints		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		

Defects					
Location	Defect	Immediate Remedial Action			
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair			
Defect Comments					
five rod is broke under the cu	uff at bolt hole. scheduled to be replaced on monda	y or tuesday			



KEYSTONE KS-ALI	EYSTONE KS-ALI 2/3/2022 to 2/4/2023					
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI			
Divisior	KEYSTONE	Date Inspected	01/30/2023			
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep			
Inspection ID	10287685					
Comments FRA patrol						

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	



2/3/2022 to 2/4/2023

Location Date Range

Comments FRA patrol

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/26/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
Inspection ID	10287075		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 60.0200	Boilerworks	
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500	Salem Industrial	

Defects			
Location Defect Immediate Remedial Action			
RD 61.5 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Removed tree			

Location	Defect	Immediate Remedial Action		
RD 65.4 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Removed tree				





KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/25/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10286810		
Comments	nents Switch inspection. Whitaker Grear, Morgan Engeneering, and Pit Track OOS		

Following tracks to	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only

Switches Walked		
Location	Switch Name	
RD 66.1400	Mahoning Yard	
RD 66.1500	Mahoning Crossover E-End	
RD 66.1900	Mahoning Crossover W-End	



KEYS	STONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	01/25/2023
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
	Inspection ID	10286780		
	Comments	Switch Inspection Only		

Following tracks to	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only

Switches Walked	
Location Switch Name	
RD 55.2800	Bayard Siding E-End
RD 55.7700	Bayard Siding W-End



2/3/2022 to 2/4/2023

Location Date Range KEYSTONE KS-ALI

Comments FRA patrol

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/24/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10286678		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location	Switch Name	
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	

Defects				
Location	Defect	Immediate Remedial Action		
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair		
Defect Comments				
five rod is broke under the cuff at bolt hole. scheduled to be replaced on monday or tuesday				



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/23/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10286119		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked	
Location	Switch Name
PC 39.2800	Bognar/Hot Top
PC 47.4600	NVR/Ryan Homes

Defect Subpart DTrack Structure - Turnouts	Immediate Remedial Action			
Subpart DTrack Structure - Turnouts	Cahadulad for Danair			
and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	·			
Defect Comments				
	Fastening Intact / Component Secured Die. scheduled to be replaced on monda			

Location	Defect	Immediate Remedial Action
PC 39.3 Main 2	Subpart DTrack Structure - Switches -	Fixed



Track Inspections

	(b) Switch point improperly fit against stock rail	
Defect Comments		
Switch out of adjustment- fixed		

Location	Defect	Immediate Remedial Action	
PC 35.9 Main 1	Subpart DTrack Structure - Frogs - (b) Frog point chipped, broken, or worn more than 5/8 inches down and 6 inches back	Slow Ordered and Fixed	
Defect Comments			
Chip out point and riser on 1B switch in CP Wood- fixed			



Date Range Location

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	01/20/2023
In	spected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon

Inspection ID 10286024

Comments FRA patrol

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 40.4700	Clayworks	
PC 49.0100	State Line	

Location	Defect	Immediate Remedial Action
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair
Defect Comments		

Location	Defect	Immediate Remedial Action		
	Subpart DTrack Structure - Defective Rails - Ordinary Break	Out of Service and Fixed		
Defect Comments				
Broken rail at thermit weld at RD 67.2 main 1- fixed				



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/19/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10285498		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location	Switch Name	
PC 39.2800	Bognar/Hot Top	
PC 60.6500	Columbiana Camp Car	
PC 73.4600	#3B CP Murph	
PC 73.7200	#1A CP Murph	

Defects			
Location	Defect	Immediate Remedial Action	
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair	
Defect Comments			
five rod is broke under the c	uff at bolt hole. scheduled to be replaced on monda	y or tuesday	

Location	Defect	Immediate Remedial Action	
PC 75.2 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
removed tree from track and right of way			

Location	Defect	Immediate Remedial Action
PC 73.7 Main 2	Subpart DTrack Structure - Rail	Fixed
	Fastening Systems - Rail Fastening	



Track Inspections

Systems	
Defect Comments	
Gage widening ahead of switch- spikes added, fixed	

Location	Defect	Immediate Remedial Action
PC 39.3 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		·
wide gage in Bognars sidin	g track- spikes added, fixed	

Location	Defect	Immediate Remedial Action
PC 76.4 Main 1	Subpart DTrack Structure - Rail Joints - (d) Insufficient number of bolts for class of track	Fixed
Defect Comments		
Missing bolt in joint at 76.4	main 1- fixed	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/18/2023
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose
Inspection ID	10285221		
Comments	Switch Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	82.0000	83.0800		Inspected Only
Main 2	PC	82.0000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 82.9300	#9 CP Alliance	
PC 83.0000	#7B CP Alliance	
PC 83.0800	#7B CP Alliance	
PC 83.1400	#5B CP Alliance	
PC 83.2600	#3 CP Alliance	
PC 83.3300	#1A CP Alliance	
RD 67.0500	#5A CP Alliance	
RD 67.0900	Switch #13 CP Alliance	
RD 67.1700	#11B CP Alliance	
RD 67.2400	#11A CP Alliance	
RD 75.0400	Atwater	
RD 82.8000	Ohio Edison	
RD 85.7800	#3B CP 86	
RD 85.8500	#3A CP 86	

Crossing Diamonds Walked	
Location Diamond Name	
PC 83.2500	Alliance Diamond

Defects	
---------	--



Track Inspections

Location	Defect	Immediate Remedial Action
RD 67.09 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		
Two missing Pandrol clips - ti	ghtened three rail braces - tightened guardrail b	olts - Fixed

Location	Defect	Immediate Remedial Action
RD 67.17 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		
Missing Pandrol clip - Fixed		

Location	Defect	Immediate Remedial Action
PC 83.26 Lead	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		
Four missing Pandrol clips -	Tightened two rail braces - Fixed	

Location	Defect	Immediate Remedial Action
PC 83.25 Lead	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair
Defect Comments	·	
Two missing diamond bolts	- Scheduled for Repair	



KEYSTONE KS-ALI		(S-ALI	2/3/2022 to 2/4/2023		
	Division E	ingineer	Spadone, Joe	Subdivision or District	KS-ALI
		Division	KEYSTONE	Date Inspected	01/17/2023

Inspected By Rose, Rose 2nd Qualified Inspector Mike Heslep
Track Patrol Foreman

Inspection ID 10284896

Comments FRA patrol

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix					How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked			
Location	Switch Name		
PC 35.8000	#3A New CP Wood		
PC 35.8200	#1B New CP Wood		
RD 85.8500	#3A CP 86		
RD 85.9200	#1B CP 86		

Defects				
Location	Defect	Immediate Remedial Action		
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair		
Defect Comments				
five rod is broke under the c	uff at bolt hole. scheduled to be replaced on monda	y or tuesday		



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	KEYSTONE	Date Inspected	01/16/2023
Inspected I	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection	ID 10284736		
Commen	ts FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/13/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Scott Steinbach
Inspection ID	10284335		
Comments	FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix					How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Switches Walked			
Location	Switch Name		
PC 45.3000	#3A CP Enon		
PC 45.3200	#1B CP Enon		
PC 57.5500	#3A CP Lum		
PC 57.5700	#1B CP Lum		

Defects						
Location Defect Immediate Remedial Action						
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair				
Defect Comments						
five rod is broke under the cuff at bolt hole. scheduled to be replaced on monday or tuesday						



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/12/2023
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Tom Kellogg
Inspection ID	10283935		
Comments	Hoopes, Alliance Camp Car switches out of service. Alliance Castings switch REMOVED.		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked			
Location Switch Name			
RD 53.7800	Hoopes		
RD 64.6600	Spring Switch		
RD 66.2200	Alliance Camp Car		
RD 66.3700	Alliance Castings		

Defects					
Location Defect Immediate Remedial Action					
PC 38.2 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
Two missing Pandrol clips in	curve - Fixed				



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/11/2023
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10283581		
Comments Alliance Runner & 80.5 Switch Inspection			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	80.0000	82.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 80.4500	Alliance Runner/80.5 Switch	

Defects				
Location	Immediate Remedial Action			
PC 80.45 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed		
Defect Comments				
Three missing Pandrol clips - Fixed				



KEYSTONE KS-A	ALI 2/3/2022 to 2/4/2023		

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/10/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10283278		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range Type		
RD 67.0000 - 86.0000 Main 1	Straight Joints	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location Switch Name		
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	

Defects				
Location	Defect	Immediate Remedial Action		
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair		
Defect Comments				
five rod is broke under the c	uff at bolt hole. scheduled to be replaced on monda	y or tuesday		

ion Defect Immediate Remedial Action	
--------------------------------------	--



Track Inspections

PC 73.5 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed
Defect Comments		
1 missing clip in the 3A switch in CP Mu	rph- fixed	



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/09/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10283102		
Comments	FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range Type		
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location Switch Name		
PC 35.9500	#1A New CP Wood	
PC 83.3300	#1A CP Alliance	
RD 66.8600	#15 CP Alliance	
RD 66.8800	Switch #1B CP Alliance	
PC 35.7100	#3B CP Wood	



2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/06/2023
	Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	Jamie Swanson
Inspection ID	10282732		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Defects			
Location	Immediate Remedial Action		
PC 73.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair	
Defect Comments			
five rod is broke under the c	uff at bolt hole. scheduled to be replaced on monda	y or tuesday	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/05/2023
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10282272		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



ONE KS-ALI 2/3/2022 to 2/4/202

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	01/04/2023
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Rose Rose
Inspection ID	10281989		
Comments	Curve Walking Only within Mile Po	st Limits.	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	83.0000	85.0000		Walked
Main 2	RD	83.0000	85.0000		Walked

Defects				
Location	Defect	Immediate Remedial Action		
RD 83.6 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Scheduled for Repair		
Defect Comments				

Location	Defect	Immediate Remedial Action
RD 84.7 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Scheduled for Repair
Defect Comments	·	·
High Spikes/ Plate push ea	st of Lake St Crossing. Need to pull and plug.	

Location	Defect	Immediate Remedial Action
RD 84.6 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Scheduled for Repair
Defect Comments		
High spikes on high side of cu	urve. Need pulled and plugged.	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	01/03/2023
Inspected E	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection I	D 10281634		
Commen	ts FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	



KEYSTONE K	(S-ALI	2/3/2022 to 2/4/2023		
Division E	ngineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	01/02/2023
Inspe	-	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Tom Kellogg
Inspe	ction ID	10281467		
Cor	mments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/30/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Tom Kellogg
Inspection ID	10281210		
Comments	FRA Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix				Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	12/29/2022
In	spected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon
In	spection ID	10280818		
	Comments	FRA patrol		

Following tra	following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked		
Location	Switch Name	
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500	Salem Industrial	



KEYSTONE KS-AL	2/3/2022 to 2/4/2023		
Division Engine	eer Spadone, Joe	Subdivision or District	KS-ALI
Divisi	on KEYSTONE	Date Inspected	12/28/2022
Inspected	By Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection	ID 10280555		
Comme	nts Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspects					How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only

Switches Walked				
Location Switch Name				
RD 55.2800	Bayard Siding E-End			
RD 55.7700	Bayard Siding W-End			
RD 66.1400 Mahoning Yard				
RD 66.1500 Mahoning Crossover E-End				
RD 66.1900	Mahoning Crossover W-End			



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/27/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10280400		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location Switch Name		
PC 35.9500	#1A New CP Wood	
PC 63.8200	Sutton Siding	
PC 73.4600	#3B CP Murph	
PC 73.7200	#1A CP Murph	
PC 78.8500	Sebring	
PC 35.7100	#3B CP Wood	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/26/2022
-	Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	Joshua Early
Inspection ID	10280104		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Ins					How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	

Switches Walked	
Location Switch Name	
PC 47.4600	NVR/Ryan Homes
PC 60.0200	Boilerworks

Defects			
Location Defect Immediate Remedial Action			
PC 47.9 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
ree on track			

Location	Defect	Immediate Remedial Action	
	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed	
Defect Comments			
two joints in switch were loose			



Track Inspections

Location	Defect	Immediate Remedial Action		
PC 54.2 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
rree				

Location	Defect	Immediate Remedial Action	
PC 53.8 Main 1	Subpart BRoadbed - Drainage - Drainage	Fixed	
Defect Comments			
metal in guage of track			



	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
ſ	Division	KEYSTONE	Date Inspected	12/26/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
	Inspection ID	10280046		
	Comments	FRA and Cold Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/24/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Eric Gardner
Inspection ID	10279849		
Comments	Cold patrol. No defects		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	12/23/2022
Inspected E	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	Joshua Early
Inspection I	D 10279777		
Commen	Cold Weather Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



Date Range Location

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	12/23/2022
Ins	pected By	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	Timothy Bacon
Ins	pection ID	10279775		
	Comments	fra/cold patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail

Switches Walked			
Location Switch Name			
PC 40.4700	Clayworks		
PC 49.0100	State Line		
PC 60.0200	PC 60.0200 Boilerworks		



2/3/2022 to 2/4/2023

Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/23/2022
Inspected By	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	N/A
Inspection ID	10279771		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail

Defects				
Location	Defect	Immediate Remedial Action		
RD 62.5 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
tree fouling track, removed				

Location	Defect	Immediate Remedial Action	
RD 64 Main 1 Subpart BRoadbed - Vegetation - Vegetation		Fixed	
Defect Comments			
tree fouling track, removed			

Location	Defect	Immediate Remedial Action		
RD 71.3 Main 1 Subpart BRoadbed - Vegetation - Vegetation		Fixed		
Defect Comments				
tree fouling track, removed				



KEYSTONE KS-	-ALI	2/3/2022 to 2/4/2023		
Division Eng	gineer	Spadone, Joe	Subdivision or District	KS-ALI
Di	vision	KEYSTONE	Date Inspected	12/22/2022
Inspect		Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
Inspecti	ion ID	10279278		
Comi	ments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 39.2800	Bognar/Hot Top	
PC 57.4800 #3B CP Lum		
PC 57.6400 #1A CP Lum		
PC 60.6500	Columbiana Camp Car	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/21/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
Inspection ID	10278953		
Comments	Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked			
Location	Switch Name		
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
PC 83.2600	#3 CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		

Crossing Diamonds Walked			
Location Diamond Name			
PC 83.2500 Alliance Diamond			

Defects		
Location	Defect	Immediate Remedial Action



Track Inspections

PC 83 Main 2	Subpart DTrack Structure - Switches - (e) Switch stand or connecting rod not securely fastened or has lost motion	Fixed			
Defect Comments					
Broken rod in 7B switch in CP Alliance- fixed					

Location	Defect	Immediate Remedial Action		
PC 83 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		
Defect Comments				
Missing clip in 7B switch in CP Alliance- fixed				



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/20/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10278828		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Ins							
Main 1	PC	35.7000	83.0800		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Joints Walked					
MP Range	Туре				
RD 67.1800 - 86.0000 Main 2	Straight Joints				
RD 67.0000 - 86.0000 Main 1	Straight Joints				
PC 35.7000 - 83.0800 Main 1	Straight Joints				
PC 35.7000 - 83.0800 Main 1	Comp Joints				
RD 67.0000 - 86.0000 Main 1	Comp Joints				

Switches Walked					
Location Switch Name					
PC 35.8000	#3A New CP Wood				
PC 35.8200	#1B New CP Wood				
RD 85.8500	#3A CP 86				
RD 85.9200	#1B CP 86				



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/19/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Tom Kellogg
Inspection ID	10278284		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:								
Track Prefix From To Suffix How Inspe								
Main 2	PC	35.7000	83.0800		Hi-Rail			
Lead	PC	83.0800	83.2800		Hi-Rail			
Main 2	PC	83.2800	83.5000		Hi-Rail			
Main 1	RD	53.0000	67.0000		Hi-Rail			
Siding	RD	64.6600	66.8600		Inspected Only			

Joints Walked					
MP Range	Туре				
PC 35.7000 - 83.0800 Main 2	Straight Joints				
PC 83.2800 - 83.5000 Main 2	Straight Joints				
RD 53.0000 - 67.0000 Main 1	Comp Joints				
PC 35.7000 - 83.0800 Main 2	Comp Joints				
RD 53.0000 - 67.0000 Main 1	Straight Joints				

Switches Walked				
Location	Switch Name			
PC 45.2300	#3B CP Enon			
PC 45.3900	#1A CP Enon			
PC 45.4300	Enon Supply			
PC 57.4800	#3B CP Lum			
PC 57.6400	#1A CP Lum			

Defects							
Location	Defect	Immediate Remedial Action					
PC 45.3 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed					
Defect Comments							
Missing clip in 3B switch in CP Enon- fixed							



Track Inspections

Location	Defect	Immediate Remedial Action				
PC 45.5 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed				
Defect Comments						
Missing clip in 1A switch in CP Enon- fixed						



KEYSTONE KS	S-ALI	2/3/2022 to 2/4/2023		
Division En	gineer	Spadone, Joe	Subdivision or District	KS-ALI
D	ivision	KEYSTONE	Date Inspected	12/16/2022
Inspec	-	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon
Inspect	tion ID	10277956		
Com	ments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail

Switches Walked			
Location	Switch Name		
PC 45.3000	#3A CP Enon		
PC 45.3200	#1B CP Enon		
PC 57.5500	#3A CP Lum		
PC 57.5700	#1B CP Lum		



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
Division	KEYSTONE	Date Inspected	12/16/2022		
	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	N/A		
Inspection ID	10277948				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	67.0000	86.0000		Hi-Rail

Switches Walked			
Location	Switch Name		
RD 67.0500	#5A CP Alliance		
RD 67.1700	#11B CP Alliance		

Defects						
Location	Immediate Remedial Action					
RD 67 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed				
Defect Comments						
cuff replaced on 11b switch						



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	12/15/2022			
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon			
Inspection ID 10277712						
Comments	FRA patrol					

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location	Switch Name	
PC 39.2800	Bognar/Hot Top	



KEYSTO	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
Divi	ision Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
	Division	KEYSTONE	Date Inspected	12/15/2022		
Inspected By		Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Dan Jurkiewicz		
Inspection ID 10		10277655				
	Comments Hoopes, Alliance Castings, Alliance Camp Car Switches - Out Of Service					

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Lead	PC	83.0800	83.2800		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked			
Location	Switch Name		
RD 53.7800	Hoopes		
RD 64.6600	Spring Switch		
RD 66.2200	Alliance Camp Car		
RD 66.3700	Alliance Castings		



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/14/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10277373		
Comments Switch and yard inspection			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Inspected Only

Switches Walked		
Location Switch Name		
PC 80.4500 Alliance Runner/80.5 Switch		



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/13/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon
Inspection ID	10277041		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked				
MP Range	Туре			
RD 67.1800 - 86.0000 Main 2	Straight Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			

Switches Walked			
Location	Switch Name		
PC 73.5800	#3A CP Murph		
PC 73.6000	#1B CP Murph		
RD 85.7800	#3B CP 86		
RD 85.9900	#1A CP 86		



2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/12/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon
Inspection ID	10276709		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked				
MP Range	Туре			
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			

Switches Walked			
Location	Switch Name		
PC 83.3300	#1A CP Alliance		
RD 66.8600	#15 CP Alliance		
RD 66.8800	Switch #1B CP Alliance		

Defects						
Location	Defect	Immediate Remedial Action				
PC 60 Main 2 Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point		Fixed				
Defect Comments						
1 missing clip and 1 worn c	hair plate- fixed					





KEYSTONE	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
Divisi	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
	Division	KEYSTONE	Date Inspected	12/09/2022		
I	nspected By	Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Tom Kellogg		
lı	nspection ID	10276514				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.1000	83.2800		Walked
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.2000	85.3000		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	12/08/2022
Inspected B	y Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection II	10276140		
Comment	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/06/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10275574		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.0000 - 86.0000 Main 1	Straight Joints		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		



2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/05/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10275196		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked				
MP Range	Туре			
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			

Defects					
Location Defect Immediate Remedial Action					
PC 65.3 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
Removed tree from track and	l right of way				



Division I	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	12/02/2022
Inspe	ected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspe	ection ID	10274928		
Co	mments	FRA patrol	<u> </u>	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Defects			
Location Defect Immediate Remedial Action			
PC 70.5 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Removed tree from track an	d right of way		

Location	Defect	Immediate Remedial Action	
RD 73.5 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Removed tree from track and right of way			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	12/01/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10274579		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500	Salem Industrial	



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023				
Division En	gineer	Spadone, Joe	Subdivision or District	KS-ALI
Di	ivision	KEYSTONE	Date Inspected	11/30/2022
Inspec	-	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspect	tion ID	10274321		
Com	ments	Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only

Switches Walked		
Location Switch Name		
RD 55.2800	Bayard Siding E-End	
RD 55.7700	Bayard Siding W-End	
RD 66.1400	Mahoning Yard	
RD 66.1500	Mahoning Crossover E-End	
RD 66.1900	Mahoning Crossover W-End	



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	11/29/2022
Ins	spected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Ins	pection ID	10273860		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track	Prefix	From	То	Suffix	How Inspected		
Main 1	PC	35.7000	83.0800		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Joints Walked				
MP Range	Туре			
RD 67.1800 - 86.0000 Main 2	Straight Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			

Switches Walked			
Location	Switch Name		
PC 63.8200	Sutton Siding		
PC 78.8500	Sebring		



_				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	11/28/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
	Inspection ID	10273550		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked				
MP Range	Туре			
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			

Switches Walked			
Location Switch Name			
PC 47.4600	NVR/Ryan Homes		
PC 60.0200 Boilerworks			



Divi	sion Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	11/25/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
	Inspection ID	10273379		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Switches Walked			
Location Switch Name			
PC 40.4700	Clayworks		
PC 49.0100	State Line		



KEYSTONE KS-	-ALI	2/3/2022 to 2/4/2023		
Division Eng	gineer	Spadone, Joe	Subdivision or District	KS-ALI
Di	vision	KEYSTONE	Date Inspected	11/23/2022
Inspect		Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon
Inspecti	ion ID	10272989		
Comi	ments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					
Main 2	PC	35.7000	83.0800		Hi-Rail

Switches Walked		
Location Switch Name		
PC 60.0200	Boilerworks	
PC 60.6500	Columbiana Camp Car	
PC 73.4600	#3B CP Murph	
PC 73.7200	#1A CP Murph	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/23/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Brian Dangelo
Inspection ID	10272900		
Comments	Walking Switch Inspections CP Alliance, Atwater/ Ohio Edison		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Walked
Lead	PC	83.0800	83.2800		Walked
Main 2	PC	83.2800	83.5000		Walked
Main 1	RD	67.0000	86.0000		Walked
Main 2	RD	67.1800	86.0000		Walked

Switches Walked			
Location	Switch Name		
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
PC 83.2600	#3 CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		

Crossing Diamonds Walked			
Location Diamond Name			
PC 83.2500 Alliance Diamond			

Defects				
Location Defect Immediate Remedial Action				
PC 83.25 Lead	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed		
Defect Comments				



4 Missing/ Loose Bolts in Diamond. Changed Out and Tightened.

Location	Defect	Immediate Remedial Action		
PC 83.25 Lead	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Missing Fasteners on Diamond. Set new screws in place.				

Location	Defect	Immediate Remedial Action		
PC 83.26 Lead	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Missing Pandrol CLips @ Backend legs of frog. Replaced.				

Location	Defect	Immediate Remedial Action		
PC 83 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Missing Pandrol Clips. Replaced.				



	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
ſ	Division	KEYSTONE	Date Inspected	11/22/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Scott Steinbach
	Inspection ID	10272615		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked			
Location Switch Name			
PC 35.8000	#3A New CP Wood		
PC 35.8200	#1B New CP Wood		
RD 85.8500	#3A CP 86		
RD 85.9200	#1B CP 86		

Defects					
Location Defect Immediate Rem					
PC 57.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed			
Defect Comments					
2 missing clips, 1 worn wedg	ge replaced- fixed				



Inspection ID 10272294

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/21/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Scott Steinbach

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked			
MP Range Type			
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2 Comp Joints			

Switches Walked			
Location Switch Name			
PC 45.2300	#3B CP Enon		
PC 45.3900	#1A CP Enon		
PC 45.4300	Enon Supply		
PC 57.4800	#3B CP Lum		
PC 57.6400	#1A CP Lum		

Defects						
Location Defect Immediate Remedial Action						
PC 46.7 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed				
Defect Comments						
Tree debris across tracks. Cleaned up, cut tree back off of track.						



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/20/2022
Inspected By	Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	Tom Kellogg
Inspection ID	10272202		
Comments cold patrol			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



KE	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
	Division	KEYSTONE	Date Inspected	11/20/2022			
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Dan Jurkiewicz			
Inspection ID		10272194					
	Comments Cold Inspection						

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/19/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Dan Jurkiewicz
Inspection ID	10272150		
Comments	Cold Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	
Main 1	RD	67.0000	86.0000		Hi-Rail	

Defects						
Location	Defect	Immediate Remedial Action				
RD 72.8 Main 1	Subpart DTrack Structure - Defective Rails - Transverse Fissure, Detail Fracture, Engine Burn Fracture, or Defective Weld	Out of Service and Fixed				
Defect Comments						
Broken thermit weld - Fixed						



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	11/19/2022
Inspected B	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Tom Kellogg
Inspection II	10272147		
Comments Cold patrol			

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	73.5000	83.0800		Hi-Rail	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/18/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10272007		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track	Prefix	From	То	Suffix	How Inspected		
Main 1	PC	35.7000	83.0800		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Switches Walked			
Location Switch Name			
PC 45.3000	#3A CP Enon		
PC 45.3200	#1B CP Enon		
PC 57.5500	#3A CP Lum		
PC 57.5700	#1B CP Lum		



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	11/17/2022			
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep			
Inspection ID	10271626					
Comments FRA patrol						
	Alliance camp car switch and Alliar	ice castings switch OOS				

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked				
Location Switch Name				
RD 53.7800	Hoopes			
RD 64.6600	Spring Switch			
RD 66.2200	Alliance Camp Car			
RD 66.3700	Alliance Castings			



KEYSTONE K	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
Division E	ngineer	Spadone, Joe	Subdivision or District	KS-ALI			
	Division	KEYSTONE	Date Inspected	11/16/2022			
Inspe	-	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A			
Inspec	tion ID	10271317					
Comments Switch and industry inspection							

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Inspected Only

Switches Walked			
Location Switch Name			
PC 80.4500 Alliance Runner/80.5 Switch			



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/15/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10271221		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked				
MP Range Type				
RD 67.1800 - 86.0000 Main 2	Straight Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			

Switches Walked				
Location Switch Name				
PC 73.5800	#3A CP Murph			
PC 73.6000	#1B CP Murph			
RD 85.7800	#3B CP 86			
RD 85.9900	#1A CP 86			



Date Range Location

KEYSTONE K	S-ALI	2/3/2022 to 2/4/2023		
Division E	ngineer	Spadone, Joe	Subdivision or District	KS-ALI
ı	Division	KEYSTONE	Date Inspected	11/14/2022
Inspe	-	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspe	ction ID	10270877		
Coi	mments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked			
Location	Switch Name		
PC 35.9500	#1A New CP Wood		
PC 83.3300	#1A CP Alliance		
RD 66.8600	#15 CP Alliance		
RD 66.8800 Switch #1B CP Alliance			
PC 35.7100	#3B CP Wood		

Defects					
Location	Defect	Immediate Remedial Action			
PC 67.6 Main 1	Subpart DTrack Structure - Rail Joints - (d) Insufficient number of bolts for class of track	Fixed			
Defect Comments					
Missing bolt in joint at PC 67	7.6 main 1- fixed				



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	11/11/2022			
Inspected By	Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Jamie Swanson			
Inspection ID	10270525					

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/10/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10270258		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Suffix	How Inspected				
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/07/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10269239		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	Suffix	How Inspected			
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		



KEYSTONE KS-	-ALI	2/3/2022 to 2/4/2023		
Division Eng	gineer	Spadone, Joe	Subdivision or District	KS-ALI
Div	vision	KEYSTONE	Date Inspected	11/04/2022
Inspect		Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspecti	ion ID	10269028		
Comr	ments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	11/03/2022
Inspected By	Gardner, Eric Assistant Foreman/CDLB	2nd Qualified Inspector	Tom Kellogg
Inspection ID	10268704		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Ins							
Main 2	PC	35.7000	83.0800		Hi-Rail		
Lead	PC	83.0800	83.2800		Hi-Rail		
Main 2	PC	83.2800	83.5000		Hi-Rail		
Main 1	RD	53.0000	67.0000		Hi-Rail		
Siding	RD	64.6600	66.8600		Inspected Only		

Switches Walked			
Location Switch Name			
PC 61.2800	Kaiser/Buckeye Transfer		
PC 70.0500	Salem Industrial		



KEYS	STONE KS-ALI	2/3/2022 to 2/4/2023		
[Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	11/02/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
	Inspection ID	10268640		
	Comments	Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail

Switches Walked		
Location	Switch Name	
RD 55.2800	Bayard Siding E-End	
RD 55.7700	Bayard Siding W-End	
RD 66.1400	Mahoning Yard	
RD 66.1500	Mahoning Crossover E-End	
RD 66.1900	Mahoning Crossover W-End	



_				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	11/01/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
	Inspection ID	10268063		
	Comments	FRA inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location	Switch Name	
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	



2/3/2022 to 2/4/2023

Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/31/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10267823		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 47.4600	NVR/Ryan Homes	
PC 60.0200	Boilerworks	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/28/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Tom Kellogg
Inspection ID	10267575		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 40.4700	Clayworks	
PC 49.0100	State Line	



KE	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
	Division	KEYSTONE	Date Inspected	10/28/2022		
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	N/A		
	Inspection ID	10267436				
	Comments	switch inspection				

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 2 PC 73.0000 74.0000 Walked						

Switches Walked			
Location Switch Name			
PC 73.4600	#3B CP Murph		
PC 73.7200	#1A CP Murph		

Defects						
Location	Defect	Immediate Remedial Action				
PC 73.47 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed				
Defect Comments						
two missing pandrol clips - fixed tightened four rail braces						



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/27/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10267134		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked				
Location Switch Name				
PC 39.2800	Bognar/Hot Top			
PC 60.6500	Columbiana Camp Car			
PC 73.4600	#3B CP Murph			
PC 73.7200	#1A CP Murph			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/26/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10266830		
Comments	Industry inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspe					How Inspected
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked				
Location Switch Name				
RD 75.0400	Atwater			
RD 82.8000	Ohio Edison			



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/26/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10266815		
Comments	Switch Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	82.0000	83.0800		Inspected Only	
Main 2	PC	82.0000	83.0800		Inspected Only	
Lead	PC	83.0800	83.2800		Inspected Only	
Main 2	PC	83.2800	83.5000		Inspected Only	
Main 1	RD	67.0000	68.0000		Inspected Only	
Main 2	RD	67.1800	68.0000		Inspected Only	

Switches Walked		
Location	Switch Name	
PC 82.9300	#9 CP Alliance	
PC 83.0000	#7B CP Alliance	
PC 83.0800	#7B CP Alliance	
PC 83.1400	#5B CP Alliance	
PC 83.2600	#3 CP Alliance	
RD 67.0500	#5A CP Alliance	
RD 67.0900	Switch #13 CP Alliance	
RD 67.1700	#11B CP Alliance	
RD 67.2400	#11A CP Alliance	

Crossing Diamonds Walked	
Location	Diamond Name
PC 83.2500	Alliance Diamond

Defects				
Location	Defect	Immediate Remedial Action		
RD 67.05 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Tightened rail braces (5), two	broken Pandrol clips - Fixed			



Track Inspections

Location	Defect	Immediate Remedial Action	
RD 67.17 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
Missing Pandrol clip - Fixed	Missing Pandrol clip - Fixed		

Location	Defect	Immediate Remedial Action		
PC 83.14 Lead	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
4 missing Pandrol joint clips missing at	4 missing Pandrol joint clips missing at joint - Fixed			



 Location
 Date Range

 STONE
 KS-ALI
 2/3/2022 to 2/4/2023

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	10/25/2022
In	spected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Ins	spection ID	10266535		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location Switch Name		
PC 35.8000	#3A New CP Wood	
PC 35.8200	#1B New CP Wood	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	



Date Range Location

KE	YSTONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	10/24/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
	Inspection ID	10266219		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/21/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Brian Dangelo
Inspection ID	10266033		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	

Defects				
Location Defect Immediate Remedial Action				
PC 75.5 Main 1	Other - Other - Other	Fixed		
Defect Comments				
Removed tree form track and right of way				

Location	Defect	Immediate Remedial Action		
PC 66.5 Main 1	66.5 Main 1 Subpart BRoadbed - Vegetation - Vegetation			
Defect Comments				
Removed tree form track and right of way				

Location	Defect	Immediate Remedial Action		
PC 57.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		
Defect Comments				
Missing clip in 3A switch in CP Lum- fixed				



Track Inspections

Location	Defect	Immediate Remedial Action		
PC 57.7 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		
Defect Comments				
Missing clip in 1B switch in CP Lum- fixed				

Location	Defect	Immediate Remedial Action		
RD 75 Main 2 Subpart BRoadbed - Vegetation - Fixed Vegetation		Fixed		
Defect Comments				
Removed tree form track and right of way				



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/20/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10265633		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location	Switch Name	
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	



Location Date Range
YSTONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	10/19/2022
Inspected B	y Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection II	10265422		
Comment	Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					
Main 2	PC	35.7000	83.0800		Inspected Only

Switches Walked		
Location Switch Name		
PC 80.4500 Alliance Runner/80.5 Switch		



Location Date Range
STONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	10/18/2022
In	spected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Ins	spection ID	10265035		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.0000 - 86.0000 Main 1	Straight Joints		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		

Switches Walked		
Location	Switch Name	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/17/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10264799		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Insp					
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		

Switches Walked		
Location	Switch Name	
PC 35.9500	#1A New CP Wood	
PC 83.3300	#1A CP Alliance	
RD 66.8600	#15 CP Alliance	
RD 66.8800	Switch #1B CP Alliance	
PC 35.7100	#3B CP Wood	

Defects				
Location Defect Immediate Remedial Action				
PC 73.4 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		



Track Inspections

Defect Comments

1 missing clip in 3B switch in CP Murph- fixed



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/14/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Scott Steinbach
Inspection ID	10264533		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	10/13/2022			
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep			
Inspection ID	10264223					
Comments	FRA patrol					

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	10/11/2022
Insp		Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspe	ection ID	10263706		
Co	omments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.0000 - 86.0000 Main 1	Straight Joints		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		



Location Date Range
//STONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Divi	sion KEYSTONE	Date Inspected	10/10/2022
Inspecte	d By Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspectio	n ID 10263438		
Comm	ents FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
Division Eng	ineer Spadone, Joe	Subdivision or District	KS-ALI			
Div	ision KEYSTONE	Date Inspected	10/07/2022			
Inspecte	ed By Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A			
Inspection ID 10263206						
Comments FRA patrol						

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	10/06/2022			
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A			
Inspection ID 10262896						
Comments FRA patrol						

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500	Salem Industrial	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	on KEYSTONE	Date Inspected	10/05/2022
Inspected I	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID 10262605			
Commen	ts Switches		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only

Switches Walked			
Location	Switch Name		
RD 55.2800	Bayard Siding E-End		
RD 55.7700	Bayard Siding W-End		
RD 66.1400	Mahoning Yard		
RD 66.1500 Mahoning Crossover E-End			
RD 66.1900	Mahoning Crossover W-End		



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	10/04/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10262349		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		

Switches Walked		
Location	Switch Name	
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	

Defects				
Location	Defect	Immediate Remedial Action		
RD 70.3 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Removed tree limb from tra	ck and right of way			

Location	Defect	Immediate Remedial Action
PC 78.85 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed



Track Inspections

Defect Comments

Missing clip in Sebring switch- fixed



Date Range Location

KEYSTONE KS-AL	2/3/2022 to 2/4/2023		
Division Engin	eer Spadone, Joe	Subdivision or District	KS-ALI
Divis	ion KEYSTONE	Date Inspected	10/03/2022
Inspected	By Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection	ID 10262068		
Comme	nts FRA inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Inspect							
Main 2	PC	35.7000	83.0800		Hi-Rail		
Lead	PC	83.0800	83.2800		Hi-Rail		
Main 2	PC	83.2800	83.5000		Hi-Rail		
Main 1	RD	53.0000	67.0000		Hi-Rail		
Siding	RD	64.6600	66.8600		Inspected Only		

Joints Walked					
MP Range	Туре				
PC 35.7000 - 83.0800 Main 2	Straight Joints				
PC 83.2800 - 83.5000 Main 2	Straight Joints				
RD 53.0000 - 67.0000 Main 1	Comp Joints				
PC 35.7000 - 83.0800 Main 2	Comp Joints				
RD 53.0000 - 67.0000 Main 1	Straight Joints				

Switches Walked			
Location Switch Name			
PC 47.4600	NVR/Ryan Homes		
PC 60.0200	Boilerworks		



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/30/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon
Inspection ID	10261827		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Inspected							
Main 1	PC	35.7000	83.0800		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Switches Walked				
Location	Switch Name			
PC 40.4700	Clayworks			
PC 49.0100	State Line			



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/29/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10261401		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Inspected							
Main 2	PC	35.7000	83.0800		Hi-Rail		
Lead	PC	83.0800	83.2800		Hi-Rail		
Main 2	PC	83.2800	83.5000		Hi-Rail		
Main 1	RD	53.0000	67.0000		Hi-Rail		
Siding	RD	64.6600	66.8600		Inspected Only		

Switches Walked				
Location	Switch Name			
PC 39.2800	Bognar/Hot Top			
PC 60.6500	Columbiana Camp Car			

Defects					
Location	Defect	Immediate Remedial Action			
PC 39.3 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed			
Defect Comments					
Missing clip in Bognars switch- fixed					



Location Date Range
EYSTONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	09/28/2022
Insp	ected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Insp	ection ID	10261138		
Co	omments	Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspe					How Inspected	
Main 1	RD	67.0000	86.0000		Inspected Only	
Main 2	RD	67.1800	86.0000		Inspected Only	

Switches Walked		
Location Switch Name		
RD 75.0400	Atwater	
RD 82.8000	Ohio Edison	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/28/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10261122		
Comments	Switch Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	82.0000	83.0800		Inspected Only
Main 2	PC	82.0000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	67.0000	68.0000		Inspected Only
Main 2	RD	67.1800	68.0000		Inspected Only

Joints Walked			
MP Range	Туре		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 67.1800 - 68.0000 Main 2	Straight Joints		
RD 67.0000 - 68.0000 Main 1	Straight Joints		
PC 82.0000 - 83.0800 Main 1	Straight Joints		
RD 67.0000 - 68.0000 Main 1	Comp Joints		

Switches Walked			
Location Switch Name			
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
PC 83.2600	#3 CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		

Crossing Diamonds Walked	
Location Diamond Name	



Track Inspections

PC 83.2500 Alliance Diamond

Defects				
Location Defect Immediate Remedial Ac				
Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
	Defect Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening			

Location	Defect	Immediate Remedial Action	
RD 67.09 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
Broken Pandrol clip - Fixed 5 loose guard rail bolts - Fixed			

Location	Defect	Immediate Remedial Action		
RD 67.05 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Two missing Pandrol clips at weld - Fixed				

Location	Defect	Immediate Remedial Action		
PC 82.93 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed		
Defect Comments				



Location Date Range
KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/27/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10260813		
Comments FRA patrol			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location Switch Name		
PC 35.8000	#3A New CP Wood	
PC 35.8200	#1B New CP Wood	
RD 85.8500	#3A CP 86	
RD 85.9200	#1B CP 86	



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023				
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI	
Divisior	KEYSTONE	Date Inspected	09/26/2022	
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A	
Inspection ID	10260486			
Comments FRA patrol				

Following tra	following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location Switch Name		
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Inspection ID 10260220

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/23/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Scott Steinbach

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	

Defects			
Location	Defect	Immediate Remedial Action	
PC 65.8 Main 1	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed	
Defect Comments			
Loose bolt - Fixed			

Location	Defect	Immediate Remedial Action
PC 41.6 Main 1	Subpart DTrack Structure - Rail Joints - (d) Insufficient number of bolts for class of track	Fixed
Defect Comments		
Missing bolt in joint - Fixed		



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	09/22/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
	Inspection ID	10259923		
Comments FRA patrol				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How I					How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location	Switch Name	
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	

Defects				
Location	Defect	Immediate Remedial Action		
RD 64.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		
Defect Comments				
1 missing clip in Spring switc	h- fixed			



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	09/21/2022
Ir	nspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
In	spection ID	10259598		
	Comments	Switch Inspection Only		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					
Main 2	PC	80.0000	81.0000		Inspected Only

Switches Walked	
Location Switch Name	
PC 80.4500	Alliance Runner/80.5 Switch

Defects			
Location Defect Immediate Remedial			
PC 80.45 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed	
Defect Comments			
Four missing Pandrol clips - Fixed			



KE	EYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
	Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
		Division	KEYSTONE	Date Inspected	09/20/2022

Inspected By Heslep, Mike 2nd Qualified Inspector Supervisor Track Inspections 2nd Qualified Inspector

Inspection ID 10259397

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location	Switch Name	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	

Defects					
Location	Defect	Immediate Remedial Action			
RD 85.78 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed			
Defect Comments					
Missing Pandrol Clip - Fixed					

Location	Defect	Immediate Remedial Action
PC 57.48 Main 1	Subpart DTrack Structure - Turnouts	Fixed



Track Inspections

	and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	
Defect Comments		
Missing Pandrol clip - Fixed		



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/19/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10258983		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix Ho						
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked			
MP Range Type			
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		

Switches Walked			
Location Switch Name			
PC 35.9500	#1A New CP Wood		
PC 83.3300	#1A CP Alliance		
RD 66.8600	#15 CP Alliance		
RD 66.8800	Switch #1B CP Alliance		
PC 35.7100	#3B CP Wood		



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	09/16/2022
Ins	spected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Ins	pection ID	10258878		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspe					How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	09/15/2022
Inspected B	y Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection I	D 10258440		
Commen	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Suffix	How Inspected			
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



Location Date Range
KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/13/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10257874		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspect					How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

	Joints Walked
MP Range	Туре
PC 35.7000 - 83.0800 Main 1	Comp Joints
RD 67.0000 - 86.0000 Main 1	Comp Joints



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	09/12/2022
Ins		Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Insp	ection ID	10257553		
C	comments	FRA patrol		

Following tra	ollowing tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

	Joints Walked	
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	



2/3/2022 to 2/4/2023

Location Date Range

Comments FRA inspection

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/09/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
Inspection ID	10257401		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

	Switches Walked
Location	Switch Name
PC 63.8200	Sutton Siding
PC 78.8500	Sebring
PC 83.0000	#7B CP Alliance

Defects		
Location	Defect	Immediate Remedial Action
PC 83 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed
Defect Comments		
Broken cuff in 7B switch in 0	CP Alliance- fixed	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/08/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10257105		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspec						
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked				
Location Switch Name				
PC 61.2800	Kaiser/Buckeye Transfer			
PC 70.0500	Salem Industrial			



KEYSTONE KS	S-ALI	2/3/2022 to 2/4/2023		
Division En	gineer	Spadone, Joe	Subdivision or District	KS-ALI
D	ivision	KEYSTONE	Date Inspected	09/07/2022
Inspec	-	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID		10256775		
Com	ments	Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspecte					
Main 1	RD	53.0000	67.0000		Inspected Only

Switches Walked				
Location Switch Name				
RD 55.2800	Bayard Siding E-End			
RD 55.7700	Bayard Siding W-End			
RD 66.1400	Mahoning Yard			
RD 66.1500	Mahoning Crossover E-End			
RD 66.1900	Mahoning Crossover W-End			



K	XEYSTONE KS-ALI 2/3/2022 to 2/4/2023						
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
	Division	KEYSTONE	Date Inspected	09/05/2022			
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Dan Jurkiewicz			
	Inspection ID	10256272					
Comments FRA patrol							

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspe						
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	
Main 1	RD	67.0000	86.0000		Inspected Only	

Switches Walked				
Location Switch Name				
PC 47.4600	NVR/Ryan Homes			
PC 60.0200	Boilerworks			

Defects							
Location Defect Immediate Remedial Action							
RD 79.4 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed					
Defect Comments	Defect Comments						
Removed tree from track and right of way							



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/02/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10255942		
Comments	FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected							
Main 1	PC	35.7000	83.0800		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Switches Walked		
Location Switch Name		
PC 40.4700	Clayworks	
PC 49.0100	State Line	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	09/01/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10255648		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 39.2800 Bognar/Hot Top		
PC 60.6500 Columbiana Camp Car		
PC 73.4600 #3B CP Murph		
PC 73.7200	#1A CP Murph	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/31/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10255370		
Comments	Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 82.9300	#9 CP Alliance	
PC 83.0000	#7B CP Alliance	
PC 83.0800	#7B CP Alliance	
PC 83.1400	#5B CP Alliance	
PC 83.2600	#3 CP Alliance	
RD 66.8800	Switch #1B CP Alliance	
RD 67.0500	#5A CP Alliance	
RD 67.0900	Switch #13 CP Alliance	
RD 67.1700	#11B CP Alliance	
RD 67.2400	#11A CP Alliance	
RD 75.0400	Atwater	
RD 82.8000	Ohio Edison	

Crossing Diamonds Walked		
Location Diamond Name		
PC 83.2500	Alliance Diamond	

Defects	
---------	--



Track Inspections

Location	Defect	Immediate Remedial Action	
RD 67.2 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
1 missing clip in the 11B switc	h in CP Alliance- fixed		

Location	Defect	Immediate Remedial Action		
PC 83.2 Lead	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point			
Defect Comments				
3 missing bolts in the diamond in CP A	lliance- fixed			

Location	Defect	Immediate Remedial Action		
PC 82.8 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		
Defect Comments				
Loose guard rail bolts in Ohio Edison switch- fixed				



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/30/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose
Inspection ID	10255136		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	

Switches Walked			
Location	Switch Name		
PC 35.8000	#3A New CP Wood		
PC 35.8200	#1B New CP Wood		
RD 85.7800	#3B CP 86		
RD 85.8500	#3A CP 86		
RD 85.9200	#1B CP 86		
RD 85.9900	#1A CP 86		

Defects						
Location	Defect	Immediate Remedial Action				
RD 85.78 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed				
Defect Comments						
Missing Pandrol clip - Fixed						



2/3/2022 to 2/4/2023

Location Date Range

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/29/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10254785		
Comments	FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	

Switches Walked		
Location	Switch Name	
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	



2/3/2022 to 2/4/2023

Location Date Range

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/29/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10254778		
Comments	FRA & Heat Inspection		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Lead	PC	83.0800	83.2800		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
RD 53.0000 - 67.0000 Main 1 Straight Joints		

Defects			
Location	Defect	Immediate Remedial Action	
RD 54.4 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Tree fouling main - Removed/Fixed			



KE	EYSTONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	08/28/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
	Inspection ID	10254648		
	Comments	Heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/28/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10254645		
Comments	Heat Inspection No Exceptions		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only



Comments FRA patrol

2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/26/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10254471		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location Switch Name		
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	

Defects				
Location	Defect	Immediate Remedial Action		
PC 57.6 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		
Defect Comments				
2 missing clips in 3A switch	in CP Lum- fixed			



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisi	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	08/25/2022
lı		Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
In	spection ID	10254241		
	Comments Alliance Casting, Alliance Camp Car, and, Hoopes out of service.			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	



KEYSTONE KS-A	ALI 2/3/2022 to 2/4/2023		
Division Engi	ineer Spadone, Joe	Subdivision or District	KS-ALI
Div	ision KEYSTONE	Date Inspected	08/24/2022
Inspecte	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection	on ID 10253862		
Comm	nents Switch inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Ins			How Inspected		
Main 2	PC	35.7000	83.0800		Inspected Only

Switches Walked	
Location Switch Name	
PC 80.4500	Alliance Runner/80.5 Switch



2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/23/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose
Inspection ID	10253482		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked	
MP Range Type	
RD 67.0000 - 86.0000 Main 1	Comp Joints
PC 35.7000 - 83.0800 Main 1	Comp Joints

Switches Walked	
Location	Switch Name
PC 73.5800	#3A CP Murph
PC 73.6000	#1B CP Murph
RD 85.8500	#3A CP 86
RD 85.9200	#1B CP 86

Defects			
Location Defect		Immediate Remedial Action	
PC 73.58 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed	
Defect Comments			
Tightened 5 rail braces - Fixed			



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/22/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Bradley Mitchell
Inspection ID	10253272		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked	
MP Range	Туре
RD 53.0000 - 67.0000 Main 1	Comp Joints
PC 35.7000 - 83.0800 Main 2	Comp Joints

Switches Walked		
Location	Switch Name	
PC 35.9500	#1A New CP Wood	
PC 83.3300	#1A CP Alliance	
RD 66.8600	#15 CP Alliance	
RD 66.8800	Switch #1B CP Alliance	
PC 35.7100	#3B CP Wood	

Defects				
Location	Defect	Immediate Remedial Action		
PC 73.46 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Pandrol clip missing - Fixed				



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/19/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	N/A
Inspection ID	10252983		
Comments	Jason Yeager accompanied me on	inspection.	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only



KE	YSTONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	08/18/2022
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
	Inspection ID	10252761		
	Comments	Accompanied by Jason Yeager		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/16/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10252019		
Comments	FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked		
MP Range	Туре	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	



2/3/2022 to 2/4/2023

_				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	08/15/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
	Inspection ID	10251734		
	Comments	FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Defects			
Location Defect Immediate Remedial Action			
PC 68.2 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Removed tree from right of	Removed tree from right of way and track		



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/12/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10251647		
Comments FRA inspection			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/12/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Jamie Swanson
Inspection ID	10251437		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range Type		
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	·	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/11/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Timothy Bacon
Inspection ID	10251129		
Comments	FRA patrol		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked		
Location Switch Name		
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500	Salem Industrial	



2/3/2022 to 2/4/2023

Location Date Range

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/10/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10250856		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Hi-Rail

Switches Walked		
Location Switch Name		
RD 55.2800	Bayard Siding E-End	
RD 55.7700	Bayard Siding W-End	
RD 66.1400	Mahoning Yard	
RD 66.1500	Mahoning Crossover E-End	
RD 66.1900	Mahoning Crossover W-End	



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	08/09/2022
lr	nspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
In	spection ID	10250765		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Inspected Only	
Main 2	RD	67.1800	86.0000		Hi-Rail	

Joints Walked				
MP Range	Туре			
RD 67.1800 - 86.0000 Main 2	Straight Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Comp Joints			
RD 67.1800 - 86.0000 Main 2	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			

Switches Walked				
Location Switch Name				
PC 63.8200	Sutton Siding			
PC 78.8500	Sebring			



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/08/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10250186		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Ins						
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked				
MP Range Type				
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			

Switches Walked				
Location Switch Name				
PC 47.4600	NVR/Ryan Homes			
PC 60.0200	Boilerworks			



KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Div	ision KEYSTONE	Date Inspected	08/07/2022
Inspecte	d By Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Timothy Bacon
Inspection	n ID 10250103		
Comm	ents Heat Patrol 92F		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



`_	ETOTONE NO NET ZIGIZOZE & ZATZOZO							
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI				
	Division	KEYSTONE	Date Inspected	08/05/2022				
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo				
	Inspection ID	10249932						
	Comments	FRA patrol						

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Inspected							
Main 1	PC	35.7000	83.0800		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Switches Walked		
Location	Switch Name	
PC 40.4700	Clayworks	
PC 49.0100	State Line	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/04/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose
Inspection ID	10249630		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspecte					
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 39.2800	Bognar/Hot Top	
PC 60.6500	Columbiana Camp Car	
PC 73.4600	#3B CP Murph	
PC 73.7200	#1A CP Murph	

Defects				
Location	Defect	Immediate Remedial Action		
PC 60.65 Main 2	Subpart CTrack Geometry - Track surface - Cross-Level/Reverse Cross- Level	Slow Ordered and Fixed		
Defect Comments				
Mud in switch causing cross l	evel - mud removed - Fixed			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/03/2022
Inspected By	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	N/A
Inspection ID	10249428		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspecte					
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/03/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose
Inspection ID	10249380		
Comments	Switch Inspection and Heat Inspec	tion	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	82.0000	83.0800		Inspected Only
Main 2	PC	82.0000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Walked
Main 2	PC	83.2800	83.5000		Walked
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked			
Location	Switch Name		
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
PC 83.2600	#3 CP Alliance		
PC 83.3300	#1A CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		

Crossing Diamonds Walked		
Location	Diamond Name	
PC 83.2500	Alliance Diamond	

Defects	
---------	--



Track Inspections

Location	Defect	Immediate Remedial Action	
RD 82.8 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed	
Defect Comments			
Loose guard rail bolts - Fixed			

Location	Defect	Immediate Remedial Action	
RD 67.17 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
Missing Pandrol clip - Fixed			

Location	Defect	Immediate Remedial Action	
RD 67.09 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed	
Defect Comments			
Loose guard rail bolts - Fixed			

Location Defect Immediate Remedial Action		Immediate Remedial Action	
PC 83.25 Lead Other - Other - Other Slow Ordered			
Defect Comments			
Point of diamond chipped - slow orderd, repair scheduled			

Location	Defect	Immediate Remedial Action
PC 83.25 Lead	Subpart DTrack Structure - Rail Joints - (d) Insufficient number of bolts for class of track	Fixed
Defect Comments		
Two missing bolts in diamond - Fixed		



2/3/2022 to 2/4/2023

	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	08/02/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
	Inspection ID	10248839		
ľ	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How				How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	

Switches Walked		
Location Switch Name		
PC 35.8000	#3A New CP Wood	
PC 35.8200	#1B New CP Wood	
RD 85.8500	#3A CP 86	
RD 85.9200	#1B CP 86	



2/3/2022 to 2/4/2023

Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	08/01/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10248523		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		

Switches Walked			
Location	Switch Name		
PC 45.2300	#3B CP Enon		
PC 45.3900	#1A CP Enon		
PC 45.4300	Enon Supply		
PC 57.4800	#3B CP Lum		
PC 57.6400	#1A CP Lum		



KEYSTONE KS-ALI		2/3/2022 to 2/4/2023		
	Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
	Divisi	on KEYSTONE	Date Inspected	07/29/2022
	Inspected	By Rose, Rose	2nd Qualified Inspector	Timothy Bacon

Inspection ID 10248310

Comments FRA patrol

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail

Switches Walked			
Location Switch Name			
PC 45.3000	#3A CP Enon		
PC 45.3200	#1B CP Enon		
PC 57.5500	#3A CP Lum		
PC 57.5700	#1B CP Lum		

Defects					
Location	Defect	Immediate Remedial Action			
PC 57.75 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
1 missing clip in the 1B switcl	n in CP Lum- fixed				



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/29/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Jamie Swanson
Inspection ID	10248223		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	

Defects						
Location	Defect	Immediate Remedial Action				
RD 72.8 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed				
Defect Comments						
ree fouling main - Removed/Fixed						



2004		Date Range		
KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/28/2022
Ins	pected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Insp	ection ID	10247866		
C	omments	Inspect behind 14N - broken knuc	kle. No exceptions.	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected				How Inspected	
Main 1	RD	67.0000	75.0000		Hi-Rail



KEYSTONE KS-AL	l 2/3/2022 to 2/4/2023		
Division Engin	eer Spadone, Joe	Subdivision or District	KS-ALI
Divis	ion KEYSTONE	Date Inspected	07/28/2022
Inspected	By Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection	ID 10247815		
Comme	nts FRA patrol and switches		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffi				Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked		
Location Switch Name		
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/27/2022
Ins	pected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Insp	ection ID	10247520		
C	Comments	Switch and yard inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspecte				How Inspected	
Main 2	PC	35.7000	83.0800		Inspected Only

Switches Walked		
Location Switch Name		
PC 80.4500	Alliance Runner/80.5 Switch	

Defects				
Location	Defect	Immediate Remedial Action		
PC 80.5 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
1 missing clip in 80.5 switch-	fixed			



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/26/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	N/A
Inspection ID	10247327		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.2000	86.0000		Inspected Only

Switches Walked		
Location Switch Name		
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	



	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/26/2022
		Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	N/A
	Inspection ID	10247101		
Comments FRA Inspection accompanied by Chris Myers				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	

Switches Walked		
Location	Switch Name	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	

Defects				
Location	Defect	Immediate Remedial Action		
PC 73.58 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed		
Defect Comments				
issing pandrol clip, replaced				



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/25/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10246945		
Comments	FRA inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 35.9500	#1A New CP Wood	
PC 83.3300	#1A CP Alliance	
RD 66.8600 #15 CP Alliance		
RD 66.8800 Switch #1B CP Alliance		
PC 35.7100	#3B CP Wood	

Defects			
Location Defect Immediate Remedial Action			
RD 66 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Removed tree from track and right of way			

Location Defect Immediate Remedial Action	
---	--



Report Generated:2/5/2023 3:50:30 PM

PC 68.4 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed
Defect Comments		
Removed tree from track and right of way		



(E)	STONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/24/2022
	Inspected By	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	N/A
	Inspection ID	10246728		
		Hot Weather Patrol Accompanied by Chris Myers		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/23/2022
In		Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	Sam Shaffo
Ins	spection ID	10246587		
	Comments	Hot Weather Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Defects					
Location	Defect	Immediate Remedial Action			
PC 68.3 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
tree fouling track, removed					



	•		
KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	07/22/2022
Inspected E	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	Sam Shaffo
Inspection I	D 10246488		
Commen	ts Hot Weather Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/22/2022
Inspected By	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10246485		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/22/2022
In	spected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jason Yeager
Ins	spection ID	10246474		
Comments FRA and heat patrol				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/21/2022
In	spected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose
In	spection ID	10246144		
	Comments	FRA Inspection and Heat Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Defects			
Location	Defect	Immediate Remedial Action	
RD 80.8 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Tree fouling main - Removed/Fixed			



EYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/20/2022
Ins		Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Brian Dangelo
Ins	pection ID	10245776		
	Comments	Heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	57.0000		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail
Main 1	PC	57.0000	83.0800		Hi-Rail



KEYSTONE KS-ALI	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	07/19/2022			
Inspected By	Jurkiewicz, Dan Foreman/CDLB	2nd Qualified Inspector	Jason Yeager			
Inspection ID	10245460					
Comments	heat patrol					

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail



KEYSTONE KS-ALI	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	07/19/2022			
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Elliott Clakeley			
Inspection ID	10245446					

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only



2/3/2022 to 2/4/2023

Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/19/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10245445		
Comments	Heat Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	

Defects				
Location	Defect	Immediate Remedial Action		
RD 82.8 Main 2 Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured				
Defect Comments				
Pandrol clip missing - Fixed				



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/18/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Dan Jurkiewicz
Inspection ID	10244922		

Following tra	-ollowing tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected		
Main 2	PC	35.7000	83.0800		Hi-Rail		
Lead	PC	83.0800	83.2800		Hi-Rail		
Main 2	PC	83.2800	83.5000		Hi-Rail		
Main 1	RD	53.0000	67.0000		Hi-Rail		
Siding	RD	64.6600	66.8600		Inspected Only		

Defects					
Location	Defect	Immediate Remedial Action			
PC 59.76 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
vegetation across industry tr	vegetation across industry track. cut up limbs and cleared.				

Location	Defect	Immediate Remedial Action		
PC 61.25 Main 2 Subpart BRoadbed - Vegetation - Vegetation		Fixed		
Defect Comments				
Trees/ Brush interfering with train operations. removed.				



	2410 1441.90		
KEYSTONE KS-AL	l 2/3/2022 to 2/4/2023		
Division Engin	eer Spadone, Joe	Subdivision or District	KS-ALI
Divis	ion KEYSTONE	Date Inspected	07/16/2022
Inspected	By Jurkiewicz, Dan Foreman/CDLB	2nd Qualified Inspector	Michael Mattes
Inspection	1 D 10244832		
Comments forgot to submit yesterd			

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/15/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Jason Yeager
Inspection ID	10244656		
Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	



Divis	sion Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/14/2022
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose
	Inspection ID	10244264		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected		
Main 2	PC	35.7000	83.0800		Hi-Rail		
Lead	PC	83.0800	83.2800		Inspected Only		
Main 2	PC	83.2800	83.5000		Hi-Rail		
Main 1	RD	53.0000	67.0000		Hi-Rail		
Siding	RD	64.6600	66.8600		Inspected Only		

Joints Walked		
MP Range	Туре	
RD 53.0000 - 67.0000 Main 1	Comp Joints	

Switches Walked	
Location Switch Name	
PC 61.2800	Kaiser/Buckeye Transfer
PC 70.0500	Salem Industrial



Date Range Location

KEYS	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI	
	Division	KEYSTONE	Date Inspected	07/13/2022	
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Rose Rose	
Inspection ID 10243965		10243965			
	Comments Switch Inspection Only				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Hi-Rail

Switches Walked		
Location	Switch Name	
RD 55.2800	Bayard Siding E-End	
RD 55.7700	Bayard Siding W-End	
RD 66.1400	Mahoning Yard	
RD 66.1500	Mahoning Crossover E-End	
RD 66.1900	Mahoning Crossover W-End	

Defects			
Location	Defect	Immediate Remedial Action	
RD 66.19 Main 1	Subpart DTrack Structure - Switches - (b) Switch point improperly fit against stock rail	Fixed	
Defect Comments			
Switch gapping in normal po	sition - Fixed		



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/12/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10243780		
Comments	FRA and heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked		
Location Switch Name		
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	



KE	EYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
	Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
		Division	KEYSTONE	Date Inspected	07/11/2022

Inspected By Rose, Rose 2nd Qualified Inspector N/A Track Patrol Foreman

Inspection ID 10243462

Comments FRA and heat patrol

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	

Switches Walked		
Location Switch Name		
PC 47.4600	NVR/Ryan Homes	
PC 60.0200		

Defects				
Location	Defect	Immediate Remedial Action		
PC 45.6 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
1 missing clip at Enon Supply	switch- fixed			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/11/2022
Inspected By	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10243457		
Comments	Hot Weather Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/11/2022
	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10243456		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/11/2022
	Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	Jason Yeager
Inspection ID	10243369		
Comments	heat patrol from 7/10/22		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



Inspection ID 10242883

2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/07/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Joshua Lonca

Comments FRA & Heat Inspection

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Comp Joints	

Switches Walked		
Location	Switch Name	
PC 39.2800	Bognar/Hot Top	
PC 60.6500	Columbiana Camp Car	

Defects			
Location	Defect	Immediate Remedial Action	
PC 60.65 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed	
Defect Comments			
Six loose guard rail bolts - Fixed			



`				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/07/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
	Inspection ID	10242832		
	Comments	FRA and Heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked		
Location Switch Name		
PC 73.4600	#3B CP Murph	
PC 73.7200	#1A CP Murph	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



S Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/06/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10242350		
Comments	Switch inspection only		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Inspected Only
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 82.9300	#9 CP Alliance	
PC 83.0000	#7B CP Alliance	
PC 83.0800	#7B CP Alliance	
PC 83.1400	#5B CP Alliance	
PC 83.2600	#3 CP Alliance	
RD 67.0500	#5A CP Alliance	
RD 67.0900	Switch #13 CP Alliance	
RD 67.1700	#11B CP Alliance	
RD 67.2400	#11A CP Alliance	
RD 75.0400	Atwater	
RD 82.8000	Ohio Edison	

Crossing Diamonds Walked		
Location Diamond Name		
PC 83.2500	Alliance Diamond	

Defects		
Location	Defect	Immediate Remedial Action



Track Inspections

RD 67 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
1 missing clip in 5A switch in CP Alliance- fixed			

Location	Defect	Immediate Remedial Action		
PC 83.1 Lead	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
2 missing clips in the 7A switch in CP Alliance- fixed				



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
Division	KEYSTONE	Date Inspected	07/05/2022		
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Dan Jurkiewicz		
Inspection ID 10242204					
Comments	FRA & Heat Patrol				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	58.0000		Hi-Rail
Main 2	PC	35.7000	45.0000		Hi-Rail
Main 2	PC	45.0000	58.0000		Inspected Only

Joints Walked			
MP Range	Туре		
PC 35.7000 - 45.0000 Main 2	Straight Joints		
PC 45.0000 - 58.0000 Main 2	Straight Joints		
PC 35.7000 - 58.0000 Main 1	Straight Joints		
PC 35.7000 - 45.0000 Main 2	Comp Joints		
PC 45.0000 - 58.0000 Main 2	Comp Joints		
PC 35.7000 - 58.0000 Main 1	Comp Joints		

Switches Walked			
Location	Switch Name		
PC 35.8000	#3A New CP Wood		
PC 35.8200	#1B New CP Wood		



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI			
Division	KEYSTONE	Date Inspected	07/05/2022			
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A			
Inspection ID	10242168					
Comments	FRA and Heat patrol					

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Inspected Only	
Main 1	PC	58.1000	83.0800		Hi-Rail	
Main 2	PC	58.1000	83.0800		Inspected Only	
Main 2	RD	67.2000	86.0000		Hi-Rail	

Joints Walked				
MP Range	Туре			
RD 67.2000 - 86.0000 Main 2	Straight Joints			
RD 67.2000 - 86.0000 Main 2	Comp Joints			
PC 58.1000 - 83.0800 Main 1	Comp Joints			
PC 58.1000 - 83.0800 Main 1	Straight Joints			

Switches Walked		
Location	Switch Name	
RD 85.8500	#3A CP 86	
RD 85.9200	#1B CP 86	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/04/2022
Inspected By	Jurkiewicz, Dan Foreman/CDLB	2nd Qualified Inspector	Mike Heslep
Inspection ID	10241910		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/04/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10241888		
Comments	FRA and Heat patrol		

Following tra	acks to include turno	outs inspected between th	e below-listed mile	posts:	
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	

Defects					
Location	Defect	Immediate Remedial Action			
PC 57.5 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
1 missing clip in 3B switch in	CP Lum- fixed				

Location	Defect	Immediate Remedial Action



Report Generated:2/5/2023 3:50:30 PM

RD 74 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed
Defect Comments		
Removed tree from track and	right of way	



KEYS	STONE KS-ALI	2/3/2022 to 2/4/2023		
[Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/04/2022
		Jurkiewicz, Dan Foreman/CDLB	2nd Qualified Inspector	Joshua Lonca
	Inspection ID	10241667		
	Comments	heat patrol		

Following tracks to	include turnouts in	spected between th	e below-listed mile	posts:	
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	45.5000		Hi-Rail



Comments FRA and Heat patrol

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	07/01/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10241568		

Following tracks to	include turnouts in	spected between th	e below-listed mile	posts:	
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	

Defects					
Location	Defect	Immediate Remedial Action			
PC 73.6 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
2 missing clips in 1B switch	in CP Murph- fixed				

Location	Defect	Immediate Remedial Action			
PC 73.58 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
1 missing clip 3A switch in CP Murph- fixed					



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	KEYSTONE	Date Inspected	07/01/2022
-	Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	Justin Hanzelka
Inspection ID	10241544		
Comments	for heat patrol and fra patrol for 6/30/22 missed deadline to put in.		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected		
Main 1	RD	53.0000	67.0000		Hi-Rail		
Siding	RD	64.6600	66.8600		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Switches Walked			
Location Switch Name			
RD 53.7800	Hoopes		
RD 64.6600	Spring Switch		
RD 66.2200	Alliance Camp Car		
RD 66.3700	Alliance Castings		

Defects						
Location Defect Immediate Remedial Action						
RD 64.66 Main 1	Fixed					
Defect Comments	Defect Comments					
age rods tightened						



Location Date Range

KEYSTONE KS-ALI

_				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	07/01/2022
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Joshua Lonca
	Inspection ID	10241543		
	Comments	FRA and Heat Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

	Defects			
Location Defect Immediate Remedial Action				
RD 55.1 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Bush obstructing whistle po	st sign - Removed/Fixed			

Location	Defect	Immediate Remedial Action		
RD 80.2 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
ree fouling main - Removed/Fixed				



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/30/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection ID	10241275		
Comments FRA and Heat patrol			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



		Date Harige		
KEYS	STONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	06/29/2022
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
	Inspection ID	10240864		
	Comments Heat Patrol Accompanied by Chris Myers			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



KEYSTONE K	S-ALI	2/3/2022 to 2/4/2023		
Division E	ngineer	Spadone, Joe	Subdivision or District	KS-ALI
[Division	KEYSTONE	Date Inspected	06/29/2022
Inspe	cted By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspec	ction ID	10240861		
Cor	mments	Heat patrol and switches		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 80.4500	Alliance Runner/80.5 Switch	



Location Date Range

KEYSTONE KS-ALI

_				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	06/28/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
	Inspection ID	10240364		
	Comments	FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked				
MP Range	Туре			
RD 67.1800 - 86.0000 Main 2	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Comp Joints			
RD 67.1800 - 86.0000 Main 2	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			

Switches Walked		
Location	Switch Name	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	



Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	1 KEYSTONE	Date Inspected	06/27/2022
Inspected B	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspection II	10240045		
Comment	FRA patrol and switches		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked				
MP Range	Туре			
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			

Switches Walked		
Location	Switch Name	
PC 35.9500	#1A New CP Wood	
PC 83.3300	#1A CP Alliance	
RD 66.8600	#15 CP Alliance	
RD 66.8800	Switch #1B CP Alliance	
PC 35.7100	#3B CP Wood	



Date Range Location

KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Divi	sion KEYSTONE	Date Inspected	06/26/2022
Inspecte	d By Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	N/A
Inspectio	n ID 10239964		
Comments Heat patrol			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 40.4700	Clayworks	
PC 49.0100	State Line	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/24/2022
Inspected By	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	N/A
Inspection ID	10239643		
Comments	nents fra patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisi	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	06/23/2022
lı	nspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Ir	spection ID	10239426		
	Comments	ts FRA patrol		

Following tra	following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



`	TOTONE NO ALI	2/0/2022 to 2/4/2020		
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	06/22/2022
	Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
	Inspection ID	10239107		
	Comments	Heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



	2 440 1 441190		
KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/21/2022
Inspected By	Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Elliott Hannen
Inspection ID	10238799		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	85.1000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/21/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10238767		
Comments	FRA and Heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked				
MP Range Type				
RD 67.1800 - 86.0000 Main 2	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Straight Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			

Defects				
Location	Defect	Immediate Remedial Action		
PC 55.7 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Removed tree from track an	d right of way			

Location	Defect	Immediate Remedial Action			
RD 80.1 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
Removed tree from track and right of way					



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/20/2022
Inspected By	Gardner, Eric Assistant Foreman/CDLB	2nd Qualified Inspector	Elliott Hannen
Inspection ID	10238215		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



Date Range Location

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	06/17/2022
Insp	-	Gardner, Eric Assistant Foreman/CDLB	2nd Qualified Inspector	Elliott Hannen
Insp	ection ID	10237992		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Track Prefix From To Suffix How Inspected					
Main 1 PC 35.7000 83.0800 Hi-Rail						

Switches Walked			
Location	Switch Name		
PC 35.8000	#3A New CP Wood		
PC 35.8200	#1B New CP Wood		
PC 35.9500	#1A New CP Wood		
PC 35.7100	#3B CP Wood		



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	06/17/2022
lı		Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
In	spection ID	10237953		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	RD	67.0000	82.0000		Inspected Only	
Main 2	RD	67.1800	82.0000		Hi-Rail	
Main 1	RD	82.0000	86.0000		Hi-Rail	
Main 2	RD	82.0000	86.0000		Inspected Only	



Date Range Location

KEYSTONE K	(S-ALI	2/3/2022 to 2/4/2023		
Division E	ngineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	06/16/2022
Inspe	-	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Justin Hanzelka
Inspe	ction ID	10237755		
Coi	mments	FRA & Heat Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	57.5000	83.0800		Inspected Only
Main 2	PC	57.5000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500	Salem Industrial	

Defects					
Location	Defect	Immediate Remedial Action			
PC 70.05 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed			
Defect Comments					
Bolt out of frog toe block - Fixed					



KEYSTONE KS-ALI	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI			
Divisio	n KEYSTONE	Date Inspected	06/16/2022			
Inspected B	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Elliott Hannen			
Inspection II	10237750					
Comment	FRA and Heat patrol					

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					How Inspected
Main 2 PC 35.7000 57.5000 Hi-Rail					



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/15/2022
Inspected By	Rose, Rose Track Patrol Foreman	2nd Qualified Inspector	Justin Hanzelka
Inspection ID	10237402		
Comments	Heat patrol. No defects		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track Prefix From To Suffix How Inspected					How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked			
Location Switch Name			
RD 55.2800	Bayard Siding E-End		
RD 55.7700	Bayard Siding W-End		
RD 66.1400	Mahoning Yard		
RD 66.1500	Mahoning Crossover E-End		
RD 66.1900	Mahoning Crossover W-End		



KEY	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
	Division	KEYSTONE	Date Inspected	06/15/2022		
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Joshua Early		
	Inspection ID	10237389				
Comments		Heat Inspection				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	72.0000		Hi-Rail
Main 2	PC	72.0000	83.0800		Inspected Only



Comments FRA/ Heat Patrol 86F, with Todd Rose.

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/14/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	
Inspection ID	10236942		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked		
Location Switch Name		
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	

Defects				
Location	Immediate Remedial Action			
PC 78.85 Main 1	Subpart DTrack Structure - Rail Joints - (d) Insufficient number of bolts for class of track	Fixed		
Defect Comments				
Stripped Joint in Return Curve @ Sebring Switch. Replaced two bolts.				

Location Defect		Immediate Remedial Action	
PC 78.85 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed	
Defect Comments			
Loose Toe Block Bolt on Frog. Tightened.			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/13/2022
Inspected By	Hannen, Elliott Trackman	2nd Qualified Inspector	N/A
Inspection ID	10236580		
Comments Accompanied by Foreman Todd Rose, FRA and heat patrol.			

Following tra	following tracks to include turnouts inspected between the below-listed mileposts:				
Track Prefix From To				Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked	
MP Range Type	
RD 53.0000 - 67.0000 Main 1	Straight Joints



Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/13/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Joshua Lonca
Inspection ID	10236577		
Comments	FRA Inspection & Heat Patrol		

Following tra	following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	63.0000		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail
Main 1	PC	63.0000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail

Joints Walked		
MP Range Type		
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	

Switches Walked		
Location Switch Name		
PC 47.4600	NVR/Ryan Homes	
PC 60.0200	Boilerworks	

Defects				
Location	Immediate Remedial Action			
PC 60.02 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Two loose guard rail bolts - Fixed				



Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI	
Division	KEYSTONE	Date Inspected	06/09/2022	
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector		
Inspection ID	10235746			
Comments	Accompanied by Todd Rose			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range Type		
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	

Switches Walked			
Location	Switch Name		
PC 39.2800	Bognar/Hot Top		
PC 45.2300	#3B CP Enon		
PC 45.3900	#1A CP Enon		
PC 45.4300	Enon Supply		
PC 57.4800	#3B CP Lum		
PC 57.6400	#1A CP Lum		
PC 60.6500	Columbiana Camp Car		
PC 73.4600	#3B CP Murph		
PC 73.7200	#1A CP Murph		



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/08/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10235456		
Comments	Switch Inspection Only		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	82.0000	83.0800		Inspected Only
Main 2	PC	82.0000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked			
Location	Switch Name		
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
PC 83.2600	#3 CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		

Crossing Diamonds Walked		
Location Diamond Name		
PC 83.2500	Alliance Diamond	

Defects				
Location Defect Immediate Remedial Action				
RD 82.8 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed		



Track Inspections

Defect Comments

Tightened 5 guardrail bolts - Fixed

Location	Defect	Immediate Remedial Action		
RD 67.09 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed		
Defect Comments				
Tightened 3 rail braces, 2 missing Pandrol clips - Fixed				

Location	Defect	Immediate Remedial Action		
PC 83.25 Lead	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed		
Defect Comments				

Location	Defect	Immediate Remedial Action		
PC 83.08 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Two missing Pandrol clips - Fixed				



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/07/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10235153		
Comments	Accompanied by Todd Rose		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track	Prefix	From	То	Suffix	How Inspected		
Main 1	PC	35.7000	83.0800		Hi-Rail		
Main 1	RD	67.0000	86.0000		Hi-Rail		
Main 2	RD	67.1800	86.0000		Inspected Only		

Joints Walked					
MP Range	Туре				
RD 67.1800 - 86.0000 Main 2	Straight Joints				
PC 35.7000 - 83.0800 Main 1	Straight Joints				
PC 35.7000 - 83.0800 Main 1	Comp Joints				
RD 67.1800 - 86.0000 Main 2	Comp Joints				
RD 67.0000 - 86.0000 Main 1	Comp Joints				
RD 67.0000 - 86.0000 Main 1	Straight Joints				

Switches Walked			
Location	Switch Name		
PC 35.8000	#3A New CP Wood		
PC 35.8200	#1B New CP Wood		
RD 85.7800	#3B CP 86		
RD 85.8500	#3A CP 86		
RD 85.9200	#1B CP 86		
RD 85.9900	#1A CP 86		

Defects						
Location	Defect	Immediate Remedial Action				
RD 85.7 Main 2	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed				
Defect Comments						
Loose bolt in joint - Fixed						

Location Defect Immediate Remedial Action	
---	--



Track Inspections

PC 73.58 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed		
Defect Comments				
Missing two Pandrol clips - Fixed				



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/06/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10235054		
	FRA & Heat Inspection. Accompanied by Todd Rose		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
RD 67.1800 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/03/2022
Inspected By	Hannen, Elliott Trackman	2nd Qualified Inspector	N/A
Inspection ID	10234584		
Comments	Comments Accompanied by Foreman Todd Rose. FRA and switch inspection.		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	

Defects				
Location	Defect	Immediate Remedial Action		
RD 79.1 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Removed tree from track and	d right of way			



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023	

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	06/02/2022
Inspected By	Hannen, Elliott Trackman	2nd Qualified Inspector	N/A
Inspection ID	10234253		
		I 1. I. I. I.	

Comments Accompanied by Foreman Todd Rose. FRA and switch inspection.

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location	Switch Name	
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	

Defects				
Location	Defect	Immediate Remedial Action		
PC 49.4 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Removed tree from track an	d right of way			

Location	Defect	Immediate Remedial Action
PC 49 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed
Defect Comments		
Removed tree from track an	d right of way	

Location	Defect	Immediate Remedial Action
PC 66.4 Main 2	Subpart BRoadbed - Vegetation -	Fixed
	Vegetation	



Defect Comments

Removed tree from track and right of way



Date Range Location

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023				
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI	
Division	KEYSTONE	Date Inspected	06/01/2022	
Inspected By	Hannen, Elliott Trackman	2nd Qualified Inspector	N/A	
Inspection ID	10234036			
Comments	Accompanied by Foreman Todd Rose. Heat patrol and switch inspection. No defects.			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail

Switches Walked	
Location	Switch Name
PC 80.4500	Alliance Runner/80.5 Switch



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023	

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/31/2022
Inspected By	Hannen, Elliott Trackman	2nd Qualified Inspector	N/A
Inspection ID	10233601		
Comments	Comments todd Rose FRA and heat patrol inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked			
MP Range Type			
PC 83.2800 - 83.5000 Main 2	Straight Joints		

Switches Walked		
Location Switch Name		
PC 83.3300	#1A CP Alliance	
RD 66.8600 #15 CP Alliance		
RD 66.8800	Switch #1B CP Alliance	

Defects				
Location	Defect	Immediate Remedial Action		
RD 66.9 Main 1	Subpart DTrack Structure - Rail Joints - (d) Insufficient number of bolts for class of track	Fixed		
Defect Comments				
Missing bolt in1B switch in C	P Alliance- fixed			



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/31/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Eric Gardner
Inspection ID	10233576		
Comments	Heat Patrol/ FRA M2. Walked CP V	Vood	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 35.9500	#1A New CP Wood	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
PC 35.7100	#3B CP Wood	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	r Spadone, Joe	Subdivision or District	KS-ALI
Divisior	KEYSTONE	Date Inspected	05/30/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Joshua Early
Inspection ID	10233303		
Comments	Heat Patrol 90F		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/30/2022
Inspected By	Gardner, Eric Assistant Foreman/CDLB	2nd Qualified Inspector	Elliott Hannen
Inspection ID	10233274		
Comments	heat patrol/ FRA patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Divi	sion KEYSTONE	Date Inspected	05/29/2022
Inspecte	d By Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	Sam Shaffo
Inspectio	n ID 10233048		
Comm	ents heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/29/2022
Inspected By	Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Eric Gardner
Inspection ID	10233047		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	05/27/2022
Inspected B	y Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	
Inspection II	10232908		
Comment	FRA Patrol from 5/26/2022 Wood to Enon Main Two. Due to train breakdowns, was unable to inspect on regular schedule.		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspect					
Main 2	PC	35.7000	45.1000		Hi-Rail

Joints Walked		
MP Range	Туре	
PC 35.7000 - 45.1000 Main 2	Straight Joints	
PC 35.7000 - 45.1000 Main 2	Comp Joints	



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	05/27/2022
Insp	ected By	Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Sam Shaffo
Insp	ection ID	10232859		
C	omments	fra patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisi	on Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	05/26/2022
lı		Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Ir	spection ID	10232710		
	Comments	Accompanied by Todd Rose		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



KEYSTONE KS	S-ALI	2/3/2022 to 2/4/2023		
Division Er	ngineer	Spadone, Joe	Subdivision or District	KS-ALI
D	Division	KEYSTONE	Date Inspected	05/26/2022
Inspec	-	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	Timothy Bacon
Inspec	tion ID	10232709		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspector					How Inspected
Main 2	PC	45.2000	83.0800		Hi-Rail



|--|

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/24/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10231889		
Comments	Accompanied by Todd Rose		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	

Defects						
Location Defect Immediate Remedial Action						
PC 66.1 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed				
Defect Comments						
Tree fouling main - Removed/Fix	ed					

Location	Defect	Immediate Remedial Action			
RD 80.9 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
Tree fouling main - Removed/Fixed					



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

_				
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	05/23/2022
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
	Inspection ID	10231753		
	Comments	Accompanied by Todd Rose		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		

Hi-Rail



2/3/2022 to 2/4/2023

Comments Heat Patrol and Storm Patrol

Location Date Range

Inspection ID 10231468

RD

KEYSTONE KS-ALI

Main 2

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/21/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Dan Jurkiewicz

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Inspec							
Lead	PC	83.0800	83.2800		Inspected Only		
Main 1	RD	53.0000	67.0000		Hi-Rail		
Siding	RD	64.6600	66.8600		Inspected Only		
Main 1	RD	67.0000	86.0000		Hi-Rail		

67.1800

86.0000

Defects						
Location Defect Immediate Remedial Action						
RD 76.2 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed				
Defect Comments						
Multiple trees across tracks (5) - Fixed					

Location	Defect	Immediate Remedial Action			
RD 79.6 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
Tree across tracks - Fixed					

Location	Defect	Immediate Remedial Action			
RD 67.1 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
Free across tracks - Fixed					



	•		
EYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/21/2022
Inspected By	Gardner, Eric Assistant Foreman/CDLB	2nd Qualified Inspector	N/A
Inspection ID	10231436		
	accompanied by Chris Myers heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/20/2022
Inspected By	Gardner, Eric Assistant Foreman/CDLB	2nd Qualified Inspector	N/A
Inspection ID	10231273		
Comments	accompanied by track patrol forem	nan Todd Rose	

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 2	PC	35.7000	57.5000		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	

Switches Walked				
Location Switch Name				
PC 40.4700	Clayworks			
PC 49.0100	C 49.0100 State Line			

Defects				
Location	Defect	Immediate Remedial Action		
PC 35.8 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (b) Insufficient anchoring to maintain switch or frog point	Fixed		
Defect Comments				
missing pandrol clip				



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/20/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Joshua Lonca
Inspection ID	10231219		
Comments	FRA Inspection & Heat Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Defects					
Location	Defect	Immediate Remedial Action			
RD 65.6 Main 1	Subpart DTrack Structure - Defective Rails - Flattend Rail or Crushed Head	Out of Service and Fixed			
Defect Comments					
Replaced two worn IJ - Fixed					



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	05/19/2022
Insp		Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Eric Gardner
Insp	ection ID	10230846		
C	omments	FRA Inspection & Heat Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked				
MP Range	Туре			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 67.1800 - 86.0000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
RD 67.1800 - 86.0000 Main 2	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/19/2022
	Dangelo, Brian Electric Welder/CDLB	2nd Qualified Inspector	N/A
Inspection ID	10230827		
	FRA Inspection, Hot Weather Inspection Accompanied by Todd Rose		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Inspected Only	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked		
Location Switch Name		
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500 Salem Industrial		

Defects					
_ocation	Immediate Remedial Action				
PC 57.64 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed			
Defect Comments					
Defect Comments Pandrol Clip hold down broke	n, fixed, welded	-			

Location	Defect	Immediate Remedial Action	
PC 61.8 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Tree limb fouling track, removed			



KEYSTONE KS-ALI		KS-ALI	2/3/2022 to 2/4/2023		
	Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
		Division	KEYSTONE	Date Inspected	05/18/2022

Inspected By Heslep, Mike 2nd Qualified Inspector Supervisor Track Inspections

Inspection ID 10230377

Comments Accompanied by Todd Rose. Switch Inspection Only.

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Hi-Rail

Switches Walked		
Location Switch Name		
RD 55.2800	Bayard Siding E-End	
RD 55.7700	Bayard Siding W-End	
RD 66.1400	Mahoning Yard	
RD 66.1500 Mahoning Crossover E-End		
RD 66.1900	Mahoning Crossover W-End	

Defects				
Location	Immediate Remedial Action			
RD 55.77 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.2) Obstruction in switch, frog, or guard rail	Fixed		
Defect Comments				
Debris in spring frog - cleared and oiled - Fixed				



2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/17/2022
Inspected By	Hannen, Elliott Trackman	2nd Qualified Inspector	N/A
Inspection ID	10230070		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked			
MP Range Type			
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Switches Walked			
Location Switch Name			
PC 63.8200	Sutton Siding		
C 78.8500 Sebring			



Date Range Location

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023				
Division Eng	ineer Spadone, Joe	Subdivision or District	KS-ALI	
Div	vision KEYSTONE	Date Inspected	05/16/2022	
Inspect	ed By Hannen, Elliott Trackman	2nd Qualified Inspector	N/A	
Inspecti	on ID 10229756			
Comr	nents fra patrol			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked				
MP Range Type				
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2 Straight Joints				
RD 53.0000 - 67.0000 Main 1				

Switches Walked			
Location Switch Name			
PC 47.4600	NVR/Ryan Homes		
PC 60.0200 Boilerworks			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/15/2022
Inspected By	Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	
Inspection ID	10229676		
Comments	heat inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspector					
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail



KEYSTONE KS-AL	_I 2/3/2022 to 2/4/2023		
Division Engir	neer Spadone, Joe	Subdivision or District	KS-ALI
Divis	KEYSTONE	Date Inspected	05/14/2022
Inspected	By Jurkiewicz, Dan Foreman/CDLB	2nd Qualified Inspector	N/A
Inspection	n ID 10229601		
Comme	ents accompanied by Todd rose. H	Heat patrol	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspecte					
Main 2	PC	35.7000	83.0800		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/13/2022
	Lonca, Joshua Foreman/CDLB	2nd Qualified Inspector	N/A
Inspection ID	10229436		
Comments	fra patrol and heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Defects						
Location Defect Immediate Remedial Action						
PC 68.3 Main 1	Other - Other - Other	Fixed				
Defect Comments						
tree across track at 68.3						



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/12/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Eric Gardner
Inspection ID	10229203		
Comments	Todd Rose is TPF, but not in syster	n yet.	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked				
Location Switch Name				
PC 39.2800	Bognar/Hot Top			
PC 60.6500	Columbiana Camp Car			
PC 73.4600	#3B CP Murph			
PC 73.7200	#1A CP Murph			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/12/2022
Inspected By	Hanzelka, Justin FOREMAN	2nd Qualified Inspector	Keith Rose
Inspection ID	10229201		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Ins					How Inspected	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Hi-Rail	



KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Divi	sion KEYSTONE	Date Inspected	05/12/2022
Inspecte	d By Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Scott Steinbach
Inspectio	n ID 10229133		
Comm	ents heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:							
Track Prefix From To Suffix How Inspect							
Main 2	PC	35.7000	73.6000		Hi-Rail		
Main 1	Main 1 PC 74.6000 83.0800 Hi-Rail						



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Inspection ID 10228913

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/11/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	N/A

Comments inspected with Todd Rose.Walking Switch inspection / heat patrol. 83F

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How I					
Main 1	PC	82.9000	83.0800		Walked
Lead	PC	83.0800	83.2800		Walked
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.2000	86.0000		Hi-Rail

Switches Walked			
Location	Switch Name		
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
PC 83.2600	#3 CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		

Crossing Diamonds Walked			
Location Diamond Name			
PC 83.2500	Alliance Diamond		

Defects						
Location Defect Immediate Remedial Action						
PC 83.25 Lead	Fixed					
Defect Comments						



loose diamond bolts. tightened up.



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/11/2022
	Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Elliott Hannen
Inspection ID	10228862		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Ins					How Inspected
Main 1	PC	35.7000	45.2000		Hi-Rail
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail

Defects		
Location	Defect	Immediate Remedial Action
PC 37.5 Main 2	Subpart CTrack Geometry - Track Alignment - Track Alignment	213.9(b) at 10mph
Defect Comments		
1/ 1/2" deviation alignment track jacked by hand		



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	05/10/2022
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
	Inspection ID	10228297		
Comments Todd Rose Accompanied				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 35.8000	#3A New CP Wood	
PC 35.8200	#1B New CP Wood	
RD 85.8500	#3A CP 86	
RD 85.9200	#1B CP 86	

Defects					
Location Defect Immediate Remedial Action					
PC 35.82 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed			
Defect Comments					
2 missing Pandrol Clips - fixed					



2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/09/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10228003		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location Switch Name		
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	



Date Range Location

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
Division Enginee	Spadone, Joe	Subdivision or District	KS-ALI		
Divisio	n KEYSTONE	Date Inspected	05/06/2022		
Inspected B	y Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Elliott Hannen		
Inspection ID 10227828					
Comments FRA Inspection					

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	

Defects				
Location	Defect	Immediate Remedial Action		
RD 70 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Tree fouling track, removed				



2/3/2022 to 2/4/2023

Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/05/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Elliott Hannen
Inspection ID	10227467		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location	Switch Name	
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	

Defects			
Location	Defect	Immediate Remedial Action	
PC 49.5 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
tree fouling track, removed			



Location Date Range
EYSTONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/04/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10227123		
Comments	SWITCH INSPECTION ONLY		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspect					How Inspected
Main 2	PC	35.7000	83.0800		Inspected Only

Switches Walked		
Location	Switch Name	
PC 80.4500	Alliance Runner/80.5 Switch	



KE	YSTONE	KS-ALI	2/3/2022 to 2/4/2023		
	Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
		Division	KEYSTONE	Date Inspected	05/03/2022
	Insp	ected By	Dangelo, Brian	2nd Qualified Inspector	Mike Heslep

Inspection ID 10226994

Track Patrol Foreman

Comments FRA Inspection

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.1800 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Switches Walked		
Location	Switch Name	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	

Defects		
Location	Defect	Immediate Remedial Action
RD 85.99 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed
Defect Comments		
Switch point roller lock nut m	issing, replaced	



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	05/02/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10226377		
Comments	FRA Inspection		

Following tra	acks to include turno	nouts inspected between the below-listed mileposts:			
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

	Joints Walked	
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

	Switches Walked	
Location	Switch Name	
PC 35.9500	#1A New CP Wood	
PC 83.3300	#1A CP Alliance	
RD 66.8600	#15 CP Alliance	
RD 66.8800	Switch #1B CP Alliance	
PC 35.7100	#3B CP Wood	

Defects		
Location	Defect	Immediate Remedial Action
PC 75 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed
Defect Comments		
Tree fouling track, removed		





KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/29/2022
-	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Elliott Hannen
Inspection ID	10226168		
Comments	FRA Inspection		

Following tra	cks to include turno	outs inspected between th	e below-listed mile	posts:	
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/28/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Brian Dangelo
Inspection ID	10225831		
Comments	FRA Inspector Ruff w/ part of patro	ol.	

Following tra	cks to include turno	outs inspected between th	e below-listed mile	posts:	
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail

	Switches Walked
Location	Switch Name
PC 39.2800	Bognar/Hot Top
PC 45.2300	#3B CP Enon
PC 45.3900	#1A CP Enon
PC 45.4300	Enon Supply
PC 47.4600	NVR/Ryan Homes
PC 60.0200	Boilerworks
PC 60.6500	Columbiana Camp Car
PC 61.2800	Kaiser/Buckeye Transfer

Defect	Immediate Remedial Action
	miniodiato itemediai Action
Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Scheduled for Repair
	Fastening Systems - Rail Fastening

Location	Defect	Immediate Remedial Action			
PC 69.4 Main 2	Subpart BRoadbed - Drainage - Drainage	Scheduled for Repair			
Defect Comments					
Mud in curve @ I-Joints					

Location Defect Immediate Remedial Acti	
---	--



Track Inspections

Report Generated:2/5/2023 3:50:30 PM

PC 69.45 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Scheduled for Repair
Defect Comments		
Loose fasteners in curve.		



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/28/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	
Inspection ID	10225747		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	



Location Date Range

/STONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	KEYSTONE	Date Inspected	04/26/2022
Inspected	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection	ID 10224958		
Comments FRA Inspection			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.1800 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/25/2022
Inspected By	Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Chris Myers
Inspection ID	10224725		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Main 2	PC	35.7000	83.0800		Hi-Rail



2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/25/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10224673		
Comments	FRA Inspection, Hot Weather Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 2	PC	83.2800	83.5000		Inspected Only	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	
Main 1	RD	67.0000	86.0000		Inspected Only	
Main 2	RD	67.1800	86.0000		Hi-Rail	

Joints Walked				
MP Range	Туре			
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 67.1800 - 86.0000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
RD 67.1800 - 86.0000 Main 2	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			

Defects					
Location	Defect	Immediate Remedial Action			
RD 67.7 Main 2	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed			
Defect Comments					
Loose bolt, tightened					



KEYST	ONE KS-ALI	2/3/2022 to 2/4/2023		
Di	ivision Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	04/24/2022
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Eric Gardner
	Inspection ID	10224452		
	Comments	Heat Patrol - No Exceptions		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 2 PC 35.7000 83.0800 Hi-Rail						



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/24/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Scott Steinbach
Inspection ID	10224437		
Comments	Hot Weather Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspec						
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Hi-Rail	

Defects				
Location	Defect	Immediate Remedial Action		
RD 55.28 Main 1	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed		
Defect Comments				
oose bolts, replaced and tightened				



KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Divi	sion KEYSTONE	Date Inspected	04/23/2022
Inspecte	d By Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	N/A
Inspectio	n ID 10224339		
Comm	ents rough track reported RD78.8 - r	no exceptions	

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 2 RD 76.0000 79.2000 Hi-Rail						



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/23/2022
	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Eric Gardner
Inspection ID	10224338		
Comments	heat patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 1 PC 35.7000 83.0800 Hi-Rail						



KEYSTONE KS-AL	2/3/2022 to 2/4/2023		
Division Engin	eer Spadone, Joe	Subdivision or District	KS-ALI
Divis	on KEYSTONE	Date Inspected	04/23/2022
Inspected	By Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Scott Steinbach
Inspection	ID 10224277		
Comme	nts Hot Weather Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.2000	86.0000		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	04/22/2022
Inspected B	y Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection I	10223995		
Commen	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



2/3/2022 to 2/4/2023

Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/21/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Brian Dangelo
Inspection ID	10223789		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 61.2800 Kaiser/Buckeye Transfer		
PC 70.0500 Salem Industrial		



2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/20/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10223172		

Following tracks to include turnouts inspected between the below-listed mileposts:								
Track Prefix From To Suffix How Inspecte								
Main 1	RD	53.0000	67.0000		Inspected Only			
Siding								

Switches Walked			
Location	Switch Name		
RD 55.2800	Bayard Siding E-End		
RD 55.7700	Bayard Siding W-End		
RD 66.1400	Mahoning Yard		
RD 66.1500	Mahoning Crossover E-End		
RD 66.1900	Mahoning Crossover W-End		



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/19/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10222800		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	

Switches Walked		
Location Switch Name		
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	

Defects				
Location Defect Immediate Remedial Action				
PC 70.9 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
tree fouling track, removed				

Location	Defect	Immediate Remedial Action
PC 63.82 Main 1	Subpart DTrack Structure - Switches - (b) Switch point improperly fit against stock rail	Fixed
Defect Comments		



connecting rod bolt tightened, switch shim added

Location	Defect	Immediate Remedial Action
PC 45.3 Main 1	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed
Defect Comments		
loose bolt, tightened		

Location	Defect	Immediate Remedial Action		
PC 63.82 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair		
Defect Comments				
loose guard rail bolts				



Comments FRA Inspection

2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/18/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10222433		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked			
Location Switch Name			
PC 47.4600 NVR/Ryan Homes			
PC 60.0200	Boilerworks		

Defects				
Location Defect Immediate Remedia				
PC 60.02 Main 2	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair		
Defect Comments				
guard rail bolts loose				



KE	YSTONE KS-AL	2/3/2022 to 2/4/2023		
	Division Engin	eer Spadone, Joe	Subdivision or District	KS-ALI
	Divis	on KEYSTONE	Date Inspected	04/15/2022
	Inspected	By Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo

Inspection ID 10222260

Comments fra inspection

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Switches Walked		
Location Switch Name		
PC 40.4700	Clayworks	
PC 49.0100	State Line	

Defects					
Location	Defect	Immediate Remedial Action			
PC 49.01 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair			
Defect Comments					
loose guard rail bolts					

Location	Defect	Immediate Remedial Action			
PC 40.5 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair			
Defect Comments					
guard rail bolts loose					

Location	Defect	Immediate Remedial Action			
PC 49.01 Main 1	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed			
Defect Comments					
loose bolts, replaced and tightened					



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/14/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10222048		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked			
Location	Switch Name		
PC 39.2800	Bognar/Hot Top		
PC 57.5500	#3A CP Lum		
PC 57.5700	#1B CP Lum		
PC 60.0200	Boilerworks		
PC 60.6500	Columbiana Camp Car		
PC 73.4600	#3B CP Murph		
PC 73.7200	#1A CP Murph		



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/13/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10221528		
Comments	SWITCH INSPECTION ONLY		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					
Lead	PC	83.0800	83.2800		Inspected Only

Switches Walked		
Location	Switch Name	
PC 83.2600	#3 CP Alliance	



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	Spadone, Joe	Subdivision or District	KS-ALI
Divisior	KEYSTONE	Date Inspected	04/13/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10221521		
Comments	SWITCH INSPECTION ONLY		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked			
Location	Switch Name		
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		
RD 85.7800	#3B CP 86		
RD 85.8500	#3A CP 86		

Crossing Diamonds Walked	
Location Diamond Name	
PC 83.2500	Alliance Diamond



Date Range Location

KEYSTONE KS-A	ALI 2/3/2022 to 2/4/2023		
Division Eng	ineer Spadone, Joe	Subdivision or District	KS-ALI
Div	rision KEYSTONE	Date Inspected	04/12/2022
Inspecte	ed By Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection	on ID 10221261		
Comn	nents FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	

Switches Walked		
Location Switch Name		
PC 35.8000	#3A New CP Wood	
PC 35.8200	#1B New CP Wood	
RD 85.8500	#3A CP 86	
RD 85.9200	#1B CP 86	



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/11/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10221014		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location Switch Name		
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

`	21010H2 No NET Eloreste to El H2525					
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
	Division	KEYSTONE	Date Inspected	04/08/2022		
	Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep		
	Inspection ID	10220743				
Comments FRA Inspection						

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Switches Walked				
Location	Switch Name			
PC 45.3000	#3A CP Enon			
PC 45.3200	#1B CP Enon			
PC 57.5500	#3A CP Lum			
PC 57.5700	#1B CP Lum			



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/07/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	
Inspection ID	10220332		
Comments	CP 86 & Ohio Edison Biannual Walking Switch Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspecte						
Main 2	RD	82.8000	86.0000		Walked	
Main 1 RD 85.8000 86.0000 Walked						

Switches Walked			
Location	Switch Name		
RD 82.8000	Ohio Edison		
RD 85.7800	#3B CP 86		
RD 85.8500	#3A CP 86		
RD 85.9200	#1B CP 86		
RD 85.9900	#1A CP 86		

Defects				
Location Defect Immediate Remedial Act				
RD 85.92 Main 2 Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured		Fixed		
Defect Comments				
Loose adjustable rail braces at switch point. Knocked in wedges to tighten.				

Location	Defect	Immediate Remedial Action		
RD 85.85 Main 2 Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems		Fixed		
Defect Comments				
Gage rod damaged ahead of switch point. Replaced with new.				

Location	Defect	Immediate Remedial Action
	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed
Defect Comments		



Adjustable switch braces at point section loose. knocked in wedges to tighten.

ocation Defect		Immediate Remedial Action		
RD 82.8 Main 2 Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems		Scheduled for Repair		
Defect Comments				
Missing joint clips in t/o.				

Location	Defect	Immediate Remedial Action		
RD 85.99 Main 1 Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured		Fixed		
Defect Comments				
Adjustable Rail Braces 1A Switch Loose at point section. Knocked up wedges to tighten.				

Location	Defect	Immediate Remedial Action		
RD 85.99 Main 1 Subpart DTrack Structure Fastening Systems - Rail Fa Systems		Fixed		
Defect Comments				
Missing joint clips in turnout of 1A Switch. Replaced. Also missing spikes @ toe of frog, replaced.				

Location	Defect	Immediate Remedial Action		
RD 85.8 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured			
Defect Comments				
Loose adjustable switch braces at point. Knocked up wedges to tighten.				

Location	Defect	Immediate Remedial Action		
RD 85.8 Main 1 Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems		Fixed		
Defect Comments				
Gage rod ahead of point section loose. tightened with hand wrench.				



KEYSTONE KS-ALI 2/3/2022 to 2/4/2023				
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI	
Divisio	n KEYSTONE	Date Inspected	04/07/2022	
Inspected B	y Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep	
Inspection II	10220312			
Comment	s FRA Inspection	·		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 80.4500	Alliance Runner/80.5 Switch	
RD 53.7800 Hoopes		
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/05/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Elliott Hannen
Inspection ID	10219871		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix		From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	

Switches Walked	
Location	Switch Name
PC 73.5800	#3A CP Murph
PC 73.6000	#1B CP Murph

Defects				
Location	Defect	Immediate Remedial Action		
PC 73.6 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
five loose chair braces, tighte	ned			

Location	Defect	Immediate Remedial Action			
PC 73.58 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
four loose chair braces, tightened. one	our loose chair braces, tightened. one chair brace replaced				



Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/05/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Joshua Lonca
Inspection ID	10219865		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked			
MP Range	Туре		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
RD 67.1800 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Switches Walked			
Location Switch Name			
RD 85.7800	#3B CP 86		
RD 85.9900 #1A CP 86			

Defects					
Location	Defect	Immediate Remedial Action			
RD 86 Main 1 Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured					
Defect Comments					
Gage rod in 1a and 3b switc	ch tightened in turnouts.				

Location	Defect	Immediate Remedial Action			
RD 86 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Scheduled for Repair			
Defect Comments					
1A Switch CP 86, #5 rod loose bolt on connection to cuff.					



Location	Defect	Immediate Remedial Action		
RD 86 Main 1	Subpart DTrack Structure - Turnouts and Track Crossings Generally - (a.1) Fastening Intact / Component Secured	Fixed		
Defect Comments				
loose adjustable rail braces. knocked up/ replaced wedge at point on field side.				



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/04/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10219412		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked				
MP Range	Туре			
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2 Comp Joints				
RD 53.0000 - 67.0000 Main 1	Straight Joints			

Switches Walked			
Location	Switch Name		
PC 35.9500	#1A New CP Wood		
PC 83.3300	#1A CP Alliance		
RD 66.8600	#15 CP Alliance		
RD 66.8800	Switch #1B CP Alliance		
PC 35.7100	#3B CP Wood		



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	04/01/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Eric Gardner
Inspection ID	10219276		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/31/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10218813		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



Location Date Range

YSTONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisi	KEYSTONE	Date Inspected	03/29/2022
Inspected	By Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection	ID 10218212		
Commer	ts FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked				
MP Range	Туре			
RD 67.1800 - 86.0000 Main 2	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Straight Joints			
PC 35.7000 - 83.0800 Main 1	Comp Joints			
RD 67.1800 - 86.0000 Main 2	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Comp Joints			
RD 67.0000 - 86.0000 Main 1	Straight Joints			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	03/28/2022
Inspected B	y Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection II	10218057		
Comment	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Inspected Only	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked				
MP Range	Туре			
PC 35.7000 - 83.0800 Main 2	Straight Joints			
PC 83.2800 - 83.5000 Main 2	Straight Joints			
RD 53.0000 - 67.0000 Main 1	Comp Joints			
PC 35.7000 - 83.0800 Main 2	Comp Joints			
RD 53.0000 - 67.0000 Main 1	Straight Joints			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/25/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
Inspection ID	10217700		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspec						
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Inspected Only	
Main 2	RD	67.1800	86.0000		Hi-Rail	



 Location
 Date Range

 YSTONE
 KS-ALI
 2/3/2022 to 2/4/2023

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Divisior	KEYSTONE	Date Inspected	03/24/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Brian Dangelo
Inspection ID	10217374		
Comments	FRA inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	То	Suffix	How Inspected		
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Inspected Only	
Main 2	PC	83.2800	83.5000		Walked	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked			
Location Switch Name			
PC 61.2800	Kaiser/Buckeye Transfer		
PC 70.0500	Salem Industrial		



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/23/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10216935		
Comments	Switch Inspection Only		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Hi-Rail

Switches Walked		
Location	Switch Name	
RD 55.2800	Bayard Siding E-End	
RD 55.7700	Bayard Siding W-End	
RD 66.1400	Mahoning Yard	
RD 66.1500	Mahoning Crossover E-End	
RD 66.1900	Mahoning Crossover W-End	

Defects			
Location	Defect	Immediate Remedial Action	
RD 66 Siding	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Tree fallen on track, removed			

Location	Defect	Immediate Remedial Action		
RD 55.28 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Missing two joint clips, repalced				



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/22/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10216655		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.1800 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Switches Walked		
Location	Switch Name	
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	

Defects			
Location	Defect	Immediate Remedial Action	
PC 81.1 Main 1	Subpart CTrack Geometry - Gage - Gage	Fixed	
Defect Comments			
gage measured at 57 3/8" in two spots, plugged and respiked, anchor spikes added			

Location	Defect	Immediate Remedial Action
PC 78.85 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		



missing cotter key, replaced

Location	Defect	Immediate Remedial Action		
PC 78.85 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
two missing joint clips, replaced				

Location	Defect	Immediate Remedial Action	
PC 59.3 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
fallen tree, removed			

Location	Defect	Immediate Remedial Action	
PC 74 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
fallen tree, removed			



2/3/2022 to 2/4/2023

Location Date Range

Comments FRA Inspection

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/21/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10216220		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 47.4600	NVR/Ryan Homes	
PC 60.0200	Boilerworks	

Defects					
Location Defect Immediate Remed					
PC 47.46 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
5 loose chair braces, tightened, fixed					

Location	Defect	Immediate Remedial Action	



Report Generated:2/5/2023 3:50:30 PM

PC 60.02 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		
missing pandrol clip, replaced		



KEYST	ONE KS-ALI	2/3/2022 to 2/4/2023		
Di	ivision Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	03/18/2022
		Bacon, Timothy Assistant Foreman/CDLB	2nd Qualified Inspector	Scott Steinbach
	Inspection ID	10215906		
	Comments	fra patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail



Clay works & Stateline Switches that were walked.

Location Date Range

2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/18/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Timothy Bacon
Inspection ID	10216526	*Missed submission deadline*	
Comments	Amending Inspection for T. Bacon from 3/18/2022 Report. Missing CP 86 to Alliance M2 Segment/		

Inspection Id	Date	Туре	Comment
10216525	03/18/2022	Original	
10216526	03/22/2022	Amendment	Amending Inspection for T. Bacon from 3/18/2022 Report. Missing CP 86 to Alliance M2 Segment/ Clay works & Stateline Switches that were walked.

Following tracks to	ollowing tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 40.4700	Clayworks	
PC 49.0100	State Line	



2/3/2022 to 2/4/2023

Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/17/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10215638		
Comments	FRA Inspection		

Following tra	owing tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked	
Location	Switch Name
PC 39.2800	Bognar/Hot Top
PC 60.6500	Columbiana Camp Car
PC 73.4600	#3B CP Murph
PC 73.7200	#1A CP Murph

	Defects	
Location	Defect	Immediate Remedial Action
PC 60.65 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		
Loose chair braces, replaced t	wo, tightened and fixed	



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/16/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10215336		
Comments	Switch Inspection Only		

Following tra	cks to include turno	s to include turnouts inspected between the below-listed mileposts:			
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	82.0000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	67.0000	76.0000		Inspected Only
Main 2	RD	67.1800	83.0000		Inspected Only

	Switches Walked
Location	Switch Name
PC 82.9300	#9 CP Alliance
PC 83.0000	#7B CP Alliance
PC 83.0800	#7B CP Alliance
PC 83.1400	#5B CP Alliance
PC 83.2600	#3 CP Alliance
RD 67.0500	#5A CP Alliance
RD 67.0900	Switch #13 CP Alliance
RD 67.1700	#11B CP Alliance
RD 67.2400	#11A CP Alliance
RD 75.0400	Atwater
RD 82.8000	Ohio Edison

Crossing Diamonds Walked	
Location	Diamond Name
PC 83.2500	Alliance Diamond

Defects		
Location	Defect	Immediate Remedial Action
RD 67.09 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		



#13 switch, missing four cotter keys, replaced

Location	Defect	Immediate Remedial Action	
RD 67.24 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
#11B switch, Loose gauge rod, tightened, fixed			

Location	Defect	Immediate Remedial Action	
PC 83.26 Lead	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
[‡] 3 switch, Three loose braces, tightened, fixed			

Location	Defect	Immediate Remedial Action		
PC 83 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
#7B switch, Six loose braces, tightened, fixed				



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/15/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10215022		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked		
MP Range	Туре	
RD 67.1800 - 86.0000 Main 2	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.1800 - 86.0000 Main 2	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	

Switches Walked			
Location Switch Name			
PC 35.8000	#3A New CP Wood		
PC 35.8200	#1B New CP Wood		
RD 85.8500	#3A CP 86		
RD 85.9200	#1B CP 86		

Defects					
Location Defect Immediate Remedial Action					
PC 35.82 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
our loose chair braces, tightened, fixed					

Location	Defect	Immediate Remedial Action
PC 35.82 Main 1	Subpart DTrack Structure - Rail	Fixed

	<u> </u>	
	Fastening Systems - Rail Fastening Systems	
Defect Comments		
Loose gauge rod, tightened, fixed		



Comments FRA Inspection

2/3/2022 to 2/4/2023

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/14/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10214665		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	From To Su	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location	Switch Name	
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	

Defects			
Location Defect Immediate Remedial Action			
PC 38.69 Main 2 Subpart DTrack Structure - Rail Joints - (f) Bolt tightness		Fixed	
Defect Comments			
loose bolts, tightened			





Location Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/13/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10214598		
Comments	Cold Weather Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Defects			
Location	Defect	Immediate Remedial Action	
RD 60.4 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	
Defect Comments			
Fallen tree, removed			



Location Date Range
EYSTONE KS-ALI 2/3/2022 to 2/4/2023

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	03/11/2022
Inspected B	y Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection II	10214453		
Comment	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location	Switch Name	
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	03/10/2022
Inspected By	y Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection II	10214009		
Comment	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location	Switch Name	
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	



KEY	STONE KS-ALI	2/3/2022 to 2/4/2023		
	Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
	Divisio	n KEYSTONE	Date Inspected	03/09/2022
	Inspected B	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
	Inspection II	10213706		
	Comment	Switch Inspection Only		

Following tracks to	include turnouts in	spected between th	e below-listed mile	posts:	
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	80.0000	81.0000		Inspected Only

Switches	s Walked
Location	Switch Name
PC 80.4500	Alliance Runner/80.5 Switch

	Defects	
Location	Defect	Immediate Remedial Action
PC 80.5 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		
Missing/Broken Pandrol clips,	replaced	



2/3/2022 to 2/4/2023

Location Date Range

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/08/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Chris Myers

Inspection ID 10213573

KEYSTONE KS-ALI

Comments FRA Inspection

Following tra	cks to include turno	outs inspected between th	e below-listed mile	posts:	
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 2	PC	83.3000	83.5000		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

	Joints Walked	
MP Range	Туре	
PC 35.7000 - 83.0800 Main 1	Straight Joints	
PC 35.7000 - 83.0800 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Comp Joints	
RD 67.0000 - 86.0000 Main 1	Straight Joints	

	Switches Walked	
Location	Switch Name	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	

Defects				
Location	Defect	Immediate Remedial Action		
RD 86 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
3b switch, loose gauge rods, t	ightened			



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	n KEYSTONE	Date Inspected	03/07/2022
Inspected E	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Elliott Hannen
Inspection I	D 10213261		
Commen	ts Flash Flood Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	56.8000		Hi-Rail
Main 2	PC	59.3000	83.0800		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only



Date Range Location

KEYSTONE I	KS-ALI	2/3/2022 to 2/4/2023		
Division	Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	03/07/2022
Insp	ected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Eric Gardner
Inspe	ection ID	10213063		
Co	mments	FRA Inspection and Flood Patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		

Switches Walked			
Location Switch Name			
PC 35.9500	#1A New CP Wood		
PC 83.3300	#1A CP Alliance		
RD 66.8600	#15 CP Alliance		
RD 66.8800	Switch #1B CP Alliance		
PC 35.7100	#3B CP Wood		



Date Range Location KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/04/2022
Inspected By	Shaffo, Sam Track Supervisor II	2nd Qualified Inspector	Brian Dangelo
Inspection ID	10212937		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.2000	86.0000		Inspected Only

Defects				
Location	Defect	Immediate Remedial Action		
PC 39.2 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
Broken spikes replaced in we	st spiral.			



Date Range Location

KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/03/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10212400		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Defects				
Location Defect Immediate Remedial A				
PC 73.72 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
missing pandrol clips, replaced				

Location	Defect	Immediate Remedial Action		
PC 75 Main 2	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
Fallen tree, removed				



Location Date Range

KEYSTONE KS-ALI

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	03/01/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo

Comments FRA Inspection

Inspection ID 10211817

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.2000	86.0000		Inspected Only	

Joints Walked			
MP Range	Туре		
RD 67.2000 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.2000 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Defects					
Location Defect Immediate Remedial Action					
RD 86 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
missing pandrol clip, replaced					



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/28/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10211432		
Comments FRA Inspection			

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Inspected Only	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		



Location Date Range

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/25/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10211252		
Comments	FRA Inspection		

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected	
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 2	PC	35.7000	57.0000		Hi-Rail	
Lead	PC	83.0800	83.2800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Defects					
Location Defect Immediate Remedial Action					
PC 80 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed			
Defect Comments					
fallen tree, removed					

Location	Defect	Immediate Remedial Action		
PC 79 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed		
Defect Comments				
fallen tree, removed				

Location	Defect	Immediate Remedial Action
RD 80.1 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed
Defect Comments		
fallen tree, removed		



Location Date Range

Division Enginee	Spadone, Joe	Subdivision or District	KS-ALI
Divisior	KEYSTONE	Date Inspected	02/24/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Eric Gardner
Inspection ID	10210785		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	57.0000	83.0800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail

Switches Walked		
Location	Switch Name	
PC 61.2800	Kaiser/Buckeye Transfer	
PC 70.0500 Salem Industrial		



Location Date Range

Comments FRA Inspection

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/24/2022
•	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Dan Jurkiewicz
Inspection ID	10210775		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Defects		
Location	Defect	Immediate Remedial Action
RD 62 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed
Defect Comments		
Fallen Tree, cut and removed		

Location	Defect	Immediate Remedial Action
RD 57 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed
Defect Comments		
Fallen Tree, cut and removed		



KEYSTONE KS-A	LI 2/3/2022 to 2/4/2023		
Division Engi	neer Spadone, Joe	Subdivision or District	KS-ALI
Div	ision KEYSTONE	Date Inspected	02/23/2022
Inspecte	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Brian Dangelo
Inspection	on ID 10210370		
Comm	nents Switch Inspection Only		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	53.0000	67.0000		Inspected Only
Siding	RD	64.6600	66.8600		Hi-Rail

Switches Walked		
Location	Switch Name	
RD 55.2800	Bayard Siding E-End	
RD 55.7700	Bayard Siding W-End	
RD 66.1400	Mahoning Yard	
RD 66.1500	Mahoning Crossover E-End	
RD 66.1900	Mahoning Crossover W-End	



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/22/2022
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Joshua Early
Inspection ID	10210100		
Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Joints Walked			
MP Range	Туре		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.1800 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Switches Walked		
Location Switch Name		
PC 63.8200	Sutton Siding	
PC 78.8500	Sebring	



Date Range Location

KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/21/2022
In	spected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Elliott Hannen
Ins	pection ID	10209825		
	Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 2	Straight Joints		
PC 83.2800 - 83.5000 Main 2	Straight Joints		
RD 53.0000 - 67.0000 Main 1	Comp Joints		
PC 35.7000 - 83.0800 Main 2	Comp Joints		
RD 53.0000 - 67.0000 Main 1	Straight Joints		

Switches Walked		
Location Switch Name		
PC 47.4600	NVR/Ryan Homes	
PC 60.0200	Boilerworks	
PC 83.3300	#1A CP Alliance	



Location Date Range

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/18/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection ID	10209539		
Comments	fra patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.1000	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked		
Location Switch Name		
PC 40.4700	Clayworks	
PC 49.0100 State Line		

Defects				
Location	Defect	Immediate Remedial Action		
PC 49.01 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
missing pandrol clip, missing	head block cotter key. replaced			



	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/17/2022
	Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Eric Gardner
	Inspection ID	10209217		
Comments FRA Inspection				

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Switches Walked		
Location Switch Name		
PC 39.2800	Bognar/Hot Top	
PC 60.6500	Columbiana Camp Car	
PC 73.4600	#3B CP Murph	
PC 73.7200	#1A CP Murph	

Defects				
Location	Defect	Immediate Remedial Action		
PC 60.65 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed		
Defect Comments				
chair brace loose, tightened				

Location	Defect	Immediate Remedial Action			
PC 73.72 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed			
Defect Comments					
gauge rods loose, tightened					

Location	Defect	Immediate Remedial Action
----------	--------	---------------------------



Track Inspections

Report Generated:2/5/2023 3:50:30 PM

PC 73.72 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
missing pandrol clip on chair brace, replaced			



Location

Date Range

KEYSTONE KS-ALI 2/3/2022 to 2/4/2023



Track Inspections

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/16/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10208918		
Comments	Switch Inspection Only		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	82.0000	83.0800		Inspected Only
Main 2	PC	82.0000	83.0800		Inspected Only
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Inspected Only

Switches Walked			
Location	Switch Name		
PC 82.9300	#9 CP Alliance		
PC 83.0000	#7B CP Alliance		
PC 83.0800	#7B CP Alliance		
PC 83.1400	#5B CP Alliance		
PC 83.2600	#3 CP Alliance		
RD 67.0500	#5A CP Alliance		
RD 67.0900	Switch #13 CP Alliance		
RD 67.1700	#11B CP Alliance		
RD 67.2400	#11A CP Alliance		
RD 75.0400	Atwater		
RD 82.8000	Ohio Edison		

Crossing Diamonds Walked		
Location	Diamond Name	
PC 83.2500	Alliance Diamond	

Defects			
Location	Defect	Immediate Remedial Action	
RD 67.05 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	



Track Inspections

Defect Comments

2 missing pandrol clips, replaced

Location	Defect	Immediate Remedial Action	
RD 67.09 Main 1	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed	
Defect Comments			
2 missing pandrol clips, replaced. Chair braces loose, tightened			

Location	Defect	Immediate Remedial Action
PC 82.93 Main 2	Subpart DTrack Structure - Rail Fastening Systems - Rail Fastening Systems	Fixed
Defect Comments		
missing lock nut on switch point roller, replaced		



	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/15/2022
		Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
ſ	Inspection ID	10208574		
	Comments	FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	83.0800		Hi-Rail
Main 1	RD	67.0000	86.0000		Inspected Only
Main 2	RD	67.1800	86.0000		Hi-Rail

Joints Walked	
MP Range	Туре
RD 67.1800 - 86.0000 Main 2	Straight Joints
PC 35.7000 - 83.0800 Main 1	Straight Joints
PC 35.7000 - 83.0800 Main 1	Comp Joints
RD 67.1800 - 86.0000 Main 2	Comp Joints
RD 67.0000 - 86.0000 Main 1	Comp Joints
RD 67.0000 - 86.0000 Main 1	Straight Joints

Switches Walked		
Location	Switch Name	
PC 35.8000	#3A New CP Wood	
PC 35.8200	#1B New CP Wood	
RD 85.8500	#3A CP 86	
RD 85.9200	#1B CP 86	

Defects				
Location	Immediate Remedial Action			
RD 74.96 Main 1	Subpart DTrack Structure - Rail Joints - (d) Insufficient number of bolts for class of track	Fixed		
Defect Comments				
nissing bolt, fixed				



	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/14/2022
		Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
	Inspection ID	10208324		
Comments FRA Inspection/Cold Weather Inspection				

Following tra	Following tracks to include turnouts inspected between the below-listed mileposts:				
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Inspected Only
Main 2	PC	83.2800	83.5000		Hi-Rail
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only

Joints Walked		
MP Range	Туре	
PC 35.7000 - 83.0800 Main 2	Straight Joints	
PC 83.2800 - 83.5000 Main 2	Straight Joints	
RD 53.0000 - 67.0000 Main 1	Comp Joints	
PC 35.7000 - 83.0800 Main 2	Comp Joints	
RD 53.0000 - 67.0000 Main 1	Straight Joints	

Switches Walked		
Location Switch Name		
PC 45.2300	#3B CP Enon	
PC 45.3900	#1A CP Enon	
PC 45.4300	Enon Supply	
PC 57.4800	#3B CP Lum	
PC 57.6400	#1A CP Lum	



	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/11/2022
		Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Joshua Early
	Inspection ID	10208001		
Comments FRA Inspection				

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspected						
Main 1	PC	35.7000	83.0800		Hi-Rail	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked			
MP Range	Туре		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Switches Walked		
Location	Switch Name	
PC 45.3000	#3A CP Enon	
PC 45.3200	#1B CP Enon	
PC 57.5500	#3A CP Lum	
PC 57.5700	#1B CP Lum	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisio	KEYSTONE	Date Inspected	02/10/2022
Inspected I	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Sam Shaffo
Inspection	ID 10207602		
Commen	ts FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track	Prefix	From	То	Suffix	How Inspected	
Main 2	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Inspected Only	
Main 2	PC	83.2800	83.5000		Hi-Rail	
Main 1	RD	53.0000	67.0000		Hi-Rail	
Siding	RD	64.6600	66.8600		Inspected Only	

Switches Walked		
Location	Switch Name	
RD 53.7800	Hoopes	
RD 64.6600	Spring Switch	
RD 66.2200	Alliance Camp Car	
RD 66.3700	Alliance Castings	



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Enginee	r Spadone, Joe	Subdivision or District	KS-ALI
Division	n KEYSTONE	Date Inspected	02/09/2022
Inspected B	y Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Eric Gardner
Inspection II	10207284		
Comment	s Switch Inspection Only		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					
Main 2	PC	80.0000	81.0000		Inspected Only

Switches Walked			
Location Switch Name			
PC 80.4500	Alliance Runner/80.5 Switch		



Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/08/2022
Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Brian Dangelo
Inspection ID	10207042		
Comments	Tracks snow covered		

Following tracks to include turnouts inspected between the below-listed mileposts:						
Track Prefix From To Suffix How Inspe						
Main 1	PC	35.7000	83.0800		Hi-Rail	
Lead	PC	83.0800	83.2800		Inspected Only	
Main 1	RD	64.0000	67.0000		Inspected Only	
Main 1	RD	67.0000	86.0000		Hi-Rail	
Main 2	RD	67.1800	86.0000		Inspected Only	

Joints Walked			
MP Range	Туре		
RD 67.1800 - 86.0000 Main 2	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Straight Joints		
PC 35.7000 - 83.0800 Main 1	Comp Joints		
RD 67.1800 - 86.0000 Main 2	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Comp Joints		
RD 67.0000 - 86.0000 Main 1	Straight Joints		

Switches Walked		
Location	Switch Name	
PC 73.5800	#3A CP Murph	
PC 73.6000	#1B CP Murph	
RD 66.8600	#15 CP Alliance	
RD 66.8800	Switch #1B CP Alliance	
RD 85.7800	#3B CP 86	
RD 85.9900	#1A CP 86	

Defects			
Location Defect Immediate Remedial Action			
PC 39.3 Main 1	Subpart BRoadbed - Vegetation - Vegetation	Fixed	



Defect Comments

Tree fouling main - Removed/Fixed



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023		
Division Engine	er Spadone, Joe	Subdivision or District	KS-ALI
Divisi	KEYSTONE	Date Inspected	02/08/2022
Inspected	Bacon, Timothy Non-Engineering	2nd Qualified Inspector	Michael Mattes
Inspection	ID 10206958		
Commer	ts fra patrol		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	59.1000	83.0800		Hi-Rail
Main 2	PC	83.2800	83.5000		Hi-Rail



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023	

Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI
Division	KEYSTONE	Date Inspected	02/07/2022
	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Mike Heslep
Inspection ID	10206917		
Comments FRA Inspection			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspected					How Inspected
Main 2	PC	35.7000	70.2000		Hi-Rail

Joints Walked				
MP Range Type				
PC 35.7000 - 70.2000 Main 2	Straight Joints			
PC 35.7000 - 70.2000 Main 2				

Switches Walked		
Location Switch Name		
PC 35.9500	#1A New CP Wood	
PC 35.7100	#3B CP Wood	

Defects				
Location Defect Immediate Remedial Action				
PC 40.47 Main 2	Subpart DTrack Structure - Rail Joints - (f) Bolt tightness	Fixed		
Defect Comments				
missing/loose bolt. fixed				

Location	Defect	Immediate Remedial Action		
PC 41.37 Main 2 Subpart DTrack Structure - Rail Jo - (f) Bolt tightness		Fixed		
Defect Comments				
missing/loose bolt. fixed				



KEYSTON	E KS-ALI	2/3/2022 to 2/4/2023		
Divis	ion Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/07/2022
	•	Jurkiewicz, Dan Foreman/CDLB	2nd Qualified Inspector	Jamie Swanson
ı	Inspection ID	10206861		
	Comments	Snow covered		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspect					How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail



KEYSTONE KS-ALI	2/3/2022 to 2/4/2023			
Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI	
Division	KEYSTONE	Date Inspected	02/06/2022	
Inspected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson	
Inspection ID	10206590			
Comments	mments cold weather inspection. tracks covered by snow			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspe					How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only



KEYSTONE I	(S-ALI	2/3/2022 to 2/4/2023		
Division I	ngineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/05/2022
Inspe	-	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Jamie Swanson
Inspe	ction ID	10206517		
Co	mments	cold patrol. tracks covered in ice/si	now	

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track Prefix From To Suffix How Inspec					How Inspected
Main 1	RD	53.0000	67.0000		Hi-Rail



KE	KEYSTONE KS-ALI 2/3/2022 to 2/4/2023					
	Division Engineer	Spadone, Joe	Subdivision or District	KS-ALI		
	Division	KEYSTONE	Date Inspected	02/04/2022		
	Inspected By	Heslep, Mike Supervisor Track Inspections	2nd Qualified Inspector	Joshua Lonca		
	Inspection ID	10206465				
	Comments	tracks snow covered				

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	PC	35.7000	74.0000		Hi-Rail
Main 2	PC	35.7000	47.0000		Hi-Rail



KEYSTONE	KS-ALI	2/3/2022 to 2/4/2023		
Divisio	n Engineer	Spadone, Joe	Subdivision or District	KS-ALI
	Division	KEYSTONE	Date Inspected	02/04/2022
Ins	spected By	Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Chris Myers
Ins	pection ID	10206302		
	Comments FRA Inspection. Tracks covered with snow			

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 1	RD	67.0000	86.0000		Hi-Rail
Main 2	RD	67.1800	86.0000		Inspected Only



KEYSTONE KS-AL	l 2/3/2022 to 2/4/2023		
Division Engin	eer Spadone, Joe	Subdivision or District	KS-ALI
Divis	ion KEYSTONE	Date Inspected	02/03/2022
Inspected	By Dangelo, Brian Track Patrol Foreman	2nd Qualified Inspector	Eric Gardner
Inspection	1 D 10206076		
Comme	nts FRA Inspection		

Following tracks to include turnouts inspected between the below-listed mileposts:					
Track	Prefix	From	То	Suffix	How Inspected
Main 2	PC	35.7000	83.0800		Hi-Rail
Lead	PC	83.0800	83.2800		Hi-Rail
Main 2	PC	83.2800	83.5000		Inspected Only
Main 1	RD	53.0000	67.0000		Hi-Rail
Siding	RD	64.6600	66.8600		Inspected Only