

Incident Report



Print Date: 4/27/2018

Incident # 1176121

Incident Date: 4/24/18 10:23 am

Train: 86 RVR-BOS

Train Date:

Total Delay Time:

WIL CTEC 86 (24) E/ 625 Reports NO. 86 TRESPASSER STRIKE at MP 119.2. Train 86 is STANDING Last Updated: 4/24/2018 10:27:00AM NORTH OF BOWIE NO. 1 TRACK AT MP 118 UPDATE at 930AM ENVIROMENTAL KING ENROUTE Updated By:BEVERLT APPROX. 20" ROAD FRM HARING ENROUTE. UPDATE 2 - NRC# 1210155 WAS ISSUED //OPERATING BY SCENE ON 3 TRACK 2158(24) ALREADY BY AND 89(24) PASSING NOW // PLANNING THE TRANSFER OF PASSENGERS TO TRAIN 182(24) - WILL UPDATE. Notified R. Santos (GF/BOS). Updates to follow (TDB)

Update Per WII CTEC at 1020AM TRAINS THAT WERE HOLDING IN BALTIMORE, WILMINGTON Last Updated: 4/24/2018 10:29:00AM AND PHILADELPHIA ARE NOW RELEASED..RESTRICTED SPEED PLACED FROM MP 118-119 ON Updated By:BEVERLT NO. 3 TRACK. (TDB)

Update Per WIL CTEC at 1026AM 182 ON THE MOVE WITH ALL PASSENGERS. (TDB)

Last Updated: 4/24/2018 10:30:00AM Updated By:BEVERLT

Data Date: 4/27/2018 9:38:10AM

Update Per N. Schum (OPS) TRAIN 86(24) WILL TERMINATE AT BOWIE WHEN RELEASED Last Updated: 4/24/2018 11:13:00AM EQUIPMENT WILL GO BACK TO WAS TRAIN 179(24) WILL BE CANCELED BOS-NYP Updated By:BEVERLT PASSENGERS CAN GO TO 177(24) OR 67(24) TRAIN 111(25) WILL ALSO BE CANCELED NYP-WAS PASSENGERS CAN GO TO 89(25) OR 183(25). Email notification forwarded to J. Caldweel (GF/WAS) and R. Santos (GF/BOS). (TDB)

Delay Comments

Service Impact Delay Time

Location

Unit	Loc/Train	Status/Trn Date		
625	WAS	so		

Annual Inspection-Loco 4/24/18 WAS

Semi-Annual-Loco 12/29/17 WAS

Overhaul (Capital) 1/21/15 WIL

Work Order:

W/O #	W/O Status	Incident Problem Desc	Status Date	Status By	Facility	Sent To Fac
6769175	Open	Trespasser Strike	04/24/18 10:27AM	BEVERLT		



Incident Report



Print Date: 4/27/2018

otes :		
Task	JOB	NOTE
		A-REPORT PART I 24APR18: At 8:58am train 86(24) engine 625, 8 cars, 251 passengers, operating north on 1 track, was placed into emergency and stopped at PW MP 118.47, after striking a trackman at MP 119.1, Bowie, MD, Prince George's County. It was a confirmed fatality. No injuries reported to passengers or crew on 86(24). The weather was 62 degrees and cloudy. Number 2 track was out of service continuously between Bowie MP 120.5 and Grove MP 112.4 for the undercutter. Local authorities, Amtrak police, transportation and engineering supervisors, and emergency management personnel responded.
		At 9:33am all employees working on the undercutter were clear of the out of service track. At 10:04am train 182(24), on 3 track, arrived alongside 86(24) and the passengers were transferred. At 10:26am the transfer was completed. At 10:20am 3 track was okayed at restricted speed between MP 118.0 and 120.0. At 2:45pm train 86(24)'s equipment was released and on the move north to Baltimore. At Baltimore, a protect engine coupled to the rear and towed the equipment to Washington. At 2:54pm both 1 and 3 tracks were released at scheduled speed and service.
		Trains were held at Wilmington, Baltimore and Washington. As a result, the following service adjustments were made. Train 179(24) was canceled between Boston and New York, passengers to 177(24) or 67(24). Train 111(25) was canceled between New York and Washington, passengers to 89(25) and 183(25).
		NRC# 1210155
		Committee: Chair - David Haring - Road Foreman Transportation Member - Adam Ragan - Trainmaster Transportation Member - Patrick Palmer- Asst. Prod Engineer Member - Kelly Hamrick - Road Foreman - Transportation
		A-REPORT PART II Delays: 86(24) 1'27" TERM XBO/DLY TO PAXS 179(24) TERM BOS-NYP 182(24) 33" ITD WAS 28" TRANSFER 86(24) PAXS 2166(24) 40" ITD WAS LATE TURN OFF 2109(24) 55"
		2168(24) 1'06" ITD WAS LATE TURN OFF 2151(24) 08"
		2170(24) 15" ITD WAS LATE TURN OFF 2153(24) 16" 2158(24) 15" 89(24) 14" 79(24) 1'06" 183(24) 1'09" 174(24) 36" 2107(24) 1'10" 2110(24) 44" 2160(24) 43" 84(24) 1'30" 185(24) 2'32" 2164(24) 1'02" 176(24) 2'01" 2109(24) 1'14" 2151(24) 2'04"
		20(23) 1'18" 95(24) 1'24" 2153(24) 1'21" 91(24) 1'03" 184(24) 1'00" 141(24) 2'04" 2117(24) 57" 94(24) 41" 95(24) 1'24" 125(24) 50" 2159(24) 07" 148(24) 17" 12 MARC trains cancelled
		11 MARC trains 27"-1'26" delay Update Per N. Schum (OPS) TRAIN 86(24) WILL TERMINATE AT BOWIE WHEN RELEASED EQUIPMENT WILL GO BACK TO WAS TRAIN 179(24) WILL BE CANCELED BOS-NYP PASSENGERS CAN GO TO 177(24) OR 67(24) TRAIN 111(25) WILL ALSO BE CANCELED NYP-WAS PASSENGERS CAN GO TO 89(25) OR 183(25). Email notification forwarded to J. Caldweel (GF/WAS) and R. Santos



Incident Report



Print Date: 4/27/2018

Remarks:			The state of the s	
System	Component	Position	Defect	Repair
Defect/Repair :	NORTH OF BOWIE NO. 1 TRACK APPROX. 20" ROAD FRM HARING //OPERATING BY SCENE ON 3 TI PLANNING THE TRANSFER OF F (GF/BOS). Updates to follow (TDB)	AT MP 118 UPDATE at 93 GENROUTE. UPDATE 2 - RACK 2158(24) ALREADY PASSENGERS TO TRAIN	OAM ENVIROMENTAL KI NRC# 1210155 WAS ISS BY AND 89(24) PASSING	ING ENROUTE SUED 3 NOW //
	WIL CTEC 86 (24) E/ 625 Reports	NO. 86 TRESPASSER ST	RIKE at MP 119.2. Train 8	86 is STANDING



RAIL INCIDENT DAMAGE TOTALS

The Rail Incident Damage Totals Report is required to be submitted twice: once immediately following an incident with estimated damage totals and again when final damage totals have been collected and the incident has been closed.

This report is intended to be completed utilizing Microsoft Word, and submitted via email to RailReports@amtrak.com. Selections and text boxes, for each section, are available to aide and guide the user through completion.

ate of Occurren		y:	Co	ounty:	ion Explosion Other: Click to enter	Zip: 20715
<u>/24/2018</u> quipment D		wie	Allena	ince Gourges	Maryland 2	20/13
Unit	Equipment ID	Labor	Material	Total	Description	
625	Click to enter	\$ 50.00		\$ 550.00	Replace F-End E/S grab iron	
625	Click to enter	\$ 50.00	\$ 500.00			
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ 350.00 \$ Click to enter	Replace E-End E/S 480v Receptical Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
	Total	\$ 100.00	\$ 600.00	\$ 700.00		
C	D.			298 V9000 19000		
frastructure	Infrastructure					
Туре	Description	Labor	Material	Total	Description	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	in the
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
Click to enter	Click to enter	\$ Click to enter	\$ Click to enter	\$ Click to enter	Click to enter	
	Total	\$ Click to enter	\$ Click to enter	\$ Click to enter		Parket S
	s					
ımage Total		Labor	Material	Total		
				O		
ımage Totalı tal Damage		\$ 100.00	\$ 600.00	\$ 700.00		rescu ju
Land State	nation		\$ 600.00	\$ 700.00		Accepted