

Operational Efficiency Testing Results

Operational Testing - Lcry

Sheet ID	Date	Time	TimeMM	TimeMM	Employee ID	Full Name	Test Number	Test Name	Result	Comments	Supervisor's Comment Selection	Supervisor ID	Test Officer: Full Name	MP/SG	Number	Location	State	Nearest Station or Interlocking	Subdivision	Railroad Property	Amtrak Division	Train	Off't	
OS-462280	9/30/2021	10:48 AM	30	48		Robert AClary	OPA2021-05	Unathorized Disab by of PTC Systems	C - Compliance	Briefing completed.			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer	
OS-462284	9/30/2021	10:50 AM	30	50		Robert AClary	OPA2021-05	1-17 MB Partial Installation Failure Rules	C - Compliance	Briefing completed.			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer	
OS-462288	8/20/2021	11:15 AM	11	15		Robert AClary	118	Subway & Switching - Instructional	C - Compliance	Instructional review: Switches and Switching			Mark E Bevin	MP	1035.95	MT		H Line	BNSF	Northwest	8	Engineer		
OS-462676	8/20/2021	11:50 AM	11	50		Robert AClary	SA-PY21-05	Safety Alert: Vaccination and Testing Mandate Briefing	C - Compliance	SA-PY21-05 briefing.			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer	
OS-462676	8/20/2021	11:54 AM	11	54		Robert AClary	118	Showing & Back-Up Moves - Instructional	C - Compliance	Instructional review: Showing and Back-Up Moves			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer	
OS-462677	8/20/2021	1:39 PM	13	39		Robert AClary	301	Stopping within One-Ha File Range of Vision	C - Compliance	Stopped within Main Track Baricade Test			Mark E Bevin	MP	1035.95	MT		H Line	BNSF	Northwest	8	Engineer		
OS-462678	8/20/2021	1:39 PM	13	39		Robert AClary	307	Delayed in Block	C - Compliance	Train was gross Main Track Baricade Test			Mark E Bevin	MP	1035.95	MT		H Line	BNSF	Northwest	8	Engineer		
OS-462679	8/20/2021	1:41 PM	13	41		Robert AClary	116	RWP Rules	C - Compliance	Standard prescribed whistle signal approaching properly			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer	
OS-462683	8/20/2021	1:28 PM	13	28		Robert AClary	119	Call Ing Signals/Restrictions	C - Compliance	Called Approach Medium signal to train crew.			Mark E Bevin	MP	1041.2	MT		H Line	BNSF	Northwest	8	Engineer		
OS-462684	8/20/2021	1:34 PM	13	34		Robert AClary	120	Radio Procedures	C - Compliance	Proper radio procedure observed when repeating insto			Mark E Bevin	MP	1036.6	MT		H Line	BNSF	Northwest	8	Engineer		
OS-462685	8/17/2021	4:38 PM	36	38		Robert AClary	138	Employee Instruction	C - Compliance	GCOR 9.8 briefing			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	7	Engineer	
OS-455121	7/7/2021	11:30 AM	11	30		Robert AClary	OPA2021-04	OP Advisory: Leaving Equipment in the Clear	C - Compliance	OPA2021-04 briefing			Mark E Bevin	MP		ShelbySub	MT		H Line	BNSF	Northwest	8	Engineer	
OS-463544	7/7/2021	8:02 AM	8	2		Robert AClary	308	Speed	C - Compliance	FAST Act 40 mph FAST Act			Mark E Bevin	MP	1208.9	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463544	7/7/2021	7:47 AM	7	47		Robert AClary	110	Air Brake Tests/Inspections	C - Compliance	Running brake test			Mark E Bevin	MP	1219	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463544	7/7/2021	8:15 AM	8	15		Robert AClary	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow for WGL station stop.			Mark E Bevin	MP	1197.4	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463550	7/7/2021	10:25 AM	10	25		Robert AClary	108	Speed	C - Compliance	FAST Act 55 mph FAST Act			Mark E Bevin	MP	1112.7	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463547	7/7/2021	9:08 AM	9	3		Robert AClary	305	Other Signal Indicators	C - Compliance	Complied with Approach signal at Jaw W.			Mark E Bevin	MP	1156.13	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463547	7/7/2021	8:48 AM	8	48		Robert AClary	308	Speed	C - Compliance	45 mph PRR			Mark E Bevin	MP	1173.7	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463548	7/7/2021	9:34 AM	9	34		Robert AClary	108	Speed	C - Compliance	25 mph TSR			Mark E Bevin	MP	1152	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463548	7/7/2021	9:40 AM	9	40		Robert AClary	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to control speed on descending grade.			Mark E Bevin	MP	1148.6	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463550	7/7/2021	11:30 AM	11	30		Robert AClary	105	Other Signal Indicators	C - Compliance	Complied with Diverging Clear signal at Ison and 50m			Mark E Bevin	MP	1098.4	MT		H Line	BNSF	Northwest	8	Engineer		
OS-463558	7/7/2021	11:03 AM	11	3		Robert AClary	308	Speed	C - Compliance	FAST Act 55 mph FAST Act			Mark E Bevin	MP	1075.1	MT		H Line	BNSF	Northwest	8	Engineer		
OS-464600	6/4/2021	11:27 AM	11	27		Robert AClary	128	Drug & Alcohol	C - Compliance	No use or possession of drugs and alcohol.			Mark E Bevin	MP	1065.6	MT		H Line	BNSF	Northwest	8	Engineer		
OS-464602	6/4/2021	11:28 AM	11	28		Robert AClary	135	Electronic Devices	C - Compliance	No use of unauthorized electronic device. Personal elec			Mark E Bevin	MP	1065.6	MT		H Line	BNSF	Northwest	8	Engineer		
OS-464604	5/2/2021	8:33 AM	8	13		Robert AClary	308	Speed	C - Compliance	25 mph PRR			Mark E Bevin	MP	4.7	NO		Glacow	BNSF	Northwest	7	Engineer		
OS-464604	5/2/2021	8:36 AM	8	6		7	Robert AClary	110	Air Brake Tests/Inspections	C - Compliance	Running brake test			Mark E Bevin	MP	1	NO		Glacow	BNSF	Northwest	7	Engineer	
OS-464604	5/2/2021	9:45 AM	9	45		7	Robert AClary	308	Speed	C - Compliance	FAST Act 55 mph FAST Act			Mark E Bevin	MP	1115.1	MT		Glacow	BNSF	Northwest	7	Engineer	
OS-464604	5/2/2021	10:11 AM	10	11		7	Robert AClary	108	Speed	C - Compliance	40 mph PRR			Mark E Bevin	MP	124.7	NO		Glacow	BNSF	Northwest	7	Engineer	
OS-464604	5/2/2021	10:42 AM	10	42		7	Robert AClary	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to control train speed on descending grade			Mark E Bevin	MP	162.4	NO		Glacow	BNSF	Northwest	7	Engineer	
OS-464607	5/2/2021	2:31 PM	14	31		7	Robert AClary	302	Stop Signal	C - Compliance	Complied with Stop signal in W. Iohann.			Mark E Bevin	MP	418.34	MT		Mik River	BNSF	Northwest	7	Engineer	
OS-464607	5/2/2021	2:46 PM	14	46		7	Robert AClary	305	Other Signal Indicators	C - Compliance	Complied with Diverging Clear signal at Ison and 50m			Mark E Bevin	MP	374.25	MT		Mik River	BNSF	Northwest	7	Engineer	
OS-464607	5/2/2021	2:43 PM	14	43		7	Robert AClary	308	Speed	C - Compliance	FAST Act 55 mph FAST Act			Mark E Bevin	MP	408	MT		Mik River	BNSF	Northwest	7	Engineer	
OS-464607	5/2/2021	12:55 PM	12	55		7	Robert AClary	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow train for 65 mph PRR			Mark E Bevin	MP	330.6	MT		Mik River	BNSF	Northwest	7	Engineer	
OS-464607	5/2/2021	4:17 PM	16	17		7	Robert AClary	308	Speed	C - Compliance	70 mph PRR			Mark E Bevin	MP	1040.3	MT		H Line	BNSF	Northwest	7	Engineer	
OS-464607	5/2/2021	2:25 PM	14	25		7	Robert AClary	305	Other Signal Indicators	C - Compliance	Complied with Diverging Approach signal after passing r			Mark E Bevin	MP	416.58	MT		Mik River	BNSF	Northwest	7	Engineer	
OS-464621	4/18/2021	8:38 AM	8	38		7	Robert AClary	128	Drug & Alcohol	C - Compliance	Praper procedure. When making a Class II brake t			Mark E Bevin	MP	1	NO		Glacow	BNSF	Northwest	7	Engineer	
OS-464623	4/18/2021	8:38 AM	8	38		7	Robert AClary	133	FRA 232-238 Hands on Brake Test/Ins	C - Compliance	Class II brake test.			Mark E Bevin	MP	1	NO		Glacow	BNSF	Northwest	7	Engineer	
OS-464623	4/18/2021	6:01 PM	18	1		7	Robert AClary	301	Stopping within One-Ha File Range of Vision	C - Compliance	Talked past Stop Indication, E Brack by dispatcher. Tr			Mark E Bevin	MP	194.1	MT		Glacow	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	5:58 PM	17	58		7	Robert AClary	302	Stop Signal	C - Compliance	Complied with Stop signal E. E. Brackton.			Mark E Bevin	MP	194.5	MT		Glacow	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	5:54 PM	17	54		7	Robert AClary	305	Other Signal Indicators	C - Compliance	Passed Approach signal complying with all requirement			Mark E Bevin	MP	136.6	MT		Glacow	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	8:09 AM	21	9		7	Robert AClary	110	Air Brake Tests/Inspections	C - Compliance	25 mph TSR			Mark E Bevin	MP	4.9	NO		Glacow	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	11:56 AM	11	56		7	Robert AClary	110	Air Brake Tests/Inspections	C - Compliance	Running brake test.			Mark E Bevin	MP	1065.2	MT		H Line	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	11:59 AM	11	59		7	Robert AClary	116	RWP Rules	C - Compliance	Standard prescribed bell/whistle signal approaching tra			Mark E Bevin	MP	1065.2	MT		H Line	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	5:58 PM	17	58		7	Robert AClary	119	Call Ing Signals/Restrictions	C - Compliance	Called Stop signal to train crew.			Mark E Bevin	MP	194.5	MT		Glacow	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	8:02 PM	21	2		7	Robert AClary	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow train for TSR, approaching grade			Mark E Bevin	MP	6	NO		Glacow	BNSF	Northwest	8	Engineer	
OS-464623	4/18/2021	8:48 AM	13	48		7	Robert AClary	118	Subway & Switching - Instructional	C - Compliance	Instructional review: Switches and Switching			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer
OS-464623	4/18/2021	10:50 AM	10	50		7	Robert AClary	118	Showing & Back-Up Moves - Instructional	C - Compliance	Instructional review: Showing and Back-Up Moves			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer
OS-464623	4/18/2021	10:52 AM	10	52		7	Robert AClary	124	Emergency Preparedness	C - Compliance	Compliance with emergency equipment in possession c			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer
OS-464623	4/18/2021	10:54 AM	10	54		7	Robert AClary	138	Positioning & Securing Unattended Equipment - Instructional	C - Compliance	Instructional review: Positioning and Securing Unattende			Mark E Bevin	MP		ShelbyCrew	MT		H Line	BNSF	Northwest	8	Engineer
OS-464623	2/9/2021	5:05 PM	17	5		Robert AClary	112	Whistle Directives	C - Compliance	Observed resulting within directives from fax machine.			Mark E Bevin	MP		ShelbySub	MT		H Line	BNSF	Northwest	7	Engineer	
OS-464623	2/9/2021	5:06 PM	17	6		Robert AClary	128	Drug & Alcohol	C - Compliance	Direct personal observation no use or possession of dru			Mark E Bevin	MP	1214.5	MT		H Line	BNSF	Northwest	7	Engineer		
OS-464623	2/9/2021	5:33 PM	17	33		Robert AClary	308	Speed	C - Compliance	55 mph PRR			Mark E Bevin	MP	1068.7	MT		H Line	BNSF	Northwest	7	Engineer		
OS-464623	2/9/2021	5:30 PM	17	30		Robert AClary	110	Air Brake Tests/Inspections	C - Compliance	Running brake test			Mark E Bevin	MP	1065.85	MT		H Line	BNSF	Northwest	7	Engineer		
OS-464623	2/9/2021	5:52 PM	17	52		Robert AClary	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow for PRR			Mark E Bevin	MP	1087.5	MT		H Line	BNSF	Northwest	7	Engineer		
OS-464623	2/9/2021	9:24 PM	21	24		Robert AClary	308	Speed	C - Compliance	20 mph PRR			Mark E Bevin	MP	1135.1	MT		H Line	BNSF	Northwest	7	Engineer		
OS-464623	2/9/2021	7:06 PM	19	6		Robert AClary	308	Speed	C - Compliance	45 mph PRR			Mark E Bevin	MP	1135.1	MT		H Line	BNSF	Northwest	7	Engineer		
OS-464623	2/9/2021	7:25 PM	19	25		Robert AClary	110	Air Brake Tests/Inspections	C - Compliance	Running brake test			Mark E Bevin	MP	1146.6	MT		H Line	BNSF	Northwest	7	Engineer		

08-481929	12/11/2020	3:22 PM	15	22	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow train.	Ark E Bevin	MP	302	MT	Mk River	BNGF	Northwest	8	Engineer
08-481934	12/11/2020	5:28 PM	17	28	Robert AClary	302 Stop Signal	C - Compliance	Complid w th Stop signal East Brk.	Ark E Bevin	MP	179.4	MT	Glaway	BNGF	Northwest	8	Engineer
08-481936	12/11/2020	4:55 PM	16	35	Robert AClary	308 Speed	C - Compliance	65 mph PFR	Ark E Bevin	MP	213.5	MT	Glaway	BNGF	Northwest	8	Engineer
08-481938	12/11/2020	6:45 PM	18	45	Robert AClary	308 Speed	C - Compliance	55 mph PFR	Ark E Bevin	MP	112.4	NO	Glaway	BNGF	Northwest	8	Engineer
08-481939	12/11/2020	8:15 PM	20	15	Robert AClary	308 Speed	C - Compliance	40 mph PFR	Ark E Bevin	MP	5.2	NO	Glaway	BNGF	Northwest	8	Engineer
08-475693	11/13/2020	11:05 AM	11	5	Robert AClary	117 Switches & Switching - Instructional	C - Compliance	Instructional review, Switches and Switching	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-475695	11/13/2020	11:08 AM	11	8	Robert AClary	118 Showing Back-Up Moves - Instructional	C - Compliance	Instructional Review, Showing and Back-Up Moves	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-475698	11/13/2020	11:55 AM	11	55	Robert AClary	112 Written Directives	C - Compliance	Compliance by T&E crew receiving written directives by	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-475701	11/13/2020	10:50 AM	10	50	Robert AClary	128 Drug & Alcohol	C - Compliance	Direct personal observation no use or possession of dr	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-475705	11/13/2020	12:00 PM	12	0	Robert AClary	110 Job Briefings	C - Compliance	Quality job briefing at beginning of tour of duty, includin	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-475708	11/13/2020	12:20 PM	12	20	Robert AClary	119 Caling Signals/Restrictions	C - Compliance	Called Clear signal to train crew departing SBY station.	Ark E Bevin	MP	1065.6	MT	H Line	BNGF	Northwest	8	Engineer
08-475709	11/13/2020	12:20 PM	12	20	Robert AClary	120 Radio Procedures	C - Compliance	Proper radio procedure observed calling signal to condu	Ark E Bevin	MP	1065.6	MT	H Line	BNGF	Northwest	8	Engineer
08-4243768	10/11/2020	10:50 AM	10	50	Robert AClary	124 Emergency/Preparedness	C - Compliance	Running brake test	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-422856	10/2/2020	11:05 AM	11	5	Robert AClary	112 Written Directives	C - Compliance	Employees checked GTS for completeness, and messa	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-422859	10/2/2020	11:13 AM	11	13	Robert AClary	110 Job Briefings	C - Compliance	Employees held a quality job briefing prior to taking cha	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-423050	10/2/2020	11:34 AM	11	34	Robert AClary	133 FRA 232-238 Hands on Brake Test/Insp	C - Compliance	Class II brake test.	Ark E Bevin	MP	1065.6	MT	H Line	BNGF	Northwest	8	Engineer
08-423052	10/2/2020	11:40 AM	11	42	Robert AClary	308 Speed	C - Compliance	10 mph T&E	Ark E Bevin	MP	1064.6	MT	H Line	BNGF	Northwest	8	Engineer
08-423053	10/2/2020	11:37 AM	11	37	Robert AClary	110 Air Brake Tests/Inspections	C - Compliance	Running brake test	Ark E Bevin	MP	1065.5	MT	H Line	BNGF	Northwest	8	Engineer
08-423054	10/2/2020	11:41 AM	11	41	Robert AClary	116 RWP Rules	C - Compliance	Sounded prescribed bell/whistle signal in proximity to r	Ark E Bevin	MP	1064.72	MT	H Line	BNGF	Northwest	8	Engineer
08-423071	10/2/2020	12:03 PM	12	3	Robert AClary	302 Stop Signal	C - Compliance	Stopped short of Stop signal at East Devon.	Ark E Bevin	MP	1046.9	MT	H Line	BNGF	Northwest	8	Engineer
08-423072	10/2/2020	11:59 AM	11	59	Robert AClary	305 Other Signal Indications	C - Compliance	Complid w th rules governing Diverging Approach sig	Ark E Bevin	MP	1048.1	MT	H Line	BNGF	Northwest	8	Engineer
08-423073	10/2/2020	11:59 AM	11	59	Robert AClary	308 Speed	C - Compliance	35 mph turnout speed West Devon.	Ark E Bevin	MP	1048.1	MT	H Line	BNGF	Northwest	8	Engineer
08-423076	10/2/2020	11:57 AM	11	57	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow to Temporary Speed Restriction	Ark E Bevin	MP	1049.4	MT	H Line	BNGF	Northwest	8	Engineer
08-423062	10/2/2020	12:35 PM	12	35	Robert AClary	305 Other Signal Indications	C - Compliance	Passed Diverging Clear, complying with rules and speed	Ark E Bevin	MP	1012	MT	H Line	BNGF	Northwest	8	Engineer
08-423063	10/2/2020	12:35 PM	12	35	Robert AClary	308 Speed	C - Compliance	50 mph turnout speed at O'Jopin.	Ark E Bevin	MP	1012	MT	H Line	BNGF	Northwest	8	Engineer
08-423064	10/2/2020	12:35 PM	12	35	Robert AClary	119 Caling Signals/Restrictions	C - Compliance	Called Diverging Clear signal to train crew.	Ark E Bevin	MP	1012	MT	H Line	BNGF	Northwest	8	Engineer
08-423066	10/2/2020	12:35 PM	12	35	Robert AClary	120 Radio Procedures	C - Compliance	Proper radio procedure when calling signal to engine	Ark E Bevin	MP	1012	MT	H Line	BNGF	Northwest	8	Engineer
08-423068	10/2/2020	1:09 PM	13	9	Robert AClary	112 Written Directives	C - Compliance	55 mph FAST Act	Ark E Bevin	MP	907.2	MT	H Line	BNGF	Northwest	8	Engineer
08-423066	10/2/2020	1:05 PM	12	50	Robert AClary	308 Speed	C - Compliance	70 mph PFR	Ark E Bevin	MP	993.3	MT	H Line	BNGF	Northwest	8	Engineer
08-423067	10/2/2020	1:22 PM	13	22	Robert AClary	123 Engineer Certificate	C - Compliance	Current log ble and unaltered certificate operating with	Ark E Bevin	Location	HAVE Station	MT	H Line	BNGF	Northwest	8	Engineer
08-423075	10/2/2020	1:15 PM	13	15	Robert AClary	308 Speed	C - Compliance	20 mph PFR.	Ark E Bevin	MP	482	MT	Mk River	BNGF	Northwest	8	Engineer
08-493207	8/30/2020	11:05 AM	11	5	Robert AClary	112 Written Directives	C - Compliance	Employees observed receiving written directives, Empli	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-493311	8/30/2020	11:30 AM	11	30	Robert AClary	110 Job Briefings	C - Compliance	Compliance with rules requiring a quality job briefing by	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-493315	8/30/2020	11:36 AM	11	36	Robert AClary	341 Personal Protective Equipment	C - Compliance	Compliance by crew with requirements to wear PPE. Prc	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-446634	7/17/2020	11:00 AM	11	0	Robert AClary	121 Required Documents	C - Compliance	All required documents, books, and instructions in their	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-413350	7/7/2020	1:54 PM	13	54	Robert AClary	398 Employee Instruction	C - Compliance	PTC to low up, PTC Enforcement Follow-up	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-412942	6/27/2020	11:35 PM	13	35	Robert AClary	308 Speed	C - Compliance	Received posted advice by before initiating Main Track	Ark E Bevin	MP	1056.5	MT	H Line	BNGF	Northwest	8	Engineer
08-412945	6/27/2020	11:44 AM	11	44	Robert AClary	119 Caling Signals/Restrictions	C - Compliance	Train crew reminded head end of upcoming slow order.	Ark E Bevin	MP	1056.5	MT	H Line	BNGF	Northwest	8	Engineer
08-412948	6/27/2020	11:46 AM	11	45	Robert AClary	120 Radio Procedures	C - Compliance	Proper radio procedure observed between crew when c	Ark E Bevin	MP	1052	MT	H Line	BNGF	Northwest	8	Engineer
08-412952	6/27/2020	2:02 PM	14	2	Robert AClary	302 Stop Signal	C - Compliance	Complid w th Stop signal Harlem East	Ark E Bevin	MP	386.8	MT	Mk River	BNGF	Northwest	8	Engineer
08-412953	6/27/2020	4:58 PM	16	58	Robert AClary	111 Highway Crossing Protection	C - Compliance	Complid with crossing notification, advance failure, Pa	Ark E Bevin	MP	228.04	MT	Glaway	BNGF	Northwest	8	Engineer
08-412955	6/27/2020	11:21 AM	11	21	Robert AClary	119 Caling Signals/Restrictions	C - Compliance	No personal electronic device. Stowed and out o	Ark E Bevin	MP	430.3	MT	Mk River	BNGF	Northwest	8	Engineer
08-407265	5/14/2020	11:20 AM	11	20	Robert AClary	306 Main Track Authority	C - Compliance	Compliance with rules regarding initiating Main Track m	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-407269	5/14/2020	11:00 AM	11	0	Robert AClary	139 Positioning & Securing Unattended Equipment - Instructional	C - Compliance	Briefing on equipment securement, post toning	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-407240	5/14/2020	11:35 AM	11	35	Robert AClary	341 Personal Protective Equipment	C - Compliance	Crew equipped with current personal issued personal pr	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-405705	5/6/2020	10:50 AM	10	50	Robert AClary	OPA202-03 Operating Practices Advisory 7U-familiar Con ditions	C - Compliance	OPA 202-03 briefing	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-403346	4/23/2020	11:00 AM	11	0	Robert AClary	OPA202-02 Operating Practices Advisory 7improved Communication and CRM	C - Compliance	OPA 202-02 briefing	Ark E Bevin	Location	ShelbySat	MT	H Line	BNGF	Northwest	8	Engineer
08-401080	4/2/2020	10:48 AM	10	48	Robert AClary	117 Switches & Switching - Instructional	C - Compliance	Instructional review	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-401082	4/2/2020	10:50 AM	10	50	Robert AClary	118 Showing & Back-Up Moves - Instructional	C - Compliance	Instructional review	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-401084	4/2/2020	10:52 AM	10	52	Robert AClary	139 Positioning & Securing Unattended Equipment - Instructional	C - Compliance	Instructional review	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-401083	3/12/2020	10:55 AM	10	55	Robert AClary	398 Employee Instruction	C - Compliance	Discussed about PTC Enforcement Follow-up	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-394704	2/6/2020	11:00 AM	11	0	Robert AClary	128 Drug & Alcohol	C - Compliance	Direct personal observation no use or possession of dr	Ark E Bevin	Location	ShelbyCrew	MT	H Line	BNGF	Northwest	8	Engineer
08-391868	1/23/2020	12:20 PM	12	20	Robert AClary	301 Stopping Within One-Ha File Range of Vision	C - Compliance	Joint test with JOINT	Ark E Bevin	MP	1036.1	MT	H Line	BNGF	Northwest	8	Engineer
08-391872	1/23/2020	12:16 PM	12	16	Robert AClary	302 Stop Signal	C - Compliance	Joint test with JOINT	Ark E Bevin	MP	1036.7	MT	H Line	BNGF	Northwest	8	Engineer
08-391877	1/23/2020	12:22 PM	12	22	Robert AClary	307 Delayed in Block	C - Compliance	Joint testing w/JOINT	Ark E Bevin	MP	1035.5	MT	H Line	BNGF	Northwest	8	Engineer
08-391821	1/23/2020	12:18 PM	12	18	Robert AClary	119 Caling Signals/Restrictions	C - Compliance	Joint testing w/JOINT	Ark E Bevin	MP	1035.5	MT	H Line	BNGF	Northwest	8	Engineer
08-391823	1/23/2020	12:23 PM	12	23	Robert AClary	120 Radio Procedures	C - Compliance	Crew completed JOINT	Ark E Bevin	MP	1035.5	MT	H Line	BNGF	Northwest	8	Engineer
08-392079	1/23/2020	12:16 PM	12	16	Robert AClary	302 Stop Signal	C - Compliance	Radar stop at W. Loshair	Ark E Bevin	MP	1036.86	MT	H Line	BNGF	Northwest	8	Engineer
08-392080	1/23/2020	11:48 AM	11	48	Robert AClary	110 Air Brake Tests/Inspections	C - Compliance	Running brake test	Ark E Bevin	MP	1055.49	MT	H Line	BNGF	Northwest	8	Engineer
08-392083	1/23/2020	11:48 AM	11	48	Robert AClary	122 Whistle/Bell/Headlight/Markers	C - Compliance	Sounded bell/whistle at preser bed location	Ark E Bevin	MP	1055.8	MT	H Line	BNGF	Northwest	8	Engineer
08-392021	1/23/2020	12:59 PM	13	29	Robert AClary	308 Speed	C - Compliance	FAST Act 55 mph FAST Act	Ark E Bevin	MP	997.2	MT	H Line	BNGF	Northwest	8	Engineer
08-392034	1/23/2020	1:57 PM	13	57	Robert AClary	308 Speed	C - Compliance	10 mph T&E	Ark E Bevin	MP	423.7	MT	Mk River	BNGF	Northwest	8	Engineer
08-392026	1/23/2020	3:05 PM	13	5	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	Blended brake to station stop MAL	Ark E Bevin	MP	344.7	MT	Mk River	BNGF	Northwest	8	Engineer
08-392050	1/23/2020	5:16 PM	17	56	Robert AClary	308 Speed	C - Compliance	65 mph PFR	Ark E Bevin	MP	213.5	MT	Glaway	BNGF	Northwest	8	Engineer
08-392052	1/23/2020	6:59 PM	18	59	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake on descending grade	Ark E Bevin	MP	97.4	NO	Glaway	BNGF	Northwest	8	Engineer
08-392054	1/23/2020	7:17 PM	19	17	Robert AClary	308 Speed	C - Compliance	65 mph PFR	Ark E Bevin	MP	76.5	NO	Glaway	BNGF	Northwest	8	Engineer
08-392056	1/23/2020	8:13 PM	20	13	Robert AClary	308 Speed	C - Compliance	60 mph PFR	Ark E Bevin	MP	11.2	NO	Glaway	BNGF	Northwest	8	Engineer
08-392431	1/23/2020	12:22 PM	12	22	Robert AClary	116 RWP Rules	C -										

08-3719130	9/9/2019	10:44 AM	30	4	Robert ACIary	308 Speed	C - Compliance	Complid with FAST Act	Mark E Bevins	MP	111.3	ND	NO	Glawog	BNF	Northwest	7	Engineer
08-3719137	9/9/2019	11:15 AM	11	1	Robert ACIary	308 Speed	C - Compliance	Complid with 30 mph PRR	Mark E Bevins	MP	124.7	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3719139	9/9/2019	11:21 AM	11	2	Robert ACIary	122 White/Bell/Headlight/Markers	C - Compliance	White/Bell at pwrer bed location	Mark E Bevins	MP	134.6	ND	NO	Glawog	BNF	Northwest	7	Engineer
08-3719147	9/9/2019	1:05 PM	13	1	Robert ACIary	308 Speed	C - Compliance	Complid with 35 mph TRR	Mark E Bevins	MP	256.7	MT	NO	Glawog	BNF	Northwest	7	Engineer
08-3719149	9/9/2019	2:20 PM	14	2	Robert ACIary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow train	Mark E Bevins	MP	138.8	MT	NO	MIR River	BNF	Northwest	7	Engineer
08-3719167	9/9/2019	3:44 PM	15	4	Robert ACIary	308 Speed	C - Compliance	Complid with FAST Act	Mark E Bevins	MP	428	MT	NO	MIR River	BNF	Northwest	7	Engineer
08-3719189	9/9/2019	5:14 PM	17	1	Robert ACIary	308 Speed	C - Compliance	Complid with 30 mph TRR	Mark E Bevins	MP	1023.3	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3720282	9/9/2019	1:47 PM	15	4	Robert ACIary	305 Other Signal Indicators	C - Compliance	Asp Med to Div Clear. Complid with 35 mph speed m	Mark E Bevins	MP	994.2	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3720787	8/15/2019	11:15 AM	13	1	Robert ACIary	124 Emergency Preparedness	C - Compliance	O. Trid. Discussed emergency equpment, non-meat/CT	Mark E Bevins	Location				ShelbyState MT	BNF	Northwest	7	Engineer
08-3719152	8/15/2019	11:20 AM	11	2	Robert ACIary	308 Employee Instruction	C - Compliance	BBP-2019 Coaching on Running 6.3.16.11 PredictiveInfo	Mark E Bevins	Location				ShelbyState MT	BNF	Northwest	7	Engineer
08-3649836	7/16/2019	4:30 PM	16	3	Robert ACIary	308 Employee Instruction	O - Failure, mentored/coached	roament	Stephen F Alspach	Location				ShelbyCrew MT	BNF	Northwest	8	Engineer
08-3610538	6/19/2019	10:48 PM	22	4	Robert ACIary	128 Drug & Alcohol	C - Compliance	direct personal observation.	Stephen F Alspach	MP	3056.4	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3610544	6/19/2019	11:12 AM	11	1	Robert ACIary	130 Job Briefings	C - Compliance	Quality job briefing	Stephen F Alspach	MP	3056.4	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3610550	6/19/2019	10:56 AM	10	5	Robert ACIary	308 Employee Instruction	C - Compliance	Summer Safety 303.2018	Stephen F Alspach	MP	3056.4	MT	NO	H Line	BNF	Northwest	8	Engineer
08-351827	4/30/2019	11:00 AM	11		Robert ACIary	130 Job Briefings	C - Compliance	DETAILED, SAFETY FOCUSED JOB BRIEFING.	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3539197	4/21/2019	10:34 AM	30	2	Robert ACIary	108 Speed	C - Compliance	PROPER RUNNING BRAKE TEST.	Mary M McGoats	MP	0.7	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3539199	4/21/2019	10:34 AM	30	2	Robert ACIary	110 Air Brake Tests/Inspections	C - Compliance	COMPLD WITH A 40 MPH PRR.	Mary M McGoats	MP	4.6	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3539200	4/21/2019	11:39 AM	11	1	Robert ACIary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO SLOW TRAIN SPEE	Mary M McGoats	MP	66.1	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3539204	4/21/2019	11:38 AM	11	2	Robert ACIary	305 Other Signal Indicators	C - Compliance	COMPLD WITH A DIVERGING ROUTE SIGNAL AT 7	Mary M McGoats	MP	78	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3539206	4/21/2019	11:20 AM	11	2	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 70 MPH PRR.	Mary M McGoats	MP	68.9	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3539209	4/21/2019	11:57 AM	11	5	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act	Mary M McGoats	MP	111.5	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3539237	4/21/2019	1:30 PM	12	3	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 25 MPH PRR.	Mary M McGoats	MP	137.4	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3539240	4/21/2019	1:24 PM	12	4	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 40 MPH PRR.	Mary M McGoats	MP	43.4	MT	NO	Glawog	BNF	Northwest	7	Engineer
08-3539274	4/21/2019	2:03 PM	14		Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 40 MPH PRR.	Mary M McGoats	MP	237.7	MT	NO	Glawog	BNF	Northwest	7	Engineer
08-3539277	4/21/2019	4:43 PM	16	4	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act	Mary M McGoats	MP	428	MT	NO	MIR River	BNF	Northwest	7	Engineer
08-3568304	3/23/2019	10:15 AM	30	1	Robert ACIary	121 Required Documents	C - Compliance	PASSED BOOK CHECK	Donald S Lacey	Location				Seattle Trans WA	BNF	Northwest	CLASS	Engineer
08-350571	3/20/2019	10:15 AM	30	1	Robert ACIary	121 Required Documents	C - Compliance	PASSED BOOK CHECK	Donald S Lacey	Location				Seattle Trans WA	BNF	Northwest	CLASS	Engineer
08-3473100	2/28/2019	12:05 AM	0	0	Robert ACIary	308 Employee Instruction	C - Compliance	Farm B Education	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3473257	2/27/2019	9:29 PM	21	2	Robert ACIary	305 Other Signal Indicators	C - Compliance	COMPLD WITH A 30 MPH PRR.	Mary M McGoats	MP	1217.9	MT	NO	Kootenai River	BNF	Northwest	7	Engineer
08-3473258	2/27/2019	9:06 PM	21		Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A DIVERGING ROUTE SIGNAL AT REGA	Mary M McGoats	MP	1106.3	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3473259	2/27/2019	8:39 PM	20	3	Robert ACIary	110 Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST DISPARING SHELBY.	Mary M McGoats	MP	3065.8	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3473263	2/27/2019	9:34 PM	21	3	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A DIVERGING ROUTE SIGNAL AT BLACK	Mary M McGoats	MP	116.3	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3473268	2/27/2019	9:34 PM	21	3	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act	Mary M McGoats	MP	1111.4	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3473284	2/27/2019	10:24 PM	22	2	Robert ACIary	110 Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST BEFORE DISCEND NG	Mary M McGoats	MP	1149.2	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3473285	2/27/2019	10:32 PM	22	3	Robert ACIary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	Proper use of dynamic brake to control train speed.	Mary M McGoats	MP	1136.3	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3473286	2/27/2019	11:29 PM	23	2	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act	Mary M McGoats	MP	1188.2	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3473298	2/27/2019	11:53 PM	23	5	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 40 MPH PRR.	Mary M McGoats	MP	2079.3	MT	NO	H Line	BNF	Northwest	7	Engineer
08-3458029	2/14/2019	4:00 PM	16		Robert ACIary	OPA2018-01 Operating Practices Advisory Review- Restricted Speed	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	Mary M McGoats	Location				ShelbyState MT	BNF	Northwest	8	Engineer
08-345652	2/9/2019	12:30 PM	12	3	Robert ACIary	128 Drug & Alcohol	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3456598	2/9/2019	12:25 PM	12	2	Robert ACIary	130 Job Briefings	C - Compliance	DETAILED, SAFETY FOCUSED JOB BRIEFING.	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3366478	11/1/2018	11:01 AM	11	1	Robert ACIary	117C Switching & Signaling - Instructional	C - Compliance	Switching & Signaling - Instructional	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3364479	12/6/2018	11:10 AM	11	1	Robert ACIary	118C Shoving & Back Up Moves - Instructional	C - Compliance	Shoving & Back Up Moves - Instructional	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3364480	12/6/2018	11:10 AM	11	1	Robert ACIary	124 Emergency Preparedness	C - Compliance	EP DISCUSSION.	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3364481	12/6/2018	11:28 AM	11	2	Robert ACIary	133 FRA 232-238 Hands on Brake Test/Ins	C - Compliance	PROPER CLASS 11 BRAKE TEST AT SHELBY.	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3364482	12/6/2018	11:10 AM	11	1	Robert ACIary	133R Positioning & Securing Unattended Equipment - Instructional	C - Compliance	Positioning & Securing Unattended Equipment - Instructional	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3375186	12/6/2018	12:02 PM	12	1	Robert ACIary	304 Stop & Proceed/ Restricted Proceed Signal	C - Compliance	COMPLD WITH A RESTRICTING SIGNAL.	Mary M McGoats	MP	432.4	MT	NO	MIR River	BNF	Northwest	8	Engineer
08-3375186	12/6/2018	12:17 PM	12	1	Robert ACIary	305 Other Signal Indicators	C - Compliance	COMPLD WITH A DIVERGING ROUTE SIGNAL AT JORUI	Mary M McGoats	MP	432.4	MT	NO	MIR River	BNF	Northwest	8	Engineer
08-3375187	12/6/2018	12:55 PM	12	5	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act	Mary M McGoats	MP	967.2	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3375188	12/6/2018	12:03 PM	12		Robert ACIary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	GOOD USE OF DYNAMIC BRAKE TO CONTROL TRAIN SPE	Mary M McGoats	MP	3003.8	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3375189	12/6/2018	11:34 PM	12	3	Robert ACIary	135 Electronic Device	C - Compliance	CELL PHONE OFF AND STOWED.	Mary M McGoats	MP	993	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3333019	11/8/2018	11:00 AM	11		Robert ACIary	308 Employee Instruction	C - Compliance	PNW STAND DOWN 29-1	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3333020	11/8/2018	11:00 AM	11		Robert ACIary	OPA2018-05 Operating Practices Advisory Review- Desr Imenets	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-3322408	10/29/2018	9:47 AM	9		Robert ACIary	105 Other Signal Indicators	C - Compliance	COMPLD WITH A DIVERGING ROUTE SIGNAL AT OP 4	Mary M McGoats	MP	48	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3322411	10/29/2018	9:12 AM	9		Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 40 MPH PRR.	Mary M McGoats	MP	4.6	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3322413	10/29/2018	9:08 AM	9		Robert ACIary	110 Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	Mary M McGoats	MP	0.2	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3322415	10/29/2018	10:49 AM	10	4	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act.	Mary M McGoats	MP	111.5	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3322417	10/29/2018	10:50 AM	10	5	Robert ACIary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF FAST Act	Mary M McGoats	MP	112.5	NO	NO	Glawog	BNF	Northwest	7	Engineer
08-3322450	10/29/2018	12:26 PM	12	2	Robert ACIary	302 Stop Signal	C - Compliance	STOPPED FOR STOP SIGNAL AT W. BROOKTON.	Mary M McGoats	MP	194.1	MT	NO	Glawog	BNF	Northwest	7	Engineer
08-3322453	10/29/2018	11:39 AM	11	3	Robert ACIary	305 Other Signal Indicators	C - Compliance	COMPLD WITH AN APPROACH SIGNAL AT E. BAINVIL	Mary M McGoats	MP	159.9	MT	NO	Glawog	BNF	Northwest	7	Engineer
08-3322454	10/29/2018	2:13 PM	14	1	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 25 MPH PRR.	Mary M McGoats	MP	311.9	MT	NO	MIR River	BNF	Northwest	7	Engineer
08-3322457	10/29/2018	2:58 PM	14	5	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 25 MPH PRR.	Mary M McGoats	MP	363.1	MT	NO	MIR River	BNF	Northwest	7	Engineer
08-3322462	10/29/2018	3:49 PM	15	4	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act	Mary M McGoats	MP	428	MT	NO	MIR River	BNF	Northwest	7	Engineer
08-2210153	10/4/2018	10:15 AM	30	1	Robert ACIary	121 Required Documents	C - Compliance	PASSED BOOK CHECK	Donald S Lacey	Location				Seattle Trans WA	BNF	Northwest	CLASS	Engineer
08-2200797	9/27/2018	5:05 PM	17		Robert ACIary	308 Employee Instruction	C - Compliance	OPA 2018-04 7 Prepared to Stop	Mary M McGoats	MP	3065.7	MT	NO	H Line	BNF	Northwest	7	Engineer
08-2138608	8/12/2018	2:24 PM	14	2	Robert ACIary	305 Other Signal Indicators	C - Compliance	COMPLD WITH AN APPROACH SIGNAL AT W. BURNHAM.	Mary M McGoats	MP	974.4	MT	NO	H Line	BNF	Northwest	8	Engineer
08-2138700	8/12/2018	1:09 PM	13	1	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 25 MPH PRR.	Mary M McGoats	MP	3048.7	MT	NO	H Line	BNF	Northwest	8	Engineer
08-2138702	8/12/2018	12:54 PM	12	5	Robert ACIary	110 Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	Mary M McGoats	MP	3065.4	MT	NO	H Line	BNF	Northwest	8	Engineer
08-2138707	8/12/2018	2:11 PM	14	3	Robert ACIary	308 Speed	C - Compliance	COMPLD WIT FAST Act.	Mary M McGoats	MP	967.2	MT	NO	H Line	BNF	Northwest	8	Engineer
08-2138713	8/12/2018	2:37 PM	14	3	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 25 MPH PRR.	Mary M McGoats	MP	431.9	MT	NO	H Line	BNF	Northwest	8	Engineer
08-2138720	8/12/2018	4:51 PM	16	5	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 40 MPH PRR.	Mary M McGoats	MP	312.1	MT	NO	H Line	BNF	Northwest	8	Engineer
08-2138724	8/12/2018	5:01 PM	17		Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 25 MPH PRR.	Mary M McGoats	MP	300	MT	NO	H Line	BNF	Northwest	8	Engineer
08-2138745	8/12/2018	8:19 PM	20	1	Robert ACIary	308 Speed	C - Compliance	COMPLD WITH A 40 MPH PRR.	Mary M McGoats	MP	345	NO	NO	H Line	BNF	Northwest	8	Engineer
08-2138747	8/12/2018	9:29 PM	21	2	Robert ACIary	134 Train Handling/Fuel-E												

08-1193743	4/30/2018	5:30 PM	17	30	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 30MPH TSL.	Aurly M McGuire	MP	1042	MT	XCO	BNSF	Northwest	7	Engineer
08-1193748	4/30/2018	5:40 PM	17	40	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH AN APPROACH SIGNAL AT W. DUNKER	Aurly M McGuire	MP	1058	MT	SBY	BNSF	Northwest	7	Engineer
08-1186222	4/23/2018	9:07 AM	9		Robert AClary	110 Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	Aurly M McGuire	MP	6.3	NO	MOT	Amtrak	Northwest	7	Engineer
08-1186227	4/23/2018	9:13 AM	9	13	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 40MPH TSL.	Aurly M McGuire	MP	4.6	NO	MOT	BNSF	Northwest	7	Engineer
08-1186231	4/23/2018	30:08 AM	30		Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO CONTROL TRAIN SF	Aurly M McGuire	MP	67.9	NO	STN	Amtrak	Northwest	7	Engineer
08-1186009	4/23/2018	30:45 AM	30	45	Robert AClary	308 Speed	C - Compliance	FAST ACT COMPLIED WITH A 55MPH PSL	Aurly M McGuire	MP	111.5	NO	XTP	BNSF	Northwest	7	Engineer
08-1186097	4/23/2018	12:00 PM	12		Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 70MPH PSL	Aurly M McGuire	MP	184.4	MT	XCU	BNSF	Northwest	7	Engineer
08-1186505	4/23/2018	11:37 AM	11	37	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 40MPH TSL.	Aurly M McGuire	MP	156.1	MT	XCU	BNSF	Northwest	7	Engineer
08-1186548	4/23/2018	12:27 PM	12	27	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH AN APPROACH SIGNAL AT E. MACON.	Aurly M McGuire	MP	239.4	MT	NPT	BNSF	Northwest	7	Engineer
08-1186934	4/23/2018	4:01 PM	35		Robert AClary	308 Speed	C - Compliance	FAST ACT COMPLIED WITH A 55MPH PSL	Aurly M McGuire	MP	428	MT	HAV	BNSF	Northwest	7	Engineer
08-1186985	4/23/2018	5:09 PM	17		Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 60MPH PSL.	Aurly M McGuire	MP	3002.5	MT	XV	BNSF	Northwest	7	Engineer
08-1181012	4/23/2018	5:43 PM	17	43	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 30MPH TSL.	Aurly M McGuire	MP	1042	MT	XCO	BNSF	Northwest	7	Engineer
08-1156422	4/2/2018	1:05 PM	13		Robert AClary	298 Employee Instruction	C - Compliance	OP&S ISSUES/AWARENESS & COMMUNICATION	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Engineer
08-1073408	1/19/2018	11:00 AM	11		Robert AClary	130 Job Briefings	C - Compliance	S&S SAFETY STAND DOWN.	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Engineer
08-1073426	1/19/2018	11:30 AM	11	30	Robert AClary	128 Drug & Alcohol	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Engineer
08-1057076	1/7/2018	11:34 AM	11	34	Robert AClary	110 Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	Aurly M McGuire	MP	306.5	MT	SBY	Amtrak	Northwest	8	Engineer
08-1057099	1/7/2018	12:15 PM	12	15	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO CONTROL TRAIN SF	Aurly M McGuire	MP	304.4	MT	XV	Amtrak	Northwest	8	Engineer
08-1057105	1/7/2018	12:31 PM	12	31	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH A DIVERGING ROUTE SIGNAL AT HIND	Aurly M McGuire	MP	99.2	MT	XV	BNSF	Northwest	8	Engineer
08-1057114	1/7/2018	12:53 PM	12	53	Robert AClary	308 Speed	C - Compliance	FAST ACT COMPLIED WITH A 55MPH PSL	Aurly M McGuire	MP	967.2	MT	HAV	BNSF	Northwest	8	Engineer
08-1057118	1/7/2018	12:58 PM	12	58	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 20MPH PSL.	Aurly M McGuire	MP	431.9	MT	HAV	BNSF	Northwest	8	Engineer
08-1057269	1/7/2018	3:16 PM	15	16	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 65MPH PSL.	Aurly M McGuire	MP	312.1	MT	XFB	BNSF	Northwest	8	Engineer
08-1057444	1/7/2018	3:35 PM	15	35	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH AN APPROACH SIGNAL AT W. TAMPCO	Aurly M McGuire	MP	280.7	MT	XFB	BNSF	Northwest	8	Engineer
08-1057498	1/7/2018	3:45 PM	15	45	Robert AClary	302 Stop Signal	C - Compliance	COMPLIED WITH A STOP SIGNAL AT E. TAMPCO.	Aurly M McGuire	MP	288.6	MT	XFB	BNSF	Northwest	8	Engineer
08-1057597	1/7/2018	6:16 PM	18	16	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 40MPH PSL.	Aurly M McGuire	MP	126.5	MT	WTN	BNSF	Northwest	8	Engineer
08-1057658	1/7/2018	8:11 PM	20	11	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 40MPH PSL.	Aurly M McGuire	MP	5.2	MT	MOT	BNSF	Northwest	8	Engineer
08-1021356	12/7/2017	3:53 PM	15	53	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	GOOD USE OF DYNAMIC BRAKE TO CONTROL TRAIN SF	Aurly M McGuire	MP	1017	MT	XCO	Amtrak	Northwest	7	Engineer
08-1021372	12/7/2017	4:05 PM	16		Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED MEDIUM APPROACH SIGNAL AT MP	Aurly M McGuire	MP	303.9	MT	XCO	Amtrak	Northwest	7	Engineer
08-1021376	12/7/2017	4:08 PM	16	35	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH AN APPROACH SIGNAL AT E. LOTHAR.	Aurly M McGuire	MP	307.5	MT	SBY	BNSF	Northwest	7	Engineer
08-1021383	12/7/2017	4:14 PM	16	14	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 70MPH PSL.	Aurly M McGuire	MP	3040.3	MT	XCO	BNSF	Northwest	7	Engineer
08-1021398	12/7/2017	4:30 PM	16	30	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH AN APPROACH SIGNAL AT W. DUNKER	Aurly M McGuire	MP	1058	MT	SBY	BNSF	Northwest	7	Engineer
08-1000321	11/29/2017	5:22 PM	17	22	Robert AClary	110 Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	Aurly M McGuire	MP	306.9	MT	SBY	Amtrak	Northwest	7	Engineer
08-1000325	11/29/2017	5:25 PM	17	25	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 50MPH TSL.	Aurly M McGuire	MP	1068	MT	SBY	BNSF	Northwest	7	Engineer
08-1000336	11/29/2017	5:33 PM	17	33	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 55MPH TSL.	Aurly M McGuire	MP	3075.5	MT	SBY	BNSF	Northwest	7	Engineer
08-1000388	11/29/2017	6:18 PM	18	18	Robert AClary	308 Speed	C - Compliance	FAST ACT COMPLIED WITH A 55MPH PSL	Aurly M McGuire	MP	1111.4	MT	MM	BNSF	Northwest	7	Engineer
08-1000455	11/29/2017	7:31 PM	19	31	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO CONTROL TRAIN SF	Aurly M McGuire	MP	1160.3	MT	ESM	Amtrak	Northwest	7	Engineer
08-1001295	11/29/2017	7:55 PM	19	55	Robert AClary	307 Delayed in Block	C - Compliance	COMPLIED WITH THE DELAYED IN THE BLOCK RULE.	Aurly M McGuire	MP	1170.1	MT	ESM	Amtrak	Northwest	7	Engineer
08-1001308	11/29/2017	8:04 PM	20		Robert AClary	122 Whistle/Bell/Headlight/Markers	C - Compliance	PROPER HORN AND BELL AT A RAIL CROSSING.	Aurly M McGuire	MP	1177.7	MT	XBL	Amtrak	Northwest	7	Engineer
08-1001342	11/29/2017	8:17 PM	20	17	Robert AClary	308 Speed	C - Compliance	FAST ACT COMPLIED WITH A 50MPH PSL	Aurly M McGuire	MP	1188.2	MT	XBL	BNSF	Northwest	7	Engineer
08-1001365	11/29/2017	8:45 PM	20	45	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH A DIVERGING ROUTE SIGNAL AT CDNK	Aurly M McGuire	MP	1208.6	MT	XFM	BNSF	Northwest	7	Engineer
08-1001375	11/29/2017	8:57 PM	20	57	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 20MPH PSL.	Aurly M McGuire	MP	1217.9	MT	WH	BNSF	Northwest	7	Engineer
08-996372	11/27/2017	11:00 AM	11		Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED THE SIGNAL AT TETON.	Aurly M McGuire	MP	3070.9	MT	SBY	Amtrak	Northwest	8	Engineer
08-996383	11/27/2017	11:03 AM	11	31	Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED AN UP COMING TSL.	Aurly M McGuire	MP	3070.9	MT	CUT	Amtrak	Northwest	8	Engineer
08-997804	11/20/2017	7:40 AM	7	40	Robert AClary	135 FRA Emergency Order 26 - Electronic Devices	C - Compliance	CELL PHONE OFF AND STOWED.	Aurly M McGuire	MP	1219	MT	WH	Amtrak	Northwest	8	Engineer
08-998310	11/20/2017	8:55 AM	8	55	Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED SIGNAL AT JAVA WEST.	Aurly M McGuire	MP	1166.5	MT	ESM	Amtrak	Northwest	8	Engineer
08-998332	11/20/2017	8:56 AM	8	56	Robert AClary	105 Other Signal Indications	C - Compliance	COMPLIED WITH A DIVERGING APPROACH MEDIUM SIG	Aurly M McGuire	MP	1165.1	MT	ESM	Amtrak	Northwest	8	Engineer
08-998396	11/20/2017	9:06 AM	9		Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH AN APPROACH SIGNAL.	Aurly M McGuire	MP	1160.2	MT	ESM	BNSF	Northwest	8	Engineer
08-998616	11/20/2017	9:26 AM	9	26	Robert AClary	304 Stop & Proceed/Revised Proceed Signal	C - Compliance	COMPLIED WITH A RESTRICTED PROCEED SIGNAL WHILE	Aurly M McGuire	MP	1153.6	MT	GPX	BNSF	Northwest	8	Engineer
08-999548	11/20/2017	30:23 AM	30	23	Robert AClary	308 Speed	C - Compliance	FAST ACT COMPLIED WITH A 55MPH PSL	Aurly M McGuire	MP	1112.7	MT	GPX	BNSF	Northwest	8	Engineer
08-999571	11/20/2017	30:38 AM	30	38	Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED AN UP COMING 25MPH TSL.	Aurly M McGuire	MP	1095	MT	CUT	Amtrak	Northwest	8	Engineer
08-999573	11/20/2017	30:38 AM	30	38	Robert AClary	134 Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO CONTROL TRAIN SF	Aurly M McGuire	MP	1092	MT	CUT	Amtrak	Northwest	8	Engineer
08-991815	11/6/2017	5:00 PM	17		Robert AClary	298 Employee Instruction	C - Compliance	TEST 139 139	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	7	Conductor
08-991819	11/6/2017	5:00 PM	17		Robert AClary	130 Job Briefings	C - Compliance	SAFETY FOCUSED, DETAILED JOB BRIEFING.	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	7	Conductor
08-976231	30/31/2017	11:30 AM	11	30	Robert AClary	130 Job Briefings	C - Compliance	DETAILED SAFETY FOCUSED JOB BRIEFING.	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Conductor
08-966613	30/24/2017	11:00 AM	11		Robert AClary	298 Employee Instruction	C - Compliance	TEST 117/118 117/118 DISCUSSION.	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Conductor
08-966617	30/24/2017	11:00 AM	11		Robert AClary	699 Emergency Reparatdness	C - Compliance	699 DISCUSSION	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Conductor
08-966917	30/24/2017	11:30 AM	11	30	Robert AClary	131 FRA 233-238 Hands on Brake Test/Ins	C - Compliance	PROPER CALLS	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Conductor
08-832637	7/2/2017	11:15 AM	11	15	Robert AClary	135 FRA Emergency Order 26 - Electronic Devices	C - Compliance	CELL PHONE OFF AND STOWED.	Aurly M McGuire	MP	1088	MT	CUT	Amtrak	Northwest	8	Conductor
08-832677	7/2/2017	11:30 AM	11	30	Robert AClary	120 Radio Procedures	C - Compliance	PROPER RADIO PROCEDURES WHILE WORKING CUT BA	Aurly M McGuire	MP	1090.1	MT	CUT	Amtrak	Northwest	8	Conductor
08-832702	7/2/2017	11:55 AM	11	15	Robert AClary	128 Drug & Alcohol	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	Aurly M McGuire	MP	1088	MT	CUT	Amtrak	Northwest	8	Conductor
08-832703	7/2/2017	11:25 AM	11	25	Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED UP COMING 25MPH TSL	Aurly M McGuire	MP	1088	MT	SBY	Amtrak	Northwest	8	Conductor
08-833218	6/21/2017	3:58 PM	15	58	Robert AClary	305 Other Signal Indications	C - Compliance	COMPLIED WITH AN APPROACH SIGNAL AT E. BURKHAM	Aurly M McGuire	MP	989.7	MT	HAV	BNSF	Northwest	7	Conductor
08-833219	6/21/2017	4:00 PM	15		Robert AClary	135 FRA Emergency Order 26 - Electronic Devices	C - Compliance	CELL PHONE OFF AND STOWED.	Aurly M McGuire	MP	989.9	MT	HAV	Amtrak	Northwest	7	Conductor
08-833221	6/21/2017	4:00 PM	15		Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED THE SIGNAL AT E. BURKHAM.	Aurly M McGuire	MP	989.9	MT	HAV	Amtrak	Northwest	7	Conductor
08-833224	6/21/2017	4:12 PM	15	12	Robert AClary	119 Cal Inng Signals/Restrictions	C - Compliance	PROPERLY CALLED AN UP COMING 25MPH TSL.	Aurly M McGuire	MP	989.5	MT	XV	Amtrak	Northwest	7	Conductor
08-833227	6/21/2017	4:15 PM	15	15	Robert AClary	308 Speed	C - Compliance	COMPLIED WITH A 25MPH TSL.	Aurly M McGuire	MP	986.6	MT	XV	BNSF	Northwest	7	Conductor
08-77427	5/6/2017	11:00 AM	11		Robert AClary	298 Employee Instruction	C - Compliance	RA2127 QZ ELECTRONIC DEVICE DISTRACTIONS	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	8	Conductor
08-75388	4/21/2017	4:55 PM	15	55	Robert AClary	128 Drug & Alcohol	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	7	Conductor
08-753847	4/21/2017	5:01 PM	17		Robert AClary	130 Job Briefings	C - Compliance	EMPLOYEE CONDUCTED A DETAILED SAFETY FOCUSED J	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	7	Conductor
08-890631	3/7/2017	9:15 AM	9	15	Robert AClary	121 Required Documents	C - Compliance	ALL ROUJ RED BOOKS AND DOCUMENTS D LACZY	Donald S Lacey	MP	0DX	WA	SEA	Amtrak	Northwest	7	Conductor
08-866365	1/3/2017	5:30 AM	5	30	Robert AClary	128 Drug & Alcohol	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	7	Conductor
08-866369	1/3/2017	5:30 AM	5	30	Robert AClary	130 Job Briefings	C - Compliance	CONDUCTED A DETAILED SAFETY FOCUSED JOB BRIEFIN	Aurly M McGuire	MP	306.7	MT	SBY	Amtrak	Northwest	7	Conductor

Operational Tests - Larso

Sheet ID	Date	Time	TimeH	TimeMM	Employee	Full Name	Test Name	Result	Comments	Supervisor's Comment	Selection	Superv	Test Officer: Full Name	MP/Location	MP/SG Number	Location	State	Nearest Station or Interlocking	Subdivision	Railroad Property	Amtrak Division	Train	Q of T
08-462279	9/30/2021	10:48 AM	10	48		Scott W Larson	OPA2021-05 Unathorized Disabling of PTC Systems	C - Compliance	Briefing completed.				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-462288	9/30/2021	10:50 AM	10	50		Scott W Larson	OPA2021-06 I-ETMS Partial Initialization Failure Rules	C - Compliance	Briefing completed.				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-463496	8/20/2021	11:21 AM	11	46		Scott W Larson	117 Switches & Switching - Instructional	C - Compliance	Instructional review Sw tches and Back-up Moves				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-464295	8/20/2021	11:54 AM	11	54		Scott W Larson	118 Showing & Back-Up Moves - Instructional	C - Compliance	Instructional review Showing and Back-Up Moves				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-464872	8/20/2021	11:40 AM	11	40		Scott W Larson	398 Employee Introduction	C - Compliance	GCOR 8/8 briefing				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-464875	8/20/2021	11:50 AM	11	50		Scott W Larson	SA-PY21-05 Safety Alert: Vaccination and Testing Mandate Briefing	C - Compliance	GCOR 8/8 briefing				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-465038	8/20/2021	1:39 PM	13	39		Scott W Larson	303 Stopping within One-Half the Range of Vision	C - Compliance	Stopped prescribed Main Track Barndale Test				Mark E Blevins	MP	1035.95	MT		H Line	BNF	Northwest	Engineer		
08-465043	8/20/2021	1:41 PM	13	41		Scott W Larson	307 Delayed in Block	C - Compliance	Train was prose Main Track Barndale Test				Mark E Blevins	MP	1035.95	MT		H Line	BNF	Northwest	Engineer		
08-465092	8/20/2021	1:41 PM	13	41		Scott W Larson	116 RWP Rules	C - Compliance	Sounded prescribed whistle signal approaching properly				Mark E Blevins	MP	1035.95	MT		H Line	BNF	Northwest	Engineer		
08-457007	7/28/2021	4:39 PM	36	39		Scott W Larson	OPA2021-04 OP Advisory Leaking Equipment in the Clear	C - Compliance	OPA2021-04 briefing				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-463497	7/3/2021	11:28 AM	11	28		Scott W Larson	123 Engineer Certificate	C - Compliance	In possession of current, legible and unaltered certifi				Mark E Blevins	MP	3065.6	MT		H Line	BNF	Northwest	Engineer		
08-463498	7/3/2021	11:28 AM	11	28		Scott W Larson	302 Stop Signal	C - Compliance	Complied with Stop signal at E. Budrow				Mark E Blevins	MP	3015.1	MT		H Line	BNF	Northwest	Engineer		
08-463497	7/3/2021	11:40 AM	11	40		Scott W Larson	305 Other Signal Indications	C - Compliance	Complied with Diverging Clear signal at W. Decon, obs				Mark E Blevins	MP	3048.1	MT		H Line	BNF	Northwest	Engineer		
08-463498	7/3/2021	1:49 PM	13	40		Scott W Larson	308 Speed	C - Compliance	FAST Act 55 mph FAST Act				Mark E Blevins	MP	967.2	MT		H Line	BNF	Northwest	Engineer		
08-463499	7/3/2021	11:33 AM	11	33		Scott W Larson	110 Air Brake Tests/Inspections	C - Compliance	Running brake test				Mark E Blevins	MP	3065.5	MT		H Line	BNF	Northwest	Engineer		
08-463499	7/3/2021	11:57 AM	11	57		Scott W Larson	116 RWP Rules	C - Compliance	Sounded prescribed whistle signal approaching roadway				Mark E Blevins	MP	3041.4	MT		H Line	BNF	Northwest	Engineer		
08-463499	7/3/2021	11:56 AM	11	56		Scott W Larson	119 Calling Signals/Restrictions	C - Compliance	Called Approach Medium signal to train crew by radio.				Mark E Blevins	MP	3056.6	MT		H Line	BNF	Northwest	Engineer		
08-463499	7/3/2021	12:55 PM	12	55		Scott W Larson	120 Radio Procedures	C - Compliance	Proper radio procedure observed when repeating instr				Mark E Blevins	MP	3051.1	MT		H Line	BNF	Northwest	Engineer		
08-463499	7/3/2021	1:59 PM	13	59		Scott W Larson	308 Speed	C - Compliance	10 mph X at West Valley				Mark E Blevins	MP	431.9	MT		Mik River	BNF	Northwest	Engineer		
08-463499	7/3/2021	12:57 PM	12	57		Scott W Larson	116 RWP Rules	C - Compliance	Sounded prescribed whistle signal approaching roadway				Mark E Blevins	MP	1082	MT		H Line	BNF	Northwest	Engineer		
08-463499	7/3/2021	11:47 AM	11	47		Scott W Larson	114 Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to slow train for upcoming speed restrict				Mark E Blevins	MP	3046.7	MT		H Line	BNF	Northwest	Engineer		
08-463499	7/3/2021	12:56 PM	12	56		Scott W Larson	117 Switches & Switching	C - Compliance	Observed crew hand ting dial control switch after reatr				Mark E Blevins	MP	1082	MT		H Line	BNF	Northwest	Engineer		
08-464604	6/4/2021	11:08 AM	11	9		Scott W Larson	308 Speed	C - Compliance	FAST Act 55 mph FAST Act				Mark E Blevins	MP	3075.1	MT		H Line	BNF	Northwest	Engineer		
08-464620	6/4/2021	10:54 AM	10	54		Scott W Larson	301 Stopping within One-Half the Range of Vision	C - Compliance	Complied with Main Track Barndale Test				Mark E Blevins	MP	1122.4	MT		H Line	BNF	Northwest	Engineer		
08-464621	6/4/2021	10:37 AM	10	37		Scott W Larson	307 Delayed in Block	C - Compliance	Complied with Main Track Barndale Test				Mark E Blevins	MP	1122	MT		H Line	BNF	Northwest	Engineer		
08-464622	6/4/2021	10:36 AM	10	36		Scott W Larson	116 RWP Rules	C - Compliance	Sounded prescribed Main Track Barndale Test				Mark E Blevins	MP	1122.3	MT		H Line	BNF	Northwest	Engineer		
08-464623	6/4/2021	10:30 AM	10	30		Scott W Larson	302 Stop Signal	C - Compliance	Complied with Main Track Barndale Test				Mark E Blevins	MP	1125.6	MT		H Line	BNF	Northwest	Engineer		
08-464624	6/4/2021	10:05 AM	10	6		Scott W Larson	120 Radio Procedures	C - Compliance	Proper radio pr Main Track Barndale Test				Mark E Blevins	MP	11242.5	MT		H Line	BNF	Northwest	Engineer		
08-464625	6/4/2021	11:02 AM	11	2		Scott W Larson	116 RWP Rules	C - Compliance	Complied with instructions from foreman to enter Em ts				Mark E Blevins	MP	1083	MT		H Line	BNF	Northwest	Engineer		
08-464629	6/4/2021	10:58 AM	10	58		Scott W Larson	119 Calling Signals/Restrictions	C - Compliance	Called Yellow/Red Flag to train crew.				Mark E Blevins	MP	1085	MT		H Line	BNF	Northwest	Engineer		
08-464629	6/4/2021	10:58 AM	10	58		Scott W Larson	302 Stop Signal	C - Compliance	Complied with Stop Signal W/Downsp.				Mark E Blevins	MP	239.6	MT		Glawag	BNF	Northwest	Engineer		
08-444747	4/8/2021	8:27 AM	8	27		Scott W Larson	305 Other Signal Indications	C - Compliance	Complied with Diverging Clear signal and turnout speed				Mark E Blevins	MP	98.9	ND		Glawag	BNF	Northwest	Engineer		
08-444747	4/8/2021	10:04 AM	10	4		Scott W Larson	308 Speed	C - Compliance	FAST Act 55 mph FAST Act				Mark E Blevins	MP	111.5	ND		Glawag	BNF	Northwest	Engineer		
08-444747	4/8/2021	8:06 AM	8	6		Scott W Larson	110 Air Brake Tests/Inspections	C - Compliance	Running brake test				Mark E Blevins	MP	1.1	ND		Glawag	BNF	Northwest	Engineer		
08-444747	4/8/2021	9:55 AM	9	55		Scott W Larson	111 Highway Crossing/Protection	C - Compliance	Complied with rules governing movement over highway				Mark E Blevins	MP	3065.8	ND		Glawag	BNF	Northwest	Engineer		
08-444747	4/8/2021	12:12 PM	12	12		Scott W Larson	123 Engineer Certificate	C - Compliance	Current, unaltered, legible cert card in possession.				Mark E Blevins	MP	239.6	MT		Glawag	BNF	Northwest	Engineer		
08-463499	4/3/2021	2:50 PM	14	30		Scott W Larson	124 Emergency Reparatres	C - Compliance	Emergency equipment in possession of working, non-m				Mark E Blevins	MP	430.5	MT		Mik River	BNF	Northwest	Engineer		
08-463499	4/9/2021	11:51 AM	11	51		Scott W Larson	133 PRA 232-238 Hands on Brake Test/Insp	C - Compliance	Completed Class II brake test.				Mark E Blevins	MP	3065.6	MT		H Line	BNF	Northwest	Engineer		
08-461466	3/9/2021	2:22 PM	14	22		Scott W Larson	308 Speed	C - Compliance	FAST Act 55 mph FAST Act				Mark E Blevins	MP	967.2	MT		H Line	BNF	Northwest	Engineer		
08-461466	3/9/2021	1:54 PM	14	54		Scott W Larson	110 Air Brake Tests/Inspections	C - Compliance	Running Brake Test				Mark E Blevins	MP	3065.5	MT		H Line	BNF	Northwest	Engineer		
08-461466	3/9/2021	1:28 PM	14	28		Scott W Larson	114 Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to reduce train speed for PSR.				Mark E Blevins	MP	3024.7	MT		H Line	BNF	Northwest	Engineer		
08-461469	3/9/2021	1:05 PM	15	5		Scott W Larson	302 Stop Signal	C - Compliance	Complied with Stop signal, W. Lehman				Mark E Blevins	MP	418.87	MT		Mik River	BNF	Northwest	Engineer		
08-461497	3/9/2021	4:20 PM	16	20		Scott W Larson	302 Stop Signal	C - Compliance	Complied with Stop signal E. Dodson.				Mark E Blevins	MP	309.7	MT		Mik River	BNF	Northwest	Engineer		
08-461498	3/9/2021	5:24 PM	17	24		Scott W Larson	308 Speed	C - Compliance	60 mph PSR				Mark E Blevins	MP	300.7	MT		M & R River	BNF	Northwest	Engineer		
08-461498	3/9/2021	7:59 PM	19	59		Scott W Larson	308 Speed	C - Compliance	40 mph PSR				Mark E Blevins	MP	126.5	ND		Glawag	BNF	Northwest	Engineer		
08-461498	3/9/2021	8:34 PM	20	34		Scott W Larson	114 Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake to control train speed on descending gra				Mark E Blevins	MP	97.2	ND		Glawag	BNF	Northwest	Engineer		
08-461499	3/9/2021	9:56 PM	21	56		Scott W Larson	308 Speed	C - Compliance	40 mph PSR				Mark E Blevins	MP	5.2	ND		Glawag	BNF	Northwest	Engineer		
08-461499	3/9/2021	9:49 PM	21	49		Scott W Larson	308 Speed	C - Compliance	60 mph PSR				Mark E Blevins	MP	11.2	ND		Glawag	BNF	Northwest	Engineer		
08-462333	2/5/2021	10:40 AM	10	40		Scott W Larson	117 Switches & Switching - Instructional	C - Compliance	Instructional review Sw tches and Switching				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-462337	2/5/2021	10:42 AM	10	42		Scott W Larson	118 Showing & Back-Up Moves - Instructional	C - Compliance	Instructional review Showing and Back-up Moves				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-462346	2/5/2021	10:38 AM	10	38		Scott W Larson	128 Drug & Alcohol	C - Compliance	Direct personal observation no use or possession of dru				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-462346	2/5/2021	10:47 AM	10	47		Scott W Larson	138 Pos Testing & Securing Unattended Equipment - Instructional	C - Compliance	Instructional review Pos Testing and Securing Unattende				Mark E Blevins	Location		ShelbyCrew MT	MT		H Line	BNF	Northwest	Engineer	
08-464539	1/5/2021	12:22 PM	12	22		Scott W Larson	301 Stopping within One-Half the Range of Vision	C - Compliance	Barmer test. St. Main Track Barndale Test				Mark E Blevins	MP	3036.1	MT		H Line	BNF	Northwest	Engineer		
08-464541	1/5/2021	12:19 PM	12	19		Scott W Larson	302 Stop Signal	C - Compliance	Complied with Main Track Barndale Test				Mark E Blevins	MP	3036.6	MT		H Line	BNF	Northwest	Engineer		
08-464541	1/5/2021	12:28 PM	12	28		Scott W Larson	307 Delayed in Block	C - Compliance	Complied with Delayed in Block rules after stopping in s				Mark E Blevins	MP	1035	MT		H Line	BNF	Northwest	Engineer		
08-464545	1/5/2021	12:24 PM	12	24		Scott W Larson	116 RWP Rules	C - Compliance	Prescribed whistle signal sounded in proximity to prope				Mark E Blevins	MP	1036	MT		H Line	BNF	Northwest	Engineer		
08-464547	1/5/2021	12:27 PM	12	27		Scott W Larson	122 Whistle/Red Flagging/Markers	C - Compliance	Whistle/Red/ sounded at prescribed location passing ovr				Mark E Blevins	MP	1035.87	MT		H Line	BNF	Northwest	Engineer		
08-464548	1/5/2021	12:26 PM	12	26		Scott W Larson	135 Electronic Devices	C - Compliance	Personal electronic devices off, stowed. Not observed o				Mark E Blevins	MP	3036.1	MT		H Line	BNF	Northwest	Engineer		
08-464550	1/5/20																						

08-4166765	8/5/2020	11:34 AM	11	34	Scott W Lanon	128 Drug & Alcohol	C - Compliance	Direct personal observation no possession or use of dru	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4166768	8/5/2020	11:20 AM	11	20	Scott W Lanon	341 Personal Protective Equipment	C - Compliance	In compliance with Amtrak facial coverings requirement	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4166783	8/6/2020	11:34 AM	11	34	Scott W Lanon	116 RWP Rules	C - Compliance	Compliance with approaching and entering working limits	Mark E Blavins	MP	1066.7	MT	H Line	BNSF	Northwest	8 Engineer
08-4166784	8/6/2020	11:31 AM	11	31	Scott W Lanon	119 Calling Signal/Restrictions	C - Compliance	Called Approach/Stop Flag by radio to train crew	Mark E Blavins	MP	1070.9	MT	H Line	BNSF	Northwest	8 Engineer
08-4166785	8/6/2020	11:12 AM	11	12	Scott W Lanon	120 Radio Procedures	C - Compliance	Observed proper radio use when communicating signals	Mark E Blavins	MP	1070.2	MT	H Line	BNSF	Northwest	8 Engineer
08-4166788	8/6/2020	11:12 AM	11	12	Scott W Lanon	119 Calling Signal/Restrictions	C - Compliance	Called Approach signal to train crew at Shelby Center	Mark E Blavins	MP	1066.9	MT	H Line	BNSF	Northwest	8 Engineer
08-4146556	7/34/2020	11:00 AM	11	00	Scott W Lanon	398 Employee Instruction	C - Compliance	AMT X 793 - 7.1 PTC Enforcement Follow-up	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	7 Engineer	
08-4102028	8/9/2020	10:30 AM	10	30	Scott W Lanon	117 Switches & Switching - Instructional	C - Compliance	Instructional review SW technique and dead switching	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4102032	8/9/2020	10:30 AM	10	35	Scott W Lanon	118 Showing & Back-Up Moves - Instructional	C - Compliance	Instructional review rules governing showing and back-u	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4080760	5/19/2020	11:30 AM	11	30	Scott W Lanon	306 Main Track Authority	C - Compliance	Proper authority to initiate Main Track movement at ore	Mark E Blavins	MP	1065.6	MT	H Line	BNSF	Northwest	8 Engineer
08-4072634	5/34/2020	11:20 AM	11	20	Scott W Lanon	306 Main Track Authority	C - Compliance	Compliance with rules regarding initiating Main Track m	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4072638	5/34/2020	11:00 AM	11	00	Scott W Lanon	139 Pos Positioning & Securing Unattended Equipment - Instructional	C - Compliance	Bringing equipment securement, positioning	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4072641	5/34/2020	11:15 AM	11	15	Scott W Lanon	341 Personal Protective Equipment	C - Compliance	Crew equipped with proper company issued personal pr	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4055140	5/5/2020	10:30 AM	10	30	Scott W Lanon	0PA2020-03 Operating Practice Advisory U/Hamiliar Conditions	C - Compliance	OPA 2020-03 briefing	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-4053466	5/1/2020	8:20 AM	8	20	Scott W Lanon	117 Switches & Switching - Instructional	C - Compliance	Instructional review of rules that govern the handling of	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	7 Engineer	
08-4053470	5/1/2020	8:25 AM	8	25	Scott W Lanon	118 Showing & Back-Up Moves - Instructional	C - Compliance	Instructional review of rules governing backup or showi	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	7 Engineer	
08-4053476	5/1/2020	8:36 AM	8	36	Scott W Lanon	128 Drug & Alcohol	C - Compliance	Direct personal observation no use or possession of dru	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	7 Engineer	
08-4053480	5/1/2020	9:02 AM	9	02	Scott W Lanon	135 Electronic Devices	C - Compliance	All personal electronic devices turned off and stored in	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	7 Engineer	
08-4053482	5/1/2020	8:38 AM	8	38	Scott W Lanon	139 Pos Positioning & Securing Unattended Equipment - Instructional	C - Compliance	Instructional review of rules that govern the positioning	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	7 Engineer	
08-4052574	5/1/2020	9:06 AM	9	06	Scott W Lanon	306 Main Track Authority	C - Compliance	Compliance with rules for occupying a main tra	Mark E Blavins	MP	1	NO	Gaigow	BNSF	Northwest	7 Engineer
08-4052578	5/1/2020	8:40 AM	8	40	Scott W Lanon	310 Job Briefings	C - Compliance	Qual ty job briefing while reporting for duty	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	7 Engineer	
08-4052494	4/30/2020	11:31 AM	11	31	Scott W Lanon	133 PRA 23a-23b Hands on Brake Test/Insp	C - Compliance	Class II brake test, direct observation	Mark E Blavins	MP	1065.6	MT	H Line	BNSF	Northwest	8 Engineer
08-4052541	4/30/2020	2:13 PM	14	13	Scott W Lanon	119 Calling Signal/Restrictions	C - Compliance	Conductor reminded engineer of upcoming form filing	Mark E Blavins	MP	409.4	MT	Mik River	BNSF	Northwest	8 Engineer
08-4052543	4/30/2020	2:15 PM	14	15	Scott W Lanon	120 Radio Procedures	C - Compliance	Crew complied with rules governing use of radio when c	Mark E Blavins	MP	409.4	MT	Mik River	BNSF	Northwest	8 Engineer
08-4052548	4/30/2020	2:19 PM	14	19	Scott W Lanon	116 RWP Rules	C - Compliance	Complied with white and bell requirements and comp	Mark E Blavins	MP	407.1	MT	Mik River	BNSF	Northwest	8 Engineer
08-4033040	4/23/2020	11:00 AM	11	00	Scott W Lanon	0PA2020-02 Operating Practice Advisory Improved Communication and CRM	C - Compliance	OPA 2020-02 briefing	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-3997688	3/18/2020	4:22 PM	36	22	Scott W Lanon	302 Stop Signal	C - Compliance	Train and engine crew complied with Stop signal at East	Mark E Blavins	MP	1034.5	MT	H Line	BNSF	Northwest	7 Engineer
08-3997691	3/18/2020	4:33 PM	36	33	Scott W Lanon	307 Delayed in Back	C - Compliance	Train and engine crew complied with rule governing fu	Mark E Blavins	MP	1035.3	MT	H Line	BNSF	Northwest	7 Engineer
08-3997693	3/18/2020	4:21 PM	36	21	Scott W Lanon	119 Calling Signal/Restrictions	C - Compliance	Train and engine crew complied with rules regarding engi	Mark E Blavins	MP	1034.5	MT	H Line	BNSF	Northwest	7 Engineer
08-3997719	3/18/2020	4:29 PM	36	29	Scott W Lanon	301 Stopping within One-Half the Range of Vision	C - Compliance	Train stopped within Main Track Brake Test	Mark E Blavins	MP	1035.5	MT	H Line	BNSF	Northwest	7 Engineer
08-3997722	3/18/2020	4:31 PM	36	31	Scott W Lanon	116 RWP Rules	C - Compliance	Sounded bell/white as prescribed in proximity to prep	Mark E Blavins	MP	1035.7	MT	H Line	BNSF	Northwest	7 Engineer
08-3997725	3/18/2020	4:32 PM	36	32	Scott W Lanon	122 White/Bell/Headlight/Markers	C - Compliance	White/bell sounded at prescribed location	Mark E Blavins	MP	1035.87	MT	H Line	BNSF	Northwest	7 Engineer
08-398620	3/3/2020	11:00 AM	11	00	Scott W Lanon	398 Employee Instruction	I - Failure, verbal counseling	Discussed unusual PTC Enforcement Follow-up	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-3986209	3/3/2020	12:58 PM	12	58	Scott W Lanon	308 Speed	C - Compliance	FAST Act 55 mph FAST Act	Mark E Blavins	MP	967.2	MT	H Line	BNSF	Northwest	8 Engineer
08-3986331	3/3/2020	11:33 AM	11	33	Scott W Lanon	110 Air Brake Tests/Inspections	C - Compliance	Running brake test	Mark E Blavins	MP	1065.5	MT	H Line	BNSF	Northwest	8 Engineer
08-3986333	3/3/2020	11:35 AM	11	35	Scott W Lanon	122 White/Bell/Headlight/Markers	C - Compliance	Sounded bell/white at prescribed location	Mark E Blavins	MP	1064.7	MT	H Line	BNSF	Northwest	8 Engineer
08-3986352	3/3/2020	1:28 PM	13	28	Scott W Lanon	308 Speed	C - Compliance	65 mph PSR	Mark E Blavins	MP	107.7	MT	Mik River	BNSF	Northwest	8 Engineer
08-398637	3/3/2020	1:25 PM	13	25	Scott W Lanon	122 White/Bell/Headlight/Markers	C - Compliance	Sounded bell/white at prescribed location	Mark E Blavins	MP	429.2	MT	Mik River	BNSF	Northwest	8 Engineer
08-398638	3/3/2020	1:42 PM	13	42	Scott W Lanon	134 Train Handling/Fuel/Energy Conservation	C - Compliance	Blended brake to slow train	Mark E Blavins	MP	226.6	MT	Gaigow	BNSF	Northwest	8 Engineer
08-398640	3/3/2020	1:46 PM	13	46	Scott W Lanon	308 Speed	C - Compliance	65 mph PSR	Mark E Blavins	MP	213.5	MT	Gaigow	BNSF	Northwest	8 Engineer
08-398642	3/3/2020	1:52 PM	13	52	Scott W Lanon	308 Speed	C - Compliance	55 mph PSR	Mark E Blavins	MP	113.4	NO	Gaigow	BNSF	Northwest	8 Engineer
08-398644	3/3/2020	1:40 PM	13	40	Scott W Lanon	134 Train Handling/Fuel/Energy Conservation	C - Compliance	Dynamic brake to control speed down hill	Mark E Blavins	MP	95.5	NO	Gaigow	BNSF	Northwest	8 Engineer
08-398646	3/3/2020	1:58 PM	13	58	Scott W Lanon	308 Speed	C - Compliance	60 mph PSR	Mark E Blavins	MP	11.2	NO	Gaigow	BNSF	Northwest	8 Engineer
08-3947522	2/7/2020	8:07 AM	8	07	Scott W Lanon	FAST Act 40 mph FAST Act	C - Compliance	FAST Act 40 mph FAST Act	Mark E Blavins	MP	1208.9	MT	H Line	BNSF	Northwest	8 Engineer
08-3947523	2/7/2020	7:52 AM	7	52	Scott W Lanon	110 Air Brake Tests/Inspections	C - Compliance	Running brake test	Mark E Blavins	MP	1239.1	MT	Kootenai River	BNSF	Northwest	8 Engineer
08-394754	2/7/2020	8:33 AM	8	33	Scott W Lanon	122 White/Bell/Headlight/Markers	C - Compliance	Sounded bell/white at prescribed location	Mark E Blavins	MP	1204.24	MT	H Line	BNSF	Northwest	8 Engineer
08-394755	2/7/2020	8:50 AM	8	50	Scott W Lanon	308 Speed	C - Compliance	45 mph PSR	Mark E Blavins	MP	117.7	MT	H Line	BNSF	Northwest	8 Engineer
08-394756	2/7/2020	8:20 AM	8	20	Scott W Lanon	134 Train Handling/Fuel/Energy Conservation	C - Compliance	Dynamic brake to slow for station stop WGL	Mark E Blavins	MP	1197.5	MT	H Line	BNSF	Northwest	8 Engineer
08-394756	2/7/2020	9:47 AM	9	47	Scott W Lanon	308 Speed	C - Compliance	25 mph TSR	Mark E Blavins	MP	1147.4	MT	H Line	BNSF	Northwest	8 Engineer
08-394759	2/7/2020	9:44 AM	9	44	Scott W Lanon	134 Train Handling/Fuel/Energy Conservation	C - Compliance	Dynamic brake to control speed on descending grade	Mark E Blavins	MP	1149	MT	H Line	BNSF	Northwest	8 Engineer
08-394757	2/7/2020	9:38 AM	9	38	Scott W Lanon	308 Speed	C - Compliance	FAST Act 55 mph FAST Act	Mark E Blavins	MP	1122.7	MT	H Line	BNSF	Northwest	8 Engineer
08-394756	2/7/2020	9:43 AM	9	43	Scott W Lanon	308 Speed	C - Compliance	FAST Act 50 mph FAST Act	Mark E Blavins	MP	1095	MT	H Line	BNSF	Northwest	8 Engineer
08-394757	2/7/2020	10:30 AM	10	30	Scott W Lanon	122 White/Bell/Headlight/Markers	C - Compliance	Sounded bell/white at prescribed location	Mark E Blavins	MP	1090	MT	H Line	BNSF	Northwest	8 Engineer
08-3918867	1/23/2020	12:20 PM	12	20	Scott W Lanon	301 Stopping within One-Half the Range of Vision	C - Compliance	Joint test with JO NT	Mark E Blavins	MP	1036.1	MT	H Line	BNSF	Northwest	8 Engineer
08-3918871	1/23/2020	12:16 PM	12	16	Scott W Lanon	302 Stop Signal	C - Compliance	Joint test with JO NT	Mark E Blavins	MP	1036.7	MT	H Line	BNSF	Northwest	8 Engineer
08-391886	1/23/2020	12:23 PM	12	23	Scott W Lanon	307 Delayed in Back	C - Compliance	Joint test with JO NT	Mark E Blavins	MP	1035.5	MT	H Line	BNSF	Northwest	8 Engineer
08-3918920	1/23/2020	12:18 PM	12	18	Scott W Lanon	119 Calling Signal/Restrictions	C - Compliance	Joint test with JO NT	Mark E Blavins	MP	1035.5	MT	H Line	BNSF	Northwest	8 Engineer
08-3918922	1/23/2020	12:23 PM	12	23	Scott W Lanon	120 Radio Procedures	C - Compliance	Crew complied JO NT	Mark E Blavins	MP	1035.5	MT	H Line	BNSF	Northwest	8 Engineer
08-3920798	1/23/2020	12:16 PM	12	16	Scott W Lanon	302 Stop Signal	C - Compliance	Radio stop at W. Lohair	Mark E Blavins	MP	1036.86	MT	H Line	BNSF	Northwest	8 Engineer
08-3920803	1/23/2020	11:46 AM	11	46	Scott W Lanon	110 Air Brake Tests/Inspections	C - Compliance	Running brake test	Mark E Blavins	MP	1055.49	MT	H Line	BNSF	Northwest	8 Engineer
08-3920802	1/23/2020	11:46 AM	11	46	Scott W Lanon	122 White/Bell/Headlight/Markers	C - Compliance	Sounded bell/white at prescribed location	Mark E Blavins	MP	1055.58	MT	H Line	BNSF	Northwest	8 Engineer
08-3920820	1/23/2020	1:29 PM	13	29	Scott W Lanon	308 Speed	C - Compliance	FAST Act 55 mph FAST Act	Mark E Blavins	MP	967.2	MT	H Line	BNSF	Northwest	8 Engineer
08-3920823	1/23/2020	1:57 PM	13	57	Scott W Lanon	308 Speed	C - Compliance	10 mph TSR	Mark E Blavins	MP	429.7	MT	Mik River	BNSF	Northwest	8 Engineer
08-3920825	1/23/2020	1:05 PM	13	05	Scott W Lanon	134 Train Handling/Fuel/Energy Conservation	C - Compliance	Blended brake to station stop MW	Mark E Blavins	MP	344.7	MT	Mik River	BNSF	Northwest	8 Engineer
08-392084	1/23/2020	1:16 PM	13	16	Scott W Lanon	308 Speed	C - Compliance	65 mph PSR	Mark E Blavins	MP	213.5	MT	Gaigow	BNSF	Northwest	8 Engineer
08-3920851	1/23/2020	1:59 PM	13	59	Scott W Lanon	134 Train Handling/Fuel/Energy Conservation	C - Compliance	Dynamic brake to control speed on descending grade	Mark E Blavins	MP	97.4	NO	Gaigow	BNSF	Northwest	8 Engineer
08-3920853	1/23/2020	1:17 PM	13	17	Scott W Lanon	308 Speed	C - Compliance	65 mph PSR	Mark E Blavins	MP	76.5	NO	Gaigow	BNSF	Northwest	8 Engineer
08-3920855	1/23/2020	1:13 PM	13	13	Scott W Lanon	308 Speed	C - Compliance	60 mph PSR	Mark E Blavins	MP	11.2	NO	Gaigow	BNSF	Northwest	8 Engineer
08-3923430	1/23/2020	1:22 PM	13	22	Scott W Lanon	116 RWP Rules	C - Compliance	White/bell sounded in proximity to roadway workers	Mark E Blavins	MP	1036.1	MT	H Line	BNSF	Northwest	8 Engineer
08-3967967	12/18/2019	11:59 AM	11	59	Scott W Lanon	123 Engineer Certificate	C - Compliance	Current Cert in possession	Mark E Blavins	Location	ShelbyCrew MT	H Line	BNSF	Northwest	8 Engineer	
08-3967994																

08-373858	9/26/2019	10:45 AM	30	45	Scott Wilson	121	Required Documents	C - Compliance	BC-19	k E Blevins	Location	Shelby Crew	MT	H Line	BNSF	Northwest	Engineer
08-373832	9/26/2019	7:00 PM	19	0	Scott Wilson	135	Electronic Devices	C - Compliance	No use of electronic devices.	k E Blevins	MP	1180	MT	H Line	BNSF	Northwest	7 Engineer
08-373832	9/26/2019	7:21 PM	19	21	Scott Wilson	305	Other Signal Indications	C - Compliance	App Med to Div Clear, complied with 35 mph crossover	k E Blevins	MP	1108.3	MT	H Line	BNSF	Northwest	7 Engineer
08-373766	8/26/2019	4:57 AM	17	17	Scott Wilson	128	Drug & Alcohol	C - Compliance	Complied with 35 mph PSR	k E Blevins	Location	Shelby Crew	MT	H Line	BNSF	Northwest	8 Engineer
08-373763	8/26/2019	4:45 PM	16	45	Scott Wilson	124	Emergency Preparedness	C - Compliance	Q Test, Discussed emergency equipment, PPP's and non	k E Blevins	Location	Shelby Crew	MT	H Line	BNSF	Northwest	Engineer
08-373450	8/26/2019	4:45 PM	16	45	Scott Wilson	198	Employee Instruction	C - Compliance	BBP-2019	k E Blevins	Location	Shelby Stat	MT	H Line	BNSF	Northwest	Engineer
08-371839	8/26/2019	6:28 PM	18	28	Scott Wilson	308	Speed	C - Compliance	Complied with 30 mph TSR	k E Blevins	MP	1068.3	MT	H Line	BNSF	Northwest	7 Engineer
08-371834	8/26/2019	6:23 PM	18	21	Scott Wilson	110	Air Brake Tests/Inspections	C - Compliance	Running brake test approaching Summit	k E Blevins	MP	1066.9	MT	H Line	BNSF	Northwest	7 Engineer
08-371835	8/26/2019	7:12 PM	19	12	Scott Wilson	308	Speed	C - Compliance	Complied with 55 mph PSR	k E Blevins	MP	1266.16	MT	H Line	BNSF	Northwest	7 Engineer
08-371836	8/26/2019	7:17 PM	19	17	Scott Wilson	308	Speed	C - Compliance	Complied with FAST Act	k E Blevins	MP	1111.4	MT	H Line	BNSF	Northwest	7 Engineer
08-371837	8/26/2019	7:26 PM	19	26	Scott Wilson	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake/fuel conservation	k E Blevins	MP	1120.87	MT	H Line	BNSF	Northwest	7 Engineer
08-371840	8/26/2019	8:08 PM	21	8	Scott Wilson	308	Speed	C - Compliance	Complied with FAST Act	k E Blevins	MP	1188.2	MT	H Line	BNSF	Northwest	7 Engineer
08-371840	8/26/2019	8:34 PM	20	34	Scott Wilson	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Running brake test approaching Summit	k E Blevins	MP	1148.3	MT	H Line	BNSF	Northwest	7 Engineer
08-371840	8/26/2019	8:34 PM	21	34	Scott Wilson	134	Train Handling/Fuel-Energy Conservation	C - Compliance	Dynamic brake on decelerating grade	k E Blevins	MP	1163.5	MT	H Line	BNSF	Northwest	7 Engineer
08-371841	8/26/2019	8:32 PM	21	32	Scott Wilson	308	Speed	C - Compliance	Complied with 55 mph PSR	k E Blevins	MP	1204.4	MT	H Line	BNSF	Northwest	7 Engineer
08-371841	8/26/2019	9:28 PM	21	28	Scott Wilson	122	White/Bell Height/Markers	C - Compliance	White/bell sounded at preselected location	k E Blevins	MP	1200.9	MT	H Line	BNSF	Northwest	7 Engineer
08-361539	6/29/2019	10:48 PM	22	48	Scott Wilson	128	Drug & Alcohol	C - Compliance	direct personal observation	John F Alspach	MP	1056.4	MT	H Line	BNSF	Northwest	8 Engineer
08-361545	6/29/2019	11:12 AM	11	12	Scott Wilson	130	Job Briefings	C - Compliance	Quality Job Briefing	John F Alspach	MP	1056.4	MT	H Line	BNSF	Northwest	7 Engineer
08-361551	6/29/2019	10:56 AM	10	56	Scott Wilson	130	Employee Instruction	C - Compliance	Summer Safety 8 & 2019	John F Alspach	MP	1056.4	MT	H Line	BNSF	Northwest	8 Engineer
08-354842	5/2/2019	9:32 AM	9	32	Scott Wilson	305	Other Signal Indications	C - Compliance	COMPLIED WITH A DIVERGING ROUTE SIGNAL ATPC203	ty M McCants	MP	26.1	NO	Gaigow	BNSF	Northwest	7 Engineer
08-354843	5/2/2019	9:12 AM	9	12	Scott Wilson	308	Speed	C - Compliance	COMPLIED WITH A 40 MPH PSR.	ty M McCants	MP	4.6	NO	Gaigow	BNSF	Northwest	7 Engineer
08-354844	5/2/2019	9:06 AM	9	6	Scott Wilson	110	Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	ty M McCants	MP	0.9	NO	Gaigow	BNSF	Northwest	7 Engineer
08-354845	5/2/2019	9:29 AM	9	29	Scott Wilson	122	White/Bell Height/Markers	C - Compliance	PROPER HORN AND BELL AT A ROAD CROSSING	ty M McCants	MP	22.4	NO	Gaigow	BNSF	Northwest	7 Engineer
08-354846	5/2/2019	10:30 AM	10	30	Scott Wilson	134	Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO SLOW TRAIN SPEED	ty M McCants	MP	71.6	NO	Gaigow	BNSF	Northwest	7 Engineer
08-354848	5/2/2019	10:54 AM	10	54	Scott Wilson	308	Speed	C - Compliance	COMPLD WIT FAST ACT	ty M McCants	MP	111.5	NO	Gaigow	BNSF	Northwest	7 Engineer
08-354855	5/2/2019	11:02 AM	11	2	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 55 MPH PSR.	ty M McCants	MP	139.2	NO	Gaigow	BNSF	Northwest	7 Engineer
08-354863	5/2/2019	2:16 PM	14	16	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 50 MPH PSR.	ty M McCants	MP	296.3	MT	M & River	BNSF	Northwest	7 Engineer
08-354865	5/2/2019	2:19 PM	14	19	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 30 MPH PSR.	ty M McCants	MP	299.1	MT	M & River	BNSF	Northwest	7 Engineer
08-354866	5/2/2019	4:12 PM	15	12	Scott Wilson	308	Speed	C - Compliance	COMPLD WIT FAST ACT	ty M McCants	MP	428	MT	MIR RIVER	BNSF	Northwest	7 Engineer
08-355187	5/1/2019	11:05 AM	11	5	Scott Wilson	130	Job Briefings	C - Compliance	CONDUCTED A DETAILED, SAFETY FOCUSED JOBBRIE	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-356548	4/26/2019	10:15 AM	10	15	Scott Wilson	121	Required Documents	C - Compliance	PASSED BOOK CHECK	Jeff S Lacey	Location	Portland Ce OR		H Line	BNSF	Northwest	CLASS Engineer
08-348843	2/28/2019	5:32 PM	17	32	Scott Wilson	OPA2019-01	Operating Practices Advisory Review - Restricted Speed	C - Compliance		ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	7 Engineer
08-348833	2/28/2019	9:17 AM	9	17	Scott Wilson	308	Speed	C - Compliance	COMPLIED WITH A 40MPH PSR.	ty M McCants	MP	4.6	NO	Gaigow	BNSF	Northwest	7 Engineer
08-348834	2/28/2019	9:12 AM	9	12	Scott Wilson	110	Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	ty M McCants	MP	0.7	NO	Gaigow	BNSF	Northwest	7 Engineer
08-348835	2/28/2019	10:44 AM	10	44	Scott Wilson	134	Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO CONTROL TRAIN S	ty M McCants	MP	105.1	NO	Gaigow	BNSF	Northwest	7 Engineer
08-348844	2/28/2019	10:50 AM	10	50	Scott Wilson	308	Speed	C - Compliance	COMPLD WIT FAST ACT	ty M McCants	MP	111.5	NO	Gaigow	BNSF	Northwest	7 Engineer
08-348845	2/28/2019	11:23 AM	11	23	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 40MPH PSR.	ty M McCants	MP	128.8	NO	Gaigow	BNSF	Northwest	7 Engineer
08-348847	2/28/2019	11:50 AM	11	50	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 55MPH PSR.	ty M McCants	MP	192	MT	Gaigow	BNSF	Northwest	7 Engineer
08-348848	2/28/2019	12:06 PM	12	6	Scott Wilson	305	Other Signal Indications	C - Compliance	Complied with a diverging route signal at E. Brocton.	ty M McCants	MP	191.7	MT	Gaigow	BNSF	Northwest	7 Engineer
08-348896	2/28/2019	1:53 PM	13	53	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 10MPH PSR.	ty M McCants	MP	277.1	MT	Gaigow	BNSF	Northwest	7 Engineer
08-348898	2/28/2019	2:30 PM	14	20	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 40MPH PSR.	ty M McCants	MP	293.1	MT	M & River	BNSF	Northwest	7 Engineer
08-348899	2/28/2019	4:08 PM	15	9	Scott Wilson	308	Speed	C - Compliance	COMPLD WIT FAST ACT	ty M McCants	MP	428	MT	MIR RIVER	BNSF	Northwest	7 Engineer
08-341658	1/14/2019	11:25 AM	11	25	Scott Wilson	128	Drug & Alcohol	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUE	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-341654	1/14/2019	11:15 AM	11	15	Scott Wilson	130	Job Briefings	C - Compliance	DETAILED SAFETY FOCUSED JOB BRIEFING.	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-337510	12/30/2018	11:30 AM	11	30	Scott Wilson	133	PRA 232+238 Hands on Brake Test/Insp	C - Compliance	PROPER CLASS A BRAKE TEST AT E.SHELW.	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-337518	12/30/2018	10:30 AM	10	30	Scott Wilson	117	Switches & Switching - Instructional	C - Compliance		ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-337518	12/30/2018	10:50 AM	10	50	Scott Wilson	118	Shoving & Back-Up Moves - Instructional	C - Compliance		ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-337517	12/30/2018	11:00 AM	11	0	Scott Wilson	124	Emergency Preparedness	C - Compliance	EP DISCUSSION.	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-337517	12/30/2018	10:50 AM	10	50	Scott Wilson	138	Positioning & Securing Unattended Equipment - Instructional	C - Compliance		ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-337514	12/30/2018	11:09 AM	11	5	Scott Wilson	135	Electronic Devices	C - Compliance	CELLPHONE OFF AND STOWED.	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-332657	10/26/2018	10:50 AM	10	50	Scott Wilson	198	Employee Instruction	C - Compliance	PNW STAND DOWN 19-1	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-332657	10/26/2018	10:55 AM	10	55	Scott Wilson	OPA2018-05	Operating Practices Advisory Review - Detachments	C - Compliance		ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-331656	10/25/2018	10:50 AM	10	50	Scott Wilson	198	Employee Instruction	C - Compliance	PNW STAND DOWN 19-1	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-331657	10/25/2018	10:50 AM	10	50	Scott Wilson	OPA2018-05	Operating Practices Advisory Review - Detachments	C - Compliance		ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-221569	10/11/2018	11:15 AM	11	15	Scott Wilson	128	Drug & Alcohol	C - Compliance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUE	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-221568	10/11/2018	11:30 AM	11	30	Scott Wilson	130	Job Briefings	C - Compliance	DETAILED SAFETY FOCUSED JOB BRIEFING.	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-331674	10/11/2018	11:32 PM	12	32	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 50MPH PSR.	ty M McCants	MP	1058.6	MT	H Line	BNSF	Northwest	8 Engineer
08-331674	10/11/2018	12:25 PM	12	25	Scott Wilson	110	Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	ty M McCants	MP	1065.5	MT	H Line	BNSF	Northwest	8 Engineer
08-331685	10/11/2018	1:57 PM	13	57	Scott Wilson	308	Speed	C - Compliance	COMPLD WIT FAST ACT.	ty M McCants	MP	967.2	MT	H Line	BNSF	Northwest	8 Engineer
08-331685	10/11/2018	3:44 PM	13	44	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 60MPH PSR.	ty M McCants	MP	130.8	MT	M & River	BNSF	Northwest	8 Engineer
08-331687	10/11/2018	5:55 PM	15	55	Scott Wilson	305	Other Signal Indications	C - Compliance	COMPLD WITH AN APPROACH SIGNAL AT W. SACO.	ty M McCants	MP	139.2	MT	MIR RIVER	BNSF	Northwest	8 Engineer
08-331689	10/11/2018	6:23 PM	15	23	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 25MPH PSR.	ty M McCants	MP	190.6	MT	Gaigow	BNSF	Northwest	8 Engineer
08-331651	10/11/2018	8:16 PM	20	16	Scott Wilson	302	Stop Signal	C - Compliance	COMPLD WITH A STOP SIGNAL AT CP&E.	ty M McCants	MP	86	NO	Gaigow	BNSF	Northwest	8 Engineer
08-331658	10/11/2018	8:23 PM	21	23	Scott Wilson	134	Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO CONTROL TRAIN S	ty M McCants	MP	24.2	NO	Gaigow	BNSF	Northwest	8 Engineer
08-331655	10/11/2018	8:40 PM	21	40	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 40MPH PSR.	ty M McCants	MP	5.2	NO	Gaigow	BNSF	Northwest	8 Engineer
08-216819	9/20/2018	11:26 AM	11	25	Scott Wilson	198	Employee Instruction	C - Compliance	QPS 2018047 Prepared to Stop	ty M McCants	MP	1065.7	MT	H Line	BNSF	Northwest	8 Engineer
08-216839	8/15/2018	10:15 AM	10	15	Scott Wilson	121	Required Documents	C - Compliance	passed book check	Jeff S Lacey	Location	Portland Ce OR		H Line	BNSF	Northwest	class Engineer
08-216839	7/19/2018	12:04 PM	12	4	Scott Wilson	110	Air Brake Tests/Inspections	C - Compliance	PROPER RUNNING BRAKE TEST.	ty M McCants	MP	1066.3	MT	H Line	BNSF	Northwest	8 Engineer
08-216840	7/19/2018	12:19 PM	12	19	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 25MPH PSR.	ty M McCants	MP	1048.7	MT	H Line	BNSF	Northwest	8 Engineer
08-216841	7/19/2018	1:01 PM	13	1	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 30MPH PSR.	ty M McCants	MP	1024.2	MT	H Line	BNSF	Northwest	8 Engineer
08-216840	7/19/2018	1:32 PM	13	32	Scott Wilson	308	Speed	C - Compliance	COMPLD WIT FAST ACT.	ty M McCants	MP	967.2	MT	H Line	BNSF	Northwest	8 Engineer
08-216851	7/19/2018	2:48 PM	14	48	Scott Wilson	302	Stop Signal	C - Compliance	COMPLD WITH A STOP SIGNAL AT CP&E.	ty M McCants	MP	386.9	MT	H Line	BNSF	Northwest	8 Engineer
08-216853	7/19/2018	6:45 PM	16	45	Scott Wilson	305	Other Signal Indications	C - Compliance	COMPLD WITH A DIVERGING APPROACH SIGNAL AT W.	ty M McCants	MP	238.4	MT	H Line	BNSF	Northwest	8 Engineer
08-216855	7/19/2018	2:42 PM	14	42	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 20MPH PSR.	ty M McCants	MP	388.3	MT	H Line	BNSF	Northwest	8 Engineer
08-216858	7/19/2018	6:53 PM	16	51	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 35MPH PSR.	ty M McCants	MP	139.2	MT	Gaigow	BNSF	Northwest	8 Engineer
08-216860	7/19/2018	11:08 PM	23	8	Scott Wilson	134	Train Handling/Fuel-Energy Conservation	C - Compliance	PROPER USE OF DYNAMIC BRAKE TO CONTROL TRAIN S	ty M McCants	MP	26.7	MT	Gaigow	BNSF	Northwest	8 Engineer
08-216876	7/19/2018	11:24 PM	23	24	Scott Wilson	308	Speed	C - Compliance	COMPLD WITH A 40MPH PSR.	ty M McCants	MP	5.2	NO	Ga			

08-210501	7/6/2018	12:00 PM	12	0	9	Dennis W Richter	130 Job Briefings	C= Comp lance	EMPLOYEE CONDUCTED A DETAILED, SAFETY FOCUSED	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	8	Assistant Conductor
08-123648	6/5/2018	6:02 PM	18	2	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED SIGNAL AT CUT BANK EAST.	By M McCants	MP	1088	MT	CUT	GCOR	Northwest	7	Assistant Conductor
08-123548	6/5/2018	8:05 PM	20	5	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED DIVERE NO CLEAR SIGNAL AT INOLA	By M McCants	MP	1177.5	MT	BSM	GCOR	Northwest	7	Assistant Conductor
08-123887	6/1/2018	2:18 PM	14	18	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED APPROACH SIGNAL AT BURINHAM	By M McCants	MP	998.7	MT	HAV	GCOR	Northwest	8	Assistant Conductor
08-123584	5/31/2018	12:45 AM	0	45	9	Dennis W Richter	130 Job Briefings	C= Comp lance	FAST Act Quality In depth detail ed job briefing, emphasis	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	8	Assistant Conductor
08-123704	5/31/2018	12:40 AM	0	40	9	Dennis W Richter	128 Drug & Alcohol	C= Comp lance	Direct personal observation.	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	8	Assistant Conductor
08-123708	5/31/2018	12:40 AM	0	40	9	Dennis W Richter	135 FRA Emergency Order 26 - Electronic Devices	C= Comp lance	Employees had all personal electronic devices turned off	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	8	Assistant Conductor
08-123588	5/30/2018	1:46 AM	1	46	9	Dennis W Richter	139 Positioning & Securing Unattended Equipment	C= Comp lance	TST 139 Properly secured equipment, AMT-3 3.5.7	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	7	Assistant Conductor
08-120291	5/10/2018	9:15 AM	9	15	9	Dennis W Richter	121 Required Documents	C= Comp lance	Passed book check	Jul S Lacey	MP	0	OR	POX	GCOR	Northwest	Class	Assistant Conductor
08-119732	5/4/2018	12:28 PM	12	28	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED A FORM B AHEAD.	By M McCants	MP	1049.2	MT	SBY	GCOR	Northwest	8	Assistant Conductor
08-119739	5/4/2018	12:31 PM	12	31	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED A 30MIN TDR.	By M McCants	MP	1047.6	MT	SBY	GCOR	Northwest	8	Assistant Conductor
08-117818	4/17/2018	5:50 PM	17	50	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED THE SIGNAL AT CUT BANK EAST.	By M McCants	MP	1088	MT	CUT	GCOR	Northwest	7	Assistant Conductor
08-116978	4/10/2018	4:45 PM	16	45	9	Dennis W Richter	198 Employee Instruction	C= Comp lance	PTC OBSERVATION	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	7	Assistant Conductor
08-1150749	3/27/2018	4:50 PM	16	50	9	Dennis W Richter	198 Employee Instruction	C= Comp lance	OPA-1-18 Situational Awareness & Communication	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	7	Assistant Conductor
08-114608	3/2/2018	12:40 AM	0	40	9	Dennis W Richter	128 Drug & Alcohol	C= Comp lance	Direct personal observation, employees in comp lance v	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	8	Assistant Conductor
08-114602	3/2/2018	12:43 AM	0	43	9	Dennis W Richter	135 FRA Emergency Order 26 - Electronic Devices	C= Comp lance	Employees had all personal electronic devices turned off	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	8	Assistant Conductor
08-114606	3/2/2018	12:45 AM	0	45	9	Dennis W Richter	130 Job Briefings	C= Comp lance	FAST Act Quality, in depth detail oriented job briefing, E	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	8	Assistant Conductor
08-112730	3/8/2018	12:40 AM	0	40	9	Dennis W Richter	130 Job Briefings	C= Comp lance	FAST Act Quality, in depth detail oriented job briefing, E	hen E Alpaugh	MP	71.6	WA	SPK	Amtrak	Northwest	8	Assistant Conductor
08-109419	1/14/2018	4:50 PM	16	50	9	Dennis W Richter	130 Job Briefings	C= Comp lance	501 SAFETY TANDOWN	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	7	Assistant Conductor
08-108427	1/14/2018	5:00 PM	17	0	9	Dennis W Richter	128 Drug & Alcohol	C= Comp lance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	7	Assistant Conductor
08-104846	12/28/2017	11:39 AM	11	39	9	Dennis W Richter	135 FRA Emergency Order 26 - Electronic Devices	C= Comp lance	CELL PHONE OFF AND 5 TOWARD	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	8	Assistant Conductor
08-102506	12/13/2017	5:40 PM	17	40	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED APPROACH MEDIUM SIGNAL AT MP 1	By M McCants	MP	1083.1	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-102550	12/13/2017	6:58 PM	18	58	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED THE SIGNAL AT SUMMIT.	By M McCants	MP	1148.7	MT	XBM	GCOR	Northwest	7	Assistant Conductor
08-98378	1/17/2017	5:00 PM	17	0	9	Dennis W Richter	198 Employee Instruction	C= Comp lance	TST 139 1.39	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	7	Assistant Conductor
08-97476	10/7/2017	11:30 AM	11	30	9	Dennis W Richter	133 FRA 212.238 Hands on Brake Test/Trp	C= Comp lance	PROPER CLASS 1 BRAKE TEST.	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	8	Assistant Conductor
08-96878	10/6/2017	11:30 AM	11	20	9	Dennis W Richter	689 Emergency Preparedness	C= Comp lance	689 DISCUSSION	By M McCants	MP	1080	MT	CUT	Amtrak	Northwest	8	Assistant Conductor
08-96873	10/6/2017	11:30 AM	11	20	9	Dennis W Richter	120 Radio Procedures	C= Comp lance	PROPER RADIO PROCEDURE WORKING CUT BANK STAT	By M McCants	MP	1080	MT	CUT	GCOR	Northwest	8	Assistant Conductor
08-96891	10/6/2017	11:25 AM	11	25	9	Dennis W Richter	198 Employee Instruction	C= Comp lance	TST 11 7/18 1.17/118	By M McCants	MP	1088	MT	CUT	Amtrak	Northwest	8	Assistant Conductor
08-96870	10/4/2017	8:56 PM	20	56	9	Dennis W Richter	130 Job Briefings	C= Comp lance	Quality, in depth detail oriented job briefing	hen E Alpaugh	MP	1219.4	MT	WFH	BNP	Northwest	7	Assistant Conductor
08-93688	9/16/2017	5:20 PM	17	20	9	Dennis W Richter	120 Radio Procedures	C= Comp lance	PROPER RADIO PROCEDURE WHILE WORKING SHELBY	By M McCants	MP	1065.7	MT	SBY	Amtrak	Northwest	7	Assistant Conductor
08-93675	9/16/2017	7:02 PM	19	2	9	Dennis W Richter	135 FRA Emergency Order 26 - Electronic Devices	C= Comp lance	CELL PHONE OFF AND 5 TOWARD.	By M McCants	MP	1148.9	MT	XBM	Amtrak	Northwest	7	Assistant Conductor
08-84404	7/5/2017	4:45 PM	16	45	9	Dennis W Richter	128 Drug & Alcohol	C= Comp lance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-84475	7/5/2017	5:05 PM	17	5	9	Dennis W Richter	130 Job Briefings	C= Comp lance	EMPLOYEE CONDUCTED A SAFETY FOCUS JOB BRIEF	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-78004	5/10/2017	5:05 PM	17	5	9	Dennis W Richter	130 Job Briefings	C= Comp lance	DET A LED, SAFETY FOCUSED JOB BRIEFING	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-78008	5/10/2017	5:07 PM	17	7	9	Dennis W Richter	198 Employee Instruction	C= Comp lance	NO 017-02 ELECTRONIC DEVICE DISTRACTIONS	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-78012	5/10/2017	5:10 PM	17	10	9	Dennis W Richter	199 All Other Tests or Observation	C= Comp lance	DISCUSSED THE IMPORTANCE OF WATCHING THE STATI	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-77259	5/5/2017	7:35 AM	7	35	9	Dennis W Richter	135 FRA Emergency Order 26 - Electronic Devices	C= Comp lance	CELL PHONE OFF AND 5 TOWARD.	By M McCants	MP	1254	MT	LIB	Amtrak	Northwest	8	Assistant Conductor
08-77232	5/5/2017	8:30 AM	8	30	9	Dennis W Richter	198 Employee Instruction	C= Comp lance	NO 017-02 ELECTRONIC DEVICE DISTRACTIONS	By M McCants	MP	1219	MT	WFH	Amtrak	Northwest	8	Assistant Conductor
08-77235	5/5/2017	8:32 AM	8	32	9	Dennis W Richter	130 Job Briefings	C= Comp lance	DET A LED SAFETY BRIEFING AT WFH.	By M McCants	MP	1219	MT	WFH	GCOR	Northwest	8	Assistant Conductor
08-77238	5/5/2017	8:35 AM	8	35	9	Dennis W Richter	128 Drug & Alcohol	C= Comp lance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	By M McCants	MP	1219	MT	WFH	GCOR	Northwest	8	Assistant Conductor
08-77292	5/5/2017	9:17 AM	9	17	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED DIVERGING ROUTE SIGNAL.	By M McCants	MP	1188	MT	XRL	GCOR	Northwest	8	Assistant Conductor
08-72845	3/24/2017	10:00 AM	10	0	9	Dennis W Richter	121 Required Documents	C= Comp lance	Book and manual check for training class.	Jul S Lacey	MP	0	OR	POX	GCOR	Northwest	Class	Assistant Conductor
08-67373	1/28/2017	11:35 AM	11	35	9	Dennis W Richter	130 Job Briefings	C= Comp lance	PROPER SAFETY AND JOB BRIEFING	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	Class	Assistant Conductor
08-67011	1/18/2017	5:15 PM	17	15	9	Dennis W Richter	130 Job Briefings	C= Comp lance	DET A LED, SAFETY FOCUSED JOB BRIEFING	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-67017	1/18/2017	5:15 PM	17	15	9	Dennis W Richter	128 Drug & Alcohol	C= Comp lance	EMPLOYEE DID NOT APPEAR TO BE UNDER THE INFLUEN	By M McCants	MP	1065.7	MT	SBY	GCOR	Northwest	7	Assistant Conductor
08-67034	1/18/2017	7:02 PM	18	2	9	Dennis W Richter	119 Ca ling Signals/Restrictions	C= Comp lance	PROPERLY CALLED SIGNAL AT WEST BISON.	By M McCants	MP	1149.8	MT	XBM	GCOR	Northwest	7	Assistant Conductor

