

Results for Vessel: **CONCEPTION****Vessel Information:**

Vessel Name: CONCEPTION
Primary Vessel Number: 638133 (Official Number (U.S.))
Hull Identification Number: N/A
Manufacturer Hull Number: N/A
IMO Number: N/A
Vessel Flag: UNITED STATES
Vessel Call Sign: WYR8548

Vessel Particulars:

Service: Passenger (Inspected)
Length: 75.00 ft
Breadth: N/A
Depth: N/A
Build Year: 1981
Alternate VINs: N/A

Service Information:

Service Status: Destroyed
Out Of Service Date: 9/2/2019
Last Removed From Service By: N/A

Tonnage Information:

Cargo Authority: N/A
Tonnage:

- 97 - Regulatory (Subpart C or D), Gross Ton
- 66 - Regulatory (Subpart C or D), Net Ton

Vessel Documents and Certifications

Document	Agency	Date Issued	Expiration Date
Certificate of Inspection	N/A	November 19,2014	November 19,2019
Certificate of Inspection - Amended	USCG	November 19,2014	November 19,2019
Certificate of Inspection	N/A	December 2,2009	December 2,2014
Certificate of Inspection - Amended	N/A	December 2,2009	December 2,2014
Certificate of Inspection	N/A	September 2,2005	September 2,2010
Certificate of Inspection - Amended	N/A	September 2,2005	September 2,2010
Certificate of Inspection	N/A	February 6,2002	February 6,2007
Certificate of Inspection - Amended	N/A	February 6,2002	February 6,2007
Certificate of Inspection	N/A	February 23,1999	February 23,2002
Certificate of Inspection - Amended	N/A	February 23,1999	February 23,2002
Stability Letter	N/A	July 10,1981	

Summary of Coast Guard Contacts

To View Contact Data **From:** 11/05/2015 **To:** 11/05/2020 (MM/DD/YYYY)

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6807826	Not Associated with a Case	Santa Barbara, California	Wednesday, August 7, 2019	Vessel Inspection
6759996	1164585	WASHINGTON, District of Columbia	Sunday, March 10, 2019	Incident Investigation
Incident Information				
Role				
Involved in a Marine Casualty				
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6625487	Not Associated with a Case	Santa Barbara, California	Wednesday, February 13, 2019	Vessel Inspection
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6625180	Not Associated with a Case	Santa Barbara, California	Wednesday, February 13, 2019	Vessel Inspection
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6501862	Not Associated with a Case	OXNARD, California	Sunday, August 5, 2018	Boarding
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6345853	Not Associated with a Case	Santa Barbara, California	Tuesday, February	Vessel

	Deficiency Information		
	System	SubSystem	Cause
	Operations/Management	Drug and Alcohol Testing	Invalid
Resolved Deficiency	Description of Deficiency		
	Provide 2018 ASTS employee list.		
	Due Date	Resolved	Resolved Date
	Thursday, March 15, 2018	True	Tuesday, February 13, 2018
	Resolution Description		
	List provided.		
	Deficiency Information		
	System	SubSystem	Cause
	Accommodation/Occupational Safety	Medical/First Aid	Invalid
Resolved Deficiency	Description of Deficiency		
	Update expired items in first aid kit.		
	Due Date	Resolved	Resolved Date
	Thursday, March 15, 2018	True	Friday, March 2, 2018
	Resolution Description		
	First aid kit updated.		
	Deficiency Information		
	System	SubSystem	Cause
	Navigation	Piloting/Steering	Invalid
Resolved Deficiency	Description of Deficiency		
	Update light list.		
	Due Date	Resolved	Resolved Date
	Thursday, March 15, 2018	True	Tuesday, February 13, 2018
	Resolution Description		
	Light list updated.		

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6086303	Not Associated with a Case	Santa Barbara, California	Thursday, February 16, 2017	Vessel Inspection
	Deficiency Information			
	System	SubSystem	Cause	
	Documentation	Logs/Records	Not Available	
Resolved Deficiency	Description of Deficiency			
	Document safety drills in logbook (fire, MOB, and abandonment).			
	Due Date	Resolved	Resolved Date	
	Thursday, February 16, 2017	True	Thursday, February 16, 2017	
	Resolution Description			
	Log updated after satisfactory drills were completed underway.			
	Deficiency Information			
	System	SubSystem	Cause	
	Lifesaving	Lifejacket/PFD (Type I)	Not Available	
Resolved Deficiency	Description of Deficiency			
	Renew 40 lifejacket lights, vessel already restricted to 60 persons until new lifefloats are installed above the bridge.			
	Due Date	Resolved	Resolved Date	
	Thursday, February 16, 2017	True	Thursday, February 16, 2017	
	Resolution Description			
	Corrected on the spot.			
	Deficiency Information			
	System	SubSystem	Cause	
	Fire Fighting	Portable Dry Chemical Fire Extinguisher	Not Available	
Resolved Deficiency	Description of Deficiency			
	Replace B-I fire extinguisher on the bridge.			
	Due Date	Resolved	Resolved Date	
	Thursday, March 16, 2017	True	Monday, February 27, 2017	
	Resolution Description			
	B-I replaced.			

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6080655	Not Associated with a Case	San Pedro, California	Wednesday, February	Vessel

	Deficiency Information		
	System	SubSystem	Cause
	Electrical	Electrical Distribution System (service)	Placed in Improper Service
Resolved Deficiency	Description of Deficiency		
	E/R: label 120V breaker panel and plug 2 holes on each side (4 total).		
	Due Date	Resolved	Resolved Date
	Wednesday, March 1, 2017	True	Thursday, February 9, 2017
	Resolution Description		
	Not Available		
	Deficiency Information		
	System	SubSystem	Cause
	Documentation	Certificates/Documents	Placed in Improper Service
Resolved Deficiency	Description of Deficiency		
	Post all pages of COI		
	Due Date	Resolved	Resolved Date
	Wednesday, March 1, 2017	True	Thursday, February 9, 2017
	Resolution Description		
	Not Available		
	Deficiency Information		
	System	SubSystem	Cause
	Engineering	Feedwater/Condensate Water System	Not Available
Resolved Deficiency	Description of Deficiency		
	Service or repalce (01) ball valve in E/R to ensure full closure.		
	Due Date	Resolved	Resolved Date
	Wednesday, March 1, 2017	True	Thursday, February 9, 2017
	Resolution Description		
	Not Available		

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
6074077	Not Associated with a Case	Santa Barbara, California	Wednesday, January 18, 2017	Vessel Inspection
	Deficiency Information			
	System	SubSystem	Cause	
	Lifesaving	Lifefloat	Not Available	
Resolved Deficiency	Description of Deficiency			
	Vessel is restricted to 60 persons until the two lifefloats mounted above the wheelhouse are renewed and inspected.			
	Due Date	Resolved	Resolved Date	
	Friday, March 31, 2017	True	Monday, April 17, 2017	
	Resolution Description			
	New lifefloats installed and inspected.			

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
5955134	1017823	WASHINGTON, District of Columbia	Saturday, March 19, 2016	Incident Investigation
	Incident Information			
	Role			
	Involved in a Marine Casualty			

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type
5817809	Not Associated with a Case	Santa Barbara, California	Thursday, February 18, 2016	Vessel Inspection
	Deficiency Information			
	System	SubSystem	Cause	
	Fire Fighting	Fire Pumps	Not Available	
Resolved Deficiency	Description of Deficiency			
	Prove proper operation of the fire pump.			
	Due Date	Resolved	Resolved Date	
	Thursday, February 18, 2016	True	Friday, February 19, 2016	
	Resolution Description			
	Not Available			
**Resolved	Deficiency Information			

Deficiency**	System	SubSystem	Cause
	Fire Fighting	Fixed Fire Detection System	Not Available
	Description of Deficiency		
	Prove proper operation of the heat detector in the galley.		
	Due Date	Resolved	Resolved Date
	Friday, March 18, 2016	True	Wednesday, February 24, 2016
	Resolution Description		
Heat detector replaced and tested sat.			
Resolved Deficiency	Deficiency Information		
	System	SubSystem	Cause
	Electrical	Electrical Distribution System (service)	Not Available
	Description of Deficiency		
	Provide suitable cover on motor controller for aft compressor.		
	Due Date	Resolved	Resolved Date
	Friday, March 18, 2016	True	Friday, February 19, 2016
Operational Control	Resolution Description		
	Not Available		
	Operation Control Information		
	Category Type	Control Type	Initiating Port
	Safety	No-Sail CG-835	Marine Safety Detachment Santa Barbara
	Date Imposed	Date Removed	Reason Imposed
	Thursday, February 18, 2016	Friday, February 19, 2016	Vessel Movement, Other
