



Activity Summary Report

MISLE Activity ID: 4274630
 Activity Type: Uninspected Towing Vessel Exam
 Title/Description: Administrative- No UTV IIE
 Status: Closed - Approved Inspection
 Point Of Contact: Pedro Rivera Jr. 787-790-5550
 Owning Unit: Sector San Juan
 Originating Unit: Sector San Juan
 Start Date/Time: 29MAR2012 13:02Z
 Prompt Date:
 Team Lead: ██████████

Vessel Information:

Vessel Name:	Call Sign:	Current Flag / Flag At Time Of Activity:
PROASSIST III	WB9012	UNITED STATES / UNITED STATES
Classification:	Primary VIN:	Length:
Towing Vessel - General - General	257007	111.3
ITC/Convention (Subpart B):	Regulatory (Subpart C or D):	Year Completed:
241	148	1949
Engine Compartment In An Open Space:	Fuel Compartment In An Open Space:	Vessel Constructed Of All Open Spaces:
No	No	No
Propulsion System Type:		
Diesel Reduction		

Vessel Associated Parties:

Name:	Type:	Role:
PROASSIST III INCORPORATED	Organization	Managing Owner
Address:		
1010 ORCHID STREET - APT 1104 SAN JUAN, PUERTO RICO 00926		
Name:	Type:	Role:
PUERTO RICO OPERATIONS INC	Organization	Operator (managing)
Address:		
RA-36 PUNTA LAS MARIAS ST MARINA BAHIA CATANO, PUERTO RICO 00962		

Inspection Results: (None)

Narrative:

Contacted Mr. Pedro Rivera of American Towing, phone number ██████████ to discuss the process for UTV examination of their vessels. Mr. Rivera stated they do not wish to carry out the UTV examination at this time, Mr. Rivera will call to schedule a time and date in the future. Advised Mr. Rivera the importance of the TVBP and the preparation of the implementation of Subchapter M regulations.

Also informed Mr. Rivera that phase II approach to the TVBP process will take effect in the near future and that any UTV that has not undergone an Industry Initiated Examination (IIE) or did not complete a UTV examination, will be targeted as a High Priority Vessel. Such examinations may take place while vessel is moored or underway. Provided Mr. Rivera with a copy of examination booklet, examination forms, and Sector San Juan contact information. As requested no UTV examination was carried out

Inspection/Examination Details: (None)

Location(s):

Latitude:	Longitude:	Recorded Date/Time:	Description:
00°00.0 N	000°00.0 E	10SEP2015 17:52Z	No Legacy Geo Location

Associated Parties: (None)

TWIC Details: (None)

Operational Controls: (None)

Log:

Effective Date:	Description/New Value:	Logged By Unit:	Logged By:
29MAR2012	Activity Created. Status: "Open - Scheduled, Action Pending"	Sector San Juan	Admin, System
08MAR2013	Status Changed to "Closed - Approved Inspection"	Sector San Juan	Admin, System
08MAR2013	Status_DtTm	Sector San Juan	Admin, System

Documents: (None)

Certificates: (None)



Activity Summary Report

MISLE Activity ID: 4830654
 Activity Type: Uninspected Towing Vessel Exam
 Title/Description: Proassist III-Twing Vessel Exam
 Status: Closed - Failed Inspection
 Point Of Contact: Pedro Rivera [REDACTED]
 Owning Unit: Sector San Juan
 Originating Unit: Sector San Juan
 Start Date/Time: 03APR2014 10:59Z
 Prompt Date:
 Team Lead: [REDACTED]

Vessel Information:

Vessel Name:	Call Sign:	Current Flag / Flag At Time Of Activity:
PROASSIST III	WB9012	UNITED STATES / UNITED STATES
Classification:	Primary VIN:	Length:
Towing Vessel - General - General	257007	111.3
ITC/Convention (Subpart B):	Regulatory (Subpart C or D):	Year Completed:
241	148	1949
Engine Compartment In An Open Space:	Fuel Compartment In An Open Space:	Vessel Constructed Of All Open Spaces:
No	No	No
Propulsion System Type:		
Diesel Reduction		

Vessel Associated Parties:

Name:	Type:	Role:
PROASSIST III INCORPORATED	Organization	Managing Owner
Address:		
1010 ORCHID STREET - APT 1104 SAN JUAN, PUERTO RICO 00926		
Name:	Type:	Role:
PUERTO RICO OPERATIONS INC	Organization	Operator (managing)
Address:		
RA-36 PUNTA LAS MARIAS ST MARINA BAHIA CATANO, PUERTO RICO 00962		

Inspection Results:

System:	Inspection Results:	Date:
Communications	Inspected Satisfactory	03APR2014
Construction/Loadline	Inspected Satisfactory	03APR2014
Documentation	Inspected Satisfactory	03APR2014
Fire Fighting	Inspected With Deficiencies Noted	03APR2014
Lifesaving	Inspected Satisfactory	03APR2014
Navigation	Inspected Satisfactory	03APR2014
Personnel	Inspected Satisfactory	03APR2014
Pollution Prevention/Response	Inspected With Deficiencies Noted	03APR2014

Deficiencies:

Item Number: 1	Due Date: 04MAY2014	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 03APR2014	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Fire Fighting	Subsystem: Fire Hoses	Component: Condition	<input type="checkbox"/> Grounds For Detention
Action:	Action Code:	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Fire hose of the portable B5 fire extinguisher bulged at the hydrant connection.

Resolution:

Semi-Portable B-5 hose replaced

Item Number: 2	Due Date: 04MAY2014	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 03APR2014	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Pollution Prevention/Response	Subsystem: Prevention Equipment	Component: Internal Cargo Transfer Capability	<input type="checkbox"/> Grounds For Detention
Action:	Action Code:	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Oil Transfer diagram missing.

Resolution:

Oil transfer diagram updated and posted

Narrative:

03APR14:Sector San Juan Towing Vessel examiners conducted an industry initiated exam with vessel Proassist III on 03 APR 04. Examiners verified vessels documents, navigation safety equipment, lifesaving equipment, MTSA verification, firefighting equipment and a visual towing gear inspection.

No decal was issued

There were 02 deficiencies noted during the examination.

1. Oil Transfer diagram missing not posted.
2. Damage hose for the B5 fire extinguisher. Needs to be replace.

Recommendations: Spill containment kit needs to be designated, all extra lifesaving equipment needs to be in good serviceable condition and periodic maintenance and replacement of fire hoses and nozzles.

//S//

██████████, DC1

Examination Details

Examination Type: Industry Initiated Exam	Date: 03APR2014	Unit: Sector San Juan
Examination Type: MTSA Verification	Date: 03APR2014	Unit: Sector San Juan
Examination Type: DAPI Audit	Date: 03APR2014	Unit: Sector San Juan

Location(s):

Latitude:	Longitude:	Recorded Date/Time:	Description:
------------------	-------------------	----------------------------	---------------------

18°03.2 N

065°50.2 W

03APR2014 10:59Z

Yabucoa, Puerto Rico

Associated Parties: (None)

TWIC Details:

Worker Type:	Checked:	Compliant:	Noncompliant:	Remarks:
Licensed Mariner	3	3	0	
Unlicensed Mariner	0	0	0	
Other	0	0	0	

Operational Controls: (None)

Log:

Effective Date:	Description/New Value:	Logged By Unit:	Logged By:
07APR2014	Activity Created. Status: "Open - In Progress"	Sector San Juan	Admin, System
15APR2014	Status Changed to "Closed - Failed Inspection"	Sector San Juan	Admin, System
15APR2014	Status_DtTm	Sector San Juan	Admin, System

Documents: (None)

Certificates: (None)



Activity Summary Report

MISLE Activity ID: 4856636
 Activity Type: Uninspected Towing Vessel Exam
 Title/Description: DEF CHECK
 Status: Closed - Approved Inspection
 Point Of Contact: Pedro Rivera Jr. [REDACTED]
 Owning Unit: Sector San Juan
 Originating Unit: Sector San Juan
 Start Date/Time: 12MAY2014 10:41Z
 Prompt Date:
 Team Lead: [REDACTED]

Vessel Information:

Vessel Name:	Call Sign:	Current Flag / Flag At Time Of Activity:
PROASSIST III	WB9012	UNITED STATES / UNITED STATES
Classification:	Primary VIN:	Length:
Towing Vessel - General - General	257007	111.3
ITC/Convention (Subpart B):	Regulatory (Subpart C or D):	Year Completed:
241	148	1949
Engine Compartment In An Open Space:	Fuel Compartment In An Open Space:	Vessel Constructed Of All Open Spaces:
No	No	No
Propulsion System Type:		
Diesel Reduction		

Vessel Associated Parties:

Name:	Type:	Role:
PROASSIST III INCORPORATED	Organization	Managing Owner
Address:		
1010 ORCHID STREET - APT 1104 SAN JUAN, PUERTO RICO 00926		
Name:	Type:	Role:
PUERTO RICO OPERATIONS INC	Organization	Operator (managing)
Address:		
RA-36 PUNTA LAS MARIAS ST MARINA BAHIA CATANO, PUERTO RICO 00962		

Inspection Results:

System:	Inspection Results:	Date:
Accommodation/Occupational Safety	Inspected With Deficiencies Noted	12MAY2014
Communications	Inspected With Deficiencies Noted	12MAY2014
Electrical	Inspected With Deficiencies Noted	12MAY2014
Engineering	Inspected With Deficiencies Noted	12MAY2014
Fire Fighting	Inspected With Deficiencies Noted	12MAY2014
Lifesaving	Inspected With Deficiencies Noted	12MAY2014
Navigation	Inspected With Deficiencies Noted	12MAY2014
Pollution Prevention/Response	Inspected With Deficiencies Noted	12MAY2014

Deficiencies:

Item Number: 1	Due Date: 11JUL2008	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 11JUN2008	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Navigation	Subsystem: Collision/Grounding Avoidance	Component: Navigation Lights	<input type="checkbox"/> Grounds For Detention
Action: 705 - Other - as specified	Action Code: c - To the satisfaction of the Coast Guard	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Remount Port/Stb. Running lights; Paint background screens black

Resolution:

Nav lights repaired and to standards

Item Number: 1	Due Date: 04MAY2014	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 03APR2014	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Fire Fighting	Subsystem: Fire Hoses	Component: Condition	<input type="checkbox"/> Grounds For Detention
Action:	Action Code:	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Fire hose of the portable B5 fire extinguisher bulged at the hydrant connection.

Resolution:

Semi-Portable B-5 hose replaced

Item Number: 2	Due Date: 11JUL2008	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 11JUN2008	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Fire Fighting	Subsystem: Fixed CO2 Fire Extinguishing System	Component: Piping	<input type="checkbox"/> Grounds For Detention
Action: 705 - Other - as specified	Action Code: c - To the satisfaction of the Coast Guard	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Replace CO2 horn connection and hoses where crimped, corroded or damaged.

Resolution:

All CO2 extinguishers in good and ready to use condition

Item Number: 2	Due Date: 04MAY2014	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 03APR2014	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Pollution Prevention/Response	Subsystem: Prevention Equipment	Component: Internal Cargo Transfer Capability	<input type="checkbox"/> Grounds For Detention
Action:	Action Code:	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Oil Transfer diagram missing.

Resolution:

Oil transfer diagram updated and posted

Item Number: 3	Due Date: 11JUL2008	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 11JUN2008	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Engineering	Subsystem: Reduction Gearing/Clutches	Component: Shaft	<input type="checkbox"/> Grounds For Detention
Action: 705 - Other - as specified	Action Code: c - To the satisfaction of the Coast Guard	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Repair/Adjust Starboard shaft packing- currently leaking steady 1-2 GPM

Resolution:

No leak detected

Item Number: 4	Due Date: 11JUL2008	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 11JUN2008	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Electrical	Subsystem: Electric Supply System (service)	Component: Cable	<input type="checkbox"/> Grounds For Detention
Action: 705 - Other - as specified	Action Code: c - To the satisfaction of the Coast Guard	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Remove dead end electrical wiring and cover electrical junction boxes,electrical fittings.

Resolution:

All dead end wiring removed, junction boxes covered, and ligh fixtures covered with lense and metal guard.

Item Number: 5	Due Date: 11JUL2008	Extended Due Date:	<input type="checkbox"/> Not Available For Inspection
Issued Date: 11JUN2008	Resolved Date: 12MAY2014		<input type="checkbox"/> Security Violation
System: Accommodation/Occupational Safety	Subsystem: Occupational Safety	Component: Tripping/Falling Hazard	<input type="checkbox"/> Grounds For Detention
Action: 705 - Other - as specified	Action Code: c - To the satisfaction of the Coast Guard	ACS/RO/TPO Finding Number:	<input type="checkbox"/> Voluntary Exam Recommendation
			<input type="checkbox"/> Worklist Item/Do Not Show In PSIX
			<input type="checkbox"/> SMS Related/Objective Evidence For MSO
			<input type="checkbox"/> Self Reported
			<input type="checkbox"/> Reported Via PR17
			<input type="checkbox"/> Refer To ACS/RO/TPO
			<input type="checkbox"/> ACS/RO/TPO Associated
			<input type="checkbox"/> Accepted As Condition Of ACS/TPO

Description:

Secure sole planking in center machinery alley where unsupported

Resolution:

Deck plates secured to the frames

Narrative:

12MAY14 - Attended vsl in Guayama, PR to conduct an Industry Initiated Exam and MTSA Verification per the Coast Guard Towing Vessel Bridging Program. In attendance for the owner was vsl rep and Master, Pedro Rivetra Jr.

Vsl is a 111.3ft x 148gt / 241gt itc Uninspected Towing Vsl harbor assist svc on Near Coastal.

Examined vsl using UTV form 001 (6/09). Vsl was found in compliance w/current applicable laws and regulations. Conducted sat operational testing of vsl installed fire pump, machinery space fire alarm and general alarm.

Vessel was found in compliance with MTSA and utilized VSP, approved by MSC. Crew was knowledgeable. Reviewed communication, restricted areas, monitoring, training, and procedures.

00 def's issued, 07 def's cleared, 00 def's remain outstanding.

UTV safety decal was issued. Exam complete.

Examination Details

Examination Type:	Date:	Unit:
Deficiency Check	12MAY2014	Sector San Juan

Location(s):

Latitude:	Longitude:	Recorded Date/Time:	Description:
00°00.0 N	000°00.0 E	12MAY2014 10:41Z	GUAYAMA-

Associated Parties: (None)

TWIC Details:

Worker Type:	Checked:	Compliant:	Noncompliant:	Remarks:
Licensed Mariner	1	1	0	

Operational Controls: (None)

Log:

Effective Date:	Description/New Value:	Logged By Unit:	Logged By:
12MAY2014	Activity Created. Status: "Open - In Progress"	Sector San Juan	Admin, System
12MAY2014	Status Changed to "Closed - Approved Inspection"	Sector San Juan	Admin, System
12MAY2014	Status_DtTm	Sector San Juan	Admin, System

Documents: (None)

Certificates:

Name:	Type:	Description:	Issued Date:	Expired Date:
UTV DECAL	Uninspected Towing Vessel (UTV) Decal			
Owning Unit:	Status:	Issued Date:	Expired Date:	
Sector San Juan	EXPIRED	12MAY2014	31MAY2017	