



**Vehicle Attachment 1 – New Jersey State Police Commercial
Driver/Vehicle Examination Reports**

**MULTIPLE VEHICLE ACCIDENT
Cranbury, NJ**

HWY14MH012

(4 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 2.14.1.1



NEW JERSEY STATE POLICE
 3925 US HWY 1
 TRANSPORTATION SAFETY BUREAU
 PRINCETON, NJ 08540
 Phone: (609)452-2601 Fax: (609)452-8495

Report Number: NJSPDP002366
Inspection Date: 06/09/2014
Start: 8:00:00 AM ET **End:** 1:18:00 PM ET
Inspection Level: I - Full
HM Inspection Type: None

ATLANTIC TRANSPORTATION SERVICES LLC
 34821 DERRICKSON DRIVE
 REHOBOTH BEACH, DE 19971
USDOT#: 01415859 **Phone#:** [REDACTED]
MC/MX#: 537941 **Fax#:** [REDACTED]
State#:

Driver: GALE, TYRONE V
License#: [REDACTED] **State:** DE
Date of Birth: [REDACTED]
CoDriver:
License#: **State:**
Date of Birth:

Location: GEORGES TOWING **MilePost:** 0 **Shipper:** SAME
Highway: NJTPK **Origin:** DOVER, DE **Bill of Lading:** 15257 PTP
County: MIDDLESEX, NJ **Destination:** CRESSKILL, NJ **Cargo:** PASSENGERS

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	CVSA Issued #	OOS Sticker
1	VN	MERC	2012	DE	[REDACTED]	0812B	WD3PE8CC1C5[REDACTED]	8,550			

BRAKE ADJUSTMENTS

Axle #	1	2
Right	N/A	N/A
Left	N/A	N/A
Chamber	HYDR	HYDR

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
395.8A	395.8(a)	D	Y	SP5424286	N	N	No drivers record of duty status when one is required
395.5A1-PASS	395.5(a)(1)	D	Y		N	N	Driving after 10 hour driving limit (Passenger carrying vehicle)
392.8	392.8	D	N		N	N	Failing to inspect emergency equipment
393.95F	393.95(f)	1	N		N	N	No / insufficient warning devices(Triangles)
393.95A	393.95(a)	1	N		N	N	No fire extinguisher
390.21B	390.21(b)	1	N		N	N	USDOT Number not displayed as required

HazMat: No HM Transported.

Placard: No **Cargo Tank:**

Special Checks: Post Crash

Pursuant to NJAC 13:60 (Federal Motor Carrier Safety Regulations Parts 390, 391, 392, 393, 394, 395, 396, 397) and NJAC 16:49 (Title 49 Code of Federal Regulations Parts 171, 172, 173, 177, 178, and 180). I hereby notify and declare TYRONE GALE named on this report OUT OF SERVICE. No motor carrier shall permit or require this driver to drive or operate any motor vehicle until 10 hours.

The undersigned certifies that all OOS violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state.

Signature Of Repairer X: _____ Facility: _____ Date: _____

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears on this report.

NOTE TO MOTOR CARRIER: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state. Please sign the certification below and return this report within fifteen days to: New Jersey State Police, 3925 US Hwy. 1 Princeton, N.J. 08540 . ATTN: Hazardous Materials

Signature Of Motor Carrier X: _____ Title: _____ Date: _____

Report Prepared By:
 TPR. I R. KOPEC

Badge #:
 6509

Copy Received By:
 TYRONE GALE

Page 1 of 1



01415859 NJ NJSPDP002366

X _____ # 6509

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 2.14.1.1



NEW JERSEY STATE POLICE
3925 US HWY 1
TRANSPORTATION SAFETY BUREAU
PRINCETON, NJ 08540
 Phone: (609)452-2601 Fax: (609)452-8495

Report Number: NJSPDP002367
Inspection Date: 06/11/2014
Start: 8:19:00 AM ET End: 1:36:00 PM ET
Inspection Level: | - Full
HM Inspection Type: None

WAL-MART TRANSPORTATION LLC
 311 NORTH WALTON BLVD
 BENTONVILLE, AR 72716-0650
 USDOT#: 00063585 Phone#: [REDACTED]
 MC/MX#: 311233 Fax#: [REDACTED]
 State#:

Driver: ROPER, KEVIN J
License#: [REDACTED] State: GA
Date of Birth: [REDACTED]
CoDriver:
License#: State:
Date of Birth:

Location: GEORGES TOWING
Highway: NJTPK
County: MIDDLESEX, NJ

MilePost: 0
Origin: BRISTOL, PA
Destination: PERTH AMBOY, NJ
Shipper:
Bill of Lading:
Cargo: EMPTY

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	CVSA Issued #	OOS Sticker
1	TT	PTRB	2011	OK	[REDACTED]	0-2568	1XPHD49X6BD [REDACTED]	50,000			
2	ST	GDAN	2003	OK	[REDACTED]	77397	1GRAA06253D [REDACTED]	68,000			

BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	1	1 3/8	1 1/2	1 1/2	1 3/4
Left	1 1/4	1 1/8	1 5/8	1 1/2	2
Chamber	C-20	C-30	MM	L-30	L-30

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392.3-FPROP	392.3	D	Y	SP5424287	N	N	Fatigue - Operate a property-carrying CMV while impaired by fatigue. As per driver's statement after the crash, "I fell asleep"
395.15C	395.15(c)	D	N		N	N	Onboard recording device improper form and manner. Driver records deliveries /"drop & hooks" as off duty, not on duty not driving.
396.5A-HNLOW	396.5(a)	2	N		N	N	Hubs - Oil and/or Grease Leaking from hub - inner wheel seals leaking on both left and right side of axle 4.

HazMat: No HM Transported.

Placard: No Cargo Tank:

Special Checks: Post Crash

Pursuant to NJAC 13:60 (Federal Motor Carrier Safety Regulations Parts 390, 391, 392, 393, 394, 395, 396, 397) and NJAC 16:49 (Title 49 Code of Federal Regulations Parts 171, 172, 173, 177, 178, and 180). I hereby notify and declare KEVIN ROPER named on this report OUT OF SERVICE. No motor carrier shall permit or require this driver to drive or operate any motor vehicle until 10 hours.

The undersigned certifies that all OOS violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state.

Signature Of Repairer X: _____ Facility: _____ Date: _____

NOTE TO DRIVER: This report must be furnished to the motor carrier whose name appears on this report.

NOTE TO MOTOR CARRIER: The undersigned certifies that all violations noted on this report have been corrected and action taken to assure compliance with New Jersey Law, Federal Motor Carrier Safety and Hazardous Material regulations insofar as they are applicable to motor carriers and drivers on the highways of this state. Please sign the certification below and return this report within fifteen days to: New Jersey State Police, 3925 US Hwy. 1 Princeton, N.J. 08540 . ATTN: Hazardous Materials

Signature Of Motor Carrier X: _____ Title: _____ Date: _____

Report Prepared By:
 TPR. I.R. KOPEC

Badge #:
 6509

Copy Received By:
 KEVIN ROPER

Page 1 of 1



00063585 NJ NJSPDP002367

X [Signature] # 6509

X

DRIVER/VEHICLE EXAMINATION REPORT

Aspen 2.14.1.1



NEW JERSEY STATE POLICE
 3925 US HWY 1
 TRANSPORTATION SAFETY BUREAU
 PRINCETON, NJ 08540
 Phone: (609)452-2601 Fax: (609)452-8495

Report Number: NJSPDP002368
 Inspection Date: 06/12/2014
 Start: 9:08:00 AM ET End: 1:28:01 PM ET
 Inspection Level: I - Full
 HM Inspection Type: None

4 WAY TRANSPORT LLC
 4823 C ST
 PHILADELPHIA, PA 19120
 USDOT#: 02402309
 MC/MX#: 826327
 State#:

Phone#: [REDACTED]
 Fax#: [REDACTED]

Driver: HASAN, AHMAD
 License#: [REDACTED] State: PA
 Date of Birth: [REDACTED]
 CoDriver:
 License#: [REDACTED] State:
 Date of Birth: [REDACTED]

Location: GEORGES TOWING
 Highway: NJTPK
 County: MIDDLESEX, NJ

MilePost: 0 Shipper: PINTO BROS & OPPENHEIMER
 Origin: VINELAND, NJ Bill of Lading: MULTIPLE
 Destination: ASSONET, MA Cargo: REFRIGERATED FOODS

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	CVSA Issued #	OOS Sticker
1	TT	FRHT	2006	PA	[REDACTED]	786	1FUJBBCK46L [REDACTED]	52,000			
2	ST	TRIM	1998	PA	[REDACTED]	427	1PT01ANH3W9 [REDACTED]	65,000			

BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	1 1/4	1 3/4	2	1 3/4	1 1/2
Left	1 1/8	2 1/4	2 1/8	1 3/4	1 3/8
Chamber	L-20	L-30	L-30	C-30	C-30

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392.9AA1	392.9a(a)(1)	1	Y	SP5424288	U	N	Operating without the Required Operating Authority
393.45DLUV	393.45(d)	1	Y	SP5424289	U	N	Brake Connections with Leaks Under Vehicle, other than proper connection. Right side, 2nd axle, service side brake hose audible air leak behind hose fitting.
393.45B2	393.45(b)(2)	1	Y		U	N	Brake hose or tubing chafing/worn through outer reinforcement ply. 3rd axle, right side service side.
396.5B	396.5(b)	1	N		N	N	Engine Oil leak, rear main seal. excessive oil on rear of engine & oil pan.
396.5B	396.5(b)	1	N		N	N	Transmission Oil leak, rear seal of transmission output shaft
390.21A	390.21(a)	1	N		N	N	Not marked in accordance with regulations, Letters US not placed before DOT# on both sides of vehicle.
393.9	393.9(a)	2	N		N	N	Inoperable required lamps - Right front Clearance lamp missing. Left front & right rear clearance lamps inop on cargo box.
393.75A	393.75(a)	2	Y		U	N	Flat tire, Left side, 5th axle, inner tire
392.2	392.2	2	N		N	N	State License Plate violation, Unclear rear license plate. Characters covered by grease. (39:3-33)
395.8E	395.8(e)	D	Y		N	N	False Log. Redundant & Destroyed log book pages for 6/4, 6/5 & 6/6/14 were found inside sleeper birth. Hours differ from initial log pages presented

HazMat: No HM Transported.

Placard: No Cargo Tank:

Special Checks: Post Crash

Report Prepared By:
 TPR. I R. KOPEC

Badge #:
 6509

Copy Received By:
 AHMAD HASAN

Page 1 of 2



02402309 NJ NJSPDP002368

X [REDACTED] # 6509

X _____