



Vehicle Factors Attachment - 2009 Ford Medium-Size Bus Tire Scan Summary

Belton, SC

HWY20FH001

(2 pages)



22265593

NTSB Office of Highway Safety
490 L'Enfant Plaza Southwest
Washington, DC 20594-003

Scanned by: NTSB - DP

VIN	1FDEE35L99DA23497	
Vehicle	2009 Ford E-150-van	
Tire Size	LT225/75R16	
License Plate	RGI203 - SC	Odo: mi.


Vehicle Scan Summary · 12/21/2019, 9:58 AM

Possible Service



Diagnostic Notes


Inspection
Vehicle Color: white



Left Front Tire

Perform Visual Tire Inspection

- Perform Visual Tire Inspection




Left Rear Tire

Groove Depth in 32nds

DOT: Size: Load:

Notes:

- Tread Depth is Marginal. Use Caution in Wet/Snowy Conditions. Consider Replacement.



GOOD

MARGINAL

REPLACE NOW