

From: [Payne Sean](#)
To: [Baker Daniel](#)
Cc: [Crookshanks Clinton](#); [Babcock Christopher](#)
Subject: WPR22FA266 (Tyron, NE) - Dynon EFIS D10 - Email Report
Date: Thursday, February 23, 2023 10:42:00 AM
Attachments: [WPR22FA266_1.jpg](#)

Email Report Instructions

The narrative and attachments from this email report may be used in other reports at the discretion of the IIC. This email, including attachments (if applicable), should also be placed in the public docket by the IIC.

Email Report

The Vehicle Recorder Division received the following electronic device: **Dynon D10 EFIS, SN 00151X**

The device was damaged in the accident and is pictured in WPR22FA266_1.jpg. The device was disassembled. After disassembly, no non-volatile memory (NVM) chip was located. A representative from Dynon confirmed that the device was not capable of recording data.

No data was recovered from the device.

Prepared by: Sean Payne, Recorder Specialist, NTSB RE-40

Sean Payne
Sr. Engineer//Investigator
NTSB Vehicle Recorder Division