

Data at: 0531 UTC 13 Jan 2019

KPAE 130453Z 10004KT 10SM CLR 09/M01 A3010 RMK AO2 SLP193 T00891011
KPAE 130353Z 00000KT 10SM CLR 08/00 A3008 RMK AO2 SLP189 T00780000
KPAE 130253Z 00000KT 10SM CLR 08/00 A3007 RMK AO2 SLP184 T00780000 52015
KPAE 130153Z 15004KT 10SM CLR 09/00 A3005 RMK AO2 SLP179 T00940000
KPAE 130053Z VRB04KT 10SM CLR 13/M01 A3003 RMK AO2 SLP170 T01281006
KPAE 122353Z 00000KT 10SM CLR 12/02 A3002 RMK AO2 SLP168 T01170022 10150
20100 53006
KPAE 122253Z 22007KT 10SM CLR 12/03 A3001 RMK AO2 SLP164 T01170028
KPAE 122153Z VRB06KT 10SM CLR 15/01 A2998 RMK AO2 SLP152 T01500006
KPAE 122053Z 12007KT 10SM CLR 13/00 A3000 RMK AO2 SLP160 T01330000 51001
KPAE 121953Z 13005KT 10SM CLR 13/01 A3000 RMK AO2 SLP160 T01280006
KPAE 121853Z 12003KT 10SM CLR 11/00 A3001 RMK AO2 SLP163 T01110000
KPAE 121753Z 12004KT 10SM CLR 10/00 A3000 RMK AO2 SLP160 T01000000 10100
20072 53018
KPAE 121653Z 09007KT 10SM CLR 09/M01 A2997 RMK AO2 SLP151 T00891006
KPAE 121553Z 00000KT 10SM CLR 08/M01 A2996 RMK AO2 SLP145 T00781006
KPAE 121453Z 08008KT 10SM CLR 08/00 A2994 RMK AO2 SLP141 T00780000 56005
KPAE 121353Z AUTO 07005KT 10SM CLR 08/00 A2995 RMK AO2 SLP144 T00780000

Time of accident – 1115 PST 1915 Z

Date – 1/12/19

Landing runway 16

PAE is 11 miles from W10.

Direction from accident site 140 degrees