DATE RE	Date: 06/12/2016	DATE 19	RECORD
2000 C	I certify that this Aircraft has had an annual inspection in accordance with FAR 3 Appendix D and was determined to be in airworthy condition this date Prepared By: Gary J Walker Certification # Checked all light, lubricated all flight controls inspected wheels and brakes pressure tested exhaust system no defects found, secured all induction clamps,replaced induction air filter installed New Brackett BA 3 element repaired right hand fwd engine baffle by sheet metal repair Replaced fuel cap Orings installed new MS2193-338 o rings replaced Egt gauge with used serviceable unit SER# 120521. CW AD 73-23-07 R2 Wing Attach by visual inspection no defects noted. CW AD 75-01-04 Fuel selector valve by inspection no defects noted. Aircraft Reweighed this date New Airclaft EW 1490.0 New C OF G 109.1 New moment 162645.0		0525 Tev. 02/09 RRD0 14 :
	Gary J Walker		

Hours: Tach 35.0 ACTT 4357 Date: 12/19/2019 S/N: MB432 Model: 19A Make: Beechcraft DATE Cert Name: Gary J Walker Date: 02/15/2020 Signed: / Co: Cardan Aircraft Make: Beechcraft Certify that this aircraft has had an annual inspection in accordance with FAR 43 Appendix D and was determined to Name: Gary J Walker be in airworthy condition this date. Co: Cardan Aircraft Removed tail nav light an Gary J Walker this date. Checked all lights lubricated all flight controls serviced battery and brake reservoir with 5606 pressure tested exhaust system Replaced ELT batteries next due 12/21 cleaned and painted battery box Replaced taxi light bulb with new installed GE4509. Replaced right wing tip strobe light bulb P/N A427 flash tube CW FAR91.207D ELT inspection as per FAR 91.207D and was found to be in satisfactory condition this date Replaced induction air filter installed new BA3 element. CW AD 87-02-08 Stabliator hinge bearings by inspection per SB 2182 no defects noted CW AD 76-07-12 Bendix Ignition switch by functional test no defects noted.

Tail: N7641R Hours: Tach 35.5 Date: 02/15/2020 S/N: MB432 Model: B19 Make: Beechcraft Cert Name: Gary J Walker Signed: Co: Cardan Aircraft Removed tail nav light and installed new uAvionix Tail nav/ ADS-B out beacon serial number 2010106 see form 337 this date. Gary J. Walker

YEAR 20_	RECORDING TACH TIME	TODAY'S FLIGHT	TIME IN	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)	YEA 20
	Beaver Avionic (530) 567-4253	CS 1550 Airpo	rt Blvd Red Bluff, CA	A 96080 Date May 1, 2021	DATE
Registration:		e: Beech	Model: 1	WO# 1200	
Description	of Inspections,	Tests, Rep	pairs and Altera	ations Hobbs: N/A	
1 Perform	ned Inspection/Test/Cert	tification requir	red by FAR 91.413 IA	AW FAR 43, Appendix F.	
		y that this airc	raft has been inspec	ted IAW EAR 42 annualis 5	
Signature					

EAR OATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Rep Entries must be endorsed with Name, Rating and Certain Technician or Repair Facility. (See back pages for other special
	Cardan Airo 1950 Airpor Red Bluff C 530-527-65	t Blvd alifornia 96	080	Make: Beechcraft Model: 19A Tail: N7641R S/N: MB-432
	Gary J Wal Checked al	ker I lights served replaced	iced battery a lexhaust sup	and brake reservoir lubricated flight controls pressure tested exhaust system no pport clamp with used serviceable unit replaced induction air filter BA3 element aned and packed wheel bearings and inspected brake linings replaced get gauge instrument block off plate in open hole CW AD 75-01-04 fuel selector by inspection not a service and packed wheel bearings and inspected brake linings replaced get gauge instrument block off plate in open hole CW AD 75-01-04 fuel selector by inspection not be a service and packed wheel bearings and inspected brake linings replaced get gauge instrument block off plate in open hole CW AD 75-01-04 fuel selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a service and the selector by inspection not be a selector by inspection not
	jacked airci with new un defects not CW AD 73-	ed next due 23-07 R2 W	next annual ing attach by	y visual inspection next due next annual CW AD 87-02-08 Stabilator hinge by s noted CW AD 76-07-12 Bendix Ignition switch by functional test next due tach section found to be in satisfactory condition this date Cert: