
 Glendale Aero Services [REDACTED] Glendale, AZ 85307 [REDACTED]	Registration: N433CS		AIRFRAME LOG	
	Date: 10/1/2018	W/O: 6002552		
	Model: T240	Tach: 543.9		
	S/N: T24002033			
Serviced all tires to proper PSI IAW the Cessna T240 Service Manual Chapter 32 & 12.				
SIGNATURE: [REDACTED]		FAA AUTHORIZATION: [REDACTED] /A		

 Glendale Aero Services [REDACTED] Glendale, AZ 85307 [REDACTED]	Registration: N433CS		ENGINE LOG	
	Date: 10/1/2018	W/O: 6002552		
	Model: T240	Tach: 543.9		
	S/N: T24002033			
Removed and replaced all spark plugs with new URHB38E Tempest plugs with new M674 gaskets and anti-seize as required. Torqued to specified limits. MX performed IAW CMi Manual M-O.				
Removed existing RH magneto p/n 10-500556-101 s/n D13DA104 and LH magneto p/n 10-500556-101 s/n D13DA099. Installed new left and right magnetos p/n 10-500556-101 s/n's D17GA012 & D17GA019 with new flange and pressure gaskets, reference FAA Form 8130-3 from Textron Aviation Inc. under work order 3270687 dated 9/28/2018 for details. Timed to engine and set to specified limits. MX performed IAW CMi TSIO-550 Series Manual M-18 CH 10-6. Full power ground run-up, ops & leak checks performed with all indications normal and no leaks noted.				
SIGNATURE: [REDACTED]		FAA AUTHORIZATION: [REDACTED] /A		