



Motor Carrier Photos 5 - 7:

Exemplar Vehicle with Qualcomm Device

Cranbury, NJ; 06/07/2014

HWY14MH012

(4 pages)



Photo 5: This photo depicts the exemplar Walmart truck-tractor observed by the NTSB. This unit was manufactured the same year and represents the identical configuration as the accident truck-tractor. This photo displays the passenger side view of the exemplar truck-tractor.



Photo 6: This photo represents frontal view of the exemplar accident truck-tractor, a 2011 Peterbilt.




Photo 7: This photo represents the Qualcomm system that was mounted in the exemplar vehicle. The functions and capabilities of this unit were demonstrated to NTSB investigators. This device tracks and monitors the driver's Hours-of-Service using an E-log system. The accident vehicle was equipped with an identical unit shown in this photo.