



# Service Work Order Summary

**Company Info**

Tweet Garot Mechanical, Inc.  
 325 Reid St  
 De Pere, WI 54115 US  
 Phone: [REDACTED]

**Customer**

Fincantieri Bay Shipbuilding Company  
 605 North Third Avenue  
 Sturgeon Bay, WI 54235-2324 US  
 Contact: Todd Thayse  
 Phone: [REDACTED]  
 Fax:  
 Email: [REDACTED];

**Service Site**

605NORTHTHIRD  
 605 North Third Avenue  
 Sturgeon Bay, WI 54235-2324 US  
 Contact:  
 Phone:

**Work Order: 250347****Status: Complete****Service Center:** GB**Description:** Roger Blough: Oil Furnace not working**Lead Technician:** 14025 - Frank, Jonathan J**Requested By:** Dave Hunt**Requested Date:** 12/29/2020**Scope:** 1 SERV**Agreement:****Status: Complete****Price Method:** Time and Material**Division:** Green Bay Service**Call Type:** Service Call**Rate Template:** Service Quoted Rate-Bay Shipbuilding Company**Serviceable Item:****Customer PO:****Description:** General Service Call**Summary of Work Performed**

Service Item	Tech Labor	Description	Date	Hours
	Frank, Jonathan J	Labor	12/29/2020	4.00
<p>The oil furnace was on a hard lock out when I arrived, the crew said the damper moved and that might of caused it to soot up. Figured out how to reset it, didn't light the first time so I pulled out the burner head and adjusted the electrodes to the specks in the manual, it lit adjusted, the exhaust damper, checked the combustion, and adjusted the damper a little more according to the combustion. After about 20 minuets of run time one of the contractors chattered briefly, we couldn't tel witch one they are going to keep an eye on it. I recommend doing a PM during lay up and documenting every measurement for the burner settings for future use. I'll get pricing for parts they should keep on hand.</p>				