



Highway Factors Photographs 1 through 3

Louisville, NY

HWY23FH005

(3 pages)



Highway Factors Photograph 1 – View of centerline rumble strips along State Route 37 in the vicinity of the crash



Highway Factors Photograph 2 – Taken on January 28, 2023, at 8:26 a.m., approximately 2 hours and 24 minutes after the crash looking to the west, illustrates bare pavement conditions on State Route 37 in the vicinity of the crash (Source: New York State Police)



Highway Factors Photograph 3 – Taken on January 28, 2023, at 8:32 a.m., approximately 2 hours and 30 minutes after the crash looking to the east, illustrates bare pavement conditions on State Route 37 in the vicinity of the crash (Source: New York State Police)