

Visual Track Inspections - Carrington Subdivision

Inspection Number	Roadmaster	Subdivision/Yard	Asset Description	Asset Type	Inspection Type	Start MP	End MP	Mode	Performed Date	Backdated from Date	Comments
004008850645	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Joint Bar Inspection	340.73	342.84	TRAVERSE - WALKING	07/03/2024		
004008932826	Enderlin	Carrington Sub	DRY LAKE WEST SIDING SWITCH	Turnout	Regulatory, Regular Inspection	342.84	342.84	TRAVERSE - WALKING	05/10/2024		
004008932835	Enderlin	Carrington Sub	BORDULAC EAST 1 TRACK SWITCH	Turnout	Regulatory, Regular Inspection	343.50	343.50	TRAVERSE - WALKING	05/10/2024		
004008932836	Enderlin	Carrington Sub	BORDULAC EAST 2 TRACK SWITCH	Turnout	Regulatory, Regular Inspection	343.53	343.53	TRAVERSE - WALKING	05/10/2024		
004008932837	Enderlin	Carrington Sub	DRY LAKE EAST SIDING SWITCH	Turnout	Regulatory, Regular Inspection	340.73	340.73	TRAVERSE - WALKING	05/10/2024		
004008936222	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	OBSERVE FROM ADJACENT TRACK	05/03/2024		
004008937794	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	352.40	TRAVERSE - VEHICLE	05/01/2024		
004008940595	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	287.60	380.00	TRAVERSE - VEHICLE	05/07/2024		
004008942448	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	352.40	TRAVERSE - VEHICLE	05/03/2024		
004008942905	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	OBSERVE FROM ADJACENT TRACK	05/11/2024		
004008942989	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	380.00	TRAVERSE - VEHICLE	05/04/2024		
004008945958	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	352.40	TRAVERSE - VEHICLE	05/11/2024		
004008946638	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	338.50	TRAVERSE - VEHICLE	05/08/2024		
004008948083	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	338.50	352.40	TRAVERSE - VEHICLE	05/09/2024		
004008948978	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	352.40	TRAVERSE - VEHICLE	05/13/2024		
004008949453	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	330.90	353.40	TRAVERSE - VEHICLE	05/10/2024		
004008949968	Enderlin	Carrington Sub	DRY LAKE WEST SIDING SWITCH	Turnout	Regulatory, Regular Inspection	342.84	342.84	TRAVERSE - WALKING	06/28/2024		
004008949969	Enderlin	Carrington Sub	BORDULAC EAST 1 TRACK SWITCH	Turnout	Regulatory, Regular Inspection	343.50	343.50	TRAVERSE - WALKING	06/28/2024		
004008949970	Enderlin	Carrington Sub	BORDULAC EAST 2 TRACK SWITCH	Turnout	Regulatory, Regular Inspection	343.53	343.53	TRAVERSE - WALKING	06/28/2024		
004008949971	Enderlin	Carrington Sub	DRY LAKE EAST SIDING SWITCH	Turnout	Regulatory, Regular Inspection	340.73	340.73	TRAVERSE - WALKING	06/28/2024		
004008950205	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	OBSERVE FROM ADJACENT TRACK	05/17/2024		
004008951583	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	352.40	TRAVERSE - VEHICLE	05/16/2024		
004008952205	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	352.40	TRAVERSE - VEHICLE	05/14/2024		
004008954471	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	05/20/2024		
004008956343	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	352.40	TRAVERSE - VEHICLE	05/17/2024		
004008956778	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	TRAVERSE - VEHICLE	05/23/2024		
004008957687	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	05/25/2024		
004008958415	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	352.40	TRAVERSE - VEHICLE	05/21/2024		
004008961287	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	300.00	352.40	TRAVERSE - VEHICLE	05/23/2024		
004008961899	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	TRAVERSE - VEHICLE	05/30/2024		
004008961921	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	05/28/2024		
004008965679	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	352.40	TRAVERSE - VEHICLE	05/30/2024		
004008968711	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	OBSERVE FROM ADJACENT TRACK	06/05/2024		
004008968752	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	06/03/2024		
004008969448	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	352.40	TRAVERSE - VEHICLE	05/31/2024		
004008969825	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	380.00	TRAVERSE - VEHICLE	06/01/2024		
004008971767	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	06/05/2024		
004008972129	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	330.00	380.00	TRAVERSE - VEHICLE	06/04/2024		
004008974310	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	OBSERVE FROM ADJACENT TRACK	06/15/2024		
004008974362	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	06/10/2024		MARTY CARLSON INSPECTED 335.O - 286.70
004008976472	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	380.00	TRAVERSE - VEHICLE	06/07/2024		
004008978425	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	06/12/2024		HEAT PATROL 91 F

Visual Track Inspections - Carrington Subdivision

Inspection Number	Roadmaster	Subdivision/Yard	Asset Description	Asset Type	Inspection Type	Start MP	End MP	Mode	Performed Date	Backdated from Date	Comments
004008981221	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	06/17/2024		
004008983633	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	380.00	TRAVERSE - VEHICLE	06/15/2024		
004008983729	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	OBSERVE FROM ADJACENT TRACK	06/21/2024		
004008985249	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	06/21/2024		
004008985861	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	352.40	TRAVERSE - VEHICLE	06/18/2024		JASON MANN MP 300 TO MP 286.7
004008987946	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	06/24/2024		
004008990332	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	TRAVERSE - VEHICLE	06/28/2024		
004008992002	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	352.40	TRAVERSE - VEHICLE	06/27/2024	06/28/2024	
004008992645	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	300.00	352.40	TRAVERSE - VEHICLE	06/25/2024		
004008994890	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	352.40	TRAVERSE - VEHICLE	07/02/2024		
004008997455	Enderlin	Carrington Sub	DRY LAKE SIDING	Siding (Signalled)	Regulatory, Regular Inspection	340.73	342.84	OBSERVE FROM ADJACENT TRACK	07/02/2024		
004008997627	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	380.00	TRAVERSE - VEHICLE	06/29/2024		
004008999805	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Regulatory, Regular Inspection	286.70	380.00	TRAVERSE - VEHICLE	07/05/2024		
004009000625	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	Special Inspection - Oil / Ethanol	286.70	380.00	TRAVERSE - VEHICLE	07/03/2024		

Visual Inspection - Conditions

Condition Number	Roadmaster	Subdivision/Yard	Asset Description	Asset Type	Start MP	End MP	Date Found	Category	Sub Category	Description	User Status	Repair Due Date	Detail Section Comments	Immediate Action	Immediate Comments	Final Action	Final Comments	Final Action Completed Date	Ref Inspection
002001527108	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	Main Track	342.80	342.80	05/11/2024	Track Structure	Rail Joint - Insulated	Insulated Joint Condition	Closed	06/10/2024	1 BOLT BROKE	Scheduled for Repair	REPLACE INSULATED PLUG	Repaired		05/17/2024	004008945958

Visual Inspections - Defects

Defect Number	Roadmaster	Subdivision/Yard	Asset Description	Asset Type	Start MP	End MP	Date Found	Category	Sub Category	Description	User Status	Value 1	Repair Due Date	Regulatory Reference	Detail Section Comments	Immediate Action	Immediate Comments	Final Action	Final Comments	Final Action Completed Date	Ref Inspection
002001526975	Enderlin	Carrington Sub	DRY LAKE EAST SIDING SWITCH	Turnout	340.73	340.73	05/10/2024	Track Structure Turnouts	General	Fastenings Not Intact Or Maintained	Closed		06/09/2024	FRA 133A15 Turnout or track crossing fastenings not intact or maintained.	CLIPS			Repaired	REPLACED	05/10/2024	004008932837
002001526976	Enderlin	Carrington Sub	DRY LAKE WEST SIDING SWITCH	Turnout	342.84	342.84	05/10/2024	Track Structure Turnouts	Frog / Guard Rail	Loose, Worn, Or Missing Frog Bolts	Closed		06/09/2024	FRA 133A12 Loose, worn, or missing frog bolts.				Repaired		05/10/2024	004008932826
002001527000	Enderlin	Carrington Sub	DRY LAKE WEST SIDING SWITCH	Turnout	342.84	342.84	05/10/2024	Track Structure Turnouts	Frog / Guard Rail	Loose, Worn, Or Missing Frog Bolts	Closed	1	06/09/2024	FRA 133A12 Loose, worn, or missing frog bolts.	LOSE HUCK BOLT	Scheduled for Repair		Repaired	REPLACED BOLTS JACOBSON	06/14/2024	004008932826
002001527001	Enderlin	Carrington Sub	DRY LAKE WEST SIDING SWITCH	Turnout	342.84	342.84	05/10/2024	Track Structure Turnouts	General	Fastenings Not Intact Or Maintained	Closed		06/09/2024	FRA 133A15 Turnout or track crossing fastenings not intact or maintained.	CLIPS			Repaired	REPLACED	05/10/2024	004008932826
002001541276	Enderlin	Carrington Sub	DRY LAKE EAST SIDING SWITCH	Turnout	340.73	340.73	06/28/2024	Track Structure Turnouts	General	Fastenings Not Intact Or Maintained	Closed		07/28/2024	FRA 133A15 Turnout or track crossing fastenings not intact or maintained.	CLIPS			Repaired	REPLACED	06/28/2024	004008949971

Visual Inspections - Maintenance Records - CWR

CWR Number	Item Number	Roadmaster	Subdivision/Yard	Asset Description	Rail	Start MP	End MP	Created On	User Status	Rail Section	Rail Manufacturer	Year Rail Rolled	Tie Type	Anchor Type	Anchor Pattern	Repair Info Type	Final Repair Due	Current Rail Temp	Rail Gap/Overlap Value	Est RNT Before Repair	Anchors/Clips Removed	R1 Exclude Gap	R2 Include Closure	Rail Added/Removed	Est RNT After Repair	Closure Method	Date Performed	Duplicate/RNOT Reason	Comments
002001528729	0002	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	RIGHT RAIL	342.80	342.80	05/16/2024	Closed	115RE	Nippon Steel	1997	Hardwood	Unit 5	ETA (Elastic or Clips)	Restressing	05/16/2025	105			400	300	300	0	105	Thermite Conventional +1" (Closure)	05/16/2024		
002001528729	0002	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	RIGHT RAIL	342.80	342.80	05/16/2024	Closed	115RE	Nippon Steel	1997	Hardwood	Unit 5	ETA (Elastic or Clips)	Restressing	05/16/2025	105			400	300	300	0	105	Thermite Conventional +1" (Closure)	05/17/2024		

Visual Inspection - Maintenance Record TWLD

Track Weld Number	Roadmaster	Subdivision/Yard	Asset Description	Rail	MilePoint	Date Performed	Type of Weld	Weld Reference Number	Rail Temperature	Created On	Comments
002001528730	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	RIGHT RAIL	342.80	05/16/2024	Thermite Conventional +1" (Closure)	#16-17	105	01/16/2024	CUT IN A SLUG AT DRY LAKE WEST
002001529518	Enderlin	Carrington Sub	CARRINGTON ML 253.60-395.8	RIGHT RAIL	338.76	05/20/2024	Thermite Conventional +1" (Closure)	#18AND#19	85	01/20/2024	