



**EVENT DATA RECORDER
FACTUAL REPORT**

**ATTACHMENT – F
2003 BlueBird Schoolbus
ABS ECU Data**

**GRAY SUMMIT, MISSOURI
HWY-10-MH-018**

Meritor WABCO HABS Fault Report

VIN: 21009488
Date: 8/9/2010
Time: 3:45:55 PM
Page: 1

Fault #	Description	Status	SID	FMI	Count
1	Power Supply - Low voltage	Inactive	251	4	4
2	Right Rear Sensor - Incorrect data	Inactive	4	2	127
3	Right Front Sensor - Incorrect data	Inactive	2	2	255
4	Left Front Sensor - Incorrect data	Inactive	1	2	255
5	Right Rear Sensor - Speed drop out	Inactive	4	10	3
6	Left Front Sensor - Speed drop out	Inactive	1	10	3
7	Left Rear Sensor - Air gap too large	Inactive	3	1	3



Meritor WABCO Hydraulic ABS



Tractor ECU Display Component Tests End of Line Help



ECU Information

ECU Type HABS (12V)

Part Number 4460440860

Manufacture Date 15/02

Serial Number 21009488

Software Rev. HABS

Wheel Sensor

	RPM	MPH
Front Left	9	1.1
Front Right	9	1.1
Rear Left	9	1.1
Rear Right	9	1.1

Faults

None
 Existing
 Yes
 Stored

Learned Component

Retarder Relay

Controller Information

	Project #	Version #
Channel	8	10
Safety	5	7

Status

ABS Lamp Off

ABS Brake Off

ABS Retarder Off

Voltages

Battery 12.09

Ignition 12.09



8/9/2010

3:43 PM