

DAILY RECORD OF FACILITY OPERATION				PAGE NO
				Page 1 of 2
LOCATION Indianapolis, IN				IDENTIFICATION
				IND
TYPE FACILITY				OPERATING POSITION
				ATCT
OPERATING POSITION				CHECKED BY
				ALL
				AIR TRAFFIC MANAGER
				Barry L. Jeffries
UTC TIME	REMARKS			
0500	C.WAGNER ON CIC.WCLC; SECON LEVEL YELLOW IN EFFECT; TIPH AT RY23L AT TXY C2, D2 AND RY23R AT TXY A2 AND B2 SUSPENDED; TOWER PROVIDING VISUAL SEPARATION IAW SOP; RY 23L/R IN USE.IDS-5 TOUCHSCREEN BETWEEN LCC ANG GC NOT CALIBRATED.FREQ 135.45 OTS DUE TO CONSTANT NOISE. MSAW SPEAKERS AT ALL TWR POSITIONS HAVE BACKGROUND NOISE.Sink in Tower Cab emitting foul odor. -- EZ			
0758	T.HILTON ON -- EZ			
1101	K. GALITSKY ON. -- EZ			
1209	S. JAEGER ON. -- LO			
1307	WCLC. -- LO			
1334	RWY23R/5L CLSD. -- LO			
1438	RWY 23R/5L OPEN. -- LO			
1621	C. MUSIC ON. -- CM			
1633	E. BAKER ON. -- EB			
1706	D. LEWIS ON. -- DD			
1734	TOWER PROVIDING VISUAL @ 4 MILES. -- DD			
1809	TOWER NOT PROVIDING VISUAL SEPARATION. -- DD			
M 1831	IND-M-2012/12/02-0001 -- DD			
1849	SPARE CARD KEY #1 ISSUED TO BOB KLIER(ERAM). -- DD			
2001	WCLC. -- DD			
2022	C. MUSIC ON. -- CM			
2055	K. HOFMANN ON. -- KL			
2124	TOWER PROVIDING VISUAL SEPARATION at 4 MILE Final. -- KL			
2217	WCLC. -- KL			
E 2222	BAK Push To Talk line OTS, MOCC (BT) notified. -- KL			
2300	M. MCCOY ON CIC. -- KL			
0050	T. KOONCE ON, OVER DUE AIRCRAFT N92315/PA46 IFR LANDING I34 DID NOT CANCEL IFR FLIGHT PLAN. INREQ/ALNOT STARTED 2320z. -- TK			
0101	K. HOFMANN ON. -- KL			
0115	TOWER NOT PROVIDING VISUAL SEPARATION. -- KL			
0229	RY05R/L in use. -- KL			
0301	J AYLWARD ON CIC. -- KL			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.			SIGNATURE(S) OF WATCH SUPERVISOR(S)	

DAILY RECORD OF FACILITY OPERATION				PAGE NO
				Page 2 of 2
				DATE
				Dec 2, 2012
LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION	CHECKED BY
Indianapolis, IN	IND	ATCT	ALL	AIR TRAFFIC MANAGER Barry L. Jeffries
UTC TIME	REMARKS			
0335	C. FERRO ON CIC. -- CF			
0405	RY 23 L/R IN USE. -- CF			
0430	NOTIFIED SEARCH AND RESCUE FOUND N92315, FOUR FATALITIES. INFORMATION RECORDED ON 8020-9. -- HR			
0445	SPARE CARD KEY #1 OBSERVED BACK IN CABINET. -- EK			
0459	COB. -- HR			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.		SIGNATURE(S) OF WATCH SUPERVISOR(S)		

DAILY RECORD OF FACILITY OPERATION				PAGE NO
				Page 1 of 1
				DATE
				Dec 3, 2012
LOCATION	IDENTIFICATION	TYPE FACILITY	OPERATING POSITION	CHECKED BY
Indianapolis, IN	IND	ATCT	ALL	AIR TRAFFIC MANAGER Barry L. Jeffries
UTC TIME	REMARKS			
0500	E. KIRK JR. ON. WCLC; SECON LEVEL YELLOW IN EFFECT; TIPH AT RY23L AT TXY C2, D2 AND RY23R AT TXY A2 AND B2 SUSPENDE; TOWER PROVIDING VISUAL SEPARATION IAW SOP; RY 23L/R IN USE.CFPL: IDS-5 TOUCHSCREEN BETWEEN LCC ANG GC NOT CALIBRATED. FREQ 135.45 OTS DUE TO CONSTANT NOISE. MSAW SPEAKERS AT ALL TWR POSITIONS HAVE BACKGROUND NOISE. Sink in Tower Cab emitting foul odor. BAK Push To Talk line OTS, MOCC (BT) notified. -- EK			
0507	LATE ENTRY: DVRS/STARS FACILITY. -- HR			
0508	LATE ENTRY: 12/2/2012, 0045Z, E. KIRK JR ON. -- HR			
I CERTIFY that entries above are correct, that all scheduled operations have been accomplished except as noted, and that all abnormal occurrences and conditions have been recorded.		SIGNATURE(S) OF WATCH SUPERVISOR(S)		